



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKR5244E

Cycle & Carriage Industries Pte Ltd

239 Alexandra Road
Singapore 159930

Vehicle & Document Information

WIP No 25196
Reg No/Reg Date SKR5244E / 13/02/2015
Date In/Mileage / 0
Chassis No WDD246243J299968
Engine No 27091030572709
Make/Model MB/B 200 SEDAN (W246) "STYLE
Colour/Trim 027 761 Polar Silv/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator				
CSI00001	Cash	13/07/2018/ 17:35	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A BPILAB								960 1200.00
DISASSEMBLE AND REPLACE ON FRONT BUMPER AND GRILLE								600 1200.00
A BPIRES								
RESPRAY ON FRONT BUMPER								
A BPILAB							0.10	✓ 380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
M BPNSUN								
POLICY NO/ACC DATE : B29070379MCY // 12.07.18								
DRIVE IN/EXCESS : 13.07.18 // TP CAR NO.:GX3303Y= AXA INS								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
M	FRONT BUMPER				1.00	1360.40	00.00	de ✓ 1360.40
M	LOCK CLIP				2.00	2.51	00.00	rec ✓ 5.02
M	COMPANY SIGN				1.00	59.73	00.00	rec ✓ 59.73
M	TOP BASIC MOUNTING FOR BUMPER				1.00	136.43	00.00	? 136.43
M	IMPACT ABSORBER				1.00	127.50	00.00	? 127.50
M	RIGTH BOTTOM ORNAMENTAL TRIM				1.00	64.91	00.00	? 64.91
M	LEFT BOTTOM ORNAMENTAL TRIM				1.00	64.91	00.00	? 64.91
M	RIGHT TOP ORNAMENTAL TRIM				1.00	64.91	00.00	? 64.91
M	LEFT TOP ORNAMENTAL TRIM				1.00	67.74	00.00	? 67.74
M	BRACKET				1.00	16.56	00.00	? 16.56
M	RADAR SENSOR				1.00	1157.08	00.00	? 1157.08
M	BEAM-STAR				1.00	72.06	00.00	? 72.06
M	MERCEDES STAR				1.00	130.65	00.00	mis ✓ 130.65
M	RAD. GRILLE MESH				1.00	160.15	00.00	de ✓ 160.15
M	RIGHT AIR FLOW SERRATION				1.00	66.25	00.00	? 66.25
M	LEFT AIR FLOW SERRATION				1.00	66.25	00.00	? 66.25
M	CROSS MEMBER				1.00	310.54	00.00	? 310.54
M	CENTRAL RIGHT COVER CROSS MEMBER				1.00	66.98	00.00	x 66.98
M	FRONT PANEL SEALING LIP				1.00	12.52	00.00	x 12.52
M	FRONT SUPPORT PANEL				1.00	622.03	00.00	x 622.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Tanfer 97495749

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Authorized signatory and company stamp

Nett 7,412.62
7% GST on 7412.62 518.88
Total Payable 7,931.50

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg