

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 5251220Hat Workshop m/s 2nd

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

CA / PR Seen: 2

Consistent? : Yes or No

Est. Repairs: 7 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5251220HYr Regn: 9, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mazda 5c.c. 1998Colour: 3000

A/C: Insured / Std / NI / NA

Sp. Reading: 25-41

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6CW1071H0126453Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 13/7/18D.O.I. 17/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rear w/screen shattered.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AM 277 56569
2/5 @ 9000 (Red: 8381:48%)

RECEIVED 30 JUL 2018

Date/Time, File Pass to?



: Prel. Report

1) 8019 Typist

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 7Resurvey No. of Trip: 1+1

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee: 170+105Transportation: 50Photos: 50+50Others: 129TOTAL: 80TOTAL: 634Report Format: TPLump Sum / I.B.I. (\$) 9000/-

Ref. No : <u>CS/TP/8012857/utb n2</u>	Res. Date: <u>18/7/18</u>	Date Received:
Veh. No : <u>SL512204</u>	SP: _____	WKSP: <u>A. M. J.</u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	
3. Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation / b) Days of repair	
others:	<u>✓</u>	
Final Re-inspection or Progress Photos		Inspected By: <u>[Signature]</u>

MSME18081295 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 16/07/2018 12:28
SUBMITTED BY: Chio Poh Yng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available storesale.

ACCIDENT STATEMENT

Date Of Report	16/07/2018 12:29
Date Of Accident	13/07/2018 11:20
Exact Location Of Accident	JUNCTION OF EUNOS LINK ALONG AIRPORT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS1220H
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD AZTAN BIN AHMAD
NRIC No	S7040933Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +85-91170568
Alternative Phone No	OFFICE-91170568
Vehicle Particulars	
Manufacturer	MAZDA
Model	5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700055919
Cover Note Number	
Driver	
Name of Driver	SHARIFAH MARDZIAH ALJUNIED
NRIC No	S6841146G
Date Of Birth	21/10/1968
Occupation	INDOOR
Date Of Driving Pass	06/04/1990
Driving Experience	28 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97337836
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 637D PUNGGOL DRIVE #03-367
 Postcode 824637
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name PUNGGOL N.P.C
 Police Station Address ROAD: 21A TEBING LANE , POSTCODE: 828637 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20180713/2133.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YL8024U
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

SHARIFAH MARDZIAH ALJUNIED

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLS1220H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

— As per police report —

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CLAIMC SketchPlanForm_V3

2



SINGAPORE POLICE FORCE



T/20180713/2133

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 4

Report No. T/20180713/2133

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/07/2018 18:37		Vide Report No.: G/20180713/0097		Station Diary No.: 59	
Informant's Particulars					
Name of Informant: SHARIFAH MARDZIAH ALJUNIED			Address: APT BLK 637D PUNGGOL DRIVE #03-387 SINGAPORE 824637		
ID Type / ID No.: NRIC NO / S6841146G			Contact No.: Home/Office: Mobile: 97337836		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 49	Date of Birth: 21/10/1968	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: Housewife			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/07/2018 11:20	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 AIRPORT ROAD EUNOS LINK Travelling along Airport Road after exit from KPE. Accident happened at junction of Airport Road and Eunos Link.				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving vehicle against - stopped vehicle				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SLS1220H	Car	MAZDA		Brown	Seriously Damaged	0
YL8024U	Lorry	MITSUBISHI		White	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20180713/2133

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 4

Report No. T/20180713/2133

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLS1220H	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700055919	08/09/2017	07/09/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SHARIFAH MARDZIAH ALJUNIED	ID No.	S6841146G
Related Vehicle	SLS1220H (Car)	Contact No.	97337836
Hospital/Clinic	RAFFLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	13/07/2018	Date Discharge	13/07/2018
No. of Days granted Medical Leave	05	Degree of Injury	NIL
Driver			
Name	THONG KWEE MENG	ID No.	S2689698C
Related Vehicle	YL8024U (Lorry)	Contact No.	96547628
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 13/07/2018 at about 1120hrs, I was driving my car one brown colour Mazda bearing plate no. SLS1220H along Airport Road and I had stopped at the traffic light cross junction of Eunos Link as the traffic light had turned red. I have a habit of looking at the rear view mirror whenever I stop at traffic light and I spotted a white colour lorry bearing plate no. YL 8024U approaching my car at a very fast speed. The next moment, the said lorry collided to the rear of my car.

I was shocked from the collision and was unable to move to get out of the car. At that point, my neck and back hurts as well. I was then approached by a male passerby who informed that he is medically trained and he asked me not to move and stay still. He also assisted to call the police and ambulance. The driver of the lorry also came to make a check on me and apologised for causing the accident. Subsequently ambulance arrived and I was conveyed to Raffles Hospital.

After I left for the hospital, my husband went to the accident scene to takeover the car and he had handed over both the front and back in-car camera SD card to the Traffic Police who was at scene. I was also



**SINGAPORE
POLICE FORCE**



T/20180713/2133

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

4 of 4

Report No. T/20180713/2133

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Staff Sgt ANG PEI YING, AGNES
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR FAIZAL BIN YAHYA Contact No.: 65476202
Authentication Stamp NP168

Signature Of Informant:
Date/Time: 13/07/2018 18:37
Classification Of Case:



**SINGAPORE
POLICE FORCE**



T/20180713/2133

Police Station Of Origin:

Punggol N.P.C

21A Tebing Lane SINGAPORE 828837

Tel No: 1800-6049999

3 of 4

Report No. T/20180713/2133

CONTINUATION OF REPORT

advised to proceed to the nearest police station to lodge a traffic accident report vide G/20170713/0097,
in-charge case IO Ivan, Tel: 65476170.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0933Z
Vehicle Details	
Vehicle No.:	SLS1220H
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 WAGON 2.0 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	PE10520512
Chassis No.:	JM6CW1071H0126153
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,537.00
Original Registration Date:	08 Sep 2017
First Registration Date:	08 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$17,537.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Sep 2027
PARF Rebate Amount:	\$13,152.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$43,417.00
Total Rebate Amount:	\$56,569.00

The information contained herein is correct as at 17 Jul 2018

OK

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement

Sell it yourself! Advertise it at just


\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A RSZ







\$2800 Downpayment Monthly
From \$738 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd


[Browse by Category](#)
[Sort by](#)

6 vehicles

Mazda 5

[Advanced](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
Search Selection	Mazda 5		Any	Any	2017	Any	
	Mazda 5	Mazda 5 2.0A Sunroof	\$98,800	\$10,240 /yr	27-Mar-2017	1,998 cc	37
10% Down Payment And Monthly Of Only \$1290! Mpv With A Big Personality! Fully Agent Serviced With 3 Years Or 100K No Hassle At All! Always Parked Under Shelter, Bidded Carplat...							
Cars 88 Pte Ltd							
Posted: 16-Jul-2018 Tags: 2017 Mazda 5, Mazda 5, Mazda, 5, Used Mazda							
	Mazda 5	Mazda 5 2.0A Sunroof	\$99,800	\$10,050 /yr	23-Jun-2017	1,998 cc	11
Road Tax Renewed Till 22 December 2018. 10k Free Servicing Not Done Yet. I'm Migrating, Would Like To Sell Quick. Pr Some Scratches Due To Parking. See Pictures.							
Posted: 14-Jul-2018 Tags: 2017 Mazda 5, Mazda 5, Mazda, 5, Used Mazda							
	Mazda 5	Mazda 5 2.0A Sunroof	\$99,800	\$10,310 /yr	11-Apr-2017	1,998 cc	16
\$0 Down Payment For Limited Period Only! Other Loan Packages From Bank/In House/Balloon Scheme Available With M Approval Rates! 1 Owner Only! Full Service History And 3 Yea...							
Le Motor Enterprise							
Posted: 13-Jul-2018 Tags: 2017 Mazda 5, Mazda 5, Mazda, 5, Used Mazda							
	Mazda 5	Mazda 5 2.0A Sunroof	\$106,800	\$10,430 /yr	15-Dec-2017	1,998 cc	3
Down Payment 10% Only! From \$1264/Month. Agent Unit With Records. 3 Years Warranty From Reg Date. Road Tax Till Mileage. Great Handling And Stocked With Plenty Of Features...							
Audax Auto Pte Ltd							
Posted: 14-Jun-2018 Tags: 2017 Mazda 5, Mazda 5, Mazda, 5, Used Mazda							

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Compare](#)
[On The Move](#)
[Lifestyle](#)



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

Not Allowed
 2/5 9000
 707.

SLS1220H

	Rear windscreen	Skotted	1071.80	✓
	Rear windscreen moulding	per	57.60	✓
	Rear windscreen inner seal	per	52.50	✓
	Rear windscreen inner side garnish o/s	subn	181.20	✓
	Tailgate	body	1559.20	✓
	Tailgate Rear logo	per	65.00	✓
	Tailgate 'maxx' emblem	per	43.10	✓
	Tailgate 'S' emblem	per	76.10	✓
	Tailgate 'SKYACTIV' emblem	per	34.50	✓
	Tailgate inner lock	tw/sm	244.00	✓
	Tailgate weatherstrip	tw	169.20	✓
2 pc	Tailgate reflectors @ 381.20	cm	770.40	✓
2 pc	Tailgate reflector gaskets @ 90.80	per	181.60	✓
	Tailgate inner trim board	per/cm	488.20	✓
1 set	Tailgate inner trim board clips	per	50.00	✓
	Tailgate outer garnish	cm	459.80	✓
	Tailgate rear wiper motor	short	650.30	✓
	Rear bumper	D.S	915.40	✓
2 pcs	Rear bumper side holders @ 66.50	o/s	133.00	✓
1 set	Rear bumper clips	per	50.00	✓
	Rear bumper reinforcement	per	150.80	✓
	Rear bumper reflector o/s	cm	55.00	✓
	Rear bumper splash shield o/s	tpn	63.20	✓
	Rear end panel	body	491.10	✓
	Rear end panel top garnish	tw	248.50	✓
	Rear fender inner trim board o/s	per/cm	645.30	✓
2 pcs	Rear taillamps @ 573.00	o/s/cm	1146.00	✓
	Taillamp housing panel o/s	DD	245.50	✓
	Rear floor panel	n	1045.30	X
	Rear floor panel top board	n	488.20	X

(207)

11831.00

9658
 7726.4



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-29-53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

SLS122014

	S. Wolf			
1 set	Rear bumper reverse sensor	Shokh	280.00	200
	Rear and panel sealant	u	50.00	✓
	Rear windscreen sealant	u	20.00	40
	Rear windscreen solar film	u	380.00	200
1 set	Rear in-car camera	Daye	500.00	380
	Rear floor panel insulato-	u	250.00	X
	Rear licence plate w/holder	sent	50.00	40
	To check wiring		80.00	-30
	To dismantle & replacing reverse sensor		80.00	-50
	To dismantle & replacing rear windscreen		150.00	-120
	To dismantle & ref. seat / cushion upholstery		150.00	-100
	To dismantle & ref. tailgate components		120.00	-60
	To dismantle & ref. rear exhaust	11	100.00	X
	To spray rust proofing		150.00	80
	To mount vehicle on car-o-liner	11	380.00	X
	labour for panel beating, cut, weld, straighten		1280.00	1000
	replacing parts			
	To putty & spray painting		1500.00	1200

TOTAL 17380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1276-P



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18012857/Utbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 01-08-2018



ON BEHALF OF MUHAMMAD AZTAN BIN AHMAD Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLS 1220H
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	17/07/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6CW1071H0126153	Colour	BROWN
Odometer	25414	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	TOYO	7 mm
L/H Front Tyre	205/55 R16	TOYO	7 mm
R/H Rear Tyre	205/55 R16	TOYO	7 mm
L/H Rear Tyre	205/55 R16	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/07/2018	Inspection Date	17/07/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 1220H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN	SHATTERED	1,071.80	1,071.80
1	REAR WINDSCREEN MOULDING	NECESSARY	57.60	57.60
1	REAR WINDSCREEN INNER SEAL	NECESSARY	52.50	52.50
1	REAR WINDSCREEN INNER SIDE GARNISH O/S	DEFORMED / TORN	181.20	181.20
1	TAILGATE	BADLY DENTED	1,559.00	1,559.00
1	TAILGATE REAR LOGO	NECESSARY	65.00	65.00
1	TAILGATE "MAZDA" EMBLEM	NECESSARY	43.10	43.10
1	TAILGATE "5" EMBLEM	NECESSARY	76.10	76.10
1	TAILGATE "SKYACTIV" EMBLEM	NECESSARY	34.50	34.50
1	TAILGATE INNER LOCK	TWISTED / JAMMED	244.00	244.00
1	TAILGATE WEATHERSTRIP	TWISTED	169.00	169.00
2	TAILGATE REFLECTORS @\$385.20	CRACKED	770.40	770.40
2	TAILGATE REFLECTOR GASKETS @\$90.80	NECESSARY	181.60	181.60
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	488.20	488.20
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE OUTER GARNISH	CRACKED	459.40	459.40
1	TAILGATE REAR WIPER MOTOR	SHORTED	650.30	650.30
1	REAR BUMPER	DISTORTED	915.40	915.40
2	REAR BUMPER SIDE HOLDERS @\$66.50	O/S BENT	133.00	66.50
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER REINFORCEMENT	BENT	150.80	150.80
1	REAR BUMPER REFLECTOR O/S	CRACKED	55.00	55.00
1	REAR BUMPER SPLASH SHIELD O/S	TORN	63.20	63.20
1	REAR END PANEL	BADLY DENTED	491.10	491.10
1	REAR END PANEL TOP GARNISH	TWISTED	248.50	248.50
1	REAR FENDER INNER TRIM BOARD O/S	DEFORMED / CRACKED	645.30	645.30
2	REAR TAILLAMPS @\$573.00	O/S CRACKED	1,146.00	573.00
1	TAILLAMP HOUSING PANEL O/S	DENTED	245.50	245.50
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,045.30	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	488.20	-

Report Ref No. CS/TP18012857/Utbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-1,931.60
			11,831.00	7,726.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NECESSARY	380.00	200.00
1	SET REAR IN-CAR CAMERA (SN)	DAMAGED	500.00	380.00
1	REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	250.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
			1,560.00	910.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	100.00
	TO DISMANTLE & REFIX TAILGATE COMPONENTS.		120.00	60.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		150.00	80.00
	TO MOUNT VEHICLE ON CAR-O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,280.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			3,990.00	2,640.00
GRAND TOTAL			17,381.00	11,276.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CS/TP18012857/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.