

REPAIR BILL

合合車廠私人有限公司 HUP HUP WORKSHOP PTE. LTD.

27-A, JURONG PORT ROAD, #01-29, SINGAPORE 619101

TEL: 6265 5270, 6261 3407, 6265 1966 FAX: 6261 8456

Email: hupwshop@hotmail.com

Business Regn. / GST Regn. No. 19-8004325-G

No. OD/1955

Date: 15/09/2018

M/s. AXA INSURANCE PTE LTD

Vehicle No. SLF 6712R

Make Honda Vezel 1.5 (A)

Your Ref:

Our Ref: HHW/OD 3098/2018

1 pc	Tailgate		1100.90
1 pc	Rear windscreen glass outer moulding		151.80
1 pc	Tailgate inner lock		96.60
1 pc	Rear bumper		508.50
1 pc	Tailgate (VEZEL) name plate		55.30
5 pcs	Rear bumper clips	@ \$ 3.90	19.50

			1932.60
Less 20%			- 386.52

			1546.08
2 tube	Rear windscreen glass sealant	@ \$20.00	40.00SN
1 set	Reverse sensor & fixing		200.00SN
Dismantle and fix rear windscreen glass.			120.00
Labour charge to knock, repair rear end panel, tail lamp panel, dismantle, replace, align/fix parts and transfer accessories and mechanism. Repair rear silencer box.			500.00
Spray paint on rear end panel-inside/outside, tail gate-inside/outside, rear bumper, tail lamps inner panel, reverse sensor.			450.00

Less Policy Excess			2856.08
			- 500.00

Add GST 7%			2356.08
			164.93

(D/S: TWO THOUSAND FIVE HUNDRED TWENTY ONE AND CENTS ONE ONLY)			2521.01
			=====

for HUP HUP WORKSHOP PTE. LTD.