



New address:

160 Sin Ming Drive #03-01
Sin Ming AutoCity
Singapore 575722
Tel: 64533167

H/P 97909779

安 徒 生 摩 咯

HENDERSON MOTORS

SUBSIDIARY: HENDERSON AUTOMOTIVE ENGINEERS

~~BLOCK 21, SIN MING INDUSTRIAL ESTATE #01-50 TO 54, SINGAPORE 575679.~~

~~TEL : 453 3167, 453 2602 FAX : (65) 453 7683 TELEX : RS 23861 "RALEIGH"~~

16th July 2018

ESCO Pte Ltd
6 Harper Road #06-08
Leong Huat Building
Singapore 369674

*Not Authorized
C/Ling & T
Running After Paint
12 days*

Vehicle No. GBA3962A (Third party against GN8588L)

Quantity	Particulars	Amount	
1 pc	Bonnet	809.13	✓
1 pc	Bonnet Logo	41.75	✓
1 pc	Front Grille	490.96	✓
1 pc	Front Bumper Cover	479.57	✓
1 pc	Bonnet Lock <i>P-?</i>	824.46	✓
1 pc	Bumper Retainer	162.53	✓
1 pc	Support Panel	302.92	✓
1 pc	Spare Tank <i>P-?</i>	545.38	✓
1 pc	Washer Tank <i>P-?</i>	64.09	?
1 pc	Air Cooler	383.26	?
1 pc	Support Panel	302.92	X
1 pc	Aircon Condenser	231.15	✓
1 pc	Front Mudguard - L/H	207.47	✓
2 pcs	Front Head Lamp (R & L)	1,155.09	✓
2 pcs	Front Bumper Retainer Side (R & L)	55.85	✓
1 pc	Back Door	1,789.33	✓
1 pc	Back W/Screen Glass	1,274.78	✓
1 pc	Back Door Mirror	465.13	✓
1 pc	Back Door Logo	41.75	✓
1 pc	Ganish Back Door - outside	127.46	✓
1 pc	Toyota Sticker & Hiace	40.87	✓
1 pc	Rear Bumper Retainer	55.85	✓
1 pc	Board Back Door Trim	190.67	✓
1 pc	Rear Door Lock	267.09	✓
1 pc	Rear Door Rubber	394.79	?
1 pc	Rear Bumper Cover	399.13	✓
2 pcs	Tail Lamp (R & L)	549.77	✓
1 pc	Back Door Scuff	148.41	?
1 pc	Rear Cross Member Outer	331.49	✓
1 pc	Rear Cross Member - Inner	1,116.22	✓
		13,249.27	
	Less 20% <i>25%</i>	2,649.85	
		10,599.42	



安 徒 生 摩 咯
HENDERSON MOTORS

SUBSIDIARY: HENDERSON AUTOMOTIVE ENGINEERS

New address: .

160 Sin Ming Drive #03-01
Sin Ming AutoCity
Singapore 575722
Tel: 64533167
H/P: 97909779

BLOCK 21, SIN MING INDUSTRIAL ESTATE #01-50 TO 54, SINGAPORE 575679.

TEL : 453 3167, 453 2602 FAX : (65) 453 7683 TELEX : RS 23861 "RALEIGH"

Page 2

16th July 2018

ESCO Pte Ltd
6 Harper Road #06-08
Leong Huat Building
Singapore 369674

Vehicle No. GBA3962A (Third party against GN8588L)

<u>Quantity</u>	<u>Particulars</u>	<u>Amount</u>
	Balance	(A.11) 10,599.42 ✓
	Towing fee	100.00
	To dismantle and fix aircon & feon gas	120.00 100d
	To fix rear door glass	150.00 120d
	Labour to knock out dents and replace above parts	1,800.00 1500d
	To touch painting	1,500.00 1400d
	Total amount : -	14,269.42

Thank you


Ong Lily
Henderson Motors

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: