

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBE1906E (CHINA)

Accident Date : 09-07-2018

Date : 11-07-2018

Our Ref : SKD9330L / CHAN

LIM BOK THIAM

C/O ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND. EST. SECTOR C

#01-76

SINGAPORE 575642

*Not Authorized
Repair After Paint
Today*

ESTIMATE PRICE OF REPAIR FOR PEUGEOT 3008 1.6 TURBO ADVENTURE SKD9330L

1 PC	FRONT BUMPER CENTRE GRILLE ASSY	<i>CM</i>	\$550.00	<i>✓</i>
1 PC	FRONT BUMPER NUMBER PLATE GARNISH		\$180.00	<i>?</i>
1 PC	FRONT BUMPER PEUGEOT LOGO	<i>1/2</i>	\$230.00	<i>X</i>
			\$960.00	
		LESS 10%	\$96.00	
			<u>\$864.00</u>	

\$864.00

TO PUTTY AND SPRAY FRONT BUMPER

\$300.00 *2200*

TO DISMANTLE FRONT BUMPER FOR RENEW CENTRE GRILLE , ADJUST AND
REALIGN FRONT BUMPER & REFIX

\$400.00 *1500*
\$1,564.00

Singapore Dollars One Thousand Five Hundred Sixty Four Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: