

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048VV)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore



PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	15/07/2018
Vehicle Reg. No.:	SHD6998R	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	08/10/2015
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDFU546204	Chassis No:	KMHLB41UMGU078487
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair	4 (day)		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	2,055.78
Miscellaneous Items	10.00
Labour	780.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,845.78
+ GST 7.00% (\$\$)	199.20
Nett Amount (\$\$)	3,044.98

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 16 Jul 2018)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD6998R/16/07/2018 12:19**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>x repair</i>	20.00	0.00	*603.60 FL
2	1		*REAR BUMPER REINFORCEMENT <i>?</i>	20.00	0.00	*504.35 FL
3	1		*REAR BUMPER REINFORCEMENT BRACKET (LH) <i>?</i>	20.00	0.00	*180.00 FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET (RH) <i>?</i>	20.00	0.00	*180.00 FL
5	1		*REAR BUMPER REINFORCEMENT SIDE BRACKET (RH) <i>?</i>	20.00	0.00	*49.00 FL
6	1		*REAR BUMPER REINFORCEMENT SIDE BRACKET (LH) <i>?</i>	20.00	0.00	*49.00 FL
7	10		*REAR BUMPER CLIPS <i>x</i>	20.00	0.00	*22.00 FL
8	1		*REAR BUMPER SPONGE <i>-</i>	20.00	0.00	*143.40 FL
9	1		*REAR BUMPER UNDER COVER <i>-</i>	20.00	0.00	*225.00 FL
10	1		*LICENSE LAMP COVER <i>x repair</i>	20.00	0.00	*100.00 FL
11	1		*REVERSE SENSOR <i>x</i>	0.00	0.00	*135.70 F
12	1		*REAR NUMBER PLATE <i>-</i>	0.00	0.00	*25.00 F
13	1		*REAR BUMPER ADVERTISEMENT LOGO <i>-</i>	0.00	0.00	*50.00 F
14	1		*REAR FENDER ADVERTISEMENT LOGO (LH/RH) <i>-</i>	0.00	0.00	*200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,467.05
- List Item Discount on L Items (S\$)	411.27
Total Parts (S\$)	2,055.78

ComfortDelGro Engineering Pte Ltd/SHD6998R/16/07/2018 12:19. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	380.00 200
2	SPRAYPAINT	New	250.00 200
3	WIRING	New	50.00 X
4	REMOVE/REFIX REVERSE SENSOR	New	100.00 X
Gross Labour Cost (S\$)			780.00

ComfortDelGro Engineering Pte Ltd/SHD6998R/16/07/2018 12:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Kahin (CCLK)
 16/7/18 1400h
 2 Pys
 PIP
 After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: