

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #08-16
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6419 3000 Fax : 6835 7416
DEAR SIR / MADAM :

*Not Authored
I.B.I
Resurvey Bepany*

2 days

ACCIDENT REPAIR ON: SKX8078S
MODEL : BMW 218i CONVERTIBLE
POLICY NO : CN862140
CHASSIS NO : WBA1M32070V311285
YEAR OF MANUFACTURE : 2015

Date: 17/07/2018
Page : 1 of 2

DATE / TIME OF ACCIDENT: 12/07/2018 Time: 1335Hrs at ALONG TANJONG RD BESIDE AMARA HOTEL.
THIRD PARTY VEHICLE NO: SGZ1189M

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Front bumper	1	983.00	Torn	983.00 ✓
2	Front bumper side retainer LH	1	19.00	Necessary	19.00 X
3	Front bumper side retainer RH	1	19.00	Necessary	19.00 X
4	Front bumper sponge	1	63.00	Cracked	63.00 X
5	Front bumper reinforcement	1	383.00	Bented	383.00 X
6	Front bumper nozzle LH	1	194.00	Cut	194.00 ✓
7	Front bumper nozzle cover LH	1	58.00	Torn	58.00 ✓
8	Front bumper fog lamp garnish cover LH	1	107.00	Scratches	107.00 ?
9	Front bumper fog lamp grille LH	1	79.00	Scratches	79.00 ?
10	Front bumper fog lamp LH	1	276.00	Broken	276.00 ?
11	Front fender LH	1	546.00	Dented	546.00 X
12	Front fender shield LH	1	151.00	Cut	151.00 ?
13	Front fender shield clips	10	5.00	Necessary	50.00 ?
14	Headlamp LH	1	1,903.00	Scratches	1,903.00 ✓
15	Headlamp lower bracket LH	1	58.00	Torn	58.00 ?
16	Front wheel rim LH	1	1,099.00	Scratches	1,099.00 X

Sub-Total: 5,988.00

Less: 5% discount - 299.40

Total Parts after 5% discount: 5,688.60

Special Nett Items

1	Anti-rust coating	2	80.00	na	160.00 X
					160.00

Total Parts: 5,848.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplemental parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Rep:
Signature:

Labour Charges For LH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	900.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	900.00 2501

2501

2501

- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Provide skill labour to check and re-adjust wheel alignment
- 5 Provide skill labour to remove and refit/balancing wheel rim and tyre

60.00 *201*
nr 80.00 *x*
nr 80.00 *x*

Total Labour:

2,020.00

Total Parts & Labour:

7,868.60

GST 7%

550.80

Grand Total:

8,419.40

Estimate Repair Duration

7 days

ACCIDENT VEHICLE OF : **SKX8078S**

Page : 2 of 2

2 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

Name : Kenneth

Company : UAC

Date : 18/7/18

Time : 11.20 am

Contact No : _____

Email : _____