

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER Date: 17-08-2018

ERGO INSURANCE PTE LTD

CS3/EGI18012920/T1z4d3s2

Page No.:1 of 1

FIVESINGAPORE 038985				
			Code: EGI	
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SDR 3333C	Veh. Inspected	GBD 4U
	Policy No.		Coverage (\$)	0.00
	Claim No.	SDR 3333C	Excess (\$)	0.00
	Assign From	YEE PEI LI	Assign Date	17/07/2018
2.		Vehicle F	Particulars & Condition	
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTFHT02P600051823	Colour	RED
	Odometer	435383 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195 R15	MICHELIN	6 mm
	L/H Front Tyre	195 R15	MICHELIN	6 mm
	R/H Rear Tyre	195 R15	MICHELIN	6 mm
	L/H Rear Tyre	195 R15	MICHELIN	6 mm
4.	Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT T			FRONT N/S PORTION.	
5.		Ge	neral Information	
	Accident Date	13/07/2018	Inspect Date / Time	17/07/2018 (03:30 PM)
	Survey held at	SENG HWEE MOTOR		
		BLK 1018, #01-350 YISHUN	I INDUSTRIAL PARK A SINGAP	ORE 768760
5a.			Remarks	

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500- \$4,000

5b. **Estimate Days of Repair** ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Report Ref No. CS3/EGI18012920/T1z4d3s2

Inspected By

pupin

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.