

7/0/2000

ASS. REC. BY:

REF CS/FCI 18012927/Klad3

n2

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Serene Ler

of

FCI

Date/Time: 17/07/18 @ 9.17am

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 132M

Insured:

SHC 2199L

at Workshop m/s

Volkswagen

Tel:

93867833

of

247 Alexandra Rd

Policy No:

Claim No:

D18005414MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

12/07/2018

Insp: 17 tuas Ave 9

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9.44am @ 17/7/18

Person Contacted:

Shu shi

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJD 132M -X
	SHC 2199L- NS/HNC/7020475/Klvbn2 DOA: 24/10/2017
19/7/18 @ 3.26pm	revised to Serene Ler by email.
21/8/18 @ 2.14pm	Finalised Shu shi final fig to 20459.09, 17 days.
	CRed @ 78277.14, 58%


03/11/18
Surveyor *Farou*

REF:

04/59

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SJO 132M**
 at Workshop m/s: **Volkswagen Thugs**
 of _____
 Insured: **FEI**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **77K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est Repairs: **17** days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SJO 132M** Yr Regn: **2015 Aug**
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Volkswagen Touran 1.6** C.C. **1598**
 Colour: **Black** A/C: Insured / Std / NI / NA
 Sp. Reading: **40851** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WUG2221TZFW 052941**
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil ☒ S/Rim / STD A/Rim or
 Tyre Size: F: **225/45R17**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **12/07/18** D.O.I. **12/07/18**
 Survey held at **Volkswagen**
 Des. of Damages: Frt ☒ Rear / O/S / N/S / UIC / Rooftop or
N/S Frt & Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Refer to email for repair limit

RECEIVED 03 SEP 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) **03/11/18** ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **17**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

) S + RS. St

) Photos **580**

) Others **050**

) **679/18**

TOTAL

38X15: 570

170 + 570
50
50
138
978

Report Format :

Lump Sum / I.B.I. (\$) **20459.09**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012927/R1qd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2199L	Veh. Inspected	SJD 132M
Policy No.		Coverage (\$)	0.00
Claim No.	D18005414MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	17/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/07/2018	Inspection Date	17/07/2018
Survey held at	17 TUAS AVE 9		
Repairer	VOLKSWAGEN CENTRE SINGAPORE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005414MFSH

Date: 19 July 2018

Our Ref: CS/FCI18012927/R1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJD 132M

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/07/2018 at the premises of M/s VOLKSWAGEN, and have the following to report:-

Workshop Estimate Amount	: S\$ 48,736.23 .
Revised Estimate Amount	: S\$ 26,927.51 .
"Check" Items Amount	: S\$ 8,011.64 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the n/s front and rear portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-07-2018	Our Ref No. D18005414MFSH
Accident Date	12-07-2018	Claim Type. Third Party
Insured Vehicle	SHC2199L	Third Party Vehicle. SJD132M
Survey Location	247 ALEXANDRA ROAD	
Contact Person.	TANG SHU SHI	
Contact No.	69223502/ 93867833	Fax No. 62858620
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (EST. COR - \$50,614.83)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VOLKSWAGEN CENTRE SINGAPORE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 31 August 2018 9:16 AM
To: Ong, Germaine (VWG Singapore)
Cc: Tang, Shu Shi (VWG Singapore); Chee, Steven (VWG Singapore); Shiau Chan (LKKAUTO)
Subject: RE: FINALISATION SJD132M

Hi Germaine,

As spoken to Shu shi,
Finalised amount of \$ 20,459.09 / 17 days of repair is confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Rasul (LKKAUTO)
Sent: Friday, 31 August, 2018 9:04 AM
To: 'Ong, Germaine (VWG Singapore)'
Cc: Tang, Shu Shi (VWG Singapore); Chee, Steven (VWG Singapore); Shiau Chan (LKKAUTO)
Subject: RE: FINALISATION SJD132M

Hi Germaine,

Repair limit for this case is 20K only. I will submit as 20K
Refer to my email on 19/07/18


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Ong, Germaine (VWG Singapore) [<mailto:Germaine.ong@vw.com.sg>]
Sent: Monday, 30 July, 2018 10:11 AM
To: Rasul (LKKAUTO)
Cc: Tang, Shu Shi (VWG Singapore); Chee, Steven (VWG Singapore)
Subject: FINALISATION SJD132M

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 19 July 2018 3:26 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005414MFSH/1
Attachments: CSFCI18012927R1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SJD 132M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 17 July 2018 9:47 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005414MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 17 July 2018 9:17 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005414MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Thursday, 19 July, 2018 11:30 AM
To: 'Tang, Shu Shi (VWG Singapore)'; Admin A
Cc: Chee, Steven (VWG Singapore); Oh, Aik Seong (VWG Singapore)
Subject: RE: SJD132M

Hi Shushi,

The repair limit for this case is 20K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Tang, Shu Shi (VWG Singapore) [<mailto:shushi.tang@vw.com.sg>]
Sent: Tuesday, 17 July, 2018 6:10 PM
To: Rasul (LKKAuto); Admin A
Cc: Chee, Steven (VWG Singapore); Oh, Aik Seong (VWG Singapore)
Subject: FW: SJD132M

Hi,

May I know if there is any repair limit for this vehicle?


Please revert asap, thank you.

Best Regards,

Tang Shu Shi
Insurance Service Advisor
Aftersales

Volkswagen Centre Singapore (Macpherson)
1 Kampong Ampat
Singapore 368314

DID: +65 6922-3502
Mobile: +65 9386-7833
Main Line : +65 6305-7299
Main Fax: +65 6285-8620
shushi.tang@vw.com.sg
<http://www.vw.com.sg>



From: Oh, Aik Seong (VWG Singapore)
Sent: Tuesday, 17 July, 2018 5:44 PM
To: Tang, Shu Shi (VWG Singapore); Chee, Steven (VWG Singapore)
Subject: SJD132M

FYI


Best Regards

Oh Aik Seong
(Body & Paint Dept)
Aftersale

Volkswagen Group Singapore Pte Ltd
No: 17 Tuas Ave 9

Mobile No: +65-85187912

aikseong.oh@vw.com.sg
<http://www.vw.com.sg>



From: aikseong.oh@vw.com.sg [mailto:aikseong.oh@vw.com.sg]
Sent: Tuesday, July 17, 2018 5:31 PM
To: Oh, Aik Seong (VWG Singapore)
Subject: Scan von MyMFP

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0415G
Vehicle Details	
Vehicle No.:	SJD132M
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.6 TDI AT 1T332Z
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CAYAX6285
Chassis No.:	WVGZZZ1TZFW052941
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$25,114.00
Original Registration Date:	21 Aug 2015
First Registration Date:	21 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$22,160.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2025
PARF Rebate Amount:	\$16,620.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,209.00
COE Rebate Amount:	\$39,829.00
Total Rebate Amount:	\$56,449.00

The information contained herein is correct as at 19 Jul 2018

OK

77,000
56,449

20,551

20K



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

VW DRIVEEASY
Comprehensive

Certificate No. A 28797983 AVW

Excess : SGD1,000

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SJD132M

2. Name of Policyholder
Humaiyah binte Yusuf

3. Effective Date of the Commencement of Insurance for the purposes of the Act
21/08/2017

4. Date of Expiry of Insurance
20/08/2018

5. Persons or Classes of Persons entitled to drive*

Siti Aisyah Bahruddin Eilyaas
Ahmad Nu'man Bahruddin Eilyaas

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.



Signature / Date

Counter-Signatory:

Winner Consultancy Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Amy Ler
Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

XWCPLSASX2017071415537070

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8002395B



Name: NURASYIQIN BAHRUDDIN
EILYAAS
نورعاشقين بحرالدین إلیاس
Race: JAVANESE
Date of Birth: 29-01-1980 Sex: F
Country of Birth: SINGAPORE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2150415G



Name: HUMAIYAH BINTE YUSUF
حمیاء بنت یوسف
Race: JAVANESE
Date of Birth: 02-06-1955 Sex: F
Country of Birth: JOHORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8002395B
Name: NURASYIQIN BAHRUDDIN
EILYAAS
Birth Date: 29 Jan 1980
Issue Date: 05 May 2016

002564385J

A0239560



NRIC No. S8002395B



Blood Group: - Date of issue: 18-10-2002

Address: 43 BEDOK WALK
SINGAPORE 469144

1393141



NRIC No. S2150415G



Blood Group: O+ Date of issue: 31-10-1993

Address: 43 BEDOK WALK
SINGAPORE 1646

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg 05 May 2016

Measurement printout

VAS car measurement (camber centering and castor adjustment) (runout compensation)

Beissbarth © * VAS 6767 (SL)

M * R+ ** OK * VOLKSWAGEN_AG / 20.00 / 179 / C

Date: 13.07.2018 08:26:41

VOLKSWAGEN AG

Version (program)
v5.0b3102/v5.0b3102

Version (FWA)
v5.0b1507

Version (target data)
VOLKSWAGEN AG v20.00

Serial number
QY0000305

Last service
18.07.2016

Customer

Name: HUMAIYAH BINTE YUSUF

VOLKSWAGEN GROUP SINGAPORE PTE LTD
17 TUAS AVENUE 9
SINGAPORE

Vehicle

VIN: WVGZZZ1TZFW052941
Registration: SJD132M
Odometer: 40851KM

Order

Operator: 659/202
Order No.: 1794

Vehicle: VOLKSWAGEN AG v20.00

VOLKSWAGEN [EUROPE] * Touran [Typ 1T] * G27,G28 * Sport suspension

Reason: ACCIDENT ON FRONT & REAR PORTION...

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-1°32'	-0°30' [-1°20'] +0°30'	-1°33'
	right	-1°09'		-1°10'
Cross Camber		-0°22'	[0°30']	-0°23'
Individual Toe	left	+0°12'	-0°06' [+0°07'] +0°06'	+0°12'
	right	+0°15'		+0°12'
Total Toe		+0°27'	-0°12' [+0°14'] +0°13'	+0°24'
Setback		-0°07'		-0°06'
Geometrical driving axis		+0°01'	-0°10' [+0°00'] +0°10'	+0°00'
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+6°56'	-0°30' [+7°47'] +0°30'	+6°58'
	right	+7°43'		+7°47'
K.P.I. 20°	left	+15°15'		+15°15'
	right	+14°50'		+14°45'
Toe out on turns	left	-1°34'	-0°20' [-1°40'] +0°20'	-1°33'
	right	-1°24'		-1°26'
Camber	left	-1°11'	-0°30' [-0°41'] +0°30'	-1°10'
	right	-0°14'		-0°15'
Cross Camber		-0°57'	[0°30']	-0°55'
Individual Toe	left	-0°21'	-0°05' [+0°05'] +0°05'	-0°22'
	right	-0°23'		-0°21'
Total Toe		-0°44'	-0°10' [+0°10'] +0°10'	-0°44'
Setback		+0°20'		+0°20'
Included Angle 20°	left	+14°05'		+14°05'
	right	+14°34'		+14°31'
Max Steer to Left	left	+41°00'		+40°56'
	right	+33°23'		+33°27'
Max Steer to Right	left	+31°08'		+31°09'
	right	+38°09'		+38°07'

First capital (TP)



Service Order Confirmation

SERVICE ORDER NO: 18IP1794

CUSTOMER NO.: CV030708

CUSTOMER NAME: HUMAIYAH BINTE YUSUF

TELEPHONE NO.:

ADDRESS: 43 BEDOK WALK

Singapore

VEH No.: SJD132M

Order Date: 07/12/18

Reg Date: 08/21/15

KM: 36,930

VIN NO.: WVZZZ1TZFW052941

ENGINE NO:

SA: Tang Shu Shi

MODEL: Touran 6 1.6 TDI (DSG7) BMT MODEL NO.: 1T332Z

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P SUNDRIES AIR CON GAS	48	TU	1.25	?	60 ?x11
2	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280		224 280
3	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		384 480
4	B&P AIRCON VACUUM & REGAS AIRCON-NETT	1	TU	420	?	420 ?x11
5	B&P MECH R&R FRT U/CARRIAGE	3	TU	840		2520 1260 2520 1008
6	B&P MECH R&R RIM & BALANCE	1	TU	50		50 40
7	B&P WHEEL ALIGNMENT B&P WHEEL ALIGNMENT NETT	1	TU	360		360 288
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
9	B&P MACP LABOUR LABOUR REAR	8	UNIT	840		2520 2016
10	B&P MACP PAINT SPRAY PAINT REAR	6	UNIT	800	2940	3200 2240
11	B&P MACP LABOUR LABOUR FRT	8	UNIT	840		2520 2016
12	B&P MACP PAINT SPRAY PAINT REAR FX	6	UNIT	800		3200 2560
13	B&P MACP LABOUR R&R REAR W/SCREEN	1	UNIT	840		840 672
14	B&P MACP LABOUR TRANSFER BOOT LID MECHANISM	1	UNIT	840		420 336
15	B&P NUMBER PLATE B&P NUMBER PLATE -REAR	1	ST	80		80 64
16	EXT00009 SUPPLY/INSTALL REVERSE SENSOR	1	PCS	400		400 320
17	CINTURATO 225/45R17 Pirelli Cinturato P7 K1 225/45R	1	ST	680		702 476
Item						
18	D 004660M2 2K GLUE	1	PCS	183.87	ne / 101.17	183.87
19	D 002000A2 CLEANER	1	PCS	147.85	ne / 81.72	147.85
20	D 00920002 PRIMER	1	PCS	32.19	ne / 17.70	32.19
21	D 00950025 APPLICATOR	2	PCS	11.19	ne / 12.31	22.38
22	D 181802M1 ACTIVATOR	1	PCS	29.46	ne / 16.20	29.46
23	1T0827025Q LID	1	PCS	1,957.00	ne / 1076.05	1,957.00
24	WHT007341 NUT	4	PCS	2.52	ne / 5.54	10.08
25	8D0853419D RR NUMBER PLATE PACKING	1	PCS	14.61	ne / 8.04	14.61
26	1K9971829D GROMMET	2	PCS	29.16	ne / 52.08	58.32
27	1T0827566B PUSH BUTTON	1	PCS	677.59	? 400	677.59
28	1T0827505J 9B9 LOCK	1	PCS	204.43	ne / 113.44	204.43

Service Order Confirmation

SERVICE ORDER NO: 18IP1794

CUSTOMER NO.: CV030708

CUSTOMER NAME: HUMAIYAH BINTE YUSUF

TELEPHONE NO.:

ADDRESS: 43 BEDOK WALK

Singapore

VEH No.: SJD132M

Order Date: 07/12/18

Reg Date: 08/21/15

KM: 36,930

VIN NO.: WVGZZZ1TZFW052941

ENGINE NO:

SA: Tang Shu Shi

MODEL: Touran 5 1.6 TDI (DSG7) BMT

MODEL NO.: 1T332Z

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	3CN945087 3RD BRAKELIGHT	1	PCS	204.88	na - 112.68	204.88
30	1T0853630D ULM VW SIGN	1	PCS	99.72	na - 54.85	99.72
31	1T0853687C 739 NAME PLATE-TOURAN	1	PCS	79.89	na - 43.94	79.89
32	1T0853675AEGQF NAME PLATE-TDI	1	PCS	60.84	na - 33.46	60.84
33	1T0853675AGWWS NAME PLATE-BLUEMOTION	1	PCS	66.99	na - 36.34	66.99
34	1T0807421K GRU REAR BUMPER	1	PCS	1,329.72	DE - 731.35	1,329.72
35	1T0807521H GRU SPOILER	1	PCS	520.06	cea - 286.03	520.06
36	1T0807441C GRU TOWING COVER	1	PCS	54.90	cut - 30.20	54.90
37	1T0807305D REINFORCEMENT	1	PCS	560.31	? Xsu	560.31
38	1T0807863D BUMPER CENTRE BRACKET	1	PCS	63.27	na - 34.80	63.27
39	1T0807453 TAILLIGHT LOWER BRACKET LH	1	PCS	38.08	? ?	38.08
40	1T0807454 TAILLIGHT LOWER BRACKET RH	1	PCS	83.74	? ? } Xsu	83.74
41	1T0807393D BUMPER SIDE BRACKET LH	1	PCS	30.81	? ? } Xsu	30.81
42	1T0807394D BUMPER SIDE BRACKET RH	1	PCS	30.81	? ? } Xsu	30.81
43	1T0945105C REFELCTOR LH	1	PCS	87.97	su - 46.38	87.97
44	1T0945106C REFELCTOR RH	1	PCS	77.74	cea - 42.76	77.74
45	1T0823031Q FRT BONNET	1	PCS	1,432.65	na - 787.96	1,432.65
46	1T0807221M GRU FRT BUMPER	1	PCS	1,143.82	DE - 629.10	1,143.82
47	1T0805903D 9B9 SPOILER	1	PCS	406.47	? ? } Xsu	406.47
48	1T0807248K FOAM INSER	1	PCS	52.03	? ? } Xsu	52.03
49	1T0807109D REINFORCEMENT	1	PCS	558.81	? ? } Xsu	558.81
50	1T0807183C BUMPER SIDE BRACKET LH	1	PCS	53.08	na - 29.19	53.08
51	1T0807184C BUMPER SIDE BRACKET RH	1	PCS	53.08	X ? } Xsu	53.08
52	1T0853651BQWPF RADIATOR GRILLE	1	PCS	576.61	? ? } Xsu	576.61
53	1T0853677D 9B9 CENTRE LOWER GRILLE	1	PCS	223.33	? ? } Xsu	223.33
54	1T0853101B 2ZZ CENTRE LOWER GRILLE CHROME	1	PCS	193.81	na - 100.34	193.81
55	1T0853665M 9B9 LHS FOG LAMP GRILLE	1	PCS	108.24	su - 313.52	108.24
56	1T2941005H HEADLAMP LH	1	PCS	570.03	Bro - 100.74	570.03
57	5K0941699F FOG LAMP LH	1	PCS	182.43	cut - 100.74	182.43
58	1T0805588AF9B9 LOCK CARRIER	1	PCS	952.23	? Xsu	952.23



Service Order Confirmation

SERVICE ORDER NO: 18IP1794

CUSTOMER NO.: CV030708

CUSTOMER NAME: HUMAIYAH BINTE YUSUF

TELEPHONE NO.:

ADDRESS: 43 BEDOK WALK

Singapore

VEH No.: SJD132M

Order Date: 07/12/18

Reg Date: 08/21/15

KM: 35,930

VIN NO.: WVGZZZ1TZFW052941

ENGINE NO:

SA: Tang Shu Shi

MODEL: Touran 6 1.6 TDI (DSG7) BMT

MODEL NO.: 1T332Z

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
59	1T0805931A H/LAMP TOP PANEL LH	1	PCS	42.97		23.63 42.97 61 -
60	G 013040M2 COOLANT ADD 1.5 Ltr Ready Mix	2	PCS	27.00		54.00 ?-3 xan
61	1T0121283D AIR GUIDE LH	1	PCS	59.46		59.46 ?-3 xan
62	1T0821021D FENDER LH	1	PCS	814.98		448.24 814.98 Bue -
63	1T0821135C LHS FENDER BRACKET	1	PCS	30.19		16.60 30.19 nuc -
64	1T0805911N LHS FENDER LINER	1	PCS	143.16		78.74 143.16 DB -
65	1T0853515F GRU LHS FRT DOOR MLDG	1	PCS	105.10		57.51 105.10 xan -
66	5G0073147A FZZ ALLOY WHEELS 17" BLADE	1	PCS	1,166.97		641.83 1,166.97 cut -
67	311601361 RUBBER VALVE	1	PCS	1.72		0.19 1.72 nuc -
68	1K0407151BC FRT LHS LOWER ARM	1	PCS	518.17		254.59 518.17 ?-Bf -
69	1K0407365C FRT LHS LOWER ARM JOINT	1	PCS	200.43		110.28 200.43 ?-Bf -
70	1K0407255AC LHS WHEEL BEARING HOUSING	1	PCS	517.15		254.43 517.15 ?-Bf -
71	5K0498621 WHEEL BEARING	1	PCS	815.40		446.47 815.40 ?-nuc -
72	1T0413031GQ GAS SHOCK ABSORBER	1	PCS	394.80		217.14 394.80 ?-Bf -
73	1K0412249B TOP BEARING	1	PCS	40.74		22.41 40.74 ?-nuc -
74	1K0412331B TOP MOUNT	1	PCS	80.40		64.32 80.40 ?-nuc -
75	1K0423810A FRT LHS TRACK ROD	1	PCS	174.79		96.13 174.79 ?-Bf -
76	1K0423811K TIEROD END	1	PCS	230.65		126.86 230.65 ?-Bf -
77	N 90834901 CLIP	1	PCS	6.42		3.53 6.42 ?-nuc -
78	LIQUIMOLY3318 DEGREASER CLEANER 500ml	1	PCS	54.60		30.10 54.60 ?-nuc -

Remarks: FIRST CAPITAL INSURANCE

DOA: 12/07/2018

SURVEY BY



Service Order Confirmation

SERVICE ORDER NO.: 18IP1794

CUSTOMER NO.: CV030708

CUSTOMER NAME: HUMAIYAH BINTE YUSUF

TELEPHONE NO.:

ADDRESS: 43 BEDOK WALK

Singapore

VEH No.: SJD132M

Order Date: 07/12/18

Reg Date: 08/21/15

KM: 36,930

VIN NO.: WVZZZ1TZFW052941

ENGINE NO:

SA: Tang Shu Shi

MODEL: Touran 6 1.6 TDI (DSG7) BMT

MODEL NO.: 1T332Z

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

Reson

Hp 90010068

19/7/18

17 days

17/07/18 @ 1710

Reeq by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

TOTAL	48,736.23
GST AMOUNT	3,411.54
TOTAL AMOUNT	52,147.77



On Behalf Of COMPANY

Authorized Signature

Certified Goods/Service received:

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

Service Order Confirmation

SERVICE ORDER NO: 18IP1794

CUSTOMER NO.: CV030708

CUSTOMER NAME: HUMAIYAH BINTE YUSUF

TELEPHONE NO.:

ADDRESS: 43 BEDOK WALK

Singapore

VEH No.: SJD132M

Order Date: 12/07/18

Reg Date: 21/08/15

KM: 40,850

VIN NO.: WVGZZZ1TZFW052941

ENGINE NO:

SA: Tang Shu Shi

MODEL: Touran 6 1.6 TDI (DSG7) BMT

MODEL NO.: 1T332Z

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280	20	224
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480	20	384
3	B&P MECH R&R FRT U/CARRIAGE	1.5	TU	840	20	1,008
4	B&P MECH R&R RIM & BALANCE	1	TU	50	20	40
5	B&P WHEEL ALIGNMENT B&P WHEEL ALIGNMENT NETT	1	TU	360	20	288
6	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
7	B&P MACP LABOUR LABOUR REAR	3	UNIT	840	20	2,016
8	B&P MACP PAINT SPRAY PAINT REAR	3.5	UNIT	800	20	2,240
9	B&P MACP LABOUR LABOUR FRT	3	UNIT	840	20	2,016
10	B&P MACP PAINT SPRAY PAINT FRT	4	UNIT	800	20	2,560
11	B&P MACP LABOUR R&R REAR W/SCREEN	1	UNIT	840	20	672
12	B&P MACP LABOUR TRANSFER BOOT LID MECHANISM	0.5	UNIT	840	20	336
13	B&P NUMBER PLATE B&P NUMBER PLATE -REAR	1	ST	80	20	64
14	EXT00009 SUPPLY/INSTALL REVERSE SENSOR	1	PCS	400	20	320
15	CINTURATO 225/45R17 Pirelli Cinturato P7 K1 225/45R	1	ST	680	30	476
16	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
17	D 004660M2 2K GLUE	1	PCS	183.87	45 10/12	101.13
18	D 002000A2 CLEANER	1	PCS	147.85	45	81.32
19	D 00920002 PRIMER	1	PCS	32.19	45	17.70
20	D 00950025 APPLICATOR	2	PCS	11.19	45	12.31
21	D 181802M1 ACTIVATOR	1	PCS	29.46	45	16.20
22	1T0827025Q LID	1	PCS	1,957.00	45	1,076.35
23	WHT007341 NUT	4	PCS	2.52	45	5.54
24	8D0853419D RR NUMBER PLATE PACKING	1	PCS	14.61	45	8.04
25	1K9971829D GROMMET	2	PCS	29.16	45	32.08
26	1T0827505J 989 LOCK	1	PCS	204.43	45	112.44
27	3CN945067 3RD BRAKE LIGHT	1	PCS	204.88	45	112.68
28	1T0853630D ULM VW SIGN	1	PCS	99.72	45	54.85

Service Order Confirmation

SERVICE ORDER NO: 18IP1794

CUSTOMER NO.: CV030708

CUSTOMER NAME: HUMAIYAH BINTE YUSUF

TELEPHONE NO.:

ADDRESS: 43 BEDOK WALK

Singapore

VEH No.: SJD132M

Order Date: 12/07/18

Reg Date: 21/08/15

KM: 40,850

VIN NO.: WVGZZZ1TZFW052941

ENGINE NO:

SA: Tang Shu Shi

MODEL: Touran 6 1.6 TDI (DSG7) BMT MODEL NO.: 1T332Z

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	1T0853687C 739 NAME PLATE-TOURAN	1	PCS	79.89	45	43.94
30	1T0853675AEGQF NAME PLATE-TDI	1	PCS	60.84	45	33.46
31	1T0853675AGWWS NAME PLATE- BLUEMOTION	1	PCS	66.99	45	36.84
32	1T0807421K GRU REAR BUMPER	1	PCS	1,329.72	45	731.35
33	1T0807521H GRU SPOILER	1	PCS	520.06	45	286.03
34	1T0807441C GRU TOWING COVER	1	PCS	54.90	45	30.20
35	1T0807863D BUMPER CENTRE BRACKET	1	PCS	63.27	45	34.80
36	1T0945105C REFELCTOR LH	1	PCS	87.97	45	48.38
37	1T0945106C REFELCTOR RH	1	PCS	77.74	45	42.76
38	1T0823031Q FRT BONNET	1	PCS	1,432.65	45	787.96
39	1T0807221M GRU FRT BUMPER	1	PCS	1,143.82	45	629.10
40	1T0807183C BUMPER SIDE BRACKET LH	1	PCS	53.08	45	29.19
41	1T0853665P 9B9 LHS FOG LAMP GRILLE	1	PCS	182.43	45	100.34
42	1T2941005H HEADLAMP LH	1	PCS	570.03	45	313.52
43	5K0941699F FOG LAMP LH	1	PCS	182.43	45	100.34
44	1T0805931A H/LAMP TOP PANEL LH	1	PCS	42.97	45	23.63
45	1T0821021D FENDER LH	1	PCS	814.98	45	448.24
46	1T0821135C LHS FENDER BRACKET	1	PCS	30.19	45	16.60
47	1T0805911N LHS FENDER LINER	1	PCS	143.16	45	78.74
48	1T0853515F GRU LHS FRT DOOR MLDG	1	PCS	105.10	45	57.81
49	5G0073147A FZZ ALLOY WHEELS 17" BLADE	1	PCS	1,166.97	45	641.83
50	311601361 RUBBER VALVE	1	PCS	1.72	45	0.95
51	1K0407151BC FRT LHS LOWER ARM	1	PCS	518.17	45	284.99
52	1K0407365C FRT LHS LOWER ARM JOINT	1	PCS	200.43	45	110.24
53	1K0407255AC LHS WHEEL BEARING HOUSING	1	PCS	517.15	45	284.43
54	5K0498621 WHEEL BEARING	1	PCS	815.40	45	448.47
55	1T0413031QG GAS SHOCK ABSORBER	1	PCS	394.80	45	217.14
56	1K0412249B TOP BEARING	1	PCS	40.74	45	22.41
57	1K0412331B TOP MOUNT	1	PCS	80.40	45	44.22
58	1K0423810A FRT LHS TRACK ROD	1	PCS	174.79	45	96.13

Service Order Confirmation

SERVICE ORDER NO: 18IP1794

CUSTOMER NO.: CV030708

CUSTOMER NAME: HUMAIYAH BINTE YUSUF

TELEPHONE NO.:

ADDRESS: 43 BEDOK WALK
Singapore

VEH No.: SJD132M

Order Date: 12/07/18

Reg Date: 21/08/15 KM: 40,850

VIN NO.: WVGZZZ1TZFW052941 ENGINE NO:

SA: Tang Shu Shi

MODEL: Touran 6 1.6 TDI (DSG7) BMT MODEL NO.: 1T332Z

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
59	1K0423811K TIEROD END	1	PCS	230.65	45	126.86
60	N 90834901 CLIP	1	PCS	6.42	45	3.53
61	LIQUIMOLY3318 DEGREASER CLEANER 500ml	1	PCS	54.60	45	30.03

Remarks : FIRST CAPITAL INSURANCE

DOA : 12/07/2018

TP VEHICLE NO: SHC2199L

SURVEY BY: RASUL

LIMIT REPAIR: \$20,500

TOTAL	20,459.09
GST AMOUNT	1,432.14
TOTAL AMOUNT	21,891.22

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012927/R1qd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-09-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2199L	Veh. Inspected	SJD 132M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005414MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TOURAN 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WVGZZZ1TZFW052941	Colour	BLACK	
Odometer	40851	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	PIRELLI	6 mm	
L/H Front Tyre	225/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/07/2018	Inspection Date	17/07/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		17 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 132M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	2K GLUE (SN)	NECESSARY	183.87	101.12
1	CLEANER (SN)	NECESSARY	147.85	81.32
1	PRIMER (SN)	NECESSARY	32.19	17.70
2	APPLICATOR (SN)	NECESSARY	22.38	12.31
1	ACTIVATOR (SN)	NECESSARY	29.46	16.20
1	LID (SN)	BUCKLED	1,957.00	1,076.35
4	NUT (SN)	NECESSARY	10.08	5.54
1	RR NUMBER PLATE PACKING (SN)	NECESSARY	14.61	8.04
2	GROMMET (SN)	NECESSARY	58.32	32.08
1	PUSH BUTTON (SN)	SERVICEABLE	677.59	-
1	LOCK (SN)	SCRATCHED	204.43	112.44
1	3RD BRAKELIGHT (SN)	NECESSARY	204.88	112.68
1	VW SIGN (SN)	NECESSARY	99.72	54.85
1	NAME PLATE-TOURAN (SN)	NECESSARY	79.89	43.94
1	NAME PLATE-TDI (SN)	NECESSARY	60.84	33.46
1	NAME PLATE-BLUEMOTION (SN)	NECESSARY	66.99	36.84
1	REAR BUMPER (SN)	DEFORMED	1,329.72	731.35
1	SPOILER (SN)	CRACKED	520.06	286.03
1	TOWING COVER (SN)	CUT	54.90	30.20
1	REINFORCEMENT (SN)	SERVICEABLE	560.31	-
1	BUMPER CENTRE BRACKET (SN)	NECESSARY	63.27	34.80
1	TAILLIGHT LOWER BRACKET LH (SN)	SERVICEABLE	38.08	-
1	TAILLIGHT LOWER BRACKET RH (SN)	SERVICEABLE	83.74	-
1	BUMPER SIDE BRACKET LH (SN)	SERVICEABLE	30.81	-
1	BUMPER SIDE BRACKET RH (SN)	SERVICEABLE	30.81	-
1	REFLECTOR LH (SN)	SCRATCHED	87.97	48.38
1	REFLECTOR RH (SN)	CRACKED	77.74	42.76
1	FRT BONNET (SN)	BENT	1,432.65	787.96
1	FRT BUMPER (SN)	DEFORMED	1,143.82	629.10
1	SPOILER (SN)	SERVICEABLE	406.47	-
1	FOAM INSERT (SN)	SERVICEABLE	52.03	-

Report Ref No. CS/FC118012927/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REINFORCEMENT (SN)	SERVICEABLE	558.81	-
1	BUMPER SIDE BRACKET LH (SN)	NECESSARY	53.08	29.19
1	BUMPER SIDE BRACKET RH (SN)	SERVICEABLE	53.08	-
1	RADIATOR GRILLE (SN)	SERVICEABLE	576.61	-
1	CENTRE LOWER GRILLE (SN)	SERVICEABLE	223.33	-
1	CENTRE LOWER GRILLE CHROME (SN)	SERVICEABLE	193.81	-
1	LHS FOG LAMP GRILLE (SN)	SCRATCHED	108.24	100.34
1	HEADLAMP LH (SN)	BROKEN	570.03	313.52
1	FOG LAMP LH (SN)	CUT	182.43	100.34
1	LOCK CARRIER (SN)	SERVICEABLE	952.23	-
1	H/LAMP TOP PANEL LH (SN)	BENT	42.97	23.63
2	COOLANT ADD 1.5 LTR READY MIX (SN)	NOT NECESSARY	54.00	-
1	AIR GUIDE LH (SN)	NOT NECESSARY	59.46	-
1	FENDER LH (SN)	BUCKLED	814.98	448.24
1	LHS FENDER BRACKET (SN)	BUCKLED	30.19	16.60
1	LHS FENDER LINER (SN)	DEFORMED	143.16	78.74
1	LHS FRT DOOR MLDG (SN)	NECESSARY	105.10	57.81
1	ALLOY WHEELS 17 BLADE (SN)	CUT	1,166.97	641.83
1	RUBBER VALVE (SN)	NECESSARY	1.72	0.95
1	FRT LHS LOWER ARM (SN)	BENT	518.17	284.99
1	FRT LHS LOWER ARM JOINT (SN)	BENT	200.43	110.24
1	LHS WHEEL BEARING HOUSING (SN)	BENT	517.15	284.43
1	WHEEL BEARING (SN)	NECESSARY	815.40	448.47
1	GAS SHOCK ABSORBER (SN)	BENT	394.80	217.14
1	TOP BEARING (SN)	NECESSARY	40.74	22.41
1	TOP MOUNT (SN)	NECESSARY	80.40	44.22
1	FRT LHS TRACK ROD (SN)	BENT	174.79	96.13
1	TIE ROD END (SN)	BENT	230.65	126.86
1	CLIP (SN)	NECESSARY	6.42	3.53
1	DEGREASER CLEANER 500ML (SN)	NECESSARY	54.60	30.03
1	B&P NUMBER PLATE-REAR (SN)	SCRATCHED	80.00	64.00
1	PIRELLI CINTURATO P7 K1 225/45R (70%)(SN)	CUT	680.00	476.00
			19,446.23	8,355.09

Report Ref No. CS/FCI18012927/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	AIR CON GAS.	NOT NECESSARY	60.00	-
	CHECK WIRE HARNESS ECU,SENSOR,SOCKET.		280.00	224.00
	PROGRAMMING & CALIBRATION.		480.00	384.00
	VACUUM & REGAS AIRCON.	NOT NECESSARY	420.00	-
	R&R FRT U/CARRIAGE.		2,520.00	1,008.00
	R&R RIM & BALANCE.		50.00	40.00
	B&P WHEEL ALIGNMENT.		360.00	288.00
	LABOUR REAR.		6,720.00	2,016.00
	SPRAY PAINT REAR.		4,800.00	2,240.00
	LABOUR FRT.		6,720.00	2,016.00
	SPRAY PAINT FRT.		4,800.00	2,560.00
	R&R REAR W/SCREEN.		840.00	672.00
	TRANSFER BOOT LID MECHANISM.		840.00	336.00
	SUPPLY/INSTALL REVERSE SENSOR.		400.00	320.00
			29,290.00	12,104.00
	GRAND TOTAL		48,736.23	20,459.09
RECOMMENDED COST OF REPAIRS				20,459.09

Report Ref No. CS/FCI18012927/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.