

ASS. REC. BY:

REF: CS/FWD18012928/Avd322

Special Instruction:

Surveyor
Merimen

Adrian

ASSIGNMENT (Office)

From (Person):

Jasey Koh

of

FWD

Date/Time:

17/7/18 @ 9:45am

Estimated Cost:

Bill to:

☒

TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLG 4419X

Insured:

at Workshop m/:

Progressive Automotive

Tel:

6741 5336

of

Blk 3022A Ubi Rd 1 # 01-45/46

Policy No:

PNPV 2017-00006429

Claim No:

12018 00009007

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A.

16/07/2018

CA

☒

REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:36am @ 17/7/18

Person Contacted:

Pei Wen

Vehicle

☒

OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 4419X - X
18/7/18	Revert via merimen
18/7/18	Rec approved \$662 from Jasey by merimen
18/7/18	Informed Pei Wen c/A & \$600 by email
31/7/18	@ 11:30am Ray said pending for parts invoice
10/8/18	final fig \$7175 confirmed by email (Red 3146.50, 3490)

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection,

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days: Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/R/m / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages:

Frt /

Rear /

O/S /

N/S /

U/C /

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Progressive

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

17/07/18

Date / Time

Action / Instruction

OD FWD.

MV: 901K

PV: 52.8K

Nett: 372K.

Date/Time, File Pass to?

☐

Prel. Report

()

☐

Final Report

Date/Time, File Return to?

10/8 - typist

Report Format:

Lump Sum / T.B. / \$

meimen

7175/2

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Workend (\$

Survey Fee

Transportation

5 + 85 = 90

Photo

Other

TOTAL

250

50+50

10

360



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS/FWD18012928/Avd3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986		Date : 17-07-2018	
		Code : FWD	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLG 4419X
Policy No.	PNPV2017-00006429	Coverage (\$)	0.00
Claim No.	1201800009007	Excess (\$)	600.00
Assign From	MERIMEN (JOSEY LOH)	Assign Date	17/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/07/2018	Inspection Date	17/07/2018
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

View Received Message

This mail is associated with :

SLG4419X (1201800009007)

OD

Jul 16 2018 8:00AM

[CHOW CHEN HOW]

Progressive Automotive Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 08/08/2018 16:55 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7175.00) - SLG4419X - Claim Handler: Josey Loh

Approved:7175.00:

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Josey Loh	Date: 08 Aug 2018

Preliminary Advice

Vehicle No	: SLG4419X	Accident Date	: 16/07/2018
Make	: AUDI A3	Policy No.	: PNPV2017-00006429
Assignment Date	: 17/07/2018	Excess	: S\$600.00
Date of Inspection	: 17/07/2018	Est. Duration of Repair	: 7.00
Inspection At	: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,921.50	(incl.supplementary \$1190)
Revised Amount	:S\$	7,175.00	(incl.supplementary \$1190)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	7,175.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$		
Pre-Accident Value	:S\$	90,000.00	
COE / PARF Rebate	:S\$	53,800.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	36,200.00	

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 18 July 2018 1:59 PM
To: peiwen@progauto.com.sg
Cc: Ray Progressive; SUR
Subject: SLG 4419X-DOA: 16/7/2018 (FORWARD OD)

Dear Pei Wen,

As instructed by our client , please proceed to repair the **insured vehicle SLG 4419X (Excess S600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLG4419X (1201800009007)

OO

Jul 16 2018 8:00AM

[CHOW CHEN HOW]

Progressive Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 18/07/2018 13:34 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$6062.00) - SLG4419X - Claim Handler: Josey Loh

Approved:6062.00:Hi! Please re-seek mandate on check items after being verified

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 18 Jul 2018

Preliminary Advice

Vehicle No	: SLG4419X	Accident Date	: 16/07/2018
Make	: AUDI A3	Policy No.	: PNPV2017-00006429
Assignment Date	: 17/07/2018	Excess	: S\$600.00
Date of Inspection	: 17/07/2018	Est. Duration of Repair	: 7.00
Inspection At	: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,731.50
Revised Amount	:S\$	5,960.00
Check Items (Estimated)	:S\$	102.00
Total	:S\$	6,062.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	53,800.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,200.00

Remarks

(X)

The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

()

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

()

Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4765D
Vehicle Details	
Vehicle No.:	SLG4419X
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (ATTRACTION)
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	CZC564564
Chassis No.:	WAUZZZ8V4G1105109
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,074.00
Original Registration Date:	29 Sep 2016
First Registration Date:	29 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$17,104.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2026
PARF Rebate Amount:	\$12,828.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$40,972.00
Total Rebate Amount:	\$53,800.00

The information contained herein is correct as at 18 Jul 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	4765D
Vehicle Details	
Vehicle No.:	SLG4419X
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (ATTRACTION)
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	CZC564564
Chassis No.:	WAUZZZ8V4G1105109
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,074.00
Original Registration Date:	29 Sep 2016
First Registration Date:	29 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$17,104.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2026
PARF Rebate Amount:	\$12,828.00
COE Details	
COE Expiry Date:	28 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$40,000.00
Total Rebate Amount:	\$52,828.00

The information contained herein is correct as at 17 Jul 2018

OK



☐ Audi A3 Sedan 1.4A TFSI S-tronic Attraction \$94,800 \$10,870 /yr 21-Jun-2016 1,395 cc 33,452 km Luxury Available

Suave And Sophisticated A3 Sedan Powered By A Responsive And Frugal 1.4 TFSI Engine And Mated To A 7 Speed DSG Ensuring You A Powerful Daily Drive, Yet Returning Excellent Fuel Efficiency! Spacious Ca...

Select By Performance Premium Selection

☆ Posted: 09-Jul-2016 Tag: 2016 Audi A3, Audi A3, Audi A3, Used Audi

Placeholder ID



☐ Audi A3 Sedan 1.4A TFSI Attraction \$92,800 \$10,600 /yr 28-Jun-2016 1,395 cc 48,000 km Luxury Available

Facelift Model! Up To 90% Loan! Interest From 2.78%! Full Serviced And Warranty Till 2019 By Premium Auto! Sexy Red Luxurious! Powerful And Comfortable! Super Low Mileage! 1 Owner, Agent Unit! As Good...

☆ Posted: 04-Jul-2016 Tag: 2016 Audi A3, Audi A3, Audi A3, Used Audi

Placeholder ID



☐ Audi A3 Sedan 1.4A TFSI Attraction \$92,800 \$10,510 /yr 21-Jul-2016 1,395 cc - Luxury Available

Very Rare Highest Spec Attraction Model With 4-Door Keyless Sensors And Keyless Start Engine. Upgraded Audi MMI System With In-Built GPS. Additional Sporty Side Skirt Added By Previous Owner. Beautiful...

☆ Posted: 13-Jul-2016 Tag: 2016 Audi A3, Audi A3, Audi A3, Used Audi

Placeholder ID



How much is your car really worth?

Find out how much your car can sell for. Quotz helps owners like you, sell their cars at the HIGHEST PRICE guaranteed! If we fail, you'll get \$100 CASH! Free valuation via phone/online. Absolutely No obligations!

Find out more!



☐ Audi A3 Cabriolet 1.4A TFSI S-tronic \$132,800 \$14,240 /yr 19-Aug-2016 1,395 cc 24,470 km Sports Available

Super Low Mileage! 1 Owner Agent Unit, Rare And Most Exotic Audi Cabriolet 1.4 TFSI 123Bhp. Head Turner Sporty Audi Cabriolet. Most Suitable For Daily Usage As A 4 Seater High Coe. High ARF. With Lowes...

☆ Posted: 08-Aug-2016 Tag: 2016 Audi A3, Audi A3, Audi A3, Used Audi

Placeholder ID



☐ Audi A3 Sedan 1.4A TFSI S-tronic Attraction \$92,555 \$10,340 /yr 29-Aug-2016 1,395 cc 59,000 km Luxury Available

Attraction Model! 1 Owner! 2.28% Loan Interest. Free 1 Years Warranty Plus Free Car Servicing, Free Car Spa Polishing! Highest Trade In For Your Car. Low Down Payment, High Loan Available. \$3k Deposit...

Cars Inn Credit Pte Ltd

☆ Posted: 14-Aug-2016 Tag: 2016 Audi A3, Audi A3, Audi A3, Used Audi

Placeholder ID



☐ Audi A3 Sportback 1.0A TFSI S-tronic \$94,800 \$10,330 /yr 22-Dec-2016 999 cc 12,644 km Hatchback Available

Suave And Sophisticated A3 In Hatchback Guise With Knockdown Rear Seats Providing You With More Load Lugging Space And Configurations For Your Daily Lifestyle! Powered By A Responsive And Frugal 1.0 T...

Select By Performance Premium Selection

☆ Posted: 14-Aug-2016 Tag: 2016 Audi A3, Audi A3, Audi A3, Used Audi

Placeholder ID



☐ Audi A3 Sedan 1.0A TFSI S-tronic \$99,388 \$10,780 /yr 29-Dec-2016 999 cc 5,400 km Luxury Available

10% Down Payment From Only \$1330 Monthly! Agent Unit. Still Under Warranty. Still Have 2 Free Servicing. Lowest Mileage And In Immaculate Condition! Always Parked Under Shelter And Under-Utilized Henc...

Audas Auto Pte Ltd

☆ Posted: 13-Aug-2016 Tag: 2016 Audi A3, Audi A3, Audi A3, Used Audi

Placeholder ID

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car marketplace for parallel import cars. Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars to stationwagons, SUV, MPV, hatchback, to CNG cars & OPC cars. You can also buy from a car auction. Look up car loans, low mileage cars, car brands, compare rates & car insurance. Find buy used Audi A3, Audi A3 Singapore, used Audi A3 Singapore, used Audi A3, used vehicles Singapore or even buy used Audi A3 Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CNG results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that we believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

SHORTLISTED
Compare

Follow sgCarMart.com



Download on the App Store

GET IT ON Google play

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/07/2018 10:21
Date Of Accident	16/07/2018 08:05
Exact Location Of Accident	PIE TOWARDS TUAS NEAR EXIT 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG4419X
Insured/Policyholder	
Name Of Registered Owner	CHOW CHEN HOW
NRIC No	S8384765D
Email Address	CHENHOW83@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93691843
Alternative Phone No	OTHERS-93691843

Vehicle Particulars

Manufacturer	AUDI
Model	A3-1.4 TFSI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00006429
Cover Note Number	

Driver

Name of Driver	CHOW CHEN HOW
NRIC No	S8384765D
Date Of Birth	30/09/1983
Occupation	INDOOR
Date Of Driving Pass	28/06/2014
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93691843
Fax Number	
Contact Number	OTHERS-93691843
Email Address	CHENHOW83@GMAIL.COM

Address	45 SIMEI RISE #03-31 SINGAPORE
Postcode	528786
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YAP FOONG MEI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ6095D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	XC2313C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GSA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report in the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used by complete claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, settling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

15:25 AM
16/7/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

MIC/I No:

permer

Sketch Plan #2

SKETCH PLAN

	Vehicle No.
	A - SLG 4479X
	B - SKS 609SD
	C - XC 2313C
	Legend
Vehicle	Bike

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened near PIE toward Tucs (at Exit 9) The car front (SKS 609SD) suddenly jammed the break, i was not able to stop the car in time, therefore causing the accident.

ABS light was on after the accident. And the front headlight (left) and bumper was damage as well. And both windscreen got some scratches.

In addition, during the accident, vehicle B was hit by a trailer from the right lane when vehicle B trying to cut to the left lane.

There is some minor scratches on vehicle B left front.

Vehicle C didn't stop and drove away.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated time frame from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

16/11/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

10:25am

Reporting Centre/Personnel's Signature

Name:

NRIC/ID No.:

perman



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel:: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0718-6580
Policy No:	PNPV2017-00006429	Date of Loss:	16/07/2018
Vehicle Reg. No.:	SLG4419X	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOW CHEN HOW	Contact No:	+6593691843
Driver:	CHOW CHEN HOW		
Make/Model:	AUDI A3, 1.4 TFSI (A)	Vehicle Reg. Date:	29/09/2016
Vehicle Colour:	GREY		
Engine No:	CZC564564	Chassis No:	WAUZZZ8V4G1105109
Odometer:	33660 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336		
Remarks:	VEHICLE IS IN WORKSHOP		
Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	7,326.50
Miscellaneous Items	55.00
Labour	1,250.00
Paintwork Labour	1,100.00
Towing	0.00
Gross Total (\$\$)	9,731.50
+ GST 7.00% (\$\$)	681.21
Nett Amount (\$\$)	10,412.71

This claim is handled by: NG PEI WEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2018)

Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BONNET <i>distorted</i>	0.00	0.00	*1,100.00 F ✓
2	1	NA	*FRONT BONNET HINGE - LH <i>Best</i>	0.00	0.00	*25.00 F ✓
3	1	NA	*FRONT BONNET HINGE - RH <i>?</i>	0.00	0.00	*25.00 F <i>3</i>
4	1	NA	*FRONT BONNET ABSORBER - RH <i>new</i>	0.00	0.00	*50.00 F <i>+</i>
5	1	NA	*FRONT BONNET TOP LOCK - CENTRE <i>new</i>	0.00	0.00	*35.00 F <i>+</i>
6	2	NA	*FRONT BONNET TOP HOOK - LH; RH <i>new</i>	0.00	0.00	*80.00 F <i>+</i>
7	1	NA	*FRONT BONNET BOTTOM LOCK - CENTRE <i>not new</i>	0.00	0.00	*25.00 F <i>+</i>
8	1	NA	*FRONT BONNET INSULATOR <i>not new</i>	0.00	0.00	*80.00 F <i>+</i>
9	5	NA	*FRONT BONNET INSULATOR CLIP <i>new</i>	0.00	0.00	*7.50 F <i>+</i>
10	1	NA	*FRONT BONNET RUBBER <i>new</i>	0.00	0.00	*10.00 F ✓
11	1	NA	*FRONT BUMPER <i>distorted</i>	0.00	0.00	*700.00 F ✓
12	1	NA	*FRONT BUMPER CLIPS <i>new</i>	0.00	0.00	*50.00 F ✓
13	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>damaged</i>	0.00	0.00	*15.00 F ✓
14	1	NA	*FRONT BUMPER SIDE HOLDER - RH <i>not new</i>	0.00	0.00	*15.00 F <i>+</i>
15	1	NA	*FRONT BUMPER FOAM <i>crushed</i>	0.00	0.00	*50.00 F ✓
16	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	*265.00 F ✓
17	1	NA	*FRONT BUMPER TOWING COVER - RH <i>new</i>	0.00	0.00	*15.00 F <i>+</i>
18	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - LH <i>Missing</i>	0.00	0.00	*45.00 F ✓
19	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - RH <i>not new</i>	0.00	0.00	*45.00 F <i>+</i>
20	1	NA	*FRONT BUMPER NOZZLE COVER - LH <i>distorted</i>	0.00	0.00	*20.00 F ✓
21	1	NA	*FRONT BUMPER NOZZLE COVER - RH <i>new</i>	0.00	0.00	*20.00 F <i>+</i>
22	1	NA	*FRONT BUMPER NOZZLE PIPE - LH <i>crushed not new</i>	0.00	0.00	*100.00 F <i>+</i>
23	1	NA	*FRONT BUMPER NOZZLE - LH <i>crushed</i>	0.00	0.00	*80.00 F ✓
24	1	NA	*FRONT BUMPER NOZZLE - RH <i>not new</i>	0.00	0.00	*80.00 F <i>+</i>
25	1	NA	*FRONT BUMPER LOWER LIP - CENTRE <i>not new</i>	0.00	0.00	*60.00 F <i>+</i>
26	1	NA	*GRILLE ASSY <i>crushed</i>	0.00	0.00	*250.00 F ✓
27	1	NA	*GRILLE LOGO <i>new</i>	0.00	0.00	*40.00 F ✓
28	1	NA	*SUPPORT PANEL <i>crushed</i>	0.00	0.00	*265.00 F ✓
29	1	NA	*RADIATOR - OUTER <i>not new</i>	0.00	0.00	*250.00 F <i>+</i>
30	1	NA	*RADIATOR - INNER <i>not new</i>	0.00	0.00	*250.00 F <i>+</i>
31	1	NA	*CONDENSER	0.00	0.00	*280.00 F <i>+</i>
32	1	NA	*AUTO COOLER	0.00	0.00	*200.00 F <i>+</i>
33	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH <i>?</i>	0.00	0.00	*12.00 F <i>?</i>
34	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH <i>not new</i>	0.00	0.00	*12.00 F <i>+</i>
35	1	NA	*AIRCON FAN MOTOR W/FAN BLADE <i>not new</i>	0.00	0.00	*625.00 F <i>+</i>
36	1	NA	*HEAD LAMP - RH <i>not new</i>	0.00	0.00	*715.00 F <i>+</i>
37	1	NA	*HEAD LAMP - LH <i>smashed</i>	0.00	0.00	*715.00 F ✓
38	1	NA	*RADIATOR TOP HOSE <i>not new</i>	0.00	0.00	*110.00 F <i>+</i>
39	1	NA	*RADIATOR BOTTOM HOSE <i>new</i>	0.00	0.00	*75.00 F <i>+</i>
40	1	NA	*FRONT FENDER - LH <i>distorted</i>	0.00	0.00	*300.00 F ✓
41	1	NA	*FRONT FENDER COWLING - LH <i>torn</i>	0.00	0.00	*60.00 F ✓
42	1	NA	*FRONT FENDER COWLING CLIPS - LH <i>new</i>	0.00	0.00	*25.00 F ✓
43	1	NA	*WIPER TANK ASSY <i>distorted</i>	0.00	0.00	*80.00 F ✓
44	1	NA	*WIPER TANK MOTOR <i>?</i>	0.00	0.00	*65.00 F <i>?</i>

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
R=Franchise part.						
Total Parts (S\$)						7,326.50

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>New</i>	20.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>New</i>	35.00 ✓
Sub Total (S\$)			55.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,100.00 <i>900</i>
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; LH FRONT WHEEL HOUSE; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00 <i>900</i>
3	TO CHECK WIRING	New	20.00 ✓
4	TO RESET CHECK LIGHT	New	60.00 ✓
5	TO 4 WHEEL ALIGNMENT	New	70.00 ✓
Gross Labour Cost (S\$)			2,350.00

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling.
P/P 17/07/18.
Not Authorised.
OT Days.
Excess \$600.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2018)
 Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen S
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:2
 Validity: These estimates are valid only if they contain the print code (ab
 the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an ast

Estimates on Parts

No. Qty Part No. Particulars

1	1	NA	*FRONT BONNET <i>distorted</i>
2	1	NA	*FRONT BONNET HINGE - LH <i>Best</i>
3	1	NA	*FRONT BONNET HINGE - RH <i>new</i>
4	1	NA	*FRONT BONNET ABSORBER - RH <i>new</i>
5	1	NA	*FRONT BONNET TOP LOCK - CENTRE <i>new</i>
6	2	NA	*FRONT BONNET TOP HOOK - LH; RH <i>new</i>
7	1	NA	*FRONT BONNET BOTTOM LOCK - CENTRE <i>not 1</i>
8	1	NA	*FRONT BONNET INSULATOR <i>not new</i>
9	5	NA	*FRONT BONNET INSULATOR CLIP <i>new</i>
10	1	NA	*FRONT BONNET RUBBER <i>new</i>
11	1	NA	*FRONT BUMPER <i>distorted</i>
12	1	NA	*FRONT BUMPER CLIPS <i>new</i>
13	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>Repaired</i>
14	1	NA	*FRONT BUMPER SIDE HOLDER - RH <i>Not new</i>
15	1	NA	*FRONT BUMPER FOAM <i>crushed</i>
16	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>
17	1	NA	*FRONT BUMPER TOWING COVER - RH <i>not new</i>
18	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER
19	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER
20	1	NA	*FRONT BUMPER NOZZLE COVER - LH <i>Repaired</i>
21	1	NA	*FRONT BUMPER NOZZLE COVER - RH <i>new</i>
22	1	NA	*FRONT BUMPER NOZZLE PIPE - LH <i>crushed</i>
23	1	NA	*FRONT BUMPER NOZZLE - LH <i>crushed</i>
24	1	NA	*FRONT BUMPER NOZZLE - RH <i>not new</i>
25	1	NA	*FRONT BUMPER LOWER LIP - CENTRE <i>not 1</i>
26	1	NA	*GRILLE ASSY <i>crushed</i>
27	1	NA	*GRILLE LOGO <i>new</i>
28	1	NA	*SUPPORT PANEL <i>crushed</i>
29	1	NA	*RADIATOR - OUTER
30	1	NA	*RADIATOR - INNER <i>Not new</i>
31	1	NA	*CONDENSER
32	1	NA	*AUTO COOLER
33	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH <i>new</i>
34	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH <i>not</i>
35	1	NA	*AIRCON FAN MOTOR W/FAN BLADE <i>not new</i>
36	1	NA	*HEAD LAMP - RH <i>not new</i>
37	1	NA	*HEAD LAMP - LH <i>smashed</i>
38	1	NA	*RADIATOR TOP HOSE <i>new</i>
39	1	NA	*RADIATOR BOTTOM HOSE <i>new</i>
40	1	NA	*FRONT FENDER - LH <i>Distorted</i>
41	1	NA	*FRONT FENDER COWLING - LH <i>to new</i>
42	1	NA	*FRONT FENDER COWLING CLIPS - LH <i>new</i>
43	1	NA	*WIPER TANK ASSY <i>distorted</i>
44	1	NA	*WIPER TANK MOTOR <i>new</i>

g/ev

1,100. +

25. +

10. +

700. +

50. +

15. +

50. +

265. +

45. +

20. +

80. +

250. +

265. +

715. +

300. +

60. +

25. +

80. +

65. +

4,120. +

10.00 F

700.00 F

50.00 F

240. +

500. +

250. +

20. +

35. +

80. +

65. +

1,190. +

20.00 F

20.00 F

100.00 F

80.00 F

20. +

25. +

45. +

265.00 F

250.00 F

250.00 F

250.00 F

280.00 F

200.00 F

20. +

1,820. +

12.00 F

625.00 F

715.00 F

715.00 F

4,120. +

110.00 F

75.00 F

300.00 F

60.00 F

25.00 F

80.00 F

65.00 F

numbers with

Amount

*1,100.00 F

*25.00 F

*25.00 F

*50.00 F

*35.00 F

*80.00 F

*25.00 F

*80.00 F

*7.50 F

*10.00 F

*700.00 F

*50.00 F

*15.00 F

*15.00 F

*50.00 F

*265.00 F

*15.00 F

*45.00 F

*45.00 F

*20.00 F

*20.00 F

*100.00 F

*80.00 F

*80.00 F

*60.00 F

*250.00 F

*40.00 F

*265.00 F

*250.00 F

*250.00 F

*250.00 F

*280.00 F

*200.00 F

*12.00 F

*12.00 F

*625.00 F

*715.00 F

*715.00 F

*110.00 F

*75.00 F

*300.00 F

*60.00 F

*25.00 F

*80.00 F

*65.00 F

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09

Generated using Merimen e-Cl

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>New</i>	20.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>New</i>	35.00 25
Sub Total (S\$)			55.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,100.00 900
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; LH FRONT WHEEL HOUSE; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00 900
3	TO CHECK WIRING	New	20.00 ✓
4	TO RESET CHECK LIGHT	New	60.00 ✓
5	TO 4 WHEEL ALIGNMENT	New	70.00 ✓
Gross Labour Cost (S\$)			2,350.00

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Adrian Ling.
P/P 17/07/18.
Not Authorised
07 Days.
Excess \$600.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2018)
Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG4419X)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LHF HEADLAMP HID BULB <i>inst</i>	0.00	0.00	*240.00 F ✓
2	1		*LHF HEADLAMP HID CONTROL UNIT <i>inst</i>	0.00	0.00	*500.00 F ✓
3	1		*LHF HEADLAMP HID MODULE <i>inst</i>	0.00	0.00	*250.00 F ✓
4	1		*LHF FENDER BRACKET, TOP <i>inst</i>	0.00	0.00	*20.00 F ✓
5	1		*LHF FENDER BRACKET, SIDE <i>inst</i>	0.00	0.00	*20.00 F ✓
6	1		*HORN <i>inst</i>	0.00	0.00	*80.00 F ✓
7	1		*WIPER TANK MOTOR <i>inst</i>	0.00	0.00	*65.00 F ✓
Total Parts (S\$)						1190 1,175.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Adrian Lij
 20/07/18.
 H.L.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2018)
 Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

00 6980

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BONNET <i>valid</i>	0.00	0.00	*1,100.00 F ✓
2	1	NA	*FRONT BONNET HINGE - LH <i>Best</i>	0.00	0.00	*25.00 F ✓
3	1	NA	*FRONT BONNET HINGE - RH <i>Not in</i>	0.00	0.00	*25.00 F ✓
4	1	NA	*FRONT BONNET ABSORBER - RH <i>Not in</i>	0.00	0.00	*50.00 F ✓
5	1	NA	*FRONT BONNET TOP LOCK - CENTRE <i>Not in</i>	0.00	0.00	*35.00 F ✓
6	2	NA	*FRONT BONNET TOP HOOK - LH; RH <i>Not in</i>	0.00	0.00	*80.00 F ✓
7	1	NA	*FRONT BONNET BOTTOM LOCK - CENTRE <i>Not in</i>	0.00	0.00	*25.00 F ✓
8	1	NA	*FRONT BONNET INSULATOR <i>Not in</i>	0.00	0.00	*80.00 F ✓
9	5	NA	*FRONT BONNET INSULATOR CLIP <i>Not in</i>	0.00	0.00	*7.50 F ✓
10	1	NA	*FRONT BONNET RUBBER <i>Not in</i>	0.00	0.00	*40.00 F ✓
11	1	NA	*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*700.00 F ✓
12	1	NA	*FRONT BUMPER CLIPS <i>in</i>	0.00	0.00	*50.00 F ✓
13	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>Not in</i>	0.00	0.00	*15.00 F ✓
14	1	NA	*FRONT BUMPER SIDE HOLDER - RH <i>Not in</i>	0.00	0.00	*15.00 F ✓
15	1	NA	*FRONT BUMPER FOAM <i>Cracked</i>	0.00	0.00	*50.00 F ✓
16	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	*285.00 F ✓
17	1	NA	*FRONT BUMPER TOWING COVER - RH <i>Not in</i>	0.00	0.00	*15.00 F ✓
18	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - LH <i>Missing</i>	0.00	0.00	*45.00 F ✓
19	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - RH <i>Not in</i>	0.00	0.00	*45.00 F ✓
20	1	NA	*FRONT BUMPER NOZZLE COVER - LH <i>Not in</i>	0.00	0.00	*20.00 F ✓
21	1	NA	*FRONT BUMPER NOZZLE COVER - RH <i>Not in</i>	0.00	0.00	*20.00 F ✓
22	1	NA	*FRONT BUMPER NOZZLE PIPE - LH <i>Not in</i>	0.00	0.00	*100.00 F ✓
23	1	NA	*FRONT BUMPER NOZZLE - LH <i>Cracked</i>	0.00	0.00	*80.00 F ✓
24	1	NA	*FRONT BUMPER NOZZLE - RH <i>Not in</i>	0.00	0.00	*80.00 F ✓
25	1	NA	*FRONT BUMPER LOWER LIP - CENTRE <i>Not in</i>	0.00	0.00	*50.00 F ✓
26	1	NA	*GRILLE ASSY <i>Cracked</i>	0.00	0.00	*250.00 F ✓
27	1	NA	*GRILLE LOGO <i>in</i>	0.00	0.00	*40.00 F ✓
28	1	NA	*SUPPORT PANEL <i>Cracked</i>	0.00	0.00	*265.00 F ✓
29	1	NA	*RADIATOR - OUTER <i>Not in</i>	0.00	0.00	*250.00 F ✓
30	1	NA	*RADIATOR - INNER <i>Not in</i>	0.00	0.00	*250.00 F ✓
31	1	NA	*CONDENSER	0.00	0.00	*280.00 F ✓
32	1	NA	*AUTO-COOLER	0.00	0.00	*200.00 F ✓
33	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH <i>Not in</i>	0.00	0.00	*12.00 F ✓
34	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH <i>Not in</i>	0.00	0.00	*12.00 F ✓
35	1	NA	*AIRCON FAN MOTOR W/FAN BLADE <i>Not in</i>	0.00	0.00	*625.00 F ✓
36	1	NA	*HEAD LAMP - RH <i>Not in</i>	0.00	0.00	*715.00 F ✓
37	1	NA	*HEAD LAMP - LH <i>Smashed</i>	0.00	0.00	*715.00 F ✓
38	1	NA	*RADIATOR TOP HOSE <i>Not in</i>	0.00	0.00	*140.00 F ✓
39	1	NA	*RADIATOR BOTTOM HOSE <i>Not in</i>	0.00	0.00	*75.00 F ✓
40	1	NA	*FRONT FENDER - LH <i>Distorted</i>	0.00	0.00	*300.00 F ✓
41	1	NA	*FRONT FENDER COWLING - LH <i>Not in</i>	0.00	0.00	*80.00 F ✓
42	1	NA	*FRONT FENDER COWLING CLIPS - LH <i>Not in</i>	0.00	0.00	*25.00 F ✓
43	1	NA	*WIPER TANK ASSY <i>Distorted</i>	0.00	0.00	*80.00 F ✓
44	1	NA	*WIPER TANK MOTOR <i>By 2</i>	0.00	0.00	*65.00 F ✓

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

4420

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>New</i>	20.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>New</i>	35.00 ✓
Sub Total (S\$)			55.00 ✓

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,100.00 ✓ 900 ✓
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; LH FRONT WHEEL HOUSE; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00 ✓ 900 ✓
3	TO CHECK WIRING	New	20.00 ✓
4	TO RESET CHECK LIGHT	New	50.00 ✓
5	TO 4 WHEEL ALIGNMENT	New	70.00 ✓
Gross Labour Cost (S\$)			2,350.00 ✓ 1830

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment includes the latest and reliable CAR-O-LINER MARE 5 repair bench, 4 bar aligner and the support jolly system to provide accurate re-alignment and speedy repairs.

Adrian Ling.
P/P 17/07/18
Not Authorised.
07 Days.
Excess \$600.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2018)
 Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLG4419X)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LHF HEADLAMP HID BULB <i>by car</i>	0.00	0.00	*240.00 F
2	1		*LHF HEADLAMP HID CONTROL UNIT <i>car</i>	0.00	0.00	*500.00 F
3	1		*LHF HEADLAMP HID MODULE <i>car</i>	0.00	0.00	*250.00 F
4	1		*LHF FENDER BRACKET, TOP <i>by car</i>	0.00	0.00	*20.00 F
5	1		*LHF FENDER BRACKET, SIDE <i>car</i>	0.00	0.00	*80.00 F
6	1		*HORN <i>car</i>	0.00	0.00	*80.00 F
7	1		*WIPER TANK MOTOR <i>car</i>	0.00	0.00	*65.00 F
Total Parts (S\$)						1,175.00 <i>1190</i>

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

SUPP 1190.00

PARTS 4120.00

SN 45.00

VAT 1820.00

7175.00

Adrian Lij
 20/07/18.
 H.L.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 10 August 2018 8:12 AM
To: 'Ray'; Adrian Ling (LKKAUTO)
Cc: Wayne; Dawn; Peiwen; SUR
Subject: RE: SLG4419X - TO FINALIZE

Dear Ray,

Confirmed amount \$7175 before excess \$600 and GST

No of days: 7 days

Will offer in merimen shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray <ray@procarcare.com.sg>
Sent: Wednesday, 8 August 2018 2:32 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Wayne <wayne@procarcare.com.sg>; Dawn <dawn@procarcare.com.sg>; Peiwen <peiwen@procarcare.com.sg>
Subject: SLG4419X - TO FINALIZE

Hi Adrian/ Veron,

Please refer to finalize

Supp	\$1190.00
Parts	\$4120.00
Sn	\$45.00
Lab	\$1820.00
Total	\$7175.00

Regards,

Ray LIN

Damage Assessment

Progressive Automotive Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd will be rebranded as **Progressive Car Care Pte Ltd**.
* You may now reach us at our new email addresses (@procarcare.com.sg) and our old email addresses
(@progauto.com.sg) shall cease to function with effect from 1 Sep 2018. We look forward to your continued support.*



日美汽車私人有限公司

JAE AUTO PTE LTD

Bk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729872

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 198307741M

WINDSHIELD GLASS
Dept Direct: 6417 8791 / 8748 9029



Dept Direct: 6305 0010

Dept Direct: 6205 9011

Dept Direct: 6417 8792



Dept Direct: 6417 8794

Dept Direct: 6417 8793

Dept Direct: 6417 8796

Dept Direct: 6417 8795

Wiper blade: HWB (Nippon Wiper blade), Silper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY

ATTN : WENDY

TAX INVOICE : AR201807-10698

DATE : 19/07/2018

CUSTOMER ID : PRO005

VEH REG. NO. : SLG4419X

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 8V5821467A/B A3	FRT FENDER TOP BRACKET LH	U1 SUPPLIER	1	20.00	20.00

SUB-TOTAL : 20.00

ADD GST 7.00 % 1.40

E. & O.E TOTAL AMOUNT SGD : 21.40

[P] 19/07/2018 2:22:10PM

[E] 19/07/2018 2:17:32PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HUA



* AR 201807-10698 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9701 / 6745 9520



Dept Direct: 6305 9919

Dept Direct: 6305 9911

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9707

Wiper blades: NWD (Nippon Wiper blades), S&P (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

006580

TAX INVOICE : AR201807-10600

DATE : 19/07/2018

CUSTOMER ID : PRO005

VEH REG. NO. : SLG4419X

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	8V0951209	HORN LOW TONE	CC	1	80.00	80.00
			CC5-G-05AA			

SUB-TOTAL : 80.00
ADD GST 7.00 % 5.60

E & O E

TOTAL AMOUNT SGD : 85.60

[P] 19/07/2018 12:36:57PM

[E] 19/07/2018 12:29:24PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HUA

This is computer generated document.

No signature is required.



* AR201807-10600 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9731 / 6745 9723



Wiper blade: NWD (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

TAX INVOICE : AR201807-10651

DATE : 19/07/2018

CUSTOMER ID : PRO005

VEH REG. NO. : SLG4419X

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	5Q0955453M/R A3 2013	WASHER TANK	CC CC5-C-06BD	1	80.00	80.00
2.	6R0955681 A3 2013	WASHER TANK PUMP (HEADLAMP)	CC CC5-F-08A	1	65.00	65.00

SUB-TOTAL : 145.00
ADD GST 7.00 % 10.15

E & O E TOTAL AMOUNT SGD: 155.15

[P] 19/07/2018 1:46:41PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 19/07/2018 1:44:50PM

JAE Auto Pte. Ltd.

Sales Executive: HUA

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9829



Wiper blade: HVB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

006580

TAX INVOICE : AR201807-10226
DATE : 18/07/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLG4419X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 3
CURR : SGD

SO STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. 8V5823029A A3 SEDAN	BONNET	CC CC4-G-060	1	1100.00	1,100.00
2. 8V0823301G A3 2017	FRONT BONNET HINGE LH	CC CC5-D-08AA	1	25.00	25.00
3. 8V0823126B	FRONT BONNET EDGE PROTECTION	CC CC5-H-07B	1	10.00	10.00
4. 8V5807065A GRU A3 SEDAN	FRT BUMPER	CC CC4-I-01C	1	700.00	700.00
5. 8V0098623/A A3	FRT BUMPER CLIP (SET)	CC CC5-H-05AA	1	50.00	50.00
6. 8V3807550B A3	FRT BUMPER SPONGE	CC CC5-H-07D	1	50.00	50.00
7. 8V0807109/B A3 2013	FRT REINFORCEMENT	CC CC5-F-070	1	265.00	265.00

CONTINUE NEXT PAGE

[P] 18/07/2018 5:16:52PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 18/07/2018 5:02:54PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 6745 9933



Dept Direct: 6417 9781

Dept Direct: 6417 9782

Dept Direct: 6417 9783

Dept Direct: 6417 9784

Wiper blade: HWB (Nippon Wiper blade), Seiper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

00 6580

TAX INVOICE : AR201807-10226
DATE : 18/07/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLG4419X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 3
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8	8V5955275 GRU A3	HEADLAMP WASHER CAP LH	CC CC5-D-07CB	1	20.00	20.00
9	8V0955101 A3 2013	HEADLAMP WASHER LIFT CYLINDER LH	CC CC5-D-07CD	1	80.00	80.00
10	8V5853651 1QP A3	RADIATOR GRILLE	CC CC5-B-09A	1	250.00	250.00
11	8V0805588A A3 SEDAN	FRT SUPPORT PANEL	CC CC5-D-02C	1	265.00	265.00
12	8V0941043D A3 SEDAN	HEADLAMP LH	CC CC5-C-08B	1	715.00	715.00
13	8V5821105A A3 SEDAN	FRT FENDER LH	CC CC5-C-08D	1	300.00	300.00
14	8V5821171B/C A3	FRT FENDER SHIELD LH	CC CC5-M-01D	1	60.00	60.00

CONTINUE NEXT PAGE

[P] 18/07/2018 5:16:52PM

[E] 18/07/2018 5:02:54PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 9792 9023



Wiper blade: HWD (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY
ATTN: WENDY

TAX INVOICE : AR201807-10226
DATE : 18/07/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLG4419X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 3 of 3
CURR : SGD

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
15	8V0098629	FRT/RR FENDER SHIELD CLIP (SET)	CC	1	25.00	25.00
	A3		CC5-F-08AA			
16	1K5955651	WIPER TANK MOTOR (FRT WINDSCREEN)	CC	1	65.00	65.00
	EOS		CC5-G-06AA			
17	N 10721801/5	GAS BULB D3S-42V35W	CC	1	240.00	240.00
			CC5-E-08AJ			
18	8K0941597B	CONTROL UNIT FOR GAS DISCHARGE LAMP	CC	1	500.00	500.00
	Q7		CC5-H-04AC			
19	4G0907397P/R	HEADLAMP MODULE	CC	1	250.00	250.00
			CC5-G-05AA			
20	8V0821135A/C	FRT FENDER BRACE LH	CC	1	35.00	35.00
	A3 2013		CC5-E-08BB			

SUB-TOTAL : 5,005.00
ADD GST 7.00 % 350.35

E. & O.E

TOTAL AMOUNT SGD: 5,355.35

[P] 18/07/2018 5:16:52PM

[E] 18/07/2018 5:02:54PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HUA

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1265 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERBLADE GLASS
Dept Direct 6417 9291 / 6745 8028



Dept Direct 6417 9294

Dept Direct 6417 9295

Dept Direct 6417 9296

Dept Direct 6417 9297

Wiper blade: NWD (Nippon Wiper blade), Silper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67453833 FAX: 67454442 / 67450616

ATTN: WENDY

OP 6550

TAX INVOICE : AR201807-10734

DATE : 19/07/2018

CUSTOMER ID : PRO005

VEH REG. NO. : SLG4419X

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
1.	8V5807183 A3 SEDAN	FRT BUMPER RETAINER LH	CC CC5-E-08AH	1	15.00	15.00

SUB-TOTAL : 15.00
ADD GST 7.00 % 1.05

E. & O.E

TOTAL AMOUNT SGD : 16.05

[P] 19/07/2018 2:49:51PM

[E] 19/07/2018 2:44:02PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HUA

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

001580

WINDSCREEN GLASS
Dept Direct 6417 9781 / 6745 9529



Dept Direct 6417 9784

Dept Direct 6417 9785

Dept Direct 6417 9786

Dept Direct 6417 9787

Wiper Blade: NWS (Nippon Wiper blade), Silpor (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201807-10246
DATE : 18/07/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLG4419X
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 8V5807681 9B9 A3	FOG LAMP GRILLE LH	U1 SUPPLIER	1	45.00	45.00

SUB-TOTAL : 45.00
ADD GST 7.00 % 3.15

E. & O.E TOTAL AMOUNT SGD : 48.15

[P] 18/07/2018 5:24:44PM

[E] 18/07/2018 5:24:27PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HUA



* AR201807-10246 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018	17 Jul 2018	17 Jul 2018	S\$7,175.00	S\$7,175.00		Pending for Survey Report
	Sendback Est	09:22 S\$9,731.50	09:45 Edit Adj Rpt	Edit Estimates	View Rpt		
Supp #1	20 Jul 2018 14:18	28 Jul 2018 13:20 S\$1,175.00	28 Jul 2018 13:20			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHOW CHEN HOW , ID: S8384765D, Tel: +6593691843, Email: chenhow83@gmail.com		
Vehicle Reg. No.:	SLG4419X	Date of Loss:	16/07/2018 08:00 - :59 [21 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800009007	Policy/Cover Note No.:	PNPV2017-00006429 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/07/2018]		
Driver/Custodian:	CHOW CHEN HOW (34 / Male), NRIC: S8384765D, Tel: +6593691843		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- FWD_SG (08/08/2018): **Alert - Adj Mandate Approved (S\$7175.00) - SLG4419X - Claim Handler: Josey Loh**
- FWD_SG (18/07/2018): **Alert - Adj Mandate Approved (S\$6062.00) - SLG4419X - Claim Handler: Josey Loh**

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLG4419X (1201800009007)
OD
Jul 16 2018 8:00AM
[CHOW CHEN HOW]
Progressive Automotive Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Video				1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print	
1	16/07/18 10:35	Video - Accident [Linked Accident Report Documents]	1 Load MP4		

Assessment Reports				1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print	
1	17/07/18 09:22	Repairer Estimates	1 Load HTM		
2	28/07/18 13:20	Repairer Estimates Suppl. #1	1 Load HTM		

LKK Auto Consultants Pte Ltd (HQ)				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	18/07/18 10:36	Adjuster Immediate Advice	1 Load HTM		
2	08/08/18 16:08	Adjuster Immediate Advice	1 Load HTM		

Photos/Images				3 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print	
1	17/07/18 09:21	1	1 Load JPG		☒
2	17/07/18 09:21	2	1 Load JPG		☒
3	17/07/18 09:21	3	1 Load JPG		☒
4	17/07/18 09:21	4	1 Load JPG		☒
5	17/07/18 09:21	5	1 Load JPG		☒
6	17/07/18 09:21	6	1 Load JPG		☒
7	17/07/18 09:21	7	1 Load JPG		☒
8	17/07/18 09:21	8	1 Load JPG		☒
9	17/07/18 09:21	9	1 Load JPG		☒
10	17/07/18 09:21	10	1 Load JPG		☒
11	17/07/18 09:21	11	1 Load JPG		☒
12	17/07/18 09:21	12	1 Load JPG		☒
13	17/07/18 09:21	13	1 Load JPG		☒
14	17/07/18 09:21	14	1 Load JPG		☒
15	17/07/18 09:21	15	1 Load JPG		☒
16	17/07/18 09:21	16	1 Load JPG		☒
17	17/07/18 09:21	17	1 Load JPG		☒
18	17/07/18 09:21	18	1 Load JPG		☒
19	17/07/18 09:21	19	1 Load JPG		☒
20	17/07/18 09:21	20	1 Load JPG		☒
21	17/07/18 09:21	21	1 Load JPG		☒
22	17/07/18 09:21	22	1 Load JPG		☒
23	17/07/18 09:21	23	1 Load JPG		☒
24	17/07/18 09:21	24	1 Load JPG		☒
25	17/07/18 09:21	25	1 Load JPG		☒
26	17/07/18 09:21	26	1 Load JPG		☒
27	17/07/18 09:21	27	1 Load JPG		☒
28	17/07/18 09:21	28	1 Load JPG		☒

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
29	17/07/18 09:21	29	 Load JPG	☒
30	17/07/18 09:21	30	 Load JPG	☒
31	17/07/18 09:21	31	 Load JPG	☒
32	17/07/18 09:21	32	 Load JPG	☒
33	17/07/18 09:21	33	 Load JPG	☒
34	17/07/18 09:21	34	 Load JPG	☒
35	17/07/18 09:21	35	 Load JPG	☒
36	17/07/18 09:21	36	 Load JPG	☒
37	17/07/18 09:21	37	 Load JPG	☒
38	17/07/18 09:21	38	 Load JPG	☒
39	17/07/18 09:21	39	 Load JPG	☒
40	17/07/18 09:21	40	 Load JPG	☒
41	17/07/18 09:21	41	 Load JPG	☒
42	17/07/18 09:21	42	 Load JPG	☒
43	17/07/18 09:21	43	 Load JPG	☒
44	17/07/18 09:21	44	 Load JPG	☒
45	17/07/18 09:21	45	 Load JPG	☒
46	17/07/18 09:21	46	 Load JPG	☒
47	17/07/18 09:21	47	 Load JPG	☒
48	17/07/18 09:21	48	 Load JPG	☒
49	17/07/18 09:21	49	 Load JPG	☒
50	17/07/18 09:21	50	 Load JPG	☒
51	17/07/18 09:21	51	 Load JPG	☒
52	17/07/18 09:21	52	 Load JPG	☒
53	17/07/18 09:21	53	 Load JPG	☒
54	17/07/18 09:21	54	 Load JPG	☒
55	17/07/18 09:21	55	 Load JPG	☒
56	17/07/18 09:21	56	 Load JPG	☒
57	17/07/18 09:21	57	 Load JPG	☒
58	17/07/18 09:21	58	 Load JPG	☒
59	17/07/18 09:21	59	 Load JPG	☒
60	17/07/18 09:21	60	 Load JPG	☒
61	17/07/18 09:21	61	 Load JPG	☒
62	17/07/18 09:21	62	 Load JPG	☒
63	17/07/18 09:21	63	 Load JPG	☒
64	17/07/18 09:21	64	 Load JPG	☒
65	17/07/18 09:21	65	 Load JPG	☒
66	17/07/18 09:21	66	 Load JPG	☒
67	17/07/18 09:22	67	 Load JPG	☒
68	17/07/18 09:22	68	 Load JPG	☒
69	17/07/18 09:22	69	 Load JPG	☒
70	17/07/18 09:22	70	 Load JPG	☒
71	17/07/18 09:22	71	 Load JPG	☒
72	17/07/18 09:22	72	 Load JPG	☒
73	17/07/18 09:22	73	 Load JPG	☒
74	17/07/18 09:22	74	 Load JPG	☒
75	17/07/18 09:22	75	 Load JPG	☒
76	17/07/18 09:22	76	 Load JPG	☒
77	17/07/18 09:22	77	 Load JPG	☒
78	17/07/18 09:22	78	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
79	17/07/18 09:22	79	 Load JPG	☒
80	17/07/18 09:22	80	 Load JPG	☒
81	17/07/18 09:22	81	 Load JPG	☒
82	17/07/18 09:22	82	 Load JPG	☒
83	17/07/18 09:22	83	 Load JPG	☒
84	17/07/18 09:22	84	 Load JPG	☒
85	17/07/18 09:22	85	 Load JPG	☒
86	17/07/18 09:22	86	 Load JPG	☒
87	17/07/18 09:22	87	 Load JPG	☒
88	17/07/18 09:22	88	 Load JPG	☒
89	17/07/18 09:22	89	 Load JPG	☒
90	17/07/18 09:22	90	 Load JPG	☒
91	17/07/18 09:22	91	 Load JPG	☒
92	17/07/18 09:22	93	 Load JPG	☒
93	17/07/18 09:22	94	 Load JPG	☒
94	17/07/18 09:22	95	 Load JPG	☒
95	17/07/18 09:22	96	 Load JPG	☒
96	17/07/18 09:22	97	 Load JPG	☒
97	17/07/18 09:22	98	 Load JPG	☒
98	17/07/18 09:22	99	 Load JPG	☒
99	17/07/18 09:22	100	 Load JPG	☒
100	17/07/18 09:22	101	 Load JPG	☒
101	17/07/18 09:22	102	 Load JPG	☒
102	17/07/18 09:22	103	 Load JPG	☒
103	17/07/18 09:22	104	 Load JPG	☒
104	17/07/18 09:22	105	 Load JPG	☒
105	17/07/18 09:22	106	 Load JPG	☒
106	17/07/18 09:22	107	 Load JPG	☒
107	17/07/18 09:22	108	 Load JPG	☒
108	17/07/18 09:22	109	 Load JPG	☒
109	17/07/18 09:22	110	 Load JPG	☒
110	17/07/18 09:22	111	 Load JPG	☒
111	17/07/18 09:22	112	 Load JPG	☒
112	17/07/18 09:22	113	 Load JPG	☒
113	17/07/18 09:22	114	 Load JPG	☒
114	17/07/18 09:22	115	 Load JPG	☒
115	17/07/18 09:22	116	 Load JPG	☒
116	17/07/18 09:22	117	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 09:52	General View	 Load JPG	☒
2	18/07/18 09:52	General View	 Load JPG	☒
3	18/07/18 09:52	General View	 Load JPG	☒
4	18/07/18 09:52	General View	 Load JPG	☒
5	18/07/18 09:52	General View	 Load JPG	☒
6	18/07/18 09:52	General View	 Load JPG	☒
7	18/07/18 09:52	General View	 Load JPG	☒
8	18/07/18 09:52	General View	 Load JPG	☒
9	18/07/18 09:52	General View	 Load JPG	☒
10	18/07/18 09:52	General View	 Load JPG	☒
11	18/07/18 09:52	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
12	18/07/18 09:52	General View	 Load JPG	☒
13	18/07/18 09:52	General View	 Load JPG	☒
14	18/07/18 09:52	General View	 Load JPG	☒
15	18/07/18 09:52	General View	 Load JPG	☒
16	18/07/18 09:52	General View	 Load JPG	☒
17	18/07/18 09:52	General View	 Load JPG	☒
18	18/07/18 09:53	General View	 Load JPG	☒
19	18/07/18 09:53	General View	 Load JPG	☒
20	18/07/18 09:53	General View	 Load JPG	☒
21	18/07/18 09:53	General View	 Load JPG	☒
22	18/07/18 09:53	General View	 Load JPG	☒
23	18/07/18 09:53	General View	 Load JPG	☒
24	18/07/18 09:53	General View	 Load JPG	☒
25	18/07/18 09:53	General View	 Load JPG	☒
26	18/07/18 09:53	General View	 Load JPG	☒
27	18/07/18 09:53	General View	 Load JPG	☒
28	18/07/18 09:53	General View	 Load JPG	☒
29	18/07/18 09:53	General View	 Load JPG	☒
30	18/07/18 09:53	General View	 Load JPG	☒
31	18/07/18 09:53	General View	 Load JPG	☒
32	18/07/18 09:53	General View	 Load JPG	☒
33	18/07/18 09:53	General View	 Load JPG	☒
34	18/07/18 09:53	General View	 Load JPG	☒
35	18/07/18 09:53	General View	 Load JPG	☒
36	18/07/18 09:53	General View	 Load JPG	☒
37	18/07/18 09:53	General View	 Load JPG	☒
38	18/07/18 09:53	General View	 Load JPG	☒
39	18/07/18 09:53	General View	 Load JPG	☒
40	18/07/18 09:53	General View	 Load JPG	☒
41	18/07/18 09:53	General View	 Load JPG	☒
42	18/07/18 09:53	General View	 Load JPG	☒
43	18/07/18 09:53	General View	 Load JPG	☒
44	18/07/18 09:53	General View	 Load JPG	☒
45	18/07/18 09:53	General View	 Load JPG	☒
46	18/07/18 09:53	General View	 Load JPG	☒
47	18/07/18 09:53	General View	 Load JPG	☒
48	18/07/18 09:53	General View	 Load JPG	☒
49	18/07/18 09:53	General View	 Load JPG	☒
50	18/07/18 09:53	General View	 Load JPG	☒
51	18/07/18 09:53	General View	 Load JPG	☒
52	18/07/18 09:53	General View	 Load JPG	☒
53	18/07/18 09:53	General View	 Load JPG	☒
54	18/07/18 09:53	General View	 Load JPG	☒
55	18/07/18 09:53	General View	 Load JPG	☒
56	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
57	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
58	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
59	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
60	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
61	08/08/18 15:58	Reinspection Photo	 Load JPG	☒

Vidéo			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
62	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
63	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
64	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
65	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
66	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
67	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
68	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
69	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
70	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
71	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
72	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
73	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
74	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
75	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
76	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
77	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
78	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
79	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
80	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
81	08/08/18 15:58	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 09:13	E-filed GIA report	 Load PDF	
2	17/07/18 09:13	Certificate of Insurance	 Load TIF	
3	17/07/18 09:13	Claimant's NRIC & LICENSE	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 10:41	MARK ESTIMATE	 Load PDF	
2	08/08/18 16:09	SUPPLEMENTARY	 Load PDF	
3	10/08/18 15:53	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Vidéo			View	View in Browser
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 10:35	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 11:21	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 11:20	Accident Photo	 Load JPG	☒
2	16/07/18 11:20	Accident Photo	 Load JPG	☒
3	16/07/18 11:20	Accident Photo	 Load JPG	☒
4	16/07/18 11:20	Accident Photo	 Load JPG	☒
5	16/07/18 11:20	Accident Photo	 Load JPG	☒
6	16/07/18 11:20	Accident Photo	 Load JPG	☒
7	16/07/18 11:20	Accident Photo	 Load JPG	☒
8	16/07/18 11:20	Accident Photo	 Load JPG	☒
9	16/07/18 11:20	Accident Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
10	16/07/18 11:20	Accident Photo	 Load JPG	☒
11	16/07/18 11:20	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 10:36	CI	 Load TIF	
2	16/07/18 10:36	DRIVER NRIC & LICENSE	 Load TIF	
3	16/07/18 10:39	Sketch Plan	 Load JPG	☒
4	16/07/18 10:39	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18012928/AVD3E2

Date: 10/08/2018

REFERENCE

Insured/Claimant: CHOW CHEN HOW Policy No: PNPV2017-00006429
Date of Loss: 16/07/2018 Nature of Claim: OD Claim No: 1201800009007

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG4419X**
Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: CZC564564
Reg. Date: 29/09/2016 (Man. Year: 2016) Chassis No: WAUZZZ8V4G1105109
Colour: Grey Odometer: 33660 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,501.50	5,310.00	3,191.50	37.54
Miscellaneous Items	55.00	45.00	10.00	18.18
Labour	1,250.00	920.00	330.00	26.40
Paintwork Labour	1,100.00	900.00	200.00	18.18
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,906.50	7,175.00	3,731.50	34.21
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	10,906.50	6,575.00	4,331.50	39.71
+ GST 7.00/7.00% (S\$)	763.46	460.25	303.21	39.72
Nett Amount (S\$)	11,669.96	7,035.25	4,634.71	39.71

INSPECTION

Date of Assignment: 17/07/2018 Present Location: Progressive Automotive Pte Ltd (HQ)
Date Inspected: 17/07/2018 Inspected At: Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2018)
Parts:	143	AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG4419X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BONNET	Distorted	1,100.00 F	*1,100.00 F
2	1	NA	*FRONT BONNET HINGE - LH	Bent	25.00 F	*25.00 F
3	1	NA	*FRONT BONNET HINGE - RH	Not Necessary	25.00 F	*- F
4	1	NA	*FRONT BONNET ABSORBER - RH	Not Necessary	50.00 F	*- F
5	1	NA	*FRONT BONNET TOP LOCK - CENTRE	Not Necessary	35.00 F	*- F
6	2	NA	*FRONT BONNET TOP HOOK - LH; RH	Not Necessary	80.00 F	*- F
7	1	NA	*FRONT BONNET BOTTOM LOCK - CENTRE	Not Necessary	25.00 F	*- F
8	1	NA	*FRONT BONNET INSULATOR	Not Necessary	80.00 F	*- F
9	5	NA	*FRONT BONNET INSULATOR CLIP	Not Necessary	7.50 F	*- F
10	1	NA	*FRONT BONNET RUBBER	Necessary	10.00 F	*10.00 F
11	1	NA	*FRONT BUMPER	Distorted	700.00 F	*700.00 F
12	1	NA	*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 F
13	1	NA	*FRONT BUMPER SIDE HOLDER - LH	Damaged	15.00 F	*15.00 F
14	1	NA	*FRONT BUMPER SIDE HOLDER - RH	Not Necessary	15.00 F	*- F
15	1	NA	*FRONT BUMPER FOAM	Cracked	50.00 F	*50.00 F
16	1	NA	*FRONT BUMPER REINFORCEMENT	Bent	265.00 F	*265.00 F
17	1	NA	*FRONT BUMPER TOWING COVER - RH	Not Necessary	15.00 F	*- F
18	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - LH	Missing	45.00 F	*45.00 F
19	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - RH	Not Necessary	45.00 F	*- F
20	1	NA	*FRONT BUMPER NOZZLE COVER - LH	Deformed	20.00 F	*20.00 F
21	1	NA	*FRONT BUMPER NOZZLE COVER - RH	Not Necessary	20.00 F	*- F
22	1	NA	*FRONT BUMPER NOZZLE PIPE - LH	Not Necessary	100.00 F	*- F
23	1	NA	*FRONT BUMPER NOZZLE - LH	Cracked	80.00 F	*80.00 F
24	1	NA	*FRONT BUMPER NOZZLE - RH	Not Necessary	80.00 F	*- F
25	1	NA	*FRONT BUMPER LOWER LIP - CENTRE	Not Necessary	60.00 F	*- F
26	1	NA	*GRILLE ASSY	Cracked	250.00 F	*250.00 F
27	1	NA	*GRILLE LOGO	Not Necessary	40.00 F	*- F
28	1	NA	*SUPPORT PANEL	Cracked	265.00 F	*265.00 F
29	1	NA	*RADIATOR - OUTER	Not Necessary	250.00 F	*- F
30	1	NA	*RADIATOR - INNER	Not Necessary	250.00 F	*- F
31	1	NA	*CONDENSER	Not Necessary	280.00 F	*- F
32	1	NA	*AUTO COOLER	Not Necessary	200.00 F	*- F
33	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH	Not Necessary	12.00 F	*- F
34	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH	Not Necessary	12.00 F	*- F
35	1	NA	*AIRCON FAN MOTOR W/FAN BLADE	Not Necessary	625.00 F	*- F
36	1	NA	*HEAD LAMP - RH	Not Necessary	715.00 F	*- F
37	1	NA	*HEAD LAMP - LH	Smashed	715.00 F	*715.00 F
38	1	NA	*RADIATOR TOP HOSE	Not Necessary	110.00 F	*- F
39	1	NA	*RADIATOR BOTTOM HOSE	Not Necessary	75.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1	NA	*FRONT FENDER - LH	Distorted	300.00 F	*300.00 F
41	1	NA	*FRONT FENDER COWLING - LH	Torn	60.00 F	*60.00 F
42	1	NA	*FRONT FENDER COWLING CLIPS - LH	Necessary	25.00 F	*25.00 F
43	1	NA	*WIPER TANK ASSY	Distorted	80.00 F	*80.00 F
44	1	NA	*WIPER TANK MOTOR	Damaged	65.00 F	*65.00 F
Supplementary #1						
45	1		*LHF HEADLAMP HID BULB	Damaged	240.00 F	*240.00 F
46	1		*LHF HEADLAMP HID CONTROL UNIT	Cracked	500.00 F	*500.00 F
47	1		*LHF HEADLAMP HID MODULE	Cracked	250.00 F	*250.00 F
48	1		*LHF FENDER BRACKET, TOP	Bent	20.00 F	*20.00 F
49	1		*LHF FENDER BRACKET, SIDE	Bent	20.00 F	*35.00 F
50	1		*HORN	Cracked	80.00 F	*80.00 F
51	1		*WIPER TANK MOTOR	Cracked	65.00 F	*65.00 F
Total Parts (S\$)					8,501.50	5,310.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	COOLANT (NECESSARY)	20.00	20.00
2	1	FRONT NUMBER PLATE WITH CASING (NECESSARY)	35.00	25.00
Sub Total (S\$)			55.00	45.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,100.00	900.00
<u>Labour Items</u>				
2	TO KNOCK OUT DENTS; LH FRONT WHEEL HOUSE; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00	900.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO RESET CHECK LIGHT	New	60.00	0.00
5	TO 4 WHEEL ALIGNMENT	New	70.00	0.00
Gross Labour Cost (S\$)			2,350.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2018)
 Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BONNET <i>Distorted</i>	0.00	0.00	*1,100.00 F ✓
2	1	NA	*FRONT BONNET HINGE - LH <i>Best</i>	0.00	0.00	*25.00 F ✓
3	1	NA	*FRONT BONNET HINGE - RH <i>new</i>	0.00	0.00	*25.00 F ✗
4	1	NA	*FRONT BONNET ABSORBER - RH <i>new</i>	0.00	0.00	*50.00 F +
5	1	NA	*FRONT BONNET TOP LOCK - CENTRE <i>new</i>	0.00	0.00	*35.00 F +
6	2	NA	*FRONT BONNET TOP HOOK - LH; RH <i>new</i>	0.00	0.00	*80.00 F +
7	1	NA	*FRONT BONNET BOTTOM LOCK - CENTRE <i>not new</i>	0.00	0.00	*25.00 F +
8	1	NA	*FRONT BONNET INSULATOR <i>not new</i>	0.00	0.00	*80.00 F +
9	5	NA	*FRONT BONNET INSULATOR CLIP <i>new</i>	0.00	0.00	*7.50 F +
10	1	NA	*FRONT BONNET RUBBER <i>new</i>	0.00	0.00	*10.00 F ✓
11	1	NA	*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*700.00 F ✓
12	1	NA	*FRONT BUMPER CLIPS <i>new</i>	0.00	0.00	*50.00 F ✓
13	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>Replaced</i>	0.00	0.00	*15.00 F ✓
14	1	NA	*FRONT BUMPER SIDE HOLDER - RH <i>Not new</i>	0.00	0.00	*15.00 F +
15	1	NA	*FRONT BUMPER FOAM <i>Cracked</i>	0.00	0.00	*50.00 F ✓
16	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	*265.00 F ✓
17	1	NA	*FRONT BUMPER TOWING COVER - RH <i>new</i>	0.00	0.00	*15.00 F +
18	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - LH <i>Missing</i>	0.00	0.00	*45.00 F ✓
19	1	NA	*FRONT BUMPER FOG LAMP CHROME W/COVER - RH <i>Not new</i>	0.00	0.00	*45.00 F +
20	1	NA	*FRONT BUMPER NOZZLE COVER - LH <i>Replaced</i>	0.00	0.00	*20.00 F ✓
21	1	NA	*FRONT BUMPER NOZZLE COVER - RH <i>new</i>	0.00	0.00	*20.00 F +
22	1	NA	*FRONT BUMPER NOZZLE PIPE - LH <i>Cracked</i>	0.00	0.00	*100.00 F +
23	1	NA	*FRONT BUMPER NOZZLE - LH <i>Cracked</i>	0.00	0.00	*80.00 F ✓
24	1	NA	*FRONT BUMPER NOZZLE - RH <i>Not new</i>	0.00	0.00	*80.00 F +
25	1	NA	*FRONT BUMPER LOWER LIP - CENTRE <i>Not new</i>	0.00	0.00	*60.00 F +
26	1	NA	*GRILLE ASSY <i>Cracked</i>	0.00	0.00	*250.00 F ✓
27	1	NA	*GRILLE LOGO <i>new</i>	0.00	0.00	*40.00 F ✓
28	1	NA	*SUPPORT PANEL <i>Cracked</i>	0.00	0.00	*265.00 F ✓
29	1	NA	*RADIATOR - OUTER	0.00	0.00	*250.00 F +
30	1	NA	*RADIATOR - INNER	0.00	0.00	*250.00 F +
31	1	NA	*CONDENSER	0.00	0.00	*280.00 F +
32	1	NA	*AUTO COOLER	0.00	0.00	*200.00 F +
33	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH <i>new</i>	0.00	0.00	*12.00 F ✗
34	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH <i>Not new</i>	0.00	0.00	*12.00 F +
35	1	NA	*AIRCON FAN MOTOR W/FAN BLADE <i>Not new</i>	0.00	0.00	*625.00 F +
36	1	NA	*HEAD LAMP - RH <i>Not new</i>	0.00	0.00	*715.00 F +
37	1	NA	*HEAD LAMP - LH <i>Smashed</i>	0.00	0.00	*715.00 F ✓
38	1	NA	*RADIATOR TOP HOSE <i>new</i>	0.00	0.00	*110.00 F +
39	1	NA	*RADIATOR BOTTOM HOSE <i>new</i>	0.00	0.00	*75.00 F +
40	1	NA	*FRONT FENDER - LH <i>Distorted</i>	0.00	0.00	*300.00 F ✓
41	1	NA	*FRONT FENDER COWLING - LH <i>to be</i>	0.00	0.00	*60.00 F +
42	1	NA	*FRONT FENDER COWLING CLIPS - LH <i>new</i>	0.00	0.00	*25.00 F ✓
43	1	NA	*WIPER TANK ASSY <i>Distorted</i>	0.00	0.00	*80.00 F ✓
44	1	NA	*WIPER TANK MOTOR <i>new</i>	0.00	0.00	*65.00 F ✓

Progressive Automotive Pte Ltd/SLG4419X/17/07/2018 09:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS