



Third Party Insurer : ~~XXXX~~
 Insured's Veh No : ~~5B8570A~~
 Date of accident : ~~23.06.2017~~
 14.07.2018

Messrs Grab Rentals Pte Ltd

Date : ~~24.06.2017~~

Estimate To Repair Toyota Vios 1.5E CVT
 Vehicle No : SLM1827X
 Chassis No :

Pages: 1 of 2

S/No	Quantity	Description	Amount
		LIST ITEM	
1	1 pc	bootlid	\$ 34 836.80
2	1 ps	bootlid lock top	\$ TA 90.40
3	1 ps	bootlid lock stricker bottom	\$ PA 18.50
4	1 pc	bootlid weatherstrip	\$ me 188.80
5	1 ps	bootlid E badge	\$ me 34.40
6	1 pc	bootlid Vios badge	\$ me 44.10
7	1 pc	bootlid centre emblem badge	\$ me 59.80
8	2 ps	bootlid hinges @ \$79.80	\$ X 159.60
9	1 pc	bootlid inner trimboard	\$ X 398.70
10	8 ps	bootlid inner trim clips @ \$4.30	\$ me 34.40
11	4 ps	bootlid lock cable clips @ \$4.30	\$ me 17.20
12	1 pc	rear end panel	\$ repair 694.70
13	1 pc	rear end panel inner trim	\$ me 234.30
14	3 ps	rear end panel inner trim clips @ \$4.30	\$ me 12.90
15	1 pc	rear bumper	\$ DE 504.90
16	1 pc	rear bumper reinforcement	\$ DE 323.30
17	2 pc	rear bumper side retainers @\$116.30	\$ X 232.60
18	2 ps	rear bumper side holders @\$22.30	\$ X 44.60
19	2 ps	rear bumper fog lights @ \$130.50	\$ X 261.00
20	10 ps	rear bumper clips @\$4.30	\$ me 43.00
21	2 ps	rear bumper splashshield cover @ \$57.50	\$ me 115.00
22	2 ps	rear bumper parking sensor holders @\$12.50	\$ me 25.00
23	1 pc	rear bumper parking sensor wire harness	\$ me 87.80
25	2 ps	rear bumper yellow clips @ \$5.00	\$ me 10.00
26	2 ps	rear lamps @ \$375.80	\$ X 751.60
27	4 ps	rear lamp clip holders @ \$4.30	\$ X 17.20
28	2 ps	rear lamp panels @ \$238.90	\$ X 477.80
29	2 ps	rear fenders @ \$969.70	\$ X 1,939.40
30	2 ps	rear fender inner trim @ \$395.10	\$ X 790.20
31	12 ps	rear fender inner trim clips @ \$4.50	\$ X 54.00
32	2 ps	rear fender air vent @ \$44.70	\$ X 89.40
			\$ 8,591.40
	1 pc (A)	Bootlid Outer Top Moulding - \$290.00 ✓ DE	
		Balance c/f	\$ 8,591.40

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51, Defu Lane 10 Singapore 539216