

(08/11/13) wef

REG. REC. BY: MG/CLJ

REF:

MS16/

CC3/ MCH/ 8012935 / Utbez

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLA 7270Tat Workshop m/s LP

of _____

Insured: SFJ 880CPolicy No. B28870873 QMYClaims No. 564631

Sum Insured: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 706

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA 7270T Yr Regn: 3 / 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda Verza cc 1496Colour: 3rd A/C: Insured / Std / NI / NASp. Reading: 6035.7 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11112059Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or okBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 15/7/18

Survey held at _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 17/7/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S &

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Carbon Burnt. LTA 45994 Reg 8502 74px. Sub. not 2400619/7 - Report via email28/9/18 L/S #21000 confirmed with ALU. (Ref. 4002751/65%)

RECEIVED 05 OCT 2018

Date/Time, File Pass to?

1) 4/10 Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 14Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 300

Transportation: _____

Photos _____

Others 10

TOTAL

Report Format: TPLump Sum / I.B.I. (\$ 21,000)310

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 19 July 2018 2:10 PM
To: Catherine Thia
Cc: SUR; Accounts (LKKAUTO); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 15/7/2018, SLA 7270T (TP VEHICLE), SFJ 886C (OI VEHICLE)
Attachments: gia report.pdf

Dear Catherine,

Please be informed that we had inspected the vehicle SLA 7270T at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 41788.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/07/2018 14:06
Date Of Accident	15/07/2018 00:15
Exact Location Of Accident	UPPER BUKIT TIMAH ROAD AFTER SPRING DULE CONDO.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA7270T
Insured/Policyholder	
Name Of Registered Owner	WONG CHUI KIN
NRIC No	S2564934F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94874321
Alternative Phone No	OFFICE-94874321

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTP01004550
Cover Note Number	

Driver

Name of Driver	IVY SEOW WEI YING
NRIC No	S9529930Z
Date Of Birth	27/08/1995
Occupation	INDOOR
Date Of Driving Pass	14/06/2017
Driving Experience	1 YEAR AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-90071661
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 431 BUKIT PANJANG RING ROAD #07-685
Postcode	670431
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2448999 - FAX NO: 62446558
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT NO.T/20180716/2130.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFJ886L
Vehicle Make/Model/Colour	TOYOTA ALTIS
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	LIM HUI EN
NRIC/Passport Number	S8609582C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name IVY SEOW WEI YING

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLA7270T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/PIN No.:

Alpha

SKETCH PLAN



Vehicle A : SLA7270T
Vehicle B : SFJ 886L

vehicle B: SFJ 886L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature _____

Telephone:

NRC/PW No.



SINGAPORE POLICE FORCE



T/20180716/2130

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

1 of 3

Report No. T/20180716/2130

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/07/2018 17:06		Vide Report No.:		Station Diary No.: 44	
Informant's Particulars					
Name of Informant: IVY SEOW WEI YING			Address: APT BLK 431 BUKIT PANJANG RING ROAD #07-685 SINGAPORE 670431		
ID Type / ID No.: NRIC NO / S9529930Z			Contact No.: Home/Office: Mobile: 90071661		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 22	Date of Birth: 27/08/1995	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Pre-primary education teacher			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/07/2018 00:15	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 UPPER BUKIT TIMAH ROAD CLEMENTI AVENUE 2 Outside Southaven 2 Condominium				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No.

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFJ886L	Car	TOYOTA	TOYOTA COROLLA ALTIS 1.6L CVT		Seriously Damaged	0
SLA7270T	Car	HONDA	VEZEL 1.5X CVT		Seriously Damaged	0



Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIN HUI'EN, HAZEL ANNE	ID No.	S8609582C
Related Vehicle	SFJ886L (Car)	Contact No.	94873862
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	IVY SEOW WEI YING	ID No.	S9529930Z
Related Vehicle	SLA7270T (Car)	Contact No.	90071661
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	15/07/2018	Date Discharge	15/07/2018
No. of Days granted Medical Leave	10	Degree of Injury	Slight

Brief Details.

On the 15/07/2018 at about 0015hrs, I was driving my car, SLA7270T, along Upper Bukit Timah Road on lane 1 when suddenly a car, SFJ886L, coming from the opposite direction made a U-turn. I did not manage to stop in time and collided with the vehicle on the left rear side. I was immediately unconscious. A passerby then approached me and helped me get out of the vehicle to the side of the road. I then immediately called my boyfriend to inform him about the accident. I wish to state that the driver did not stop and give way to oncoming traffic.

Traffic police officer and ambulance was also at scene. The paramedics made a check on me and wants to convey me to the hospital. However I refused as my boyfriend will send me to the hospital.

I then went to Mount Alvernia Hospital and received 10 days MC from the 15/07/2018 to 24/07/2018. I suffered back and neck pains, abrasion on my right forearm and also bruises on both my arms and right shoulder. I have an in-car camera in my vehicle.



**SINGAPORE
POLICE FORCE**



T/20180716/2130

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

3 of 3

Report No. T/20180716/2130

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 MUHAMMAD FAZLI BIN ZAILANI

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

16/07/2018 17:06

Officer In Charge Of Case:

TP / GIT /

Insp MOHAMMED FADZLY BIN ABDUL AZIZ

Contact No.: 65476355



Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4934F

Vehicle Details

Vehicle No.: SLA7270T
Vehicle to be Exported: No
Intended De-registration Date: 17 Jul 2018
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: L15B4032066
Chassis No.: RU11112059
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$22,669.00
Original Registration Date: 14 Mar 2016
First Registration Date: 14 Mar 2016
Transfer Count: 0
Actual ARF Paid: \$13,737.00 *6868*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Mar 2026
PARF Rebate Amount: \$10,302.00

Intended COE Rebate Details

COE Expiry Date: 13 Mar 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$46,651.00
COE Rebate Amount: \$35,692.00
Total Rebate Amount: \$45,994.00

The information contained herein is correct as at 17 Jul 2018

OK

LOOKING FOR AN
INDEPENDENT SPECIALIST?

Find the specialty Workshops for your vehicle

honda vezel

Price Range

Depreciation

2016

Vehicle Type



Advanced Search

Home » Used Cars » AL Autocar Pte Ltd » Honda Vezel 1.5A X

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Take your debts and enjoy
interest rate
from as low
as 4.70% p.a.
(EIR: 8.48% p.a.)
Maybank Debt Consolidation Plan

FIND OUT MORE

Terms and Conditions apply



Compare

Honda Vezel 1.5A X

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$77,800	
Depreciation	\$9,610 /yr View models with similar depreciation	?
Reg Date	02-Mar-2016 (7yrs 7mths 12days COE left)	
Manufactured	2015	?
Mileage	40,000 km (16.8k /yr)	
Transmission	Auto	
Engine Cap	1,496 cc	
Road Tax	\$682 /yr	?
Power	96.0 kW (128 bhp) View specs of the Honda Vezel (2014)	
Curb Weight	1,190 kg	?
Features	LED/Fog Lights, Auto Head Lights, 8 SRS Airbags, Cruise Control, Smart Key, Keyless Engine Start, Leather Steering Wheel, Electric Brake, Sports Rims	
Accessories	DVD Player, Reverse Sensors And Camera, Sports Rims, Auto Headlights/LED DRL, Auto Fold Mirrors, Multi Function Steering, Bluetooth Interface	
Description	Best Condition Unit Need No Compare, Just Arrived Yet Only 1 Owner For Your Peace Of Mind As It Is Non Rental Unit, Low And Easy Maintenance And Fuel Economy, Flexible Loan, High Trade In, Please Contact Direct To Salesperson Phone For Enquiry Or Appointment, Fast Selling Unit And Don't Miss This New Car Conditions Unit.	
COE	\$43,000	?
OMV	\$18,997	?
ARF	\$8,997	?
Dereg Value	\$39,546 as of today (change)	?
No. of Owners	1	?
Type of Veh	SUV	
Category	PARF Car, Premium Ad Car	
Availability	Available	



Seller Information

Company	AL Autocar Pte Ltd » dealer's pricelist » 34 vehs sold 43 vehs available	
Address	210 Turf Club Road Lot #01 Search cars nearby this location	
Location	Car Mall @ The Grandstand	
Office No	63655335	
Contact Person(s)	Daniel Fu Andrew Lau	9385430 9295959

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note



not allowed
 in SA 21000/-
 17/7/18
 to be paid after 14 days.

FASTECH AUTO PTE LTD
 1 Kakit Bukit Ave 6
 #01-46,48,50 Autobay
 SINGAPORE 417883

VEHICLE NO: SLA 7270T

QTY	PARTICULAR		
2 PCS	BONNET HINGES @\$85.00	12	\$170.00X
1 PCS	BONNET INSULATOR	11	\$211.30X
1 SET	BONNET INSULATOR CLIPS	11	\$35.00X
1 PCS	BONNET LOCK	TW1	\$135.50✓
2 PCS	BONNET RUBBERS @\$32.00	11	\$64.00X
1 PCS	BONNET LOCK BRACKET	can / 11	\$115.00
1 PCS	FRONT BUMPER	70.5	\$950.00
1 PCS	FRONT BUMPER REINFORCEMENT	70.5	\$480.00
2 PCS	FRONT BUMPER SIDE RETAINERS @\$65.00 45x2=90	2	\$130.00
2 PCS	FRONT BUMPER BRACKETS @\$115.00	NS	\$230.00X
1 PCS	FRONT BUMPER CENTRE GRILLE 145	can / 70.5	\$285.00
1 PCS	FRONT BUMPER LOWER SPOILER 391.10	70.5	\$525.00
1 PCS	FRONT BUMPER UNDER COVER 165.20	To. n	\$480.00
1 SET	FRONT BUMPER UNDER COVER CLIPS	11	\$35.00
1 PCS	FRONT BUMPER TOW COVER	11	\$45.00X
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$180.00 98	N/S 11	\$360.00 1PC
2 PCS	FRONT BUMPER FOG LAMPS @\$445.00 327.70	N/S can	\$890.00 1PC
1 SET	FRONT BUMPER CLIPS	11	\$40.00
1 PCS	FRONT GRILLE 389.50	can	\$525.00
1 PCS	FRONT GRILLE OUTER GARNISH 385	sur / can	\$548.00
1 PCS	FRONT GRILLE 'H' LOGO	11	\$38.80
2 PCS	HEADLAMPS @\$2250.00 1759x2=3518	N/S 11	\$4,500.00
2 PCS	HEADLAMP LOWER BRACKETS @\$85.00	can	\$170.00
1 PCS	FRONT SUPPORT PANEL 576.20	but / 11	\$745.11
1 PCS	FRONT SUPPORT PANEL TOP GARNISH 166.30	70.5	\$322.30
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	11	\$50.00
2 PCS	FRONT FENDERS @\$688.00 580	N/S 11	\$1,376.00 1PC
2 PCS	FRONT FENDER INNER SHIELDS @\$166.50	N/S 70.5	\$333.00 1PC
2 PCS	FRONT FENDER OUTER PROTECTORS @\$295.00 210x2=420	To. n	\$590.00
1 PCS	AIR CON CONDENSER 785	but / 11	\$1,568.00
2 PCS	AIR CON CONDENSER SIDE GARNISH @\$148.00	11	\$296.00X
1 PCS	RADIATOR 1615.20	11	\$1,817.50X
1 PCS	RADIATOR FAN COWLING	11	\$288.30X
1 PCS	RADIATOR FAN MOTOR	11	\$488.20X
1 PCS	RADIATOR FAN BLADE	11	\$101.50X
1 PCS	FRONT FENDER INNER PANEL N/S 345.50	5-600	\$525.30
1 PCS	FRONT WHEEL HOUSING PANEL N/S	12	\$988.20X

1 PCS	FUSE BOX	2	\$2,665.00	X
1 PCS	FUSE BOX BRACKET	one	\$89.60	
1 PCS	WIPER GARNISH	11	\$166.30	X
1 PCS	BATTERY TRAY 105.00	Wagon	\$180.20	
1 PCS	AIR RESONATOR 198.30	cm	\$305.20	
1 PCS	FRONT DOOR 'A' PILLAR OUTER	1	\$899.20	X
1 PCS	FRONT DOOR N/S	2	\$866.30	X
1 PCS	FRONT WINDSCREEN	11	\$1,488.20	X
1 PCS	FRONT WINDSCREEN MOULDING	17	\$122.30	X
1 PCS	ENGINE MOUNTING N/S	20	\$188.20	X
1 PCS	ENGINE MOUNTING O/S	20	\$195.30	X
1 PCS	FRONT LOWER ARM N/S 392.30	3w/	\$488.20	
1 PCS	FRONT KNUCKLE ARM N/S 388.50	Set	\$499.50	
1 PCS	FRONT KNUCKLE ARM BEARING N/S 185.20	Set	\$250.50	
1 PCS	FRONT shock absorber N/S 650	rm/ Set	\$1,150.20	
1 PCS	FRONT ENGINE CROSS MEMBER	Set	\$1,660.80	X
1 PCS	STEERING RACK ASSY 2445.90	Set/Jm	\$2,715.00	
1 PCS	SRS AIR BAG IMPACT SENSOR	Head	\$150.00	
1 PCS	SRS AIR BAG STEERING WHEEL 1805	Head	\$2,448.00	
1 PCS	SRS STEERING WHEEL SPIRAL SENSOR 268.90	Head	\$399.00	
1 PCS	PASSENGER AIR BAG 2436.80	Head	\$2,880.00	
1 PCS	INSTRUMENT DASHBOARD ASSY 892.50	To. n	\$1,466.20	
1 PCS	DRIVER SEAT BELT 780	Head	\$980.00	
1 PCS	PASSENGER SEAT BELT 780	Head	\$980.00	
1 PCS	SRS AIR BAG CONTROL UNIT 980	Head	\$1,450.00	
1 PCS	ROOF LINING 1445.00	To. n	\$1,800.00	
1 PCS	CURTAIN AIR BAG N/S 1400.50	Head	\$1,660.00	
1 PCS	FRONT MUDFLAP N/S	To. n	\$105.30	
1 PCS	ROCKER PANEL GARNISH N/S 645.20	Set/Jm	\$899.20	
1 PCS	ROCKER PANEL N/S	2	\$850.50	X
1 PCS	STABILIZER BAR	Set	\$366.30	X
1 PCS	FRONT LINKAGE N/S 89.20	rm	\$166.00	
1 PCS	BONNET 892.30	Bus	\$1,500.00	
1 PCS	FRONT TEMPERATURE SENSOR	11	\$115.00	X
			\$52,597.51	
	S.NETT			
1 PCS	FRONT LICENCE PLATE	11	\$50.00	X
1 BOT	RADIATOR COOLANT	rm	\$50.00	30
1 PCS	BATTERY	20	\$200.00	80
1 PCS	FRONT WINDSCREEN SEALANT	11	\$50.00	X
1 PCS	FRONT WINDSCREEN ERP BRACKET	11	\$30.00	X
	LABOUR CHARGES:			
	TOWING KING ROLLER		\$150.00	50
	TO CHECK WIRING		\$80.00	30

202

TO DISMENTLE & REFIX FRONT WINDSCREEN	11	\$150.00	X
TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE		\$500.00	350
TO DISMENTLE & REFIX ENGINE & GEARBOX	11	\$500.00	X
TO MOUNT VEHICLE ON CAR O-LNER & STRAIGHTEN CHASSIS	11	\$380.00	X
TO SPRAY RUST PROOFING		\$150.00	100
TO CONDUCT WHEEL ALIGNMENT		\$120.00	60
TO DISMENTLE & REPLACING DASHBOARD		\$380.00	300
TO DISMENTLE & REPLACING AIR BAG, SEATBELT		\$380.00	200
TO RESET AIRBAG SYSTEM & REPROGRAMME		\$500.00	300
TO DISMENTLE & REFIX WIRE HARNESS		\$280.00	80
TO DISMENTLE & REPLACING ROOF LINING		\$280.00	150
LABOUR FOR PANEL BEATING, CUT, WELD STRAIGHTEN & REPLACING PARTS		\$2,200.00	1500
TO PUTTY & SPRAY PAINTING		\$2,000.00	1200
TOTAL		\$61,027.51	

6430

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018		03 Oct 2018 17:54 Edit Adj Rpt	S\$26,338.64 Edit Estimates	S\$26,338.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM HIM TECK , ID: S1168784I, Tel: +6598270718.								
Main Claimant:	WONG CHUI KIN , ID: S2564934F								
Vehicle Reg. No.:	SLA7270T	Date of Loss:	15/07/2018 00:00 - :59 [28 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 564631	Policy/Cover Note No.:	B28870873QMY (Comprehensive) Coverage: 29/01/2018 - 28/01/2019						
Vehicle Reg. No. (Insured):	SFJ886L	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 04/10/2018]								
Driver/Custodian (Insured):	LIN HUI'EN HAZEL ANNE (), NRIC: S8609582C, Tel: +6594873862								
Adj Asp. Remarks:	Direct survey done.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA7270T (564631)
[SFJ886L]
TP
WONG CHUI KIN
Jul 15 2018 12:00AM
[LIM HIM TECK]
Fastech Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	04/10/18 15:36	General View			Load JPG	☒				
2	04/10/18 15:36	General View			Load JPG	☒				
3	04/10/18 15:36	General View			Load JPG	☒				
4	04/10/18 15:36	General View			Load JPG	☒				
5	04/10/18 15:36	General View			Load JPG	☒				
6	04/10/18 15:36	General View			Load JPG	☒				
7	04/10/18 15:36	General View			Load JPG	☒				
8	04/10/18 15:36	General View			Load JPG	☒				
9	04/10/18 15:36	General View			Load JPG	☒				
10	04/10/18 15:36	General View			Load JPG	☒				
11	04/10/18 15:36	General View			Load JPG	☒				
12	04/10/18 15:36	General View			Load JPG	☒				
13	04/10/18 15:36	General View			Load JPG	☒				
14	04/10/18 15:36	General View			Load JPG	☒				
15	04/10/18 15:36	General View			Load JPG	☒				
16	04/10/18 15:36	General View			Load JPG	☒				
17	04/10/18 15:36	General View			Load JPG	☒				
18	04/10/18 15:36	General View			Load JPG	☒				
19	04/10/18 15:36	General View			Load JPG	☒				
20	04/10/18 15:36	General View			Load JPG	☒				
21	04/10/18 15:36	General View			Load JPG	☒				
22	04/10/18 15:36	General View			Load JPG	☒				
23	04/10/18 15:36	General View			Load JPG	☒				
24	04/10/18 15:36	General View			Load JPG	☒				
25	04/10/18 15:36	General View			Load JPG	☒				
26	04/10/18 15:36	General View			Load JPG	☒				
27	04/10/18 15:36	General View			Load JPG	☒				
28	04/10/18 15:36	General View			Load JPG	☒				
29	04/10/18 15:36	General View			Load JPG	☒				
30	04/10/18 15:36	General View			Load JPG	☒				
31	04/10/18 15:36	General View			Load JPG	☒				
32	04/10/18 15:36	General View			Load JPG	☒				
33	04/10/18 15:36	General View			Load JPG	☒				
34	04/10/18 15:36	General View			Load JPG	☒				
35	04/10/18 15:36	General View			Load JPG	☒				
36	04/10/18 15:36	General View			Load JPG	☒				
37	04/10/18 15:36	General View			Load JPG	☒				

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/10/18 15:36	General View	 Load JPG	☒
39	04/10/18 15:36	General View	 Load JPG	☒
40	04/10/18 15:36	General View	 Load JPG	☒
41	04/10/18 15:36	General View	 Load JPG	☒
42	04/10/18 15:36	General View	 Load JPG	☒
43	04/10/18 15:36	General View	 Load JPG	☒
44	04/10/18 15:36	General View	 Load JPG	☒
45	04/10/18 15:36	General View	 Load JPG	☒
46	04/10/18 15:36	General View	 Load JPG	☒
47	04/10/18 15:36	General View	 Load JPG	☒
48	04/10/18 15:36	General View	 Load JPG	☒
49	04/10/18 15:36	General View	 Load JPG	☒
50	04/10/18 15:36	General View	 Load JPG	☒
51	04/10/18 15:36	General View	 Load JPG	☒
52	04/10/18 15:36	General View	 Load JPG	☒
53	04/10/18 15:36	General View	 Load JPG	☒
54	04/10/18 15:36	General View	 Load JPG	☒
55	04/10/18 15:36	General View	 Load JPG	☒
56	04/10/18 15:36	General View	 Load JPG	☒
57	04/10/18 15:36	General View	 Load JPG	☒
58	04/10/18 15:36	General View	 Load JPG	☒
59	04/10/18 15:36	General View	 Load JPG	☒
60	04/10/18 15:36	General View	 Load JPG	☒
61	04/10/18 15:36	General View	 Load JPG	☒
62	04/10/18 15:36	General View	 Load JPG	☒
63	04/10/18 15:36	General View	 Load JPG	☒
64	04/10/18 15:36	General View	 Load JPG	☒
65	04/10/18 15:36	General View	 Load JPG	☒
66	04/10/18 15:36	General View	 Load JPG	☒
67	04/10/18 15:36	General View	 Load JPG	☒
68	04/10/18 15:36	General View	 Load JPG	☒
69	04/10/18 15:36	General View	 Load JPG	☒
70	04/10/18 15:36	General View	 Load JPG	☒
71	04/10/18 15:36	General View	 Load JPG	☒
72	04/10/18 15:36	General View	 Load JPG	☒
73	04/10/18 15:36	General View	 Load JPG	☒
74	04/10/18 15:36	General View	 Load JPG	☒
75	04/10/18 15:36	General View	 Load JPG	☒
76	04/10/18 15:36	General View	 Load JPG	☒
77	04/10/18 15:36	General View	 Load JPG	☒
78	04/10/18 15:36	General View	 Load JPG	☒
79	04/10/18 15:36	General View	 Load JPG	☒
80	04/10/18 15:36	General View	 Load JPG	☒
81	04/10/18 15:36	General View	 Load JPG	☒
82	04/10/18 15:36	General View	 Load JPG	☒
83	04/10/18 15:36	General View	 Load JPG	☒
84	04/10/18 15:36	General View	 Load JPG	☒
85	04/10/18 15:36	General View	 Load JPG	☒
86	04/10/18 15:36	General View	 Load JPG	☒
87	04/10/18 15:36	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	04/10/18 15:36	General View	 Load JPG	☒
89	04/10/18 15:36	General View	 Load JPG	☒
90	04/10/18 15:36	General View	 Load JPG	☒
91	04/10/18 15:36	General View	 Load JPG	☒
92	04/10/18 15:36	General View	 Load JPG	☒
93	04/10/18 15:36	General View	 Load JPG	☒
94	04/10/18 15:36	General View	 Load JPG	☒
95	04/10/18 15:36	General View	 Load JPG	☒
96	04/10/18 15:36	General View	 Load JPG	☒
97	04/10/18 15:36	General View	 Load JPG	☒
98	04/10/18 15:36	General View	 Load JPG	☒
99	04/10/18 15:36	General View	 Load JPG	☒
100	04/10/18 15:36	General View	 Load JPG	☒
101	04/10/18 15:36	General View	 Load JPG	☒
102	04/10/18 15:36	General View	 Load JPG	☒
103	04/10/18 15:36	General View	 Load JPG	☒
104	04/10/18 16:08	General View	 Load JPG	☒
105	04/10/18 16:13	General View	 Load JPG	☒
106	05/10/18 09:44	General View	 Load JPG	☒
107	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
108	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
109	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
110	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
111	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
112	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
113	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
114	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
115	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
116	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
117	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
118	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
119	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
120	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
121	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
122	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
123	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
124	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
125	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
126	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
127	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
128	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
129	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
130	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
131	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
132	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
133	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
134	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
135	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
136	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
137	05/10/18 09:50	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
139	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
140	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
141	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
142	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
143	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
144	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
145	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
146	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
147	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
148	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
149	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
150	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
151	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
152	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
153	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
154	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
155	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
156	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
157	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
158	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
159	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
160	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
161	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
162	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
163	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
164	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
165	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
166	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
167	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
168	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
169	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
170	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
171	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
172	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
173	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
174	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
175	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
176	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
177	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
178	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
179	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
180	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
181	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
182	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
183	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
184	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
185	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
186	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
187	05/10/18 09:50	Reinspection Photo	 Load JPG	☒

Photos/Images			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
189	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
190	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
191	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
192	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
193	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
194	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
195	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
196	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
197	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
198	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
199	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
200	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
201	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
202	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
203	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
204	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
205	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
206	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
207	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
208	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
209	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
210	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
211	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
212	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
213	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
214	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
215	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
216	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
217	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
218	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
219	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
220	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
221	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
222	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
223	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
224	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
225	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
226	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
227	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
228	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
229	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
230	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
231	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
232	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
233	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
234	05/10/18 09:50	Reinspection Photo	Load JPG	☒
235	05/10/18 09:50	Reinspection Photo	Load JPG	☒
236	05/10/18 09:50	Reinspection Photo	Load JPG	☒
237	05/10/18 09:50	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
238	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
239	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
240	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
241	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
242	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
243	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
244	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
245	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
246	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
247	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
248	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
249	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
250	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
251	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
252	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
253	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
254	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
255	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
256	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
257	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
258	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
259	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
260	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
261	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
262	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
263	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
264	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
265	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
266	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
267	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
268	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
269	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
270	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
271	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
272	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
273	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
274	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
275	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
276	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
277	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
278	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
279	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
280	05/10/18 09:50	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/10/18 17:52	GIA report From: CIO - Reg. No: SF3888L, Claimant: LIM HIM TECK	 Load PDF	
2	03/10/18 17:52	TP SLA7270T GIA REPORT	 Load PDF	
3	03/10/18 17:53	Direct Survey - LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18012935/UTBE2

Date: 05/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28870873QMY

Claimant Vehicle
No : SLA7270T

Insured Vehicle No : SFJ886L

Date of Loss: 15/07/2018

Nature of Claim: TP

Claim No: 564631

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA7270T

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B4032066

Reg. Date: 14/03/2016 (Man. Year: 2015)

Chassis No: RU11112059

Colour: Blue

Odometer: 60357 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18

Rear Tyre Size: 225/45Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	52,977.51	22,018.64	30,958.87	58.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,050.00	4,320.00	3,730.00	46.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	61,027.51	26,338.64	34,688.87	56.84
+ GST 7.00/7.00% (S\$)	4,271.93	1,843.70	2,428.23	56.84
Nett Amount (S\$)	65,299.44	28,182.34	37,117.10	56.84

INSPECTION

Date of Assignment: 03/10/2018

Date Inspected: 17/07/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA7270T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*BONNET HINGES	Repair	170.00 F	*- FL
2	1		*BONNET INSULATOR	Not Necessary	211.30 F	*- FL
3	1		*SET BONNET INSULATOR CLIPS	Not Necessary	35.00 F	*- FL
4	1		*BONNET LOCK	Twisted	135.50 F	*135.50 FL
5	2		*BONNET RUBBERS	Not Necessary	64.00 F	*- FL
6	1		*BONNET LOCK BRACKET	Cracked / Twisted	115.00 F	*115.00 FL
7	1		*FRONT BUMPER	Distorted	950.00 F	*801.70 FL
8	1		*FRONT BUMPER REINFORCEMENT	Distorted	480.00 F	*321.00 FL
9	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 F	*90.00 FL
10	2		*FRONT BUMPER BRACKETS	No such part	230.00 F	*- FL
11	1		*FRONT BUMPER CENTRE GRILLE	Twisted / Torn	285.00 F	*145.00 FL
12	1		*FRONT BUMPER LOWER SPOILER	Distorted	525.00 F	*391.10 FL
13	1		*FRONT BUMPER UNDER COVER	Torn	480.00 F	*165.20 FL
14	1		*SET FRONT BUMPER UNDER COVER CLIPS	Necessary	35.00 F	*35.00 FL
15	1		*FRONT BUMPER TOW COVER	Not Necessary	45.00 F	*- FL
16	1		*FRONT BUMPER FOG LAMP COVERS	N/S Torn	360.00 F	*98.00 FL
17	1		*FRONT BUMPER FOG LAMPS	N/S Cracked	890.00 F	*327.70 FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
19	1		*FRONT GRILLE	Cracked	525.00 F	*389.50 FL
20	1		*FRONT GRILLE OUTER GARNISH	Scratched / Cracked	548.00 F	*385.00 FL
21	1		*FRONT GRILLE H LOGO	Necessary	38.80 F	*38.80 FL
22	2		*HEADLAMPS	N/S Broken / O/S Cracked	4,500.00 F	*3,518.00 FL
23	2		*HEADLAMP LOWER BRACKETS	Cracked	170.00 F	*170.00 FL
24	1		*FRONT SUPPORT PANEL	Bent / Twisted	745.11 F	*576.20 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	322.30 F	*166.30 FL
26	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 F	*50.00 FL
27	1		*FRONT FENDERS	N/S Buckled	1,376.00 F	*580.00 FL
28	1		*FRONT FENDER INNER SHIELDS	N/S Torn	333.00 F	*166.50 FL
29	2		*FRONT FENDER OUTER PROTECTORS	Torn	590.00 F	*420.00 FL
30	1		*AIR CON CONDENSER	Bent / Punctured	1,568.00 F	*789.00 FL
31	2		*AIR CON CONDENSER SIDE GARNISH	Not Necessary	296.00 F	*- FL
32	1		*RADIATOR	Not Necessary	1,817.50 F	*- FL
33	1		*RADIATOR FAN COWLING	Not Necessary	288.30 F	*- FL
34	1		*RADIATOR FAN MOTOR	Not Necessary	488.20 F	*- FL
35	1		*RADIATOR FAN BLADE	Not Necessary	101.50 F	*- FL
36	1		*FRONT FENDER INNER PANEL N/S	Badly Dented	525.30 F	*345.50 FL
37	1		*FRONT WHEEL HOUSING PANEL N/S	Repair	988.20 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*FUSE BOX	Repair	2,665.00 F	*- FL
39	1		*FUSE BOX BRACKET	Cracked	89.60 F	*89.60 FL
40	1		*WIPER GARNISH	Not Necessary	166.30 F	*- FL
41	1		*BATTERY TRAY	Warped	180.20 F	*105.00 FL
42	1		*AIR RESONATOR	Cracked	305.20 F	*198.30 FL
43	1		*FRONT DOOR A PILLAR OUTER	Repair	899.20 F	*- FL
44	1		*FRONT DOOR N/S	Repair	866.30 F	*- FL
45	1		*FRONT WINDSCREEN	Not Necessary	1,488.20 F	*- FL
46	1		*FRONT WINDSCREEN MOULDING	Not Necessary	122.30 F	*- FL
47	1		*ENGINE MOUNTING N/S	Not Necessary	188.20 F	*- FL
48	1		*ENGINE MOUNTING O/S	Not Necessary	195.30 F	*- FL
49	1		*FRONT LOWER ARM N/S	Buckled	488.20 F	*392.30 FL
50	1		*FRONT KNUCKLE ARM N/S	Bent	499.50 F	*388.50 FL
51	1		*FRONT KNUCKLE ARM BEARING N/S	Necessary	250.50 F	*185.20 FL
52	1		*FRONT SHOCK ABSORBER N/S SPORT	Twisted / Bent	1,150.20 F	*650.00 FL
53	1		*FRONT ENGINE CROSS MEMBER	Serviceable	1,660.80 F	*- FL
54	1		*STEERING RACK ASSY	Bent / Jammed	2,715.00 F	*2,445.90 FL
55	1		*SRS AIR BAG IMPACT SENSOR	Activated	150.00 F	*150.00 FL
56	1		*AIR BAG STEERING WHEEL	Activated	2,448.00 F	*1,805.00 FL
57	1		*SRS STEERING WHEEL SPIRAL SENSOR	Activated	399.00 F	*268.90 FL
58	1		*PASSENGER AIR BAG	Activated	2,880.00 F	*2,436.80 FL
59	1		*INSTRUMENT DASHBOARD ASSY	Torn	1,466.20 F	*892.50 FL
60	1		*DRIVER SEAT BELT	Activated	980.00 F	*780.00 FL
61	1		*PASSENGER SEAT BELT	Activated	980.00 F	*780.00 FL
62	1		*SRS AIR BAG CONTROL UNIT	Activated	1,450.00 F	*980.00 FL
63	1		*ROOF LINING	Torn	1,800.00 F	*1,445.30 FL
64	1		*CURTAIN AIR BAG N/S	Activated	1,660.00 F	*1,400.50 FL
65	1		*FRONT MUDFLAP N/S	Torn	105.30 F	*105.30 FL
66	1		*ROCKER PANEL GARNISH N/S	Deformed / Warped	899.20 F	*645.20 FL
67	1		*ROCKER PANEL N/S	Repair	850.50 F	*- FL
68	1		*STABILIZER BAR	Serviceable	366.30 F	*- FL
69	1		*FRONT LINKAGE N/S	Twisted	166.00 F	*89.20 FL
70	1		*BONNET	Buckled	1,500.00 F	*892.30 FL
71	1		*FRONT TEMPERATURE SENSOR	Not Necessary	115.00 F	*- FL
72	1		*FRONT LICENCE PLATE	Not Necessary	50.00 FS	*- FS
73	1		*BOT RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS
74	1		*BATTERY	Dented	200.00 FS	*80.00 FS
75	1		*FRONT WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
76	1		*FRONT WINDSCREEN ERP BRACKET	Not Necessary	30.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	52,977.51	27,495.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	5,477.16
Total Parts (\$\$)	52,977.51	22,018.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING KING ROLLER	New	150.00	50.00
2	TO CHECK WIRING	New	80.00	30.00
3	TO DISMENTLE & REFIX FRONT WINDSCREEN	New	150.00	0.00
4	TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE	New	500.00	350.00
5	TO DISMENTLE & REFIX ENGINE & GEARBOX	New	500.00	0.00
6	TO MOUNT VEHICLE ON CAR O-LINER & STRAIGHTEN CHASSIS	New	380.00	0.00
7	TO SPRAY RUST PROOFING	New	150.00	100.00
8	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
9	TO DISMENTLE & REPLACING DASHBOARD	New	380.00	300.00
10	TO DISMENTLE & REPLACING AIR BAG, SEATBELT	New	380.00	200.00
11	TO RESET AIRBAG SYSTEM & REPROGRAMME	New	500.00	300.00
12	TO DISMENTLE & REFIX WIRE HARNESS	New	280.00	80.00
13	TO DISMENTLE & REPLACING ROOF LINING	New	280.00	150.00
14	LABOUR FOR PANEL BEATING, CUT, WELD STRAIGHTEN REPLACING PARTS	New	2,200.00	1,500.00
15	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			8,050.00	4,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >