

INSURANCE

INSURANCE OWNER

CC 6/AIG1801 2476, 120632

LKK
IDAC

Surveyor:

Tanfikh.

DOI:

ASSIGNMENT

16/7/18

Date / Time:

16/7/18

Registered in Merimen:

12/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKU 8940T

Name of Insured:

TAN TMI LIEW

Insured Tel No.:

HP: 968218867

Excess Sec II :SS

D.O.A:

26/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

77747014654

Policy No.:

20042517-0Y

Make / Model:

Toyota

Place of Accident:

71NTOH PANYON TUES

MAN 4 HERSOW RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

968218867



INSRS:
WSP:
Tel:
Liability:
RMKS:

penasus



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

16/7/18
vivan

968218867 - 9
SKU 8940T - 18/11/18 13014601/18/11/18

Receive video from AIG

31/7/18

Spoken to Norsiah. Try to reject 1st

31-7-18, based on 1/2 scenario his version is more credible.
To REJECT TP claim.

31/7/18 - FILE PASS TO WSP TO CLOSE

Reject Case

FILE

21/8/19

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	
After call ltr to OI	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:			
FINALIZATION Date/Time:		Confirm with:		Confirm by:	
Repair Cost:	SS	() days	Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:		Confirm with:		Email ☐ Call ☐	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:		If NO or B 28, Ass. Lia:	
Repair Cost:	SS				
Loss of Rental (LOR):	SS	() days			
Loss of Use (LOU):	SS	(S x) days			
Loss of Income (LOI):	SS	(S x) days			
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]	
GIA/LTA Search:	SS				
Medical:	SS				
Disbursement:	SS	(e.g. Tow/ Independent)			
Legal Cost:	SS				
Total:	SS	Global Sum SS:			
FINAL PAYMENT Date/Time:		Confirm with:		Email ☐ Call ☐	
Payee 1:	SS	Name 1:			
Payee 2: (Strike if N.A.)	SS	Name 2:			
Payee 3: (Strike if N.A.)	SS	Name 3:			

COPY SENT 1/8/19

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$320

The U/C / Chassis frame / Body Structure affected due to collision



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18012936/T1wb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 17-07-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 8940T	Veh. Inspected	SLL 3797J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/06/2018	Inspection Date	16/07/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

PEGASUS **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1174	Quotation Date : 26/06/2018	Terms : 30 DAYS
Vehicle No. : SLL3797J	Chassis No. : JM6BN22A8H0141878	Third Party Insurer : AIG
Model : MAZDA 3	Date of Accident : 26/06/2018	
Remarks : INSURED'S VEH NO: SKU8940T		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	Rx 1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	X 538.00
3	REAR BUMPER REFLECTOR RH	1	51.0000	X 51.00
4	REAR BUMPER SIDE RETAINER RH	1	92.0000	X 92.00
5	REAR BUMPER SIDE HOLDER RH	1	74.0000	X 74.00
6	REAR BUMPER SIDE HOLDER RIVETS	2	6.0000	X 12.00
7	REAR BUMPER TOW COVER RH	1	18.0000	X 18.00
8	REAR BUMPER CLIPS	10	5.0000	X 50.00
9	REAR FENDER RH	1	1,175.0000	Rx 1,175.00
10	REAR FENDER INNER COWLING	1	146.0000	X 146.00
11	REAR FENDER INNER COWLING CLIPS	8	5.0000	X 40.00
12	LESS 20% ON ITEM 1 - 11	1	-654.2000	-654.20
13	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	600.0000	300 600.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	600.0000	400 600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Please conduct the survey at

Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

Tanpin 97495749
wp
16/7/18 @ 1445
Review after repair
03 days
sur@lkkauto.com

Sub Total	3,816.80
Discount (20.00%)	(763.36)
GST(7.00%)	213.74
Total (SGD)	3,267.18

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Wednesday, 31 July 2019 2:59 PM
To: Md Noor, Norsiah
Subject: Your ref: 7774210146SG [ACCIDENT INVOLVING SKU8940T AND SLL3797J ON 26/06/2018]

Dear Norsiah,

We have reject the third party claim as our insured is within his lane and third party tried to overtake.

We will proceed to close this case.

Thank you.

Best Regards,

Carlton Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jjale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Friday, 12 July 2019 10:34 AM
To: 'Pegasus Engineering'; 'claims@pegasusengrg.com.sg';
'pauline.pegasusengrg@gmail.com'; 'xianchern.pegasusengrg@gmail.com';
'lioneichua@pegasusengrg.com.sg'
Subject: Your ref: SLL3797J [ACCIDENT INVOLVING VEHICLES SKU8940T AND SLL3797J ON
26/06/2018]
Attachments: SKU8940T.mp4

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SKU 8940T & SLL 3797J ON 26/06/2018

We refer to the above matter.

Based on our insured video footage, your client tried to overtake our insured vehicle and resulted the accident.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's claim.

Thank you.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jul 2018 Edit Reg		16 Jul 2018 00:00 Edit Adj Rpt	S\$550.00 Edit Estimates	S\$550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN TAI CHIEW , ID: S1303037E								
Main Claimant:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLL3797J	Date of Loss:	26/06/2018 09:00 - :59 [16 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7774210146SG	Policy/Cover Note No.:	2100425117 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKU8940T	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road, 628800 Pioneer - Tel: 65137751								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL3797J (7774210146SG)
[SKU8940T]
TP
GRAB RENTALS PTE LTD
Jun 26 2018 9:00AM
[TAN TAI CHIEW]
Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	18/07/18 14:54	Video - Accident From: SC - Reg. No: SKU8940T, Claimant: TAN TAI CHIEW													Load MP4					
Assessment Reports															1 per page		v	☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	18/07/18 14:19	Accident Statement From: SC - Reg. No: SKU8940T, Claimant: TAN TAI CHIEW													Load HTM					
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	31/07/19 15:23	Odometer Reading													Load JPG	☒				
2	31/07/19 15:23	Chassis Number													Load JPG	☒				
3	31/07/19 15:23	General View													Load JPG	☒				
4	31/07/19 15:23	General View													Load JPG	☒				
5	31/07/19 15:23	General View													Load JPG	☒				
6	31/07/19 15:23	General View													Load JPG	☒				
7	31/07/19 15:23	General View													Load JPG	☒				
8	31/07/19 15:23	General View													Load JPG	☒				
9	31/07/19 15:23	General View													Load JPG	☒				
10	31/07/19 15:23	General View													Load JPG	☒				
11	31/07/19 15:23	General View													Load JPG	☒				
12	31/07/19 15:23	General View													Load JPG	☒				
13	31/07/19 15:23	General View													Load JPG	☒				
14	31/07/19 15:23	General View													Load JPG	☒				
15	31/07/19 15:23	General View													Load JPG	☒				
Documentation															1 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	17/07/18 18:24	TP GIA REPORT													Load PDF					
2	17/07/18 18:24	TP ESTIMATE- MARKED													Load PDF					
3	31/07/19 15:21	EMAIL TO WKSP DENY LIABILITY													Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST										Reset	Save	Print
There are no document checklists configured.												

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18012936/T1DB3Q2

Date: 02/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100425117
 Claimant Vehicle No: SLL3797J Insured Vehicle No: SKU8940T
 Date of Loss: 26/06/2018 Nature of Claim: TP Claim No: 7774210146SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL3797J
 Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A) Engine No: P520429598
 Reg. Date: 23/02/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0141878
 Colour: Silver Odometer: 87690 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,616.80	0.00	2,616.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	700.00	500.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,816.80	700.00	3,116.80	81.66
Approved Total (Overridden) (S\$)		550.00		
(S\$)	3,816.80	550.00	3,266.80	85.59
+ GST 7.00/7.00% (S\$)	267.18	38.50	228.68	85.59
Nett Amount (S\$)	4,083.98	588.50	3,495.48	85.59
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 16/07/2018
 Date Inspected: 16/07/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd
 (Kian Teck)
 74 Kian Teck Road
 Singapore 628800
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,075.00 FL	*- FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	538.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR RH	Not Necessary	51.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	92.00 FL	*- FL
5	1		*REAR BUMPER SIDE HOLDER RH	Not Necessary	74.00 FL	*- FL
6	2		*REAR BUMPER SIDE HOLDER RIVETS	Not Necessary	12.00 FL	*- FL
7	1		*REAR BUMPER TOW COVER RH	Not Necessary	18.00 FL	*- FL
8	10		*REAR BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
9	1		*REAR FENDER RH	Repair	1,175.00 FL	*- FL
10	1		*REAR FENDER INNER COWLING	Not Necessary	146.00 FL	*- FL
11	8		*REAR FENDER INNER COWLING CLIPS	Not Necessary	40.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,271.00	0.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	654.20	0.00
Total Parts (\$\$)	2,616.80	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	600.00	300.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	600.00	400.00
Gross Labour Cost (S\$)			1,200.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >