

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3893J

DATE 16/7/2018 15:23

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid ✓			\$ 1,681.40	
	Boot Lid Lock Upper ✕			\$ 137.90	
	Boot Lid Lock Lower ✕			\$ 31.70	
	Boot Lid 'H' Emblem ✓			\$ 27.20	
	Boot Lid CRDI Plate ✓			\$ 41.00	
	Rear Boot Protector ✕			\$ 980.80	
	License Lamp Cover ✓			\$ 100.00	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ✓			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) 2		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket 2		\$ 49.00	\$ 98.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ✓			\$ 143.40	
	Rear Bumper Under Cover ✕			\$ 225.00	
	Rear Panel ✕ <i>Hyundai</i>			\$ 592.30	
	Rear Panel Garnish 2			\$ 57.70	
	Rear Panel Lower Panel ✕ <i>Hyundai</i>			\$ 495.50	
	SUB TOTAL			\$ 6,101.85	
	LESS 20%			\$ 1,220.37	
	DISCOUNTED TOTAL			\$ 4,881.48	
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00	Nett
	Boot Lid Advertisement Logo ✓			\$ 100.00	Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 565.70	
	Labour Charge				
	Panel Beating			\$ 850.00 ⁴⁰⁰	
	Spray Painting Charge			\$ 750.00 ⁶⁰⁰	
	Wiring Charge			\$ 50.00 ²⁰	
	Tuff Kote			\$ 50.00 ²⁰	
	Remove/Refix Reverse Sensor			\$ 120.00 ³⁰	
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 7,267.18	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin Uday
11/16/7/18 1320 L2
3 Days
45 After Repair photo