

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8097B

DATE 16/7/2018 9:18

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper X repair			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip X			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover X			\$ 185.80	
	Rear Bumper Protector (LH/RH) X		\$ 38.00	\$ 76.00	
	SUB TOTAL			\$ 1,482.90	
	LESS 20%			\$ 296.58	
	DISCOUNTED TOTAL			\$ 1,186.32	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) /		\$ 100.00	\$ 200.00	Nett
				\$ 385.70	
	Labour Charge				
	Panel Beating			\$ 350.00 100	
	Spray Painting Charge			\$ 250.00 200	
	Wiring Charge			\$ 50.00 X	
	Remove/Refix Reverse Sensor			\$ 120.00 X	
	TOTAL LABOUR			\$ 770.00	
	ESTIMATE TOTAL			\$ 2,342.02	
<p>16/7/18 1350L</p> <p>2075</p> <p>4/5</p> <p>After Repair yld</p>					
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					