

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7835G**AAD1807-077**

11/7/18
Not Authorized
11/7/18 @ 1250

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7835G

KL1LA69RJB105029

CHEVROLET

EPICA 2.0

7.7.2018

AIG

		PART		LIST
1	1	Front Fender RH	\$	R 837.60 X
2	1	Front Fender Liner RH	\$	SL 47.00 X
3	1	Front Fender Inner Wheel House Panel RH	\$	R 1,437.00 X
4	1	Front Bumper	\$	Ref/um 1,202.00 ✓
5	1	Front Bumper Lower Absorber	\$	SL 180.00
6	1	Front Bumper Reinforcement	\$	R 356.00
7	1	Front Bumper Retainer RH	\$	SL 102.00
8	1	Front Bumper Retainer LH	\$	SL 102.00
9	1	Front Bumper Lower Grille	\$	SL 78.00
10	1	Front Bumper Lower Stiffener	\$	R 134.37
11	1	Front Bumper Bracket LH	\$	R 10.00
12	1	Front Bumper Bracket RH	\$	R 10.00
13	1	Bumper Fog Lamp Cover RH	\$	SL 32.40
14	1	Bumper Fog Lamp Cover LH	\$	SL 32.40
15	1	Bonnet	\$	R 1,250.00 X
16	1	Bonnet hinge RH	\$	R 36.00
17	1	Bonnet hinge LH	\$	R 36.00
18	1	Bonnet Moulding	\$	SL 161.97
19	1	Bonnet Lock	\$	R 60.00
20	1	Bonnet cable	\$	SL 125.00
21	1	Front Support Panel Assy	\$	R 1,222.32
22	1	Headlamp RH	\$	SL 816.00
23	1	Headlamp LH	\$	SL 816.00
24	1	Windscreen Washer Tank - Filler Neck	\$	SL 4.80
25	1	Windscreen Washer Tank	\$	SL 62.00
26	1	Windscreen Washer Tank Motor	\$	SL 51.00
27	1	Washer Tank Hose	\$	SL 21.00
28	1	Radiator Assembly	\$	SL 618.00
29	1	Radiator upper hose	\$	SL 30.00

Trans-cab Auto Services Pte Ltd**AAD1807-077**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7835G

30	1	Radiator lower hose	\$	<i>SH</i> 120.00	}
31	1	Radiator Grille (Grille A-Rad)	\$	<i>SH</i> 367.00	
32	1	Radiator Grille Top Cover	\$	<i>SH</i> 45.02	
33	1	Fan Blade(A/C)	\$	<i>SH</i> 536.00	
34	1	Fan Blade(Radiator)	\$	<i>SH</i> 634.00	
35	1	Aircon Condenser	\$	<i>SH</i> 600.00	
36	1	Aircon hose - condenser to compressor	\$	<i>SH</i> 450.00	
37	1	Aircon hose - compressor to evaporator	\$	<i>SH</i> 624.00	}
38	1	Aircon hose - condenser to evaporator	\$	<i>SH</i> 580.00	

TOTAL	\$	11,505.28
10%	\$	1,150.53
	\$	10,354.75

Specical Nett

1	1 Set	Front Bumper Fastener Clip	\$	<i>nn</i> 24.00 ✓
2	2	Front Windscreen Sealant	\$	<i>nn</i> 100.00 X
3	1	Front Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00 X
4	1 Set	Radiator Grille Top Cover Clip	\$	<i>nn</i> 10.00 X
5	1 Set	Front licence plate with holder	\$	<i>nn</i> 192.00 <i>2000</i>
6	1 Set	Radiator Grille clip	\$	<i>nn</i> 35.00 X
7	1 Set	Front Fender Liner clip RH	\$	<i>nn</i> 30.00 X
8	1 Set	Louver Cowl Top clip	\$	<i>nn</i> 30.00 X
9	2	Bonnet stopper	\$	<i>nn</i> 15.00 X

TOTAL \$ 536.00**TOTAL PARTS \$ 10,890.75****LABOUR**

To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 <i>100</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>2000</i> 4,050.00
Towing Fees.	\$	<i>nn</i> 120.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-077**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7835G

Putty and spray painting of the affected portion.	\$	2001 4,200.00
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 440.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↪ 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↪ 380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	↪ 380.00 X
To check steering geometry and computer wheel alignment	\$	↪ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	↪ 170.00 X
To replace, refix and top up coolant for radiator	\$	↪ 170.00 X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	↪ 380.00 X
To rust-proofing of the affected areas.	\$	↪ 170.00 X
To transfer of end panel fittings and conduct water seepage test.	\$	↪ 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	↪ 170.00 X
To transfer of boot fittings and conduct water seepage test.	\$	↪ 170.00 X
To reinstall rear bumper parking sensor.	\$	↪ 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-077**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7835G

TOTAL	\$	11,910.00
--------------	-----------	------------------

Over All Total	\$	22,800.75
-----------------------	-----------	------------------

Repair Days	15 Days
--------------------	--------------------

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: