

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWERS
 SINGAPORE 189702

Registration No : SDP3326J

Chassis No : JHMF46206S200245

Model : CIVIC 1.6L AUTO

Owner's Name : HO YU JIN CHRISTOPHER

Ins Policy No. :

Date of Accident : 13/7/2018

Document No. : SQT18002922

Date : 14. Jul 2018

Customer No. : WZL009

Svc Advisor : RUEBEN THOMAS

Engine No : R16A11000310

Date | Time : 14. Jul 2018 4:13:03 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: HO YU JIN CHRISTOPHER OWNER INSURER: AXA INSURANCE ACC DATE: 13/07/2018 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC INSURANCE TP VEH: SJK9173Z						
04715-SNB-010ZZ	FACE, REAR BUMPER <i>20/De</i>	1	715.70	25	536.77	37.57	574.34
71593-SNA-A01	SPACERR.RR.BUMPER SIDE <i>11</i>	1	15.30	25	11.47	0.80	12.27
71598-SNA-A01	SPACERL RR BPR SIDE <i>321</i>	1	15.30	25	11.47	0.80	12.27
91503-SZ3-003	CLIP ABUMPER <i>acc</i>	2	3.90	25	5.85	0.41	6.26
91505-S9A-003	CLIP ABUMPER <i>acc</i>	8	3.90	25	23.40	1.64	25.04
68500-SNB-G00ZZ	LIDTRUNK <i>20/321</i>	1	610.70	25	458.02	32.06	490.08
74865-SNA-003	W/STRIPTRUNK LID <i>11</i>	1	89.90	25	67.42	4.72	72.14
75701-SNB-003	EMBLEMRR (H) <i>acc</i>	1	28.90	25	21.67	1.52	23.19
75722-SNB-J01	EMBLEMRR (CIVIC) <i>acc</i>	1	31.40	25	23.55	1.65	25.20
75725-SNA-K01	EMBLEMRR (I-VTEC) <i>acc</i>	1	34.70	25	26.02	1.82	27.84
75731-SNB-K31	EMBLEMREAR (1.6) <i>acc</i>	1	18.40	25	13.80	0.97	14.77
RS-2P	BUMPER SENSOR 2PCS	1	150.00		150.00	10.50	160.50
Sum Item					1349.44	94.46	1,443.90
BOSUN	SUNDRIES	1	50.00	<i>acc 10</i>	50.00	3.50	53.50
BA01R	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	100.00		100.00	7.00	107.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	280.00	<i>250</i>	280.00	19.60	299.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	<i>80</i>	100.00	7.00	107.00
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1780.00	<i>1120</i>	1780.00	124.60	1904.60

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702
Registration No : SDP3326J
Chassis No : JHMFD46206S200245
Model : CIVIC 1.6L AUTO
Owner's Name : HO YU JIN CHRISTOPHER
Ins Policy No. :
Date of Accident : 13/7/2018

Document No. : SQT18002922 Page 2
Date : 14. Jul 2018
Customer No. : WZL009
Svc Advisor : RUEBEN THOMAS
Engine No : R16A11000310
Date | Time : 14. Jul 2018 4:13:03 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2000.00	1800	2000.00	140.00	2140.00
Sum Labor					4310.00	301.70	4,611.70

Survey By

Date & Time

Excess

Status

Signature

Marcus Loh
20/7/18 @ 10:30am.
Not Authorized
take photo before painting.
5 dy.

Total Amount 5,659.44 396.16 6,055.60
Total (Inclusive of GST) 6,055.60

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 14/7/2018 4:50:09 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)