

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7889B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

AAD1807-062*Not Authored
11 Sep 836001***SHB 7889B**

KL1LA69RJB103427

CHEVROLET

EPICA 2.0

8.7.2018

III**PART****LIST**

1	1	Front Fender RH	\$	R	837.60	X
2	1	Front Fender Liner RH	\$	SL	47.00	X
3	1	Front Fender Inner Wheel House Panel RH	\$	R	1,437.00	X
4	1	Front Fender LH	\$	R	837.60	X
5	1	Front Fender Liner LH	\$	SL	47.00	X
6	1	Front Fender Inner Wheel House Panel LH	\$	R	1,437.00	X
7	1	Front Bumper	\$	CM	1,202.00	✓
8	1	Front Bumper Lower Absorber	\$	SL	180.00	X
9	1	Front Bumper Reinforcement	\$	R	356.00	X
10	1	Front Bumper Retainer RH	\$	BH	102.00	✓
11	1	Front Bumper Retainer LH	\$	SL	102.00	X
12	1	Front Bumper Lower Grille	\$	SL	78.00	X
13	1	Front Bumper Lower Stiffener	\$	R	134.37	X
14	1	Front Bumper Bracket LH	\$	R	10.00	X
15	1	Front Bumper Bracket RH	\$	R	10.00	X
16	1	Bumper Fog Lamp Cover RH	\$	SL	32.40	X
17	1	Bumper Fog Lamp Cover LH	\$	SL	32.40	X
18	1	Bonnet	\$	BH	1,250.00	✓
19	1	Bonnet hinge RH	\$	R	36.00	X
20	1	Bonnet hinge LH	\$	R	36.00	X
21	1	Bonnet Moulding	\$	PC	161.97	X
22	1	Bonnet Lock	\$	R	60.00	X
23	1	Bonnet cable	\$	SL	125.00	X
24	1	Front Support Panel Assy	\$	R	1,222.32	X
25	1	Headlamp RH	\$	mjcmm SL	816.00	✓
26	1	Headlamp LH	\$	SL	816.00	X
27	1	Windscreen Washer Tank - Filler Neck	\$	SL	4.80	X
28	1	Windscreen Washer Tank	\$	SL	62.00	X
29	1	Windscreen Washer Tank Motor	\$	SL	51.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-062**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7889B

30	1	Washer Tank Hose	\$	SH 21.00	X
31	1	Radiator Assembly	\$	SH 618.00	X
32	1	Radiator upper hose	\$	SH 30.00	X
33	1	Radiator lower hose	\$	SH 120.00	X
34	1	Radiator Grille (Grille A-Rad)	\$	CM 367.00	✓
35	1	Radiator Grille Top Cover	\$	SH 45.02	X
36	1	Fan Blade(A/C)	\$	SH 536.00	X
37	1	Fan Blade(Radiator)	\$	SH 634.00	X
38	1	Aircon Condenser	\$	SH 600.00	X
39	1	Aircon hose - condenser to compressor	\$	SH 450.00	X
40	1	Aircon hose - compressor to evaporator	\$	SH 624.00	X
41	1	Aircon hose - condenser to evaporator	\$	SH 580.00	X

TOTAL	\$	16,148.48
10%	\$	1,614.85
	\$	14,533.63

Special Nett

1	1 Set	Front Bumper Fastener Clip	\$	SH 24.00	✓
2	2	Front Windscreen Sealant	\$	SH 100.00	X
3	1	Front Windscreen Inner Sponge Seal	\$	SH 100.00	X
4	1 Set	Radiator Grille Top Cover Clip	\$	SH 10.00	X
5	1 Set	Front licence plate with holder	\$	CM 192.00	SH
6	1 Set	Radiator Grille clip	\$	SH 35.00	X
7	1 Set	Front Fender Liner clip RH	\$	SH 30.00	X
8	1 Set	Louver Cowl Top clip	\$	SH 30.00	X
9	2	Bonnet stopper	\$	SH 15.00	X

TOTAL	\$	536.00
--------------	-----------	---------------

TOTAL PARTS	\$	15,069.63
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
---	----	--------	-----

Trans-cab Auto Services Pte Ltd**AAD1807-062**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7889B

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,050.00	4000
Towing Fees.	\$	nn 120.00	X
Putty and spray painting of the affected portion.	\$	4,200.00	6000
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 440.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X
To rust-proofing of the affected areas.	\$	170.00	300
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-062**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7889B

To transfer of boot fittings and conduct water
seepage test.

\$ *~* 170.00 X

To reinstall rear bumper parking sensor.

\$ *~* 170.00 X**TOTAL \$ 11,910.00****Over All Total \$ 26,979.63****Repair Days****15 Days***2 1/2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: