

Surveyor:

mapus

DOI:

12/1/8

Date / Time:

12/1/8

Registered in Mccimen:

12/1/8

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLL 6816 T

Name of Insured:

IAN KHO KENG

Insured Tel No.:

HP:

98016990

Excess Sec II :SS

D.O.A.:

9/1/8

Is driver the owner?

(YES / NO)

Nature of Accident:

WANG UJIAO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

200503230-01

MSSAN RACHQAI

JUN TENAGA > KAKI BUKIT LAD 3

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FBG 45680



INSRS:

WSP:

Tel:

Liability:

RMKS:

Engr



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

2/1/8
mm

FBG 45680 - x: SLL 6816 T - x

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

4/1/8

Confirm accident details. Inform TP claim later find out

25/1/8

Receive PIR from O2 workshop. TP was charge Careless Driving.

25/1/8

Email to ALG to seek advice.

9/10/8

Email from ALG to reject claim.

9/10/8

Email to workshop reject claim.

RECEIVED 09 OCT 2018

REJECT CASE

VIVIAN

10/10/8

PRELIMINARY ADVICE

Date/Time:

Sent By:

04-10-18

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

50

(Agreed / Assessed) BOLA S/N No.: NIL

If NO or B 28, Ass. Lin:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(S

x

days)

Loss of Income (LOI):

S\$

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

reject

\$520.00

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

(08/11/13) wef

ASS. REC. BY: MORIS

REF:

A161**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FRG 45688at Workshop m/s Enfu

of _____

Insured: SL L 68167

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 5500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FRG 45688 Yr Regn: 8.12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PIAGGIO SILERA cc 198Colour: yellow A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2A7M 464010000 6595

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-14R: 140/60-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. _____ mm

D.O.A. 9/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

fr, o/s body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27A 937 4hrs.9/10/18 Confirm US \$ 4500.00 with 5 working days(Total \$ 4732.10
51.6)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

ANU 5120
937
4500

AIG

Owner : Muhammad Hanafi
Bin Abdul Molok

Accident Date : 9-Jul-18

Vehicle No : FBG 4568 S

Vehicle Model : Piaggio Gilera
Runner ST200

Estimated Repair Costs

to be paid After 14

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 520 165.00
1	Front fork assy	\$ 700 780.00
1	Fork under bracket	\$ 390 390.00
1	Front sport rim	\$ 350 350.00
1	Front brake disc	\$ 180 180.00
1	Front rim shaft	\$ 52 52.00
1	Top cowling	\$ 129 129.00
1	Top cowling inner panel	\$ 95 95.00
1	Windshield	\$ 248 248.00
1	Headlamp	\$ 295 295.00
2	Side mirrors	\$ 152 152.00
1	Handle bar	\$ 98 98.00
2	Handle bar balancers	\$ 160 160.00
1	Hand grip (1 set)	\$ 35 35.00
2	Brake levers	\$ 76 76.00
1	Front cowling	\$ 310 310.00
2	Front cowling side garnishes	\$ 510 510.00
1	Front centre cowling	\$ 140 140.00
1	Front cowling inner panel	\$ 150 150.00
2	Front signals	\$ 120 120.00
2	Side boards (GILERA)	\$ 310 310.00
1	Lower belly panel	\$ 250 250.00
1	Lower cowling centre grille	\$ 95 95.00
1	Radiator	\$ 260 260.00
1	Radiator spare tank	\$ 95 95.00
2	Top footstep panels	\$ 310 310.00
2	Bottom footstep panels	\$ 240 240.00
1	Rear fairing -R/H	\$ 348 348.00
1	Exhaust assy	\$ 680 680.00
1	Exhaust protector	\$ 48 48.00
		\$ 7,071.00

Fuel Tank \$350

c/f:

\$ 7,071.00

List Items

- | | |
|---|-------------------------|
| 1 | Exhaust link pipe cover |
| 1 | Rear handle -R/H |
| 1 | Rear signal -R/H |
| 1 | Engine mounting bracket |
| 1 | Main stand |
| 1 | Side stand |

\$	Scr	28.00	/
\$	n	85.00	x
\$	11	45.00	x
\$	11	280.00	x
\$	n	145.00	x
\$	n	95.00	x
\$		7,749.00	
\$		774.90	
\$		6,974.10	

Less 10%

Special Nett Items

- | | |
|---|-----------------------|
| 1 | Number plate (1 set) |
| 1 | Rear box |
| 1 | Rear box bracket |
| 1 | Steering cone (1 set) |
| 1 | ERP IU |

\$	Scr	28.00	/0
\$	67	180.00	/
\$	44	100.00	/
\$	24	120.00	/
\$	11	170.00	x
\$		598.00	

S/No. Labour

- | | |
|---|--|
| 1 | To provide towing service. |
| 2 | To check wiring and reset headlamp focusing. |
| 3 | To provide labour. |
| 4 | To respray painting. |
| 5 | To repair body frame. |

\$	35	50.00
\$	11x	80.00
\$	300	380.00
\$	500	800.00
\$	300	350.00
\$		1,660.00

Grand Total**\$ 9,232.10**

6704.8

Dollars: Nine Thousand Two Hundred Thirty-Two And Ten Cents Only.


EROFIA MOTOR TRADING PTE LTD

Let Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Muhammad Hanafi
Bin Abdul Molok

Accident Date : 9-Jul-18

Vehicle No : FBG 4568 S

Vehicle Model : Piaggio Gilera
Runner ST200

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ SW 165.00
1	Front fork assy	\$ 780.00
1	Fork under bracket	\$ 390.00
1	Front sport rim	\$ 20/24 350.00
1	Front brake disc	\$ SW 180.00
1	Front rim shaft	\$ SW 52.00
1	Top cowling	\$ SW 129.00
1	Top cowling inner panel	\$ SW 95.00
1	Windshield	\$ SW 248.00
1	Headlamp	\$ SW 295.00
2	Side mirrors	\$ SW 152.00
1	Handle bar	\$ SW 98.00
2	Handle bar balancers	\$ SW 160.00
1	Hand grip (1 set)	\$ SW 35.00
2	Brake levers	\$ 01/550 76.00
1	Front cowling	\$ SW 310.00
2	Front cowling side garnishes	\$ SW 510.00
1	Front centre cowling	\$ SW 140.00
1	Front cowling inner panel	\$ SW 150.00
2	Front signals	\$ SW 120.00
2	Side boards (GILERA)	\$ SW 310.00
1	Lower belly panel	\$ SW 250.00
1	Lower cowling centre grille	\$ SW 95.00
1	Radiator	\$ 260.00
1	Radiator spare tank	\$ 95.00
2	Top footstep panels	\$ SW 310.00
2	Bottom footstep panels	\$ SW 240.00
1	Rear fairing -R/H	\$ SW 348.00
1	Exhaust assy	\$ SW 680.00
1	Exhaust protector	\$ SW 48.00
		\$ 7,071.00

c/f:

\$ 7,071.00

List Items

- 1 Exhaust link pipe cover
- 1 Rear handle -R/H
- 1 Rear signal -R/H
- 1 Engine mounting bracket
- 1 Main stand
- 1 Side stand

\$	Scr	28.00	/
\$	n	85.00	x
\$	17	45.00	x
\$	17	280.00	q
\$	n	145.00	x
\$	n	95.00	x
\$		7,749.00	
\$		774.90	
\$		6,974.10	

Less 10%

Special Nett Items

- 1 Number plate (1 set)
- 1 Rear box
- 1 Rear box bracket
- 1 Steering cone (1 set)
- 1 ERP IU

\$	Scr	28.00	/0
\$	67	180.00	/
\$	Scr	100.00	/
\$	125	120.00	/
\$	17	170.00	x
\$		598.00	

S/No. Labour

- 1 To provide towing service.
- 2 To check wiring and reset headlamp focusing.
- 3 To provide labour.
- 4 To respray painting.
- 5 To repair body frame.

\$	35	50.00
\$	17x	80.00
\$	300	380.00
\$	500	800.00
\$	300	350.00
\$		1,660.00

Grand Total**\$ 9,232.10**

Dollars: Nine Thousand Two Hundred Thirty-Two And Ten Cents Only.


EROFIA MOTOR TRADING PTE LTD



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18012946/Uwa3

07 September 2018

TAN KUO KENG

Blk 661 Janlan Damai

#05-129

Singapore 410661

Dear Sir/Madam,

ACCIDENT INVOLVING SLL 6816T & FBG 4568S ON 09/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 17/09/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67527740 Fax: 67528669
E-Mail: erofia@singnet.com.sg
Co Registration No: 201202259N

Our Ref: EMT1355/18/lt/FBG4568S

WITHOUT PREJUDICE

Your reference: TO BE ADVISED

BY HAND TO LKK

14 August 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Attn: Officer-In-Charge (Motor Claims Department)

Dear Sir

Re: **ACCIDENT INVOLVING SLL6816T AND FBG4568S ON 09 JULY 2018**

We are instructed by our client Muhammad Hanafi Bin Abdul Molok to claim damages against your insured SLL6816T in connection with a road traffic accident on 09 July 2018 at about 15.00hrs along Jalan Tenaga with our client's motorcycle registration number FBG4568S

As a result of the accident, our client's motor bike was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1.	Final Repair Bill as per Surveyor's recommendation	S\$ 4,500.00
2.	Loss of Use (7 days X S\$20.00/day) Repair Day + PRI	S\$ 140.00
	Total to Claim	<u>S\$ 4,640.00</u>

Attached final repair bill for your early process of our claim

Kindly revert soonest

Thank you

Yours faithfully
Erofia Motor Trading Pte Ltd

Teo Hwa Heng



EROFIA MOTOR TRADING PTE LTD (201202259N)

1 Kaki Bukit Ave 6 #02-62
Singapore 417883
Tel: 67527740 Fax: 67528669
H/P: 90696165 (Mr Teo)

INVOICE

Number	Date	Page
FBG4568S	14-Aug-18	1

YOUR REF:
VEHICLE NO: FBG4568S
MAKE/MODEL: PIAGGIO GILERA RUNNER ST200
NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ACCIDENT INVOLVING SLL6816T AND FBG4568S ON 09 JULY 2018

FINAL REPAIR COST AS PER SURVEYOR'S RECOMMENDATION	S\$	4,500.00
LOSS OF USE (7 DAYS X \$20.00/DAY) REPAIR & PRI	S\$	140.00

SUB-TOTAL: S\$ 4,640.00

SINGAPORE DOLLARS: FOUR THOUSAND SIX HUNDRED AND FORTY ONLY

TOTAL : S\$ 4,640.00

EROFIA MOTOR TRADING PTE LTD

.....


Vivian Lau (LKKAUTO)

From: Md Noor, Norsiah <Norsiah.MdNoor@aig.com>
Sent: Tuesday, 9 October, 2018 2:12 PM
To: Vivian Lau (LKKAUTO)
Cc: Thin Thin (LKKAUTO)
Subject: RE: Your ref: 8948031691SG, Our Ref: CC4/AIG18012946/Uwa3, Accident involving Vehicle SLL 6816T & FBG 4568S on 09/07/2018

Dear Vivian,

Please proceed to reject Third-party claim based on the PIR.

Thank you

Norsiah Md Noor
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419-1606 | Fax +(65) 6835-7417
Norsiah.MdNoor@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Vivian Lau (LKKAUTO) [mailto:vivianlau@lkkauto.com]
Sent: Tuesday, September 25, 2018 6:17 PM
To: Md Noor, Norsiah
Cc: Thin Thin (LKKAUTO)
Subject: Your ref: 8948031691SG, Our Ref: CC4/AIG18012946/Uwa3, Accident involving Vehicle SLL 6816T & FBG 4568S on 09/07/2018

Your ref: 8948031691SG
Our Ref: CC4/AIG18012946/Uwa3

Dear Norsiah,

Accident involving Vehicle SLL 6816T & FBG 4568S on 09/07/2018

We refer to the above matter.

Based on the circumstances of both parties and available information in hand. Enclosed is PIR from OI. TP was charge by traffic police for an offence of Careless Driving.

As such, we intend to reject the claim.

Kindly advice on your view/opinion/instruction for this claim.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Tuesday, 9 October, 2018 2:37 PM
To: 'erofia@singnet.com.sg'
Cc: Thin Thin (LKKAuto)
Subject: Your Ref: FBG 4568S, Our Ref: CC4/AIG18012946/Uwa3, ACCIDENT ON 09/07/2018 INVOLVING FBG 4568S & SLL 6816T
Attachments: PIR SLL 6816T.pdf; Sketch Plan .pdf

WITHOUT PREJUDICE

Your Ref: FBG 4568S
Our Ref: CC4/AIG18012946/Uwa3

Dear Sir/Madam,

ACCIDENT ON 09/07/2018 INVOLVING FBG 4568S & SLL 6816T

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client was being charge from traffic police for careless driving.

We attached herewith our insured's accident report and PIR for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8561I

Vehicle Details

Vehicle No.:	FBG4568S
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	PIAGGIO
Vehicle Model:	GILERA RUNNER ST 200
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	M464M0009889
Chassis No.:	ZAPM4640100006595
Maximum Power Output:	-
Open Market Value:	\$3,086.00
Original Registration Date:	03 Aug 2012
First Registration Date:	03 Aug 2012
Transfer Count:	1
Actual ARF Paid:	\$463.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	02 Aug 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,859.00
COE Rebate Amount:	\$937.00
Total Rebate Amount:	\$937.00

The information contained herein is correct as at 17 Jul 2018

OK

Gilera ST200 Runner (/listing/usedbike/gilera-gilera-st200-runner/8636/)



(/listing/usedbike/gilera-gilera-st200-runner/8636/)

SGD\$5500

Reg : 10/05/2012

Type: Scooters

198cc

55267km

Black Runner. In good condition. Well maintained by Japanese owner. COE is till may 2022. Accident free. Regularly change of engine oil. First come & First serve. Cash payment only.

Posted on : 15/07/2018

★ PAID AD ★ DIRECT SELLER

■ COMPARE DETAILS > (/LISTING/USEDBIKE/GILERA-GILERA-ST200-RUNNER/8636/)

Gilera VXR200 Runner (/listing/usedbike/gilera-gilera-vxr200-runner/8452/)



(/listing/usedbike/gilera-gilera-vxr200-runner/8452/)

SGD\$7500

Reg : 06/07/2005

Type: Scooters

198cc

Visit us at Aljunied Motor Works. Well maintained condition. Seldom use, Trade in welcome / Loan available

Tip Top Condition.

Posted on : 04/07/2018

★ PAID AD ★ DEALER AD

- Pre repair inspection request - FBG45685 VS SLL6816T (OI) DOA 09/07/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@kkauto.com; assignments@kkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Chan, Yoke Shi; Azlan, Syazairdina
Sent: 17/07/2018 8:56:17 AM
Attachments:  tms2018127

Hi,

Please refer to the enclosed request from **K. KRISHNA & PARTNERS**.

Claim no : 8948031691SG003
Case Owner : NORSAH BTE MD NOOR

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Aashweenjeet Kaur (Aashween)
AIG
Claim Adjuster II, Singapore FNO, Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 196 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel: +6 03 2719 6000 | Ext: 1002218
aashweenjeetkaur.mithoosingh@aig.com | www.aig.com

IMPORTANT NOTICE

The information in this email (and any attachments herein) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privileges. If you have received this email in error, please immediately notify me by "Reply" to correct and permanently delete the original and any copies or provide thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: K Krishna & Partners [mailto:kkkrishna@singnet.com.sg]
Sent: Monday, July 16, 2018 5:24 PM
To: Mithoosingh, Aashweenjeetkaur
Cc: Chin, Lee-Ying; Chan, Yoke Shi; erofa2@gmail.com; Supramaniam, Darshene; Azlan, Syazairdina; Kaur, Baljit; Abu Kassim, Noor Mariesa; erofa@singnet.com.sg; Fong, Andy-SY; Md Ishak, Mohd Imran; Tan, Lily (AIG); Lim, Sheng Yang
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL6816T AND FBG45685 ON 09/07/2018

Your Ref: 8948031691SG003
Our Ref: KK EFM FBG45685 2018.wen

Dear Aashween:

We refer to your email of even date.

Please be informed that our client wish to appoint Mr Marcus Chua of M/s LKK Auto Consultants Pte Ltd to conduct the pre-repair inspection of the vehicle.

Please contact Mr Teo of M/s Erofa Motor Workshop at his mobile number 91078563 to arrange for the inspection.

Regards,

Yours faithfully,
K Krishna & Partners
Advocates & Solicitors
Tel: 6323 3038
Fax: 6323 2120

—Original Message—

From : Aashweenjeetkaur.Mithoosingh@aig.com
Date : 16/07/2018 - 16:42 GMT+8
To : kkkrishna@singnet.com.sg
Cc : Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Darshene.Supramaniam@aig.com, yokeschi.chan@aig.com, Syazairdina.Azlan@aig.com
Subject : PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL6816T AND FBG45685 ON 09/07/2018

Without Prejudice

Your Reference : KK EFM FBG45685 2018.wen
Our Reference : 8948031691SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

8:59am @ 17/7/2018
person @ Lee Lee
vehicle in
Sur @ Marcus

We intend to conduct a pre-repair survey of the damage to your client's/customer's vehicle jointly with your client's/customer's workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Aashwini Kaur (Aashwini)

AIG

Claim Adjuster II, Singapore FNCI, Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-Q)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel: +633 2719 6000 | Fax 1002215

aashwini.kaur@mthoosingth@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

K. KRISHNA & PARTNERS

UEN 53131210X
GST Regn. No. M90371530C
Advocates & Solicitors
Commissioner for Oaths
& Notary Public

101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533.
Tel: 6323 3038 Fax: 6323 2120 (Not for service of Court Documents)
Email: kkrishna@singnet.com.sg

K. Krishnamoorthi
LLB (Hons) (London)
Barrister-at-Law (Gray's Inn)
B.Sc(Hons)(Est.Man)(S'pore)

S. Manohar
LLB (Hons) (S'pore)

Vengadesh s/o Kumaravelu
LLB (Hons)

Our Ref : KK.EFM.FBG4568S.2018.wen
Your Ref: SLL 6816T

16th July 2018

M/s AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Dear Sirs

by fax only

**PRE-REPAIR INSPECTION OF VEHICLE NO. FBG 4568S
ACCIDENT ON 09/07/2018 INVOLVING FBG 4568S & SLL 6816T ALONG JALAN
TENAGA TOWARDS KAKI BUKIT ROAD 3**

We act for Mr Muhammad Hanafi Bin Abdul Molok, the owner and rider of FBG 4568s which was involved in the abovecaptioned accident.

We are instructed that the accident was caused by the negligence of the driver of motor vehicle no. SLL 6816T. Our search shows that you are insurers of the motor vehicle no. **SLL 6816T**.

We are requested to inform you that our client's vehicle is available for pre-repair inspection at the following address:

M/s Erofia Motor Workshop
1 Kaki Bukit Avenue 6
#02-62
Singapore 417883

Please request your assessor to contact our **Mr Teo of M/s Erofia Motor Workshop at his mobile no. 91078563 within forty-eight (48) hours** from the receipt of this fax to arrange for the inspection.

Yours faithfully,



cc

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main:	18 Jul 2018 Edit Reg		17 Jul 2018 00:00 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN KUO KENG , ID: S7142201A									
Main Claimant: MUHAMMAD HANAFI BIN ABDUL MOLOK , ID: S9138561I									
Vehicle Reg. No.: FBG45685		Date of Loss: 09/07/2018 00:00 - :59 [71 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8948031691SG		Policy/Cover Note No.: 2100503230 (Comprehensive)							
Vehicle Reg. No. (Insured): SLL6816T		Policy No. (Claimant): PNMC2018-00000593							
		Excess:							
Repairer: Erofla Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Claimant's Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (18/07/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBG4568S (8948031691SG)
[SLL6816T]
TP
MUHAMMAD HANAFI BIN ABDUL MOLOK
Jul 9 2018 12:00AM
[TAN KUO KENG]
Erofia Motor Trading Pte Ltd

Upload Documents			Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	17/07/18 17:58	General View		Load JPG	☒			
2	17/07/18 17:58	General View		Load JPG	☒			
3	17/07/18 17:58	General View		Load JPG	☒			
4	17/07/18 17:58	General View		Load JPG	☒			
5	17/07/18 17:58	General View		Load JPG	☒			
6	17/07/18 17:58	General View		Load JPG	☒			
7	17/07/18 17:58	General View		Load JPG	☒			
8	17/07/18 17:58	General View		Load JPG	☒			
9	17/07/18 17:58	General View		Load JPG	☒			
10	17/07/18 17:58	General View		Load JPG	☒			
11	17/07/18 17:58	General View		Load JPG	☒			
12	17/07/18 17:58	General View		Load JPG	☒			
13	17/07/18 17:59	General View		Load JPG	☒			
14	17/07/18 17:59	General View		Load JPG	☒			
15	17/07/18 17:59	General View		Load JPG	☒			
16	17/07/18 17:59	General View		Load JPG	☒			
17	17/07/18 17:59	General View		Load JPG	☒			
18	17/07/18 17:59	General View		Load JPG	☒			
19	17/07/18 17:59	General View		Load JPG	☒			
20	17/07/18 17:59	General View		Load JPG	☒			
21	17/07/18 17:59	General View		Load JPG	☒			
22	17/07/18 17:59	General View		Load JPG	☒			
23	17/07/18 17:59	General View		Load JPG	☒			
24	17/07/18 17:59	General View		Load JPG	☒			
25	17/07/18 17:59	General View		Load JPG	☒			
26	17/07/18 17:59	General View		Load JPG	☒			
27	17/07/18 17:59	General View		Load JPG	☒			
28	17/07/18 17:59	General View		Load JPG	☒			
29	17/07/18 17:59	General View		Load JPG	☒			
30	17/07/18 17:59	General View		Load JPG	☒			
31	17/07/18 17:59	General View		Load JPG	☒			
32	17/07/18 17:59	General View		Load JPG	☒			
33	17/07/18 17:59	General View		Load JPG	☒			
34	17/07/18 17:59	General View		Load JPG	☒			
35	17/07/18 17:59	General View		Load JPG	☒			
36	17/07/18 17:59	General View		Load JPG	☒			
37	17/07/18 17:59	General View		Load JPG	☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/07/18 17:59	General View	 Load JPG	☒
39	17/07/18 17:59	General View	 Load JPG	☒
40	17/07/18 17:59	General View	 Load JPG	☒
41	17/07/18 17:59	General View	 Load JPG	☒
42	17/07/18 17:59	General View	 Load JPG	☒
43	17/07/18 17:59	General View	 Load JPG	☒
44	17/07/18 17:59	General View	 Load JPG	☒
45	17/07/18 17:59	General View	 Load JPG	☒
46	17/07/18 17:59	General View	 Load JPG	☒
47	17/07/18 17:59	General View	 Load JPG	☒
48	17/07/18 17:59	General View	 Load JPG	☒
49	17/07/18 17:59	General View	 Load JPG	☒
50	17/07/18 17:59	General View	 Load JPG	☒
51	17/07/18 17:59	General View	 Load JPG	☒
52	17/07/18 17:59	General View	 Load JPG	☒
53	17/07/18 17:59	General View	 Load JPG	☒
54	17/07/18 17:59	General View	 Load JPG	☒
55	17/07/18 17:59	General View	 Load JPG	☒
56	17/07/18 17:59	General View	 Load JPG	☒
57	17/07/18 17:59	General View	 Load JPG	☒
58	17/07/18 17:59	General View	 Load JPG	☒
59	17/07/18 17:59	General View	 Load JPG	☒
60	17/07/18 17:59	General View	 Load JPG	☒
61	17/07/18 17:59	General View	 Load JPG	☒
62	17/07/18 17:59	General View	 Load JPG	☒
63	17/07/18 17:59	General View	 Load JPG	☒
64	17/07/18 17:59	General View	 Load JPG	☒
65	17/07/18 17:59	General View	 Load JPG	☒
66	17/07/18 17:59	General View	 Load JPG	☒
67	17/07/18 17:59	General View	 Load JPG	☒
68	17/07/18 17:59	General View	 Load JPG	☒
69	17/07/18 17:59	General View	 Load JPG	☒
70	17/07/18 17:59	General View	 Load JPG	☒
71	17/07/18 17:59	General View	 Load JPG	☒
72	17/07/18 17:59	General View	 Load JPG	☒
73	17/07/18 17:59	General View	 Load JPG	☒
74	17/07/18 17:59	General View	 Load JPG	☒
75	17/07/18 17:59	General View	 Load JPG	☒
76	17/07/18 17:59	General View	 Load JPG	☒
77	17/07/18 17:59	General View	 Load JPG	☒
78	17/07/18 17:59	General View	 Load JPG	☒
79	17/07/18 17:59	General View	 Load JPG	☒
80	17/07/18 17:59	General View	 Load JPG	☒
81	17/07/18 17:59	General View	 Load JPG	☒
82	17/07/18 17:59	General View	 Load JPG	☒
83	17/07/18 17:59	General View	 Load JPG	☒
84	17/07/18 17:59	General View	 Load JPG	☒
85	17/07/18 17:59	General View	 Load JPG	☒
86	17/07/18 17:59	General View	 Load JPG	☒
87	17/07/18 17:59	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	17/07/18 17:59	General View	 Load JPG	☒
89	17/07/18 17:59	General View	 Load JPG	☒
90	17/07/18 17:59	General View	 Load JPG	☒
91	17/07/18 17:59	General View	 Load JPG	☒
92	17/07/18 17:59	General View	 Load JPG	☒
93	17/07/18 17:59	General View	 Load JPG	☒
94	17/07/18 17:59	General View	 Load JPG	☒
95	17/07/18 17:59	General View	 Load JPG	☒
96	17/07/18 17:59	General View	 Load JPG	☒
97	17/07/18 17:59	General View	 Load JPG	☒
98	17/07/18 17:59	General View	 Load JPG	☒
99	17/07/18 17:59	General View	 Load JPG	☒
100	17/07/18 17:59	General View	 Load JPG	☒
101	17/07/18 17:59	General View	 Load JPG	☒
102	17/07/18 17:59	General View	 Load JPG	☒
103	17/07/18 17:59	General View	 Load JPG	☒
104	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
105	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
106	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
107	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
108	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
109	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
110	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
111	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
112	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
113	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
114	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
115	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
116	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
117	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
118	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
119	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
120	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
121	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
122	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
123	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
124	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
125	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
126	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
127	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
128	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
129	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
130	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
131	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
132	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
133	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
134	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
135	18/07/18 20:27	Reinspection Photo	 Load JPG	☒
136	18/07/18 20:27	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 15:32	ACKNOWLEDGEMENT EMAIL TO AIG DD 17.07.2018	Load PDF	
2	17/07/18 15:32	EMAIL FROM AIG DD 17.07.2018	Load PDF	
3	17/07/18 15:32	NOTIFICATION FROM LAWYER	Load TIF	
4	19/07/18 11:33	TP ESTIMATE - MARKED	Load PDF	
5	19/07/18 11:33	TP GIA REPORT	Load PDF	
6	25/09/18 10:47	PIR from SLL 6816T	Load JPG	☒
7	25/09/18 18:17	email to AIG to seek advise 25.9.18	Load PDF	
8	09/10/18 14:34	Email from AIG to reject claim 9.10.18.	Load PDF	
9	09/10/18 14:39	Email to wkshop reject claim 9.10.18.	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/07/18 11:47	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18012946/UWA3Q2

Date: 15/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100503230

Claimant Vehicle No: FBG4568S

Insured Vehicle No: SLL6816T

Date of Loss: 09/07/2018

Nature of Claim: TP

Claim No: 8948031691SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBG4568S

Make & Model: PIAGGIO GILERA RUNNER, 198cc ST 200

Engine No: M464M0009889

Reg. Date: 03/08/2012 (Man. Year: 2012)

Chassis No: ZAPM4640100006595

Colour: Yellow

Odometer: 0 km

Engine Capacity: 198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-14

Rear Tyre Size: 140/60-13

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,887.10	5,567.00	2,320.10	29.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,135.00	525.00	31.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,547.10	6,702.00	2,845.10	29.80
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	9,547.10	4,500.00	5,047.10	52.87
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 17/07/2018

Date Inspected: 17/07/2018 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Broken	165.00 FL	*165.00 FL
2	1		*FRONT FORK ASSY	Twisted	780.00 FL	*780.00 FL
3	1		*FORK UNDER BRACKET	Bent	390.00 FL	*390.00 FL
4	1		*FRONT SPORT RIM	Dented / Bent	350.00 FL	*350.00 FL
5	1		*FRONT BRAKE DISC	Bent	180.00 FL	*150.00 FL
6	1		*FRONT RIM SHAFT	Necessary	52.00 FL	*52.00 FL
7	1		*TOP COWLING	Broken	129.00 FL	*129.00 FL
8	1		*TOP COWLING INNER PANEL	Cracked	95.00 FL	*95.00 FL
9	1		*WINDSHIELD	Not fitted	248.00 FL	*- FL
10	1		*HEADLAMP	Cracked	295.00 FL	*295.00 FL
11	2		*SIDE MIRRORS	Cut	152.00 FL	*152.00 FL
12	1		*HANDLE BAR	Bent	98.00 FL	*98.00 FL
13	2		*HANDLE BAR BALANCERS	Not fitted	160.00 FL	*- FL
14	1		*SET HAND GRIP	Torn	35.00 FL	*35.00 FL
15	1		*BRAKE LEVERS	O/S Scratched	76.00 FL	*38.00 FL
16	1		*FRONT COWLING	Cracked	310.00 FL	*310.00 FL
17	2		*FRONT COWLING SIDE GARNISHES	Cracked	510.00 FL	*510.00 FL
18	1		*FRONT CENTRE COWLING	Cracked	140.00 FL	*140.00 FL
19	1		*FRONT COWLING INNER PANEL	Cracked	150.00 FL	*150.00 FL
20	2		*FRONT SIGNALS	Broken	120.00 FL	*120.00 FL
21	2		*SIDE BOARDS (GILERA)	Cracked	310.00 FL	*310.00 FL
22	1		*LOWER BELLY PANEL	Distorted	250.00 FL	*250.00 FL
23	1		*LOWER COWLING CENTRE GRILLE	Torn	95.00 FL	*95.00 FL
24	1		*RADIATOR	Punctured	260.00 FL	*260.00 FL
25	1		*RADIATOR SPARE TANK	Not Necessary	95.00 FL	*- FL
26	2		*TOP FOOTSTEP PANELS	Cracked	310.00 FL	*310.00 FL
27	2		*BOTTOM FOOTSTEP PANELS	Cracked (1 PCS ONLY)	240.00 FL	*120.00 FL
28	1		*REAR FAIRING -R/H	Repair	348.00 FL	*- FL
29	1		*EXHAUST ASSY	Repair	680.00 FL	*- FL
30	1		*EXHAUST PROTECTOR	Scratched	48.00 FL	*48.00 FL
31	1		*FUEL TANK	Dented	350.00 FL	*350.00 FL
32	1		*EXHAUST LINK PIPE COVER	Scratched	28.00 FL	*28.00 FL
33	1		*REAR HANDLE -R/H	Repair	85.00 FL	*- FL
34	1		*REAR SIGNAL -R/H	Not Necessary	45.00 FL	*- FL
35	1		*ENGINE MOUNTING BRACKET	Not Necessary	280.00 FL	*- FL
36	1		*MAIN STAND	Repair	145.00 FL	*- FL
37	1		*SIDE STAND	Repair	95.00 FL	*- FL
38	1		*SET NUMBER PLATE	Scratched	28.00 FS	*10.00 FS
39	1		*REAR BOX	Cut	180.00 FS	*180.00 FS
40	1		*REAR BOX BRACKET	Bent	100.00 FS	*100.00 FS
41	1		*SET STEERING CONE	Necessary	120.00 FS	*120.00 FS
42	1		*ERP IU	Not Necessary	170.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,697.00	6,140.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	809.90	573.00
Total Parts (\$\$)	7,887.10	5,567.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	300.00
4	TO RESPRAY PAINTING	New	800.00	500.00
5	TO REPAIR BODY FRAME	New	350.00	300.00
Gross Labour Cost (\$\$)			1,660.00	1,135.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >