

50 surveys by ILKKI

FAX : 6542 6039 FCI

Nett X

SHD 6552T

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHD 6552T (Supplementary)

DATE : 23.07.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (LH) <i>mounty oralc</i>			\$ 1,388.00
	SUB TOTAL			\$ 1,388.00
	LESS 20%			\$ 277.60
	DISCOUNTED TOTAL			\$ 1,110.40
 23/07/2018 24K Auto 				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				