

P/2020

INS. CASE OWNER:

CC 4/FWD1801

2957, Arab 3/

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

16/7/18

Date / Time:

16/7/18

Registered in Merimen:

18/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

FBL 3293P

Name of Insured:

Kasman bin Leman

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

11/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

JUNKI bin JUNKIN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

:

1201800009147

Policy No.:

:

PNCMCTH-1108862-01

Make / Model:

:

Yamaha

Place of Accident:

:

Puchong Rd

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SLR 4703M



INSRS:

WSP:

Tel:

Liability:

RMKS:

W-51



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLR 4703M-X

FBL 3293P-X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice: NONE

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others: PNC, DECEP:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others: PNC, DECEP:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LUP

Repair Cost:

4% S\$ 15,000

19 days Reduction:

38 %

Email

Call

FINAL SETTLEMENT

Date/Time: 05-08-19

Confirm with: PNC

Email

Call

Final Liability:

4% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

4% 16,157.00

Q: REPAIR THE RED LIGHT COLLISION WITH TP. (REFER TO WHITE VIDEO)

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 70.00

(5.10 x 11 days)

Loss of Income (LOI):

S\$ -

(5 x 11 days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ 80.00

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 500

Total:

S\$ 11,014.45

Global Sum S\$ 11,000

FINAL PAYMENT

Date/Time: 05-08-19

Confirm with: PNC

Email

Call

Payee 1:

S\$ 11,000.00

Name 1:

W-51 AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

ASS. REC BY: Abbas King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ 9 days Res: Yes or No

Lump Sum: _____ 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR4263U Yr Regn: 2017, AugustType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel cc 1496Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 88720 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru31254307Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 16/07/18Survey held at N51Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP FWD

461 → 15,100 (RED → 9,400.88 38%)

Date/Time: File Pass 107

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return 107

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS: 00

Photos:

Other:

Report Format:

Lump Sum / I.B.E: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL

N51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TP FWD:

Asher

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

Contact : 66550005 98630879

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRBAG CONTROL UNIT <i>Activated</i>	1	980.00	980.00 ✓
FRONT LH DOOR <i>Distorted</i>	1	1080.50	1,080.50 ✓
FRONT LH DOOR ARM REST GARNISH <i>New</i>	1	165.00	165.00 ✗
FRONT LH DOOR BLACK FRAME STICKER <i>New</i>	1	33.00	33.00 ✓
FRONT LH DOOR BODY WEATHER STRIP SEAL <i>New</i>	1	150.00	150.00 ✗
FRONT LH DOOR CENTER SEAL <i>New</i>	1	35.00	35.00 ✗
FRONT LH DOOR GLASS <i>Int</i>	1	580.00	580.00 ✓
FRONT LH DOOR GLASS CHANNEL <i>Best</i>	1	88.00	88.00 ✓
FRONT LH DOOR GLASS CHANNEL BRACKET <i>Damaged</i>	1	28.50	28.50 ✓
FRONT LH DOOR GLASS REGULATOR <i>Damaged</i>	1	382.90	382.90 ✓
* FRONT LH DOOR INNER MOULDING <i>Deformed</i>	1	65.50	65.50 ✗
FRONT LH DOOR INNER SEAL COVER <i>New</i>	1	35.30	35.30 ✗
FRONT LH DOOR INNER TRIM BOARD <i>Deformed</i>	1	650.00	650.00 ✓
FRONT LH DOOR LOWER SEAL <i>New</i>	1	28.00	28.00 ✗
FRONT LH DOOR MECHANISM LOCK <i>Damaged</i>	1	196.30	196.30 ✓
FRONT LH DOOR MECHANISM LOCK STRIKER <i>Best</i>	1	27.50	27.50 ✓
FRONT LH DOOR MIRROR <i>Damaged</i>	1	926.50	926.50 ✓
FRONT LH DOOR OUTER HANDLE <i>Cracked</i>	1	385.00	385.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

FRONT LH DOOR OUTER HANDLE COVER GASKET SEAL <i>? New</i>	1	12.50	12.50 ✓
FRONT LH DOOR OUTER HANDLE GASKET SEAL	1	12.50	12.50 ✓
FRONT LH DOOR OUTER MOULDING <i>behind</i>	1	60.00	60.00 ✓
FRONT LH DOOR RUBBER GUIDE STOPPER <i>new</i>	4	10.50	42.00 ✓
FRONT LH DOOR SEAL <i>Not new</i>	1	20.00	20.00 ✓
FRONT LH DOOR STEP GARNISH <i>behind</i>	1	20.60	20.60 ✓
FRONT LH DOOR SWITCH <i>new</i>	1	27.50	27.50 ✓
FRONT LH DOOR UPPER SEAL <i>Not new</i>	1	71.00	71.00 ✓
FRONT LH PILLAR INNER GARNISH <i>new</i>	1	88.00	88.00 ✓
FRONT LH SEAT AIRBAG <i>Activated</i>	1	850.00	850.00 ✓
FRONT LH SEAT BACK COVER <i>torn</i>	1	360.00	360.00 ✓
FRONT LH SEAT BACK CUSHION <i>torn</i>	1	486.00	486.00 ✓
FRONT LH SEAT BELT <i>Activated</i>	1	680.00	680.00 ✓
FRONT WINDSCREEN GLASS <i>cracked</i>	1	2335.00	2,335.00 ✓
FRONT WINDSCREEN GLASS LOWER MOULDING	1	95.00	95.00 ✓
FRONT WINDSCREEN GLASS SIDE MOULDING L/R <i>? New</i>	2	28.50	57.00 ✓
FRONT WINDSCREEN GLASS UPPER MOULDING	1	95.00	95.00 ✓
LH CENTER PILLAR LOWER GARNISH <i>cracked</i>	1	80.00	80.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

LH CENTER PILLAR UPPER GARNISH	Neu	1	95.00	95.00 X
LH SIDE CENTER INNER PILLAR	Distorted	1	133.40	133.40 ✓
LH SIDE CENTER OUTER BRACKET	for neu	1	16.50	16.50 X
LH SIDE CENTER PILLAR	Distorted	1	251.40	251.40 ✓
LH SIDE CENTER PILLAR BRACKET	Damaged	1	25.30	25.30 ✓
LH SIDE OUTER PANEL	Distorted	1	933.50	933.50 ✓
LH SIDE ROCKER INNER PANEL	Repair	1	215.10	215.10 X
LH SIDE ROCKER PANEL GARNISH	Behind	1	377.50	377.50 ✓
LH SIDE ROCKER PANEL GARNISH COVER	neu	1	18.90	18.90 ✓
LH SIDE ROOF AIRBAG	Activated	1	1076.00	1,076.00 ✓
LH SIDE ROOF AIRBAG IMPACT SENSOR	Activated	2	195.00	390.00 ✓
REAR LH DOOR	Distorted	1	930.60	930.60 ✓
REAR LH DOOR ARM REST GARNISH	neu	1	165.00	165.00 +
REAR LH DOOR BLACK FRAME STICKER	neu	1	18.50	18.50 ✓
REAR LH DOOR BODY WEATHER STRIP SEAL	neu	1	95.20	95.20 X
REAR LH DOOR CENTER WEATHER STRIP SEAL	ld	1	36.50	36.50 ✓
REAR LH DOOR CHECKER	Bent	1	55.00	55.00 ✓
REAR LH DOOR GLASS	shattered	1	428.00	428.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

REAR LH DOOR GLASS CHANNEL <i>Seat</i>	1	95.00	95.00 ✓
REAR LH DOOR GLASS CHANNEL BRACKET <i>Damaged</i>	1	36.50	36.50 ✓
REAR LH DOOR GLASS REGULATOR <i>Damaged</i>	1	390.00	390.00 ✓
REAR LH DOOR HINGES (TOP & LOWER) <i>Seat</i>	2	38.50	77.00 ✓
REAR LH DOOR INNER MOULDING <i>Damaged</i>	1	87.50	87.50 ✓
REAR LH DOOR INNER SEAL COVER <i>new</i>	1	35.50	35.50 ✗
REAR LH DOOR INNER TRIM BOARD <i>let</i>	1	498.00	498.00 ✓
REAR LH DOOR LOWER WEATHER STRIP SEAL <i>new</i>	1	14.90	14.90 ✗
REAR LH DOOR MECHANISM LOCK <i>Damaged</i>	1	295.80	295.80 ✓
REAR LH DOOR MECHANISM LOCK STRIKER <i>new</i>	1	27.50	27.50 ✗
REAR LH DOOR OUTER HANDLE <i>new</i>	1	98.00	98.00 ✗
REAR LH DOOR OUTER HANDLE INNER COVER <i>new</i>	1	28.00	28.00 ✗
REAR LH DOOR OUTER MOULDING <i>Damaged</i>	1	65.00	65.00 ✓
REAR LH DOOR PROTECTOR STICKER <i>new</i>	1	21.70	21.70 ✓
REAR LH DOOR RUBBER GUIDE STOPPER <i>new</i>	2	13.50	27.00 ✗
REAR LH DOOR STEP GARNISH <i>Damaged</i>	1	20.60	20.60 ✓
REAR LH DOOR SWITCH <i>new</i>	1	27.50	27.50 ✗
REAR LH DOOR WEATHER STRIP SEAL <i>with new</i>	1	18.50	18.50 ✗

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

REAR LH DOOR WINDOW CONTROL SWITCH	1	27.50	27.50	X
REAR LH DOOR WINDOW CONTROL SWITCH PANEL	1	34.30	34.30	X
REAR LH FENDER <i>Repair</i>	1	884.40	884.40	X
REAR LH FENDER ARCH GARNISH <i>Rehd</i>	1	195.00	195.00	✓
REAR LH FENDER INNER SHIELD	1	90.40	90.40	X
REAR LH PILLAR INNER TRIM GARNISH	1	95.00	95.00	X
REAR LH PILLAR INNER TRIM GARNISH CLIPS - SET	1	20.00	20.00	X
ROOF LINING <i>Completed</i>	1	1250.00	1,250.00	✓
Subtotal before discount			20,951.10	
Percentage discount 20%			4,190.22	
Sub-total 1			16,760.88	
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>Rec</i>	1	50.00	50.00 30	
FRONT LH DOOR SPEAKER <i>Rehd</i>	1	180.00	180.00 50	
FRONT LH DOOR STEP GARNISH CLIPS - SET <i>Rec</i>	1	20.00	20.00 10	
FRONT LH PILLAR INNER GARNISH CLIPS - SET <i>Rec</i>	1	20.00	20.00 10	
FRONT WINDSCREEN GLASS E.R.P BRACKET <i>Rec</i>	1	35.00	35.00 20	
FRONT WINDSCREEN GLASS E.R.P BRACKET STICKER <i>Rec</i>	1	15.00	15.00 5	
FRONT WINDSCREEN GLASS SEALANT <i>Rec</i>	1	100.00	100.00 60	

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

LH CENTER PILLAR GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 10
LH SIDE OUTER PANEL PLATE STICKER <i>new</i>	1	60.00	60.00 25
LH SIDE ROCKER PANEL GARNISH CLIPS - SET <i>new</i>	1	50.00	50.00 30
REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	50.00 30
REAR LH DOOR SPEAKER <i>new</i>	1	180.00	180.00 50
REAR LH DOOR STEP GARNISH CLIPS - SET <i>new</i>	1	20.00	20.00 10
REAR LH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 5
ROOF LINING CLIPS - SET <i>new</i>	1	50.00	50.00 ✓
Subtotal before discount			890.00
Percentage discount 0%			0.00
Sub-total 2			890.00
Parts-total			17,650.88

LABOUR

To remove, change air bag, air-bag sensor, air-bag wire and resetting system.

To reset system after repair works

To remove, change windscreen.

To remove, reinstall window glass. (to FR)

To remove, change window glass.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~800.00~~ 380

~~400.00~~ 100

~~120.00~~ ✓

~~80.00~~ 40

~~80.00~~ 40

~~250.00~~ 180

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-18 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

To send vehicle for cleaning, shampoo, upholstery and cushion seat.

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

6,850.00

Parts & Labour Total

24,500.88

*** This is a computer-generated document which requires no signature.***

page 7

total 18554.20

A/S 151K

09 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Monday, 16 July 2018 12:36 PM
To: sur@lkkauto.com; assignments@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: SLR4263U & FBL3293P - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD Ref: PNMC2017-00000882)
Attachments: 16072018114219.pdf

12:52pm @ 16/7/18
vehicle in
person @ see lin

Hi LKK team,

Please refer to the attached and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Kind Regards
Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg

FWD
insurance



From: Chin Hui Xin [mailto:huixin@n51.com.sg]
Sent: Monday, 16 July, 2018 11:47 AM
To: Motor Claims SG - SG Common
Cc: assignments
Subject: Re: SLR4263U & FBL3293P - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD Ref: PNMC2017-00000882)


Dear Sir/Madam,

We appoint your surveyor company Lkk Auto Consultants Pte Ltd.

Kindly arrange your surveyor come to our workshop PRI.

Thank you...

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



On Mon, Jul 16, 2018 at 10:59 AM, <motorclaims.sg@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Melody,

We refer to your letter dated 16 July 2018 of the PRI Notice of your client's vehicle SLR4263U.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg

FWD
insurance

With FWD, you get to keep your
50% NCD for Life. No matter what.
get a quick quote now. >



FWD
insurance

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Monday, 16 July, 2018 10:45 AM

To: Motor Claims SG - SG Common

Subject: SLR4263U & FBL3293P - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

7/2/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SLR4263U (1201800009147)**
[FBL3293P]

TP
GRAB RENTALS PTE LTD
Jul 11 2018 7:00AM
[RASMAN BIN SEMAWI]
N-51 Automotive Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 01/07/2019 11:02 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16904.45) - SLR4263U - Claim Handler: Josey Loh

Approved:16904.45:HII Please offer LOU at \$60 per day

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 2 July 2019 4:46 PM
To: Sabrina (N-51)
Cc: Chin Hui Xin
Subject: RE: LOD - Accident involving SLR4263U & FBL3293P on 11/07/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

On a without prejudice, for a quick and amicable settlement, we propose the settlement at Global Sum S\$16,900.00 (all-in).

Please kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sabrina (N-51) <sabrina@n51.com.sg>
Sent: Tuesday, 26 February 2019 12:27 PM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Cc: Shu Pei (LKKAuto) <shupe@lkkauto.com>; Chin Hui Xin <huixin@n51.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: Re: LOD - Accident involving SLR4263U & FBL3293P on 11/07/2018

Dear Asher,

We refer to the above subject matter.

Kindly follow up this case as soon as possible and advise your insured to report.

Thank you

Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 Jul 2018 14:47	Cim Veh Model Changed	(204152) HONDA VEZEL 1.5 HYBRID (A).	[A] Lau Shu Pei
2	17 Jul 2018 14:47	Cim Created	Reg No: SLR4263U, Acct Date: 2018/07/11. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: N-51 Automotive Pte Ltd (HQ)	[A] Lau Shu Pei
3	17 Jul 2018 14:47	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : VICOM Ltd.	[A] Lau Shu Pei
4	17 Jul 2018 14:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/26	[A] Lau Shu Pei
5	17 Jul 2018 14:47	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lau Shu Pei
6	17 Jul 2018 14:47	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
7	19 Jul 2018 16:46	Cim Registration Modified	Pol No:->PNMC2017-00000882,	[I] Josey Loh
8	13 Aug 2018 14:41	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/07/26	[A] Lau Shu Pei
9	26 Feb 2019 19:00	Label Added	(20005):Direct Settlement .	[A] Lau Shu Pei
10	24 Jun 2019 10:15	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
11	24 Jun 2019 10:15	Cim Dtl Modified	JPJ Reg. Date: -> 2017/08/15.	[A] JOANNE LEE KHANG MIN
12	24 Jun 2019 10:15	Cim Details Notified		[A] JOANNE LEE KHANG MIN
13	28 Jun 2019 16:37	Adj Mandate Request	Cur,Req:17344.45:LIABILITY: 100% B:NIL OI BEATS RED LIGHT COLLIDED INTO TP (REFER TO WITNESS VIDEO) QUANTUM: (a) COR w/GST : \$16,157.00 + (b) LOU : \$1,100.00 (11days x \$100) + (c) TOWING FEE : \$80.00 + (d) LTA: \$7.45 Total: a+b+c+d = \$17,344.45 *TP	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1885536	13/08/2018 14:41	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLR4263U	FBL3293P	10.70

Print Received Message

This mail is associated with :

***SLR4263U (1201800009147)**
[FBL3293P]

TP

GRAB RENTALS PTE LTD

Jul 11 2018 7:00AM

[RASMAN BIN SEMAWI]

N-51 Automotive Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 24/07/2019 14:53 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$17014.45) - SLR4263U - Claim Handler: Josey Loh

Approved:17014.45:HII Based on supporting document, towing + PHC decal is \$80

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921
Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510
Email: sales@n51.com.sg
Company Reg. No.: 200616038C
GST Registration No.: 200616038C

14-Nov-2018

Our Ref: CLM14638 / SLR4263U / July-31/2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER FOUR
SINGAPORE 038986

ATTN: MOTOR CLAIMS DEPARTMENT

Dear Sir @ Mdm,

Re: Accident involving SLR 4263 U & FBL 3293 P on 11/07/2018
Along Punggol road junction of Punggol field

We refer to the above accident which was caused due to the negligence of your insured driver of vehicle No: FBL 3293 T whose vehicle was insured with you at the material date of the accident.

We are proposing for a direct settlement on the claims as following **exclude** personal injury in respect of claim arising out of the abovementioned accident.

Cost of Repairs	\$	16,157.00	(Include 7% GST)
Loss of use/rental	\$	1,120.00	(\$70.00 X 16 days)
LTA search fee	\$	7.45	
Towing fee	\$	60.00	
PHC Decal	\$	20.00	
Loss of Income	\$	1,280.00	(\$80.00 X 16 days)
	S \$	<u>18,644.45</u>	

We enclosed herein the following documents for your necessary attention.

- 1) Our Final Repair Bill No: CLM14638
- 2) Grab Rentals Pte Ltd Letter
- 3) LTA search fee
- 4) Autobay Towing - SLR4263U (receipt attached)
- 5) PHC Decal - SLR4263U (receipt attached)
- 6) Letter of Authorisation to Act
- 7) GIA Report of SLR 4263 U
- 8) Police Report of SLR 4263 U
- 9) Video footage of SLR 4263 U

If you have any queries, please contact Sabrina at 6842 0051 or email at sabrina@n51.com.sg

We look forward to your prompt reply.

Yours faithfully,



N-51 Automotive Pte Ltd

S.Y. NEO

Managing Director



AUTHORISATION TO ACT

I, Grab Rentals Pte Ltd of 18 Sin Ming Lane #01-08 Midview City Singapore 573960,
owner of SLR4263U hereby authorize N-51 Automotive Pte Ltd to act for me with respect
to my claim for repair costs and / or rental and / or loss of use ('claim') for my vehicle no.
SLR4263U that was damaged pursuant to the accident which occurred on 11/07/2018
along Punggol road Junction of Punggol Field involving vehicle no/s FBL3293P.

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement
of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 11 of JULY 2018



Signed by 'the third party claimant'
(with chop if applicable)



Signed by 'the workshop'
(with chop)

(Asher)

RELEASE

Claim Reference:	1201800009147
Surveyor's Reference:	CC4/FWD18012951/Aeb3
TP Reference:	CLM14638/SLR4263U/JULY-31/2018

We, **N-51 AUTOMOTIVE PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SLR 4263U** ("Vehicle") to accept the sum of \$ **17,000.00** (Global Sum) being the amount claimed as compensation for the loss of or damage to the Vehicle / loss of use, as a result of an accident ("Accident") which occurred on **11/07/2018** (date of accident) at / along **PUNGGOL RD JUNC OF PUNGGOL FIELD** (location) involving vehicle no/s. **SLR 4263U** and **FBL 3293P**.

This is pursuant to the inspection conducted on **16/07/2018** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **FBL 3293P** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 07 day of AUG 2019

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



LWP

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

I provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for personal and special damages for my personal injuries sustained in the same accident.



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921

Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR

SINGAPORE 038986

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 98630879

TAX INVOICE

Date : 06/09/2018

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Make/Model : HONDA VEZEL HYBRID 1.5X AUTO-2017

Chassis/Eng# : RU31254307/LEB5954325

Accident Date : 11/07/2018

Claim No : CLM14638

Reference : JULY-31/2018

Policy No. : A29069766MKF (31/01/2019)

LUMP SUM REPAIR BILL

REF : CLM14638-N51 DATED 06/07/2018

BY DIRECT

Amount SS

15,100.00



E. & O.E. Sub SS : 15,100.00

Add GST (7%) SS : 1,057.00

Total Amount SS : 16,157.00

for N-51 AUTOMOTIVE PTE LTD



bizSAFE₃

CONFIDENTIAL



Date:

Grab Rentals Pte Ltd
201617200G
Grab Rentals 2 Pte. Ltd.
201701345N

28 Sin Ming Lane
#01-138 Midview City
Singapore 573972

Dear Sir / Madam,

Accident Date:	11 / 07 / 2018	Time:	07:30HRS
Accident Location:	PUNGGOL RD JUNC OF PUNGGOL FIELD		

We refer to the above-mentioned accident & wish to inform the following details at the time of occurrence of the aforementioned accident:

Registered Owner:	Grab Rentals Pte. Ltd. / Grab Rentals 2 Pte. Ltd.*
Vehicle Registration No. (the "private hire"):	SLR 4263 LI
Registered Hirer Name:	ABDUL WAHAB BIN AWANG
Registered Hirer NRIC:	S 1136569 H
Rental Rate (per day inclusive of GST):	SG\$ 70
Rental Period:	

* delete as applicable

The following procedures were followed:

Period of repair	From:	16 / 07 / 2018
	To:	26 / 07 / 2018
Rental	The company:	☒ Collects / ☐ Does not collect*
	Replacement vehicle:	☐ Provided / ☒ Not provided
	From:	
	To:	

* delete as applicable

Please liaise with our appointed workshop, NSI Automotive Pte. Ltd. directly for any settlement of claims in respect of the said accident.

We hereby authorize all agreed settlement payments made in favour of NSI Automotive Pte. Ltd.

Yours faithfully,



Name: Tay Chee Wee
Senior Operations Associate

AUTOBAY TOWING

1 Kaki Bukit Avenue 6
#01-55 AutoBAY @ Kaki Bukit
Singapore 417883
Tel: 3312 8788 (An 800n)

CASH SALE

No. _____

Date: 11/7/18

Sold to: _____

(N-51)
SLR 4263 U

Item	Quantity	Description	Unit Price	Amount
		Pangol Rd to Auto		\$ 60
		Hub Waring L-D		
E. & O. E.			Sub Total :	
			GST Tax :	
			Total :	\$ 60

Issued by: _____

CROWN

CLM 14638

P.H.C. decals (pair)
GRAB Vehicle
3rd Party Claim

VICOM INSPECTION CENTRE PTE LTD

23, Kaki Bukit Avenue 4 S(415933)

REG NO 2001025140

GST REG NO M9-0000852-A

24 Jul 2018, 03:32 PM

Receipt No. VICKBX18112133

Cashier NORISWI ABBUL HASSAN

Cost Type CS

Customer Cash

PG Number

Vehicle No. SERVEDU

Chassis No.

Item	Qty	Unit Price	Amount	GST
P.H.C. Decal Installation	1	15.00	15.00	1.31

Sub Total 15.00

Total GST 7 % 1.31

AMOUNT DUE 20.00

CASH 20.00

TENDER 20.00

CHANGE 0.00

ROUNDING OFF 0.00

*** THANK YOU ***



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 16 Jul 2018 / 09:47:13

Receipt Date/Time : 16 Jul 2018 / 09:47:13

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180716-000372

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - FBL3293P				
As at 11 Jul 2018/07:30:00				
Insurance Co: FWD SINGAPORE PTE. LTD.				
1	Insurance Enquiry - FBL3293P Enquiry Fee 20180716094645393712	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxxx2392	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jul 2018 Edit Reg		16 Jul 2018 00:00 Edit Adj Rpt	S\$15,100.00 Edit Estimates	S\$15,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	RASMAN BIN SEMAWI, ID: S1817904		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLR4263U	Date of Loss:	11/07/2018 07:00 - :59 [10 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201800009147	Policy/Cover Note No.:	PNMC2017-00000882 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBL3293P	Policy No. (Claimant):	A29069766MKF
		Excess:	
Repairer:	N-S1 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/07/2018]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- FWD_SG (24/07/2019): Alert - Adj Mandate Approved (S\$17014.45) - SLR4263U - Claim Handler: Josey Loh
- FWD_SG (23/07/2019): Alert - Adj Mandate Maintained - SLR4263U - Claim Handler: Josey Loh
- FWD_SG (01/07/2019): Alert - Adj Mandate Approved (S\$16904.45) - SLR4263U - Claim Handler: Josey Loh

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR4263U (1201800009147)
[FBL3293P]

TP

GRAB RENTALS PTE LTD

Jul 11 2018 7:00AM

[RASMAN BIN SEMAWI]

N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Letters/Correspondences									1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown									Edit	
Assessment Reports									1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	13/08/18 14:41	Adjuster Immediate Advice									Load HTML	
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	06/08/18 18:49	General View									Load JPG ☒	
2	06/08/18 18:49	General View									Load JPG ☒	
3	06/08/18 18:49	General View									Load JPG ☒	
4	06/08/18 18:49	General View									Load JPG ☒	
5	06/08/18 18:49	General View									Load JPG ☒	
6	06/08/18 18:49	General View									Load JPG ☒	
7	06/08/18 18:49	General View									Load JPG ☒	
8	06/08/18 18:49	General View									Load JPG ☒	
9	06/08/18 18:49	General View									Load JPG ☒	
10	06/08/18 18:49	General View									Load JPG ☒	
11	06/08/18 18:49	General View									Load JPG ☒	
12	06/08/18 18:49	General View									Load JPG ☒	
13	06/08/18 18:49	General View									Load JPG ☒	
14	06/08/18 18:49	General View									Load JPG ☒	
15	06/08/18 18:49	General View									Load JPG ☒	
16	06/08/18 18:49	General View									Load JPG ☒	
17	06/08/18 18:49	General View									Load JPG ☒	
18	06/08/18 18:49	General View									Load JPG ☒	
19	06/08/18 18:49	General View									Load JPG ☒	
20	06/08/18 18:49	General View									Load JPG ☒	
21	06/08/18 18:49	General View									Load JPG ☒	
22	06/08/18 18:49	General View									Load JPG ☒	
23	06/08/18 18:49	General View									Load JPG ☒	
24	06/08/18 18:49	General View									Load JPG ☒	
25	06/08/18 18:49	General View									Load JPG ☒	
26	06/08/18 18:49	General View									Load JPG ☒	
27	06/08/18 18:49	General View									Load JPG ☒	
28	06/08/18 18:49	General View									Load JPG ☒	
29	06/08/18 18:49	General View									Load JPG ☒	
30	06/08/18 18:49	General View									Load JPG ☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	06/08/18 18:49	General View	 Load JPG	☒
32	06/08/18 18:49	General View	 Load JPG	☒
33	06/08/18 18:49	General View	 Load JPG	☒
34	06/08/18 18:49	General View	 Load JPG	☒
35	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
36	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
37	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
38	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
39	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
40	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
41	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
42	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
43	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
44	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
45	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
46	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
47	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
48	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
49	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
50	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
51	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
52	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
53	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
54	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
55	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
56	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
57	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
58	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
59	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
60	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
61	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
62	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
63	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
64	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
65	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
66	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
67	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
68	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
69	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
70	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
71	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
72	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
73	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
74	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
75	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
76	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
77	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
78	06/08/18 18:49	Reinspection Photo	 Load JPG	☒
79	06/08/18 18:50	Reinspection Photo	 Load JPG	☒
80	06/08/18 18:50	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	06/08/18 18:50	Reinspection Photo		☒
82	06/08/18 18:50	Reinspection Photo		☒
83	06/08/18 18:50	Reinspection Photo		☒
84	06/08/18 18:50	Reinspection Photo		☒
85	06/08/18 18:50	Reinspection Photo		☒
86	06/08/18 18:50	Reinspection Photo		☒
87	06/08/18 18:50	Reinspection Photo		☒
88	06/08/18 18:50	Reinspection Photo		☒
89	06/08/18 18:50	Reinspection Photo		☒
90	06/08/18 18:50	Reinspection Photo		☒
91	06/08/18 18:50	Reinspection Photo		☒
92	06/08/18 18:50	Reinspection Photo		☒
93	06/08/18 18:50	Reinspection Photo		☒
94	06/08/18 18:50	Reinspection Photo		☒
95	06/08/18 18:50	Reinspection Photo		☒
96	06/08/18 18:50	Reinspection Photo		☒
97	06/08/18 18:50	Reinspection Photo		☒
98	06/08/18 18:50	Reinspection Photo		☒
99	06/08/18 18:50	Reinspection Photo		☒
100	06/08/18 18:50	Reinspection Photo		☒
101	06/08/18 18:50	Reinspection Photo		☒
102	06/08/18 18:50	Reinspection Photo		☒
103	06/08/18 18:50	Reinspection Photo		☒
104	06/08/18 18:50	Reinspection Photo		☒
105	06/08/18 18:50	Reinspection Photo		☒
106	06/08/18 18:50	Reinspection Photo		☒
107	06/08/18 18:50	Reinspection Photo		☒
108	06/08/18 18:50	Reinspection Photo		☒
109	06/08/18 18:50	Reinspection Photo		☒
110	06/08/18 18:50	Reinspection Photo		☒
111	06/08/18 18:50	Reinspection Photo		☒
112	06/08/18 18:50	Reinspection Photo		☒
113	06/08/18 18:50	Reinspection Photo		☒
114	06/08/18 18:50	Reinspection Photo		☒
115	06/08/18 18:50	Reinspection Photo		☒
116	06/08/18 18:50	Reinspection Photo		☒
117	06/08/18 18:50	Reinspection Photo		☒
118	06/08/18 18:50	Reinspection Photo		☒
119	06/08/18 18:50	Reinspection Photo		☒
120	06/08/18 18:50	Reinspection Photo		☒
121	06/08/18 18:50	Reinspection Photo		☒
122	06/08/18 18:50	Reinspection Photo		☒
123	06/08/18 18:50	Reinspection Photo		☒
124	06/08/18 18:50	Reinspection Photo		☒
125	06/08/18 18:50	Reinspection Photo		☒
126	06/08/18 18:50	Reinspection Photo		☒
127	06/08/18 18:50	Reinspection Photo		☒
128	06/08/18 18:50	Reinspection Photo		☒
129	06/08/18 18:50	Reinspection Photo		☒
130	06/08/18 18:50	Reinspection Photo		☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	06/08/18 18:50	Reinspection Photo		☒
132	06/08/18 18:50	Reinspection Photo		☒
133	06/08/18 18:50	Reinspection Photo		☒
134	06/08/18 18:50	Reinspection Photo		☒
135	06/08/18 18:50	Reinspection Photo		☒
136	06/08/18 18:50	Reinspection Photo		☒
137	06/08/18 18:50	Reinspection Photo		☒
138	06/08/18 18:50	Reinspection Photo		☒
139	06/08/18 18:50	Reinspection Photo		☒
140	06/08/18 18:50	Reinspection Photo		☒
141	06/08/18 18:50	Reinspection Photo		☒
142	06/08/18 18:50	Reinspection Photo		☒
143	06/08/18 18:50	Reinspection Photo		☒
144	06/08/18 18:50	Reinspection Photo		☒
145	06/08/18 18:50	Reinspection Photo		☒
146	06/08/18 18:50	Reinspection Photo		☒
147	06/08/18 18:50	Reinspection Photo		☒
148	06/08/18 18:50	Reinspection Photo		☒
149	06/08/18 18:50	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 14:51	EMAIL FROM FWD DD 17072018.		
2	17/07/18 14:51	WKSP NOTICE		
3	17/07/18 17:49	TP GIA REPORT		
4	19/07/18 16:46	FWD EMAIL TO INSURED DD 19072018		
5	13/08/18 18:27	TP ESTIMATE- MARKED		
6	24/06/19 10:38	WORKSHOP INVOICE		
7	24/06/19 10:38	TOWING FEE		
8	24/06/19 10:38	LTA SEARCH		
9	24/06/19 10:38	LOD		
10	05/07/19 17:13	RENTAL		
11	22/07/19 17:42	EMAIL FROM WSP DD 120719		
12	19/08/19 08:22	AUTHORISATION TO ACT FORM		
13	19/08/19 08:22	Release Voucher		
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	25/02/19 13:39	OI GIA		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBL3293P (Insd veh)	Model:	HONDA VEZEL 1.5 HYBRID
	SLR4263U (TP veh)		(A)
Date of Accident:	11/07/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	26,215.94
Final Repair Cost	:	\$	17,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	11 days
LTA / GIA Search Fee	:	\$	
Others: Towing Fee	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	17,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	N-51 Automotive Pte Ltd	:	\$ 17,000.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

19 Aug
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18012951/AEB3Q2

Date: 19/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2017-00000882

Claimant Vehicle No: SLR4263U Insured Vehicle No: FBL3293P

Date of Loss: 11/07/2018 Nature of Claim: TP Claim No: 1201800009147

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR4263U	Engine No:	LEB5954325
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31254307
Reg. Date:	15/08/2017 (Man. Year: 2017)	Odometer:	88720 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,650.88	14,989.20	2,661.68	15.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,850.00	3,920.00	2,930.00	42.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,500.88	18,909.20	5,591.68	22.82
Approved Total (Overridden) (S\$)		15,100.00		
(S\$)	24,500.88	15,100.00	9,400.88	38.37
+ GST 7.00/7.00% (S\$)	1,715.06	1,057.00	658.06	38.37
Nett Amount (S\$)	26,215.94	16,157.00	10,058.94	38.37
+ Car Rental (11.0 x S\$70.00/day) (S\$)		770.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		17,014.45		
Global Sum Settlement (S\$)		17,000.00		

INSPECTION

Date of Assignment: 16/07/2018

Date Inspected: 16/07/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLR4263U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIRBAG CONTROL UNIT	Activated	980.00 FL	*980.00 FL
2	1		*FRONT LH DOOR	Distorted	1,080.50 FL	*1,080.50 FL
3	1		*FRONT LH DOOR ARM REST GARNISH	Not Necessary	165.00 FL	*- FL
4	1		*FRONT LH DOOR BLACK FRAME STICKER	Necessary	33.00 FL	*33.00 FL
5	1		*FRONT LH DOOR BODY WEATHER STRIP SEAL	Not Necessary	150.00 FL	*- FL
6	1		*FRONT LH DOOR CENTER SEAL	Not Necessary	35.00 FL	*- FL
7	1		*FRONT LH DOOR GLASS	Cut	580.00 FL	*580.00 FL
8	1		*FRONT LH DOOR GLASS CHANNEL	Bent	88.00 FL	*88.00 FL
9	1		*FRONT LH DOOR GLASS CHANNEL BRACKET	Damaged	28.50 FL	*28.50 FL
10	1		*FRONT LH DOOR GLASS REGULATOR	Damaged	382.90 FL	*382.90 FL
11	1		*FRONT LH DOOR INNER MOULDING	Deformed	65.50 FL	*65.50 FL
12	1		*FRONT LH DOOR INNER SEAL COVER	Not Necessary	35.30 FL	*- FL
13	1		*FRONT LH DOOR INNER TRIM BOARD	Deformed	650.00 FL	*650.00 FL
14	1		*FRONT LH DOOR LOWER SEAL	Not Necessary	28.00 FL	*- FL
15	1		*FRONT LH DOOR MECHANISM LOCK	Damaged	196.30 FL	*196.30 FL
16	1		*FRONT LH DOOR MECHANISM LOCK STRIKER	Bent	27.50 FL	*27.50 FL
17	1		*FRONT LH DOOR MIRROR	Damaged	926.50 FL	*926.50 FL
18	1		*FRONT LH DOOR OUTER HANDLE	Cracked	385.00 FL	*385.00 FL
19	1		*FRONT LH DOOR OUTER HANDLE COVER GASKET SEAL	Not Necessary	12.50 FL	*- FL
20	1		*FRONT LH DOOR OUTER HANDLE GASKET SEAL	Not Necessary	12.50 FL	*- FL
21	1		*FRONT LH DOOR OUTER MOULDING	Deformed	60.00 FL	*60.00 FL
22	4		*FRONT LH DOOR RUBBER GUIDE STOPPER	Not Necessary	42.00 FL	*- FL
23	1		*FRONT LH DOOR SEAL	Not Necessary	20.00 FL	*- FL
24	1		*FRONT LH DOOR STEP GARNISH	Deformed	20.60 FL	*20.60 FL
25	1		*FRONT LH DOOR SWITCH	Not Necessary	27.50 FL	*- FL
26	1		*FRONT LH DOOR UPPER SEAL	Not Necessary	71.00 FL	*- FL
27	1		*FRONT LH PILLAR INNER GARNISH	Not Necessary	88.00 FL	*- FL
28	1		*FRONT LH SEAT AIRBAG	Activated	850.00 FL	*850.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*FRONT LH SEAT BACK COVER	Torn	360.00 FL	*360.00 FL
30	1		*FRONT LH SEAT BACK CUSHION	Torn	486.00 FL	*486.00 FL
31	1		*FRONT LH SEAT BELT	Activated	680.00 FL	*680.00 FL
32	1		*FRONT WINDSCREEN GLASS	Cracked	2,335.00 FL	*2,335.00 FL
33	1		*FRONT WINDSCREEN GLASS LOWER MOULDING	Necessary	95.00 FL	*95.00 FL
34	2		*FRONT WINDSCREEN GLASS SIDE MOULDING L/R	Necessary	57.00 FL	*57.00 FL
35	1		*FRONT WINDSCREEN GLASS UPPER MOULDING	Necessary	95.00 FL	*95.00 FL
36	1		*LH CENTER PILLAR LOWER GARNISH	Cracked	80.00 FL	*80.00 FL
37	1		*LH CENTER PILLAR UPPER GARNISH	Not Necessary	95.00 FL	*- FL
38	1		*LH SIDE CENTER INNER PILLAR	Distorted	133.40 FL	*133.40 FL
39	1		*LH SIDE CENTER OUTER BRACKET	Not Necessary	16.50 FL	*- FL
40	1		*LH SIDE CENTER PILLAR	Distorted	251.40 FL	*251.40 FL
41	1		*LH SIDE CENTER PILLAR BRACKET	Damaged	25.30 FL	*25.30 FL
42	1		*LH SIDE OUTER PANEL	Distorted	933.50 FL	*933.50 FL
43	1		*LH SIDE ROCKER INNER PANEL	Repair	215.10 FL	*- FL
44	1		*LH SIDE ROCKER PANEL GARNISH	Deformed	377.50 FL	*377.50 FL
45	1		*LH SIDE ROCKER PANEL GARNISH COVER	Necessary	18.90 FL	*18.90 FL
46	1		*LH SIDE ROOF AIRBAG	Activated	1,076.00 FL	*1,076.00 FL
47	2		*LH SIDE ROOF AIRBAG IMPACT SENSOR	Activated	390.00 FL	*390.00 FL
48	1		*REAR LH DOOR	Distorted	930.60 FL	*930.60 FL
49	1		*REAR LH DOOR ARM REST GARNISH	Not Necessary	165.00 FL	*- FL
50	1		*REAR LH DOOR BLACK FRAME STICKER	Necessary	18.50 FL	*18.50 FL
51	1		*REAR LH DOOR BODY WEATHER STRIP SEAL	Not Necessary	95.20 FL	*- FL
52	1		*REAR LH DOOR CENTER WEATHER STRIP SEAL	Cut	36.50 FL	*36.50 FL
53	1		*REAR LH DOOR CHECKER	Bent	55.00 FL	*55.00 FL
54	1		*REAR LH DOOR GLASS	Shattered	428.00 FL	*428.00 FL
55	1		*REAR LH DOOR GLASS CHANNEL	Bent	95.00 FL	*95.00 FL
56	1		*REAR LH DOOR GLASS CHANNEL BRACKET	Damaged	36.50 FL	*36.50 FL
57	1		*REAR LH DOOR GLASS REGULATOR	Damaged	390.00 FL	*390.00 FL
58	2		*REAR LH DOOR HINGES (TOP&LOWER)	Bent	77.00 FL	*77.00 FL
59	1		*REAR LH DOOR INNER MOULDING	Deformed	87.50 FL	*87.50 FL
60	1		*REAR LH DOOR INNER SEAL COVER	Not Necessary	35.50 FL	*- FL
61	1		*REAR LH DOOR INNER TRIM BOARD	Cut	498.00 FL	*498.00 FL
62	1		*REAR LH DOOR LOWER WEATHER STRIP SEAL	Not Necessary	14.90 FL	*- FL
63	1		*REAR LH DOOR MECHANISM LOCK	Damaged	295.80 FL	*295.80 FL
64	1		*REAR LH DOOR MECHANISM LOCK STRIKER	Not Necessary	27.50 FL	*- FL
65	1		*REAR LH DOOR OUTER HANDLE	Not Necessary	98.00 FL	*- FL
66	1		*REAR LH DOOR OUTER HANDLE INNER COVER	Not Necessary	28.00 FL	*- FL
67	1		*REAR LH DOOR OUTER MOULDING	Deformed	65.00 FL	*65.00 FL
68	1		*REAR LH DOOR PROTECTOR STICKER	Necessary	21.70 FL	*21.70 FL
69	2		*REAR LH DOOR RUBBER GUIDE STOPPER	Not Necessary	27.00 FL	*- FL
70	1		*REAR LH DOOR STEP GARNISH	Deformed	20.60 FL	*20.60 FL
71	1		*REAR LH DOOR SWITCH	Not Necessary	27.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
72	1		*REAR LH DOOR WEATHER STRIP SEAL	Not Necessary	18.50 FL	*- FL
73	1		*REAR LH DOOR WINDOW CONTROL SWITCH	Not Necessary	27.50 FL	*- FL
74	1		*REAR LH DOOR WINDOW CONTROL SWITCH PANEL	Not Necessary	34.30 FL	*- FL
75	1		*REAR LH FENDER	Repair	884.40 FL	*- FL
76	1		*REAR LH FENDER ARCH GARNISH	Deformed	195.00 FL	*195.00 FL
77	1		*REAR LH FENDER INNER SHIELD	Not Necessary	90.40 FL	*- FL
78	1		*REAR LH PILLAR INNER TRIM GARNISH	Not Necessary	95.00 FL	*- FL
79	1		*SET REAR LH PILLAR INNER TRIM GARNISH CLIPS	Not Necessary	20.00 FL	*- FL
80	1		*ROOF LINING	Crumpled	1,250.00 FL	*1,250.00 FL
81	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
82	1		*FRONT LH DOOR SPEAKER	Damaged	180.00 FS	*50.00 FS
83	1		*SET FRONT LH DOOR STEP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
84	1		*SET FRONT LH PILLAR INNER GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
85	1		*FRONT WINDSCREEN GLASS E.R.P BRACKET	Necessary	35.00 FS	*20.00 FS
86	1		*FRONT WINDSCREEN GLASS E.R.P BRACKET STICKER	Necessary	15.00 FS	*5.00 FS
87	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*60.00 FS
88	1		*SET LH CENTER PILLAR GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
89	1		*LH SIDE OUTER PANEL PLATE STICKER	Necessary	60.00 FS	*25.00 FS
90	1		*SET LH SIDE ROCKER PANEL GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
91	1		*SET REAR LH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
92	1		*REAR LH DOOR SPEKAER	Damaged	180.00 FS	*50.00 FS
93	1		*SET REAR LH DOOR STEP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
94	1		*SET REAR LH FENDER ARCH GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
95	1		*SET ROOF LINING CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (S\$) **21,841.10** **18,639.00**
 - List Item Discount on L Items 20.00/20.00% (S\$) **4,190.22** **3,649.80**

Total Parts (S\$) 17,650.88 14,989.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHARGE AIR BAG ,AIR-BAG SENSOR ,AIR-BAG WIRE AND RESETTING SYSTEM	New	800.00	380.00
2	TO RESET SYSTEM AFTER REPAIR WORKS	New	400.00	100.00
3	TO REMOVE ,CHARGE WINDSCREEN	New	120.00	120.00
4	TO REMOVE,REINSTALL WINDOW GLASS (TO FR)	New	80.00	40.00
5	TO REMOVE,CHARGE WINDOW GLASS	New	80.00	40.00
6	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT, TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	250.00	180.00
7	TO SEND VEHICLE FOR CLEANING ,SHAMPOO,UPHOLSTERY AND CUSHION SEAT	New	200.00	100.00
8	TO TRANSFER DOOR GLASS ,REGULATOR ,GEAR ,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	200.00	80.00
9	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	1,200.00
10	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,800.00	1,600.00
11	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
Gross Labour Cost (S\$)			6,850.00	3,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >