

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TP FWD.
 gishes.

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

Contact : 66550005 98630879

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRBAG CONTROL UNIT <i>Activated</i>	1	980.00	980.00 ✓
FRONT LH DOOR <i>Distorted</i>	1	1080.50	1,080.50 ✓
FRONT LH DOOR ARM REST GARNISH <i>He n</i>	1	165.00	165.00 ✗
FRONT LH DOOR BLACK FRAME STICKER <i>He n</i>	1	33.00	33.00 ✓
FRONT LH DOOR BODY WEATHER STRIP SEAL <i>He n</i>	1	150.00	150.00 ✗
FRONT LH DOOR CENTER SEAL <i>He n</i>	1	35.00	35.00 ✗
FRONT LH DOOR GLASS <i>ut</i>	1	580.00	580.00 ✓
FRONT LH DOOR GLASS CHANNEL <i>Best</i>	1	88.00	88.00 ✓
FRONT LH DOOR GLASS CHANNEL BRACKET <i>Ping d</i>	1	28.50	28.50 ✓
FRONT LH DOOR GLASS REGULATOR <i>Dang d.</i>	1	382.90	382.90 ✓
* FRONT LH DOOR INNER MOULDING <i>Deh d</i>	1	65.50	65.50 ✗
FRONT LH DOOR INNER SEAL COVER <i>He n</i>	1	35.30	35.30 ✗
FRONT LH DOOR INNER TRIM BOARD <i>Deh d</i>	1	650.00	650.00 ✓
FRONT LH DOOR LOWER SEAL <i>He n</i>	1	28.00	28.00 ✗
FRONT LH DOOR MECHANISM LOCK <i>Dang d</i>	1	196.30	196.30 ✓
FRONT LH DOOR MECHANISM LOCK STRIKER <i>Best</i>	1	27.50	27.50 ✓
FRONT LH DOOR MIRROR <i>Dang d.</i>	1	926.50	926.50 ✓
FRONT LH DOOR OUTER HANDLE <i>crulced.</i>	1	385.00	385.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

FRONT LH DOOR OUTER HANDLE COVER GASKET SEAL <i>? New</i>	1	12.50	12.50	✓
FRONT LH DOOR OUTER HANDLE GASKET SEAL	1	12.50	12.50	✓
FRONT LH DOOR OUTER MOULDING <i>dehnd</i>	1	60.00	60.00	✓
FRONT LH DOOR RUBBER GUIDE STOPPER <i>new</i>	4	10.50	42.00	✓
FRONT LH DOOR SEAL <i>new</i>	1	20.00	20.00	✓
FRONT LH DOOR STEP GARNISH <i>dehnd</i>	1	20.60	20.60	✓
FRONT LH DOOR SWITCH <i>new</i>	1	27.50	27.50	✓
FRONT LH DOOR UPPER SEAL <i>new</i>	1	71.00	71.00	✓
FRONT LH PILLAR INNER GARNISH <i>new</i>	1	88.00	88.00	✓
FRONT LH SEAT AIRBAG <i>Activated.</i>	1	850.00	850.00	✓
FRONT LH SEAT BACK COVER <i>torn</i>	1	360.00	360.00	✓
FRONT LH SEAT BACK CUSHION <i>torn</i>	1	486.00	486.00	✓
FRONT LH SEAT BELT <i>Activated.</i>	1	680.00	680.00	✓
FRONT WINDSCREEN GLASS <i>cracked.</i>	1	2335.00	2,335.00	✓
FRONT WINDSCREEN GLASS LOWER MOULDING	1	95.00	95.00	✓
FRONT WINDSCREEN GLASS SIDE MOULDING L/R <i>new</i>	2	28.50	57.00	✓
FRONT WINDSCREEN GLASS UPPER MOULDING	1	95.00	95.00	✓
LH CENTER PILLAR LOWER GARNISH <i>cracked.</i>	1	80.00	80.00	✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

LH CENTER PILLAR UPPER GARNISH	He m	1	95.00	95.00 X
LH SIDE CENTER INNER PILLAR	Distorted	1	133.40	133.40 ✓
LH SIDE CENTER OUTER BRACKET	He m	1	16.50	16.50 X
LH SIDE CENTER PILLAR	Distorted	1	251.40	251.40 ✓
LH SIDE CENTER PILLAR BRACKET	Damaged	1	25.30	25.30 ✓
LH SIDE OUTER PANEL	Distorted	1	933.50	933.50 ✓
LH SIDE ROCKER INNER PANEL	Repair	1	215.10	215.10 X
LH SIDE ROCKER PANEL GARNISH	De h m d	1	377.50	377.50 ✓
LH SIDE ROCKER PANEL GARNISH COVER	He m	1	18.90	18.90 ✓
LH SIDE ROOF AIRBAG	Activated	1	1076.00	1,076.00 ✓
LH SIDE ROOF AIRBAG IMPACT SENSOR	Activated	2	195.00	390.00 ✓
REAR LH DOOR	Distorted	1	930.60	930.60 ✓
REAR LH DOOR ARM REST GARNISH	He m	1	165.00	165.00 X
REAR LH DOOR BLACK FRAME STICKER	He m	1	18.50	18.50 ✓
REAR LH DOOR BODY WEATHER STRIP SEAL	He m	1	95.20	95.20 X
REAR LH DOOR CENTER WEATHER STRIP SEAL	He m	1	36.50	36.50 ✓
REAR LH DOOR CHECKER	Bent	1	55.00	55.00 ✓
REAR LH DOOR GLASS	Shattered	1	428.00	428.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

REAR LH DOOR GLASS CHANNEL <i>Set</i>	1	95.00	95.00 ✓
REAR LH DOOR GLASS CHANNEL BRACKET <i>Dmgd.</i>	1	36.50	36.50 ✓
REAR LH DOOR GLASS REGULATOR <i>Damaged</i>	1	390.00	390.00 ✓
REAR LH DOOR HINGES (TOP & LOWER) <i>Bent.</i>	2	38.50	77.00 ✓
REAR LH DOOR INNER MOULDING <i>Deformed</i>	1	87.50	87.50 ✓
REAR LH DOOR INNER SEAL COVER <i>new</i>	1	35.50	35.50 ✗
REAR LH DOOR INNER TRIM BOARD <i>lit</i>	1	498.00	498.00 ✓
REAR LH DOOR LOWER WEATHER STRIP SEAL <i>new</i>	1	14.90	14.90 ✗
REAR LH DOOR MECHANISM LOCK <i>Dmgd</i>	1	295.80	295.80 ✓
REAR LH DOOR MECHANISM LOCK STRIKER <i>new</i>	1	27.50	27.50 ✗
REAR LH DOOR OUTER HANDLE <i>new</i>	1	98.00	98.00 ✗
REAR LH DOOR OUTER HANDLE INNER COVER <i>new</i>	1	28.00	28.00 ✗
REAR LH DOOR OUTER MOULDING <i>Deformed</i>	1	65.00	65.00 ✓
REAR LH DOOR PROTECTOR STICKER <i>new</i>	1	21.70	21.70 ✓
REAR LH DOOR RUBBER GUIDE STOPPER <i>new</i>	2	13.50	27.00 ✗
REAR LH DOOR STEP GARNISH <i>Deformed</i>	1	20.60	20.60 ✓
REAR LH DOOR SWITCH <i>new</i>	1	27.50	27.50 ✗
REAR LH DOOR WEATHER STRIP SEAL <i>with new</i>	1	18.50	18.50 ✗

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

REAR LH DOOR WINDOW CONTROL SWITCH	<i>2 N/P</i>	1	27.50	27.50	X
REAR LH DOOR WINDOW CONTROL SWITCH PANEL	<i>N/P</i>	1	34.30	34.30	X
REAR LH FENDER <i>Depis</i>	<i>18249</i>	1	884.40	884.40	X
REAR LH FENDER ARCH GARNISH <i>dehd</i>	<i>14599.20</i>	1	195.00	195.00	✓
REAR LH FENDER INNER SHIELD	<i>17476.60</i>	1	90.40	90.40	X
REAR LH PILLAR INNER TRIM GARNISH	<i>13881.28</i>	1	95.00	95.00	X
REAR LH PILLAR INNER TRIM GARNISH CLIPS - SET	<i>13881.28</i>	1	20.00	20.00	X
ROOF LINING <i>Crumpled</i>		1	1250.00	1,250.00	✓
Subtotal before discount				20,951.10	
Percentage discount 20%				4,190.22	
Sub-total 1				16,760.88	
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>Nec</i>		1	50.00	50.00	30
FRONT LH DOOR SPEAKER <i>Dehd</i>		1	180.00	180.00	50
FRONT LH DOOR STEP GARNISH CLIPS - SET <i>Nec</i>		1	20.00	20.00	10
FRONT LH PILLAR INNER GARNISH CLIPS - SET <i>Nec</i>		1	20.00	20.00	10
FRONT WINDSCREEN GLASS E.R.P BRACKET <i>Nec</i>		1	35.00	35.00	20
FRONT WINDSCREEN GLASS E.R.P BRACKET STICKER		1	15.00	15.00	5
FRONT WINDSCREEN GLASS SEALANT <i>Nec</i>		1	100.00	100.00	60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638
 Date in : 11/07/2018
 Vehicle Num. : SLR4263U
 Model : HONDA VEZEL HYBRID 1.5X AUTO
 Chassis/Eng# : RU31254307/LEB5954325

LH CENTER PILLAR GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 10
LH SIDE OUTER PANEL PLATE STICKER <i>new</i>	1	60.00	60.00 25
LH SIDE ROCKER PANEL GARNISH CLIPS - SET <i>new</i>	1	50.00	50.00 30
REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	50.00 30
REAR LH DOOR SPEAKER <i>new</i>	1	180.00	180.00 50
REAR LH DOOR STEP GARNISH CLIPS - SET <i>new</i>	1	20.00	20.00 10
REAR LH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 *
ROOF LINING CLIPS - SET <i>new</i>	1	50.00	50.00 ✓
Subtotal before discount			890.00
Percentage discount 0%			0.00
Sub-total 2			890.00
Parts-total			17,650.88

LABOUR

To remove, change air bag, air-bag sensor, air-bag wire and resetting system.
 To reset system after repair works
 To remove, change windscreen.
 To remove, reinstall window glass. (to FR)
 To remove, change window glass.
 To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~800.00~~ 380
~~400.00~~ 100
~~120.00~~ ✓
~~80.00~~ 40
~~80.00~~ 40
~~250.00~~ 180

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-18 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 98630879

ESTIMATE

Repair Code : CLM14638

Date in : 11/07/2018

Vehicle Num. : SLR4263U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254307/LEB5954325

To send vehicle for cleaning, shampoo, upholstery and cushion seat.	200.00	100
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	200.00	80
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,800.00	120
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,800.00	160
To apply anti-rust chemical on repaired and replaced panel.	120.00	80
Labour Total	6,850.00	
Parts & Labour Total	24,500.88	

*** This is a computer-generated document which requires no signature.***

page 7

total 18554.20

L/S 181K

09 Days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: