



Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: **SLR 4263 U**
Your ref: **FBL 3293 P**

16 July 2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER FOUR
SINGAPORE 038986
Attn: Motor Claims Department

BY EMAIL motorclaims.sg@fwd.com ONLY

Dear Sir/Madam,

NAME OF CLAIMANT : GRAB RENTALS PTE LTD
VEHICLE NUMBER : SLR 4263 U
YOUR INSURED VEHICLE NUMBER : FBL 3293 P
ACCIDENT ON 11 July 2018 ALONG PUNGGOL RD JUNC OF PUNGGOL FIELD
AT ABOUT 07:30 HOURS

We refer to your email dated 16 July 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **Lkk Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD
Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



N-51 AUTOMOTIVE PTE LTD

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: