

Please arrange to survey vehicle at  
8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT  
SINGAPORE 415875

**ABWIN** 諭輝

Date : 13/07/2018  
TP Vehicle No. : SLQ-1672-Y  
To : AIG ASIA PACIFIC INSURANCE PTE LTD  
Attn : Motor Claim Department

IVAN TEO  
ABWIN SERVICE PTE LTD  
DID: 67139416  
Fax: 67139415  
HP: 86680608

Owner : LIN YUHAO  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5099544318  
Vehicle No. : SKA-9107-G  
Make & Model : VOLKSWAGEN GOLF GTI 2.0 A

Accident Date: 13/07/2018

**ESTIMATED REPAIR COST DETAILS**

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	FRONT BUMPER <i>o/cn</i>	\$1,062.00	✓
1	FRONT BUMPER REINFORCEMENT <i>1</i>	\$439.20	X
1	FRONT BUMPER NUMBER PLATE GARNISH	\$118.50	✓
1	FRONT GRILLE ASSY	\$568.70	X
1	FRONT BUMPER SENSOR <i>1 3mm</i>	\$136.80	✓
10	FRONT BUMPER CLIPS <i>cn</i>	\$50.00	✓
Sub Total		\$2,375.20	
Discount 5% on Parts		(\$118.76)	
		\$2,256.44	

Special Nett

1	FRONT NUMBER PLATE <i>cn</i>	\$45.00	✓ <i>405.2</i>
Sub Total		\$45.00	

Labour & Misc

LABOUR TO FACILITATE REPAIR	\$800.00	<i>200</i>
TO SPRAY PAINTING AFFECTED AREA	\$800.00	<i>300</i>
Sub Total	\$1,600.00	

Sub Total \$3,901.44  
GST 7% \$273.10  
Total \$4,174.54

*Not Abul  
Lbr  
try 1/5  
take photo before party.  
2/7/18  
2/7/18*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1