

AXA / LKK 20/7

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883

Email: ryderautoworkshop@gmail.com

Fax: 64815390

LKK

ESTIMATE OF REPAIR

TPA X A.
Thin Thin.

(Without Prejudice)

Veh # : **SGK6873S**

Model : HONDA JAZZ

Date Of Accident: 14/7/2018

JHMGK58506X203117.

Location : CENTRAL BLVD TOWARDS CROSS STREET

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>List Items</u>				
1 pc	Front bumper <i>Rehd</i>			860.60	430
10 pcs	Front bumper clips <i>m</i>			38.00	-
1 pc	Front bumper enforcement <i>He m</i>			182.40	x
1 pc	Front bumper n/s bracket <i>He m</i>			28.20	+
1 pc	Front bumper n/s retainer <i>m</i>			20.80	-
1 pc	Front bumper n/s corner clips <i>He m</i>			26.50	x
1 pc	Front bumper n/s fog lamp <i>3 pc could</i>			428.20	196
1 pc	Front bumper n/s fog lamp garnish <i>3 pc could</i>			106.20	85
1 pc	Front bumper lower grille <i>m</i>			202.20	+
1 pc	Front grille <i>3 pc</i>			362.10	x
4 pcs	Front grille clips			15.20	+
1 pc	Front n/s head-lamp <i>3 pc</i>			1,226.80	950
2 pcs	Front n/s head-lamp clips <i>2 pc</i>			7.60	2
1 pc	Front n/s fender <i>Repair</i>			426.20	x
1 pc	Front n/s fender wheel guard <i>3 pc</i>			122.60	+
8 pcs	Front n/s fender wheel guard clips			30.40	+
1 pc	Front n/s suspension strut <i>3 pc</i>			281.20	x
1 pc	Front n/s suspension lower arm <i>3 pc</i>			210.20	x
1 pc	Front n/s knuckle			268.40	x
2 pcs	Front n/s wheel bearing			140.10	x
	Sub-Total			4,983.90	
	After -20%			3,987.12	

1707.4
1365.92

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Email: ryderautoworkshop@gmail.com
Fax: 64815390

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>Special Nett Items</u>				
1 pc	Front n/s wheel rim (Sports) <i>let 450</i>			780.00	<i>450</i>
1 pc	Front n/s tyre <i>He m</i>			280.00	<i>X</i>
	Sub-Total			1,060.00	
	<u>Labour</u>				
1	To straighten and welding.			1,200.00	<i>300</i>
2	To spray painting.	<i>810</i>		1,000.00	<i>400</i>
3	To remove and replace front n/s suspension.			380.00	<i>X</i>
4	To check wheel alignment.			120.00	<i>80</i>
5	To check wiring.			80.00	<i>30</i>
6	To re-seal anti-rust.			140.00	<i>X</i>
	Sub-Total			2,920.00	
	Total			7,967.12	
	After -20%			6,373.69	

Adrian Lij
L/S 20/07/18.

03 Days.
Total: 2625.92
L/S: 2.1K.

2.1K