

Jayce | 004/ABE 180 12958, K 120352

Surveyor:

Kenneth

DOI:

ASSIGNMENT

17/12/18

Date / Time:

16/07/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJX 8053A

Name of Insured:

Um PHANG JOO

Insured Tel No.:

HP:

97860535

Excess Sec II :SS

D.O.A.:

10/7/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

VCO11649

Policy No.:

8-V000 6680-MVA

Make / Model:

H. Avante

Place of Accident:

YCK Before Begonia Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SUH 5358B



INSRS:

WSP:

Tel:

Liability:

RMKS:

 Ah Lim,
 Amk


INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
20/7	SUH 5358B - X; SJX 8053A - X	Non-Reporting ltr (1st):	
20/7		Non-Reporting ltr (2nd):	
20/7		Non-Reporting ltr (Final):	
20/7		Notification ltr (if non-pickup):	
20/7		Call OI:	
20/7		After call ltr to OI:	
10/9/18	Confirm accident details inform TP claim letter to OI	Documentation Check List: Handler	Typist
18/12/18	File pass to typist type report	Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE	Date/Time: 19/7	Sent By: Jm
--------------------	-----------------	-------------

FINALIZATION	Date/Time: 13-03-19	Confirm with: Mui HONG	Confirm by: KSC
--------------	---------------------	------------------------	-----------------

Repair Cost:	R/S	SS 24,800	(28 days) Reduction: 58 %	Email ☒ Call ☐
--------------	-----	-----------	----------------------------	---

FINAL SETTLEMENT	Date/Time: 13-03-19	Confirm with: Mui HONG	Email ☒ Call ☐
------------------	---------------------	------------------------	---

Final Liability:	%	100	(Agreed / Assessed) BOLA S/N No.: 28	If NO or B 28, Ass. Lia: 700%
------------------	---	-----	--------------------------------------	-------------------------------

Repair Cost:	0/161:	SS 26,536.00		ORD involved in S.CC
--------------	--------	--------------	--	----------------------

Loss of Rental (LOR):	SS	4,200.00	(35 days) x 120	ORD is the customer
-----------------------	----	----------	------------------	---------------------

Loss of Use (LOU):	SS	-	(\$ x days)	
--------------------	----	---	--------------	--

Loss of Income (LOI):	SS	-	(\$ x days)	
-----------------------	----	---	--------------	--

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]				
--	--	--	--	--

GIA/LTA Search	SS	2.00		
Medical:	SS	48.60		
Disbursement:	SS	55.00	(e.g. Tow/ Independent)	
Legal Cost	SS	-		
Total:	SS	30,841.60	Global Sum SS:	
FINAL PAYMENT	Date/Time: 13-03-19	Confirm with: Mui HONG	Email ☒ Call ☐	
Payee 1:	SS	30,841.60	Name 1:	AM LIM MOTOR COMPANY
Payee 2: (Strike if N.A.)	SS		Name 2:	
Payee 3: (Strike if N.A.)	SS		Name 3:	

108/11/13 wef.

REF: QBE

ASS. REC. BY:

ASSIGNMENT

From: Date: 17/07/18

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SLH5358B

at Workshop m/s Ah Lim Motor

of No. 10 AMK Ind. park 2A #01-09

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$65k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 28 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{hup}

5'26

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLH5358B Yr Regn: 06, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/7 File pass to Coroner

R/s : \$24,800 (RED: \$33,776.36 58%)

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmo@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT BONNET	1 PC	693.40	—
2 FRONT BONNET HINGE	2 PC	134.40	—
3 FRONT BONNET INSULATOR	1 PC	356.20	12012
4 FRONT BONNET INSULATOR CLIPS	12 PC	38.52	X
5 FRONT BONNET RUBBER CTR	1 PC	45.90	X
6 FRONT BONNET INNER LOCK	1 PC	149.70	✓
7 FRONT BONNET INNER LOCK CABLE	1 PC	67.92	✓
8 FRONT BONNET STAND	1 PC	57.40	✓
9 FRONT BONNET STAND HOLDER	1 PC	18.75	—
10 FRONT BONNET STAND CLIPS (AT SUPPORT)	1 PC	17.92	✓
11 FRONT GRILLE WITH CHROME ASSY	1 PC	389.81	—
12 FRONT GRILLE EMBLEM CHROME	1 PC	85.90	—
13 FRONT GRILLE TOP RUBBER	1 PC	85.90	✓
14 FRONT GRILLE CLIPS	8 PC	25.68	✓
15 HEADLAMP (NOT HID)	2 PC	1,811.22	✓
16 HEADLAMP TOP RUBBER - CHECK PRICE	2 PC	0.00	X
17 HEADLAMP HIGH BEAM BULB	2 PC	123.40	✓
18 HEADLAMP SIGNAL BULB	2 PC	36.04	X
19 HEADLAMP LOWER BEAM - CHECK PRICE	2 PC	0.00	X
20 HEADLAMP CLIPS	4 PC	12.84	✓
21 FRONT BUMPER	1 PC	493.35	✓
22 FRONT BUMPER SIDE RETAINER	2 PC	162.50	✓
23 FRONT BUMPER CLIPS	12 PC	46.68	✓
24 FRONT BUMPER TOW COVER	2 PC	48.04	X
25 FRONT BUMPER LOWER GRILLE CTR	1 PC	107.20	X - photo
26 FRONT BUMPER TOP CTR BEAM	1 PC	149.80	✓
27 FRONT BUMPER REINFORCEMENT	1 PC	425.90	X - photo
28 FRONT BUMPER REINFORCEMENT BRACKET	1 PC	217.60	X
29 FRONT BUMPER SPONGE	1 PC	68.80	X - photo
30 FRONT BUMPER LOWER RUBBER CTR	1 PC	135.60	X
31 ENGINE UNDER COVER CTR	1 PC	225.90	X
32 ENGINE UNDER COVER CLIPS	10 PC	31.10	X
33 FOGLAMP	2 PC	472.80	X
34 FOGLAMP OUTER SIDE COVER	2 PC	249.40	X
35 FRONT FENDER	2 PC	1,164.80	X
36 FRONT FENDER COWLING	2 PC	423.34	✓
37 FRONT FENDER COWLING CLIPS	20 PC	42.20	✓
38 FRONT FENDER RIVET CLIPS - CHECK PRICE	10 PC	0.00	X



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:

Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		SS	SS
39-A/C-COMPRESSOR-ASSY	1 PC	2,512.60	X
40 AIR CON CONDENSER ASSY	1 PC	1,751.60	✓
41-AIR-CON-CONDENSER-PIPE-(COND-VALVE)	1 PC	711.64	X
42-AIR-CON-CONDENSER-PIPE-(COND-COMP)	1 PC	375.60	X
43-AIR-CON-CONDENSER-PIPE-(COMP-VALVE)	1 PC	566.40	X
44 AIR CON CONDENSER FAN BLADE	1 PC	156.30	7-photo ✓
45 AIR CON CONDENSER FAN MOTOR	1 PC	511.67	7-photo ✓
46 AIR CON CONDENSER FAN COWLING	1 PC	274.63	7-photo ✓
47 RADIATOR ASSY	1 PC	2,159.60	7-photo ✓
48 RADIATOR TOP CTR PLATE	1 PC	86.01	✓
49-RADIATOR-TOP-HOSE	1 PC	69.70	X
50-RADIATOR-BOTTOM-HOSE	1 PC	61.20	X
51 RADIATOR-TOP-BRACKET	2 PC	134.80	X
52 RADIATOR TOP BRACKET BUSH	2 PC	49.40	7-photo ✓
53 RADIATOR-LOWER-BUSH	2 PC	45.40	X
54 RADIATOR FAN MOTOR	1 PC	511.67	7-photo ✓
55 RADIATOR FAN BLADE	1 PC	126.70	7-photo ✓
56 RADIATOR-SPARE-TANK	1 PC	130.40	X
57 RADIATOR-SPARE-TANK-HOSE	2 PC	95.60	X
58-RADIATOR-SPARE-TANK-CTR-PIPE	1 PC	86.90	X
59 RADIATOR SUPPORT PANEL	1 PC	1,021.70	✓
60 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE	2 PC	88.54	✓
61 RADIATOR SUPPORT PANEL TOP GARNISH	1 PC	197.60	✓
62 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	12 PC	50.52	✓
63 HORN	2 PC	285.40	?
64 ALTERNATOR ASSY	1 PC	2,370.50	?
65 ALTERNATOR BELTING	1 PC	196.70	X
66 ALTERNATOR WIRE SOCKET-CHECK PRICE	1 PC	0.00	X
67-RESONATOR-TANK-LH	1 PC	109.55	X
68-RESONATOR-TANK-UPPER-HOSE-LH	1 PC	95.70	X
69-WIPER-WASHER-TANK-RH	1 PC	141.70	X
70-WIPER-WASHER-TANK-NECK-RH	1 PC	57.80	X
71-HEADLAMP-BULB-LOWER	2 PC	123.40	X
72-WIPER-WASHER TANK MOTOR	2 PC	393.92	X
73-BATTERY-TRAY	1 PC	87.90	X
74-BATTERY-TRAY-TOP-BRACKET	1 PC	47.90	X
75-AIR-CLEANER-BOX-COMplete	1 PC	919.60	X
76 AIR DUCT OUTER	1 PC	100.70	7-photo ✓
77 AIR DUCT OUTER CLIPS	2 PC	6.42	X





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimunc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:

Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		SS	SS
78--ENGINE ECU UNIT-LH	1-PC	2,768.70-X	
79--ENGINE MOUNTING-RH	1-PC	298.70-7	
80--ENGINE MOUNTING FRONT	1-PC	141.70-7	
81--ENGINE MOUNTING-REAR	1-PC	207.80-7	
82--GEARBOX MOUNTING-LH	1-PC	244.67-7	
83 REAR WINDSCREEN MOULDING	1 PC	137.30	
84 TAILGATE	1 PC	1,592.70	
85 TAILGATE HINGE	2-PC	137.40-7	
86 TAILGATE ABSORBER MOTOR - CHECK PRICE Assy	1 set 2PC	880.00-7-photo	
87 TAILGATE EMBLEM	1 PC	65.70	
88 TAILGATE LOGO (ESTIMA) LH	1 PC	56.95	
89 TAILGATE LOGO (X) RH	1 PC	41.75	
90 TAILGATE NO-PLATE CHROME MOULDING	1-PC	245.60-X	
91 TAILGATE NO-PLATE LAMP	2-PC	119.40-X	
92 TAILGATE INNER LOCK	1 PC	391.60	
93 TAILGATE INNER LOCK COVER - missing	1 PC	41.25-7-photo	
94 TAILGATE INNER LOCK CATCH	1 PC	39.67	
95 TAILGATE OUTER SWITCH OPENING - CHECK PRICE	1-PC	0.00-X	
96 TAILGATE OUTER SWITCH OPENING COVER - CHECK PRICE	1-PC	0.00-7	
97 TAILGATE CTR REFLECTOR WHITE	1-PC	345.20-X	
98 TAILGATE CTR REFLECTOR CLIPS	2-PC	15.60-X	
99 TAILGATE LAMP WHITE	2-PC	843.40-X	
100 TAILGATE LAMP CLIPS	6 PC	40.20-7-photo	
101 TAILGATE WIPER MOTOR	1 PC	720.85-X	
102 TAILGATE RUBBER (AT BODY)	1 PC	386.40 50%a	
103 TAILGATE SIDE STOPPER RUBBER ADJUSTER missing	2 PC	15.68-7-photo	
104 TAILGATE OUTER SIDE HOLDER COVER RH	1-PC	45.90-X	
105 TAILGATE INNER TRIMBOARD	1 PC	481.74	
106 TAILGATE INNER TRIMBOARD SIDE COVER LAMP LED - CHECK PRICE	2-PC	0.00-X	
107 TAILGATE INNER UPPER SIDE GARNISH	2-PC	309.40-X	
108 REAR BUMPER	1 PC	686.20	
109 REAR BUMPER SIDE RETAINERS	2 PC	119.20	
110 REAR BUMPER CTR RETAINERS	2 PC	123.40	
111 REAR BUMPER CLIPS	12 PC	46.68	
112 REAR BUMPER SPONGE LH	1 PC	75.30	
113 REAR BUMPER TOW COVER	2 PC	55.20	
114 REAR BUMPER SIDE REFLECTOR LAMP LED WHITE - CHECK PRICE	2 PC	200-120SN	
115 REAR END PANEL	1 PC	691.70	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party - 03E
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		SS	SS
116 REAR END PANEL TOP GARNISH	1 PC	0.5 298.90	—
117 REAR END PANEL TOP GARNISH CLIPS	12 PC	m 87.00	—
118 REAR END PANEL TOP GARNISH CTR COVER	1 PC	sn 41.70	X
119 REAR END PANEL INNER LOWER GARNISH	1 PC	Bu 201.70	—
120 SPARE TYRE PANEL	1 PC	Bu 380.90	—
121 SPARE TYRE PANEL LOWER SIDE RUBBER - missing mis 6ps 4PC	4 PC	123 247.00	7-photo ✓
122 SPARE TYRE PANEL LOWER SIDE BRACKET	2 PC	R 149.70	X
123 SPARE TYRE PANEL BRACKET	1 PC	R 100.70	X
124 SPARE TYRE PANEL CTR BRACKET	1 PC	R 244.89	X
125 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	sn 1,048.40	X
126 REAR CHASSIS SIDE PANEL LH & RH	2 PC	R 2,497.40	X
127 REAR CHASSIS SIDE PANEL PUTER LH & RH	2 PC	R 1,137.80	X
128 REAR CHASSIS FRAME LH & RH	2 PC	R 1,855.60	X
129 REAR FENDER OUTER LH & RH	2 PC	R 2,095.40	X
130 REAR FENDER LOWER AIR VENT	2 PC	sn 259.48	X
131 REAR FENDER INNER TRIMBOARD LH & RH	2 PC	Return 1,440.30	—
132 REAR FENDER INNER SIDE TOOL JACK COVER	1 PC	sn 206.70	X
133 REAR A/C BLOWER & COOLING COIL ASSY 1 hrs cm	1 PC	sn 2,111.70	X 2-photo
134 REAR FENDER GLASS WITH MOULDING LH & RH	2 PC	sn 1,392.60	X
135 REAR EXHAUST BOX	1 PC	R 1,202.70	X
136 REAR EXHAUST BOX TOP HEAT PLATE	1 PC	R 126.70	X
137 REAR EXHAUST BOX MOUNTING	4 PC	sn 309.96	X
138 REAR EXHAUST CTR PIPE	1 PC	R 1,916.74	X
139 REAR EXHAUST CTR PIPE MOUNTING	3 PC	sn 232.47	X
140 TAILAMP WHITE	2 PC	cm 799.40	7-photo ✓
141 TAILAMP CLIPS - CHECK PRICE	6 PC	33 0.00	7-photo ✓
142 TAILAMP PANEL	2 PC	R 505.40	X
143 FLOOR PANEL CARPET - CHECK PRICE	1 PC	sn 0.00	X
144 SPARE TYRE PANEL CARPET - CHECK PRICE	1 PC	sn 0.00	X
145 REAR THIRD SEATBELT - CHECK PRICE	2 PC	sn 0.00	X
		58,053.46	59,086.46
	Less 25%	14,513.37	43,540.10
Special Nett			44,314.84
146 TAILGATE REVERSE CAMERA - CHECK PRICE	1 PC	sn 0.00	X
147 NUMBER PLATE FRONT	1 PC	m 35.00	—
148 RADIATOR COOLANT	1 PC	sn 35.00	20sn
149 BATTERY ASSY	1 PC	sn 250.00	X
150 POWER EARTH MODULE - CHECK PRICE	1 PC	sn 0.00	X



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimunc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
151-POWER-EARTH-MODULE-WIRE-CHECK-PRICE	1 PC	SS 0.00	SS
152 FRONT GRILLE STICKER - CHECK PRICE	1 PC	na 0.00	✓
153 REAR WINDSCREEN SEALANT	1 PC	na 60.00	80.00
154 REAR WINDSCREEN INNER SEAL	1 PC	na 60.00	30.00
155-REAR-FENDER-GLASS-SEALANT	2 PC	na 80.00	X
156 REAR FENDER GLASS INNER SEAL	2 PC	na 80.00	X
157 NUMBER PLATE REAR	1 PC	na 35.00	✓
158-REAR-CAMERA-RECORDER-CHECK-PRICE	1 PC	na 0.00	X
159 TAILGATE LAMP STICKER - CHECK PRICE	2 PC	na 0.00	X
160 TAIL LAMP STICKER - CHECK PRICE	2 PC	na 0.00	X
161 TAILGATE CTR REFLECTOR LAMP STICKER - CHECK PRICE	1 PC	na 0.00	✓
162 TAILGATE TOP CTR PLATE WITH STICKER - CHECK PRICE	1 PC	na 0.00	X
163 REAR BUMPER REFLECTOR LAMP WHITE - CHECK PRICE	2 PC	na 0.00	X
164 TAILGATE INNER TRIMBOARD SIDE LAMP - CHECK PRICE	2 PC	na 0.00	X
165 REVERSE SENSOR	1 SET	na 200.00	✓
166 REVERSE SENSOR MODULE & WIRE HARNESS - CHECK PRICE	1 SET	na 0.00	X
		835.00	835.00

LABOUR

167 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
168 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	150.00
169 TO REMOVE & REPLACE ALTERNATOR BELTING A/C COMPRESSOR	1 PC	na 200.00	X
170 TO RESET ENGINE LIGHT, HEADLAMP ECU AIRBAG	1 PC	na 280.00	120.00
171 TO REMOVE & REINSTALL/REPLACE AIR CLEANER BOX, ENGINE ECU MODULE, POWER EARTH MODULE & WIRE	1 PC	na 200.00	X
172 TO REMOVE & REINSTALL/REPLACE ENGINE MOUNTING FRONT, REAR, GEARBOX MOUNTING	1 PC	na 180.00	X
173 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	180.00	60.00
174 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT BUMPER REINFORCEMENT TO KNOCK & REPAIR FRONT DOOR LH, & RH, FRONT WHEELHOUSE, FRONT CHASSIS FRAME INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,400.00	700.00
175 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT DOOR LH & RH, RADIATOR SUPPORT PANEL, FRONT WHEELHOUSE, FRONT CHASSIS FRAME.	1 PC	1,200.00	1000.00
176 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
177 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	120.00	100
178 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	X-photo
179 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	150.00	120
180 TO REMOVE & REINSTALL/REPLACE TAILGATE MOTOR	1 PC	150.00	60
181 TO REMOVE & REINSTALL/REPLACE REAR A/C BLOWER & COOLING COIL ASSY	1 PC	250.00	700 photo
182 TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS WITH MOULDING LH & RH	1 PC	240.00	X
183 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	380.00	150
184 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE	1 PC	380.00	X
185 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	180.00	60
186 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	100.00	60
187 TO DISMANTLE & INSTALL/REPLACE REAR THIRD SEATBELT	1 PC	200.00	7-photo
188 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	✓
189 TO RESET TAILGATE MOTOR, SRS LIGHT, ENGINE LIGHT	1 PC	380.00	7-photo X
190 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	280.00	120
191 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	180.00	80
192 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD TAILLAMP PANEL, END PANEL, SPARE TYRE PANEL, RR FENDER, RR CHASSIS FRAME & SIDE PANEL & OUTER PANEL TO KNOCK & REPAIR FLOOR PANEL, REAR WHEELHOUSE, RR FENDER INNER TO REFIT LISTED PARTS BACK SAME.	1 PC	3,000.00	2200
193 TO SPRAY TAILGATE, RR BUMPER, END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL, RR FENDER, RR FENDER INNER, RR CHASSIS FRAME, RR CHASSIS SIDE PANEL OUTER, RR CHASSIS SIDE PANEL, FLOOR PANEL, RR WHEELHOUSE	1 PC	2,300.00	1600



12,320.00 12,320.00

57539.84

58576.36



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 02 Aug 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party - GBE ins
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Survey copy

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price S\$	Amount S\$
-------------	----------	-------------------	---------------

Supplementary Parts to Repair

SPARE PARTS

P11 2 -1	HEADLAMP SMALL BULB SOCKET	2 PC	CM	51.48	✓
P12-36 1-1-2	HEADLAMP SIGNAL LAMP SOCKET LH & RH	2 PC	CM	77.40	✓
P30 2-3	END PANEL SIDE OUTER LH	1 PC	R	165.67	✓
	END PANEL SIDE OUTER RH	1 PC	R	165.67	✓
P31 1-5	REAR A/C BROWER LIQUIDE PIPE NO1	1 PC	R	201.30	✓
P32 1-6	REAR A/C BROWER SUCTION PIPE NO2	1 PC	R	274.80	✓
P32 4-7	TAILGATE TOP SPOILER CLIP BIG	5 PC	M	27.50	✓
P32-52 1-1-8	REAR FENDER COWLING LH & RH	2 PC	M	241.50	✓
P36 2-9	HEADLAMP COVER CIRCLE	2 PC	M/I	77.40	✓
P39 1-10	REAR FENDER INNER TRIMBOARD SIDE CLIPS missing	6 PC	M	24.00	✓
				1,306.72	
	Less 25%			326.68	980.04

Total S\$ 980.04
GST Amount S\$ 68.60

Total Amount Payable S\$ 1,048.64

10.30 AM 3/8/18 Res

Kenneth

For AH LIM MOTOR COMPANY

for repair before paint

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 08 Sep 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price S\$	Amount S\$
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR BUMPER SPONGE RH	1 PC	75.30	
		75.30	
	Less 25%	18.83	56.48
	Total		S\$ 56.48
	GST Amount		S\$ 3.95
	Total Amount Payable		S\$ 60.43

The above vehicle was surveyed by KENNETH KONG -LKK on 18/07/2018

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

A 4132
A4164

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Claim No: MC0913266
No: MF0911290
Date: 07 Sep 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

NOIIVSITVNI

Repair Cost to Vehicle No (For Finalization):SLH5358B

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT BONNET	1 PC	693.40	
2 FRONT BONNET HINGE	2 PC	134.40	
3 FRONT BONNET INNER LOCK	1 PC	149.70	
4 FRONT BONNET INNER LOCK CABLE	1 PC	67.92	
5 FRONT BONNET STAND	1 PC	57.40	
6 FRONT BONNET STAND HOLDER	1 PC	18.75	
7 FRONT BONNET STAND CLIPS (AT SUPPORT)	1 PC	17.92	
8 FRONT GRILLE WITH CHROME ASSY	1 PC	389.81	
9 FRONT GRILLE EMBLEM CHROME	1 PC	85.90	
10 FRONT GRILLE TOP RUBBER	1 PC	85.90	
11 FRONT GRILLE CLIPS	8 PC	25.68	
12 HEADLAMP (NOT HID)	2 PC	1,811.22	
13 HEADLAMP HIGH BEAM BULB	2 PC	123.40	
14 HEADLAMP CLIPS	4 PC	12.84	
15 FRONT BUMPER	1 PC	493.35	
16 FRONT BUMPER SIDE RETAINER	2 PC	162.50	
17 FRONT BUMPER CLIPS	12 PC	46.68	
18 FRONT BUMPER LOWER GRILLE CTR	1 PC	107.20	
19 FRONT BUMPER TOP CTR BEAM	1 PC	149.80	
20 FRONT BUMPER REINFORCEMENT	1 PC	425.90	
21 FRONT BUMPER SPONGE	1 PC	68.80	
22 FRONT FENDER COWLING	2 PC	423.34	
23 FRONT FENDER COWLING CLIPS	20 PC	42.20	
24 AIR CON CONDENSER ASSY	1 PC	1,751.60	
25 AIR CON CONDENSER FAN BLADE	1 PC	156.30	
26 AIR CON CONDENSER FAN MOTOR	1 PC	511.67	
27 AIR CON CONDENSER FAN COWLING	1 PC	274.63	
28 RADIATOR ASSY	1 PC	2,159.60	
29 RADIATOR TOP CTR PLATE	1 PC	86.01	
30 RADIATOR TOP BRACKET BUSH	2 PC	49.40	
31 RADIATOR FAN MOTOR	1 PC	511.67	
32 RADIATOR FAN BLADE	1 PC	126.70	
33 RADIATOR SUPPORT PANEL	1 PC	1,021.70	
34 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE	2 PC	88.54	
35 RADIATOR SUPPORT PANEL TOP GARNISH	1 PC	197.60	
36 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	12 PC	50.52	
37 AIR DUCT OUTER	1 PC	100.70	
38 REAR WINDSCREEN MOULDING	1 PC	137.30	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint, Singapore
Tel: 6483 1244



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Claim No: MC0913266
No: MF0911290
Date: 07 Sep 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

FINALISATION

Repair Cost to Vehicle No (For Finalization):SLH5358B

Description	Quantity	List Price	Amount
		SS	SS
39 TAILGATE	1 PC	1,592.70	
40 TAILGATE EMBLEM	1 PC	65.70	
41 TAILGATE LOGO (ESTIMA) LH	1 PC	56.95	
42 TAILGATE LOGO (X) RH	1 PC	41.75	
43 TAILGATE INNER LOCK	1 PC	391.60	
44 TAILGATE INNER LOCK COVER	1 PC	41.25	
45 TAILGATE INNER LOCK CATCH	1 PC	39.67	
46 TAILGATE LAMP CLIPS	6 PC	40.20	
47 TAILGATE SIDE STOPPER RUBBER ADJUSTER	2 PC	15.68	
48 TAILGATE INNER TRIMBOARD	1 PC	481.74	
49 REAR BUMPER	1 PC	686.20	
50 REAR BUMPER SIDE RETAINERS	2 PC	119.20	
51 REAR BUMPER CTR RETAINERS	2 PC	123.40	
52 REAR BUMPER CLIPS	12 PC	46.68	
53 REAR BUMPER SPONGE LH	1 PC	75.30	
54 REAR BUMPER TOW COVER	2 PC	55.20	
55 REAR END PANEL	1 PC	691.70	
56 REAR END PANEL TOP GARNISH	1 PC	298.90	
57 REAR END PANEL TOP GARNISH CLIPS	12 PC	87.00	
58 REAR END PANEL INNER LOWER GARNISH	1 PC	201.70	
59 SPARE TYRE PANEL	1 PC	380.90	
60 SPARE TYRE PANEL LOWER SIDE RUBBER	6 PC	123.00	
61 REAR FENDER INNER TRIMBOARD LH & RH	2 PC	1,440.30	
62 REAR A/C BLOWER & COOLING COIL ASSY	1 PC	2,111.70	
63 TAILAMP WHITE	2 PC	799.40	
64 TAILAMP CLIPS	6 PC	33.00	
65 HEADLAMP SMALL BULB SOCKET	2 PC	51.48	✓
66 HEADLAMP SIGNAL LAMP SOCKET LH & RH	2 PC	77.40	✓
67 END PANEL SIDE OUTER LH	1 PC	165.67	✓
68 END PANEL SIDE OUTER RH	1 PC	165.67	✓
69 REAR A/C BLOWER LIQUIDE PIPE NO1	1 PC	201.30	✓
70 REAR A/C BLOWER SUCTION PIPE NO2	1 PC	274.80	✓
71 TAILGATE TOP SPOILER CLIP BIG	5 PC	27.50	✓
72 REAR FENDER COWLING LH & RH	2 PC	241.50	✓
73 HEADLAMP COVER CIRCLE	2 PC	77.40	✓
74 REAR FENDER INNER TRIMBOARD SIDE CLIPS	6 PC	24.00	✓
75 REAR BUMPER SPONGE RH	1 PC	75.30	✓

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : LOY LE HUI (LIU LEHUI)
 BLK 430C FERNVALE LINK
 #17-233
 SINGAPORE 793430

Claim No: MC0913266
 No: MF0911290
 Date: 07 Sep 2018
 Policy No: D17MTPV01016659
 Veh Reg No: SLH5358B
 Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
 Your Ref No: SLH5358B
 Claim Type: Third Party
 Accident Date: 10/07/2018
 TP Veh Reg No: SJX8053A

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLH5358B

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
		24,240.79	
	Less 25%	6,060.20	18,180.59
Special Nett			
76 REVERSE SENSOR	1 SET	200.00	
77 FRONT BONNET INSULATOR	1 PC	120.00	
78 TAILGATE ABSORBER MOTOR	1 PC	880.00	
79 TAILGATE RUBBER (AT BODY) 50%	1 PC	193.20	
80 REAR BUMPER SIDE REFLECTOR LAMP LED WHITE	1 PC	120.00	
81 NUMBER PLATE FRONT	1 PC	35.00	
82 RADIATOR COOLANT	1 PC	20.00	
83 FRONT GRILLE STICKER	1 PC	50.00	
84 REAR WINDSCREEN SEALANT	1 PC	40.00	
85 REAR WINDSCREEN INNER SEAL	1 PC	30.00	
86 NUMBER PLATE REAR	1 PC	35.00	
87 TAILGATE CTR REFLECTOR LAMP STICKER - CHECK PRICE	1 PC	20.00	
		1,743.20	1,743.59
LABOUR			
88 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
89 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
90 TO RESET ENGINE LIGHT, HEADLAMP ECU AIRBAG	1 PC	120.00	
91 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
92 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT BUMPER REINFORCEMENT, TO KNOCK & REPAIR FRONT DOOR LH, & RH, FRONT WHEELHOUSE, FRONT CHASSIS FRAME INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	
93 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT DOOR LH & RH, RADIATOR SUPPORT PANEL, FRONT WHEELHOUSE, FRONT CHASSIS FRAME.	1 PC	1,000.00	
94 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
95 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
96 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
97 TO REMOVE & REINSTALL/REPLACE TAILGATE	1 PC	60.00	

AM LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINAL 3.10.18

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Claim No: MC0913266
No: MF0911290
Date: 07 Sep 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Repair Cost to Vehicle No (For Finalization):SLH5358B

Description	Quantity	List Price	Amount
		SS	SS
98 TO REMOVE & REINSTALL/REPLACE REAR A/C BLOWER & COOLING COIL ASSY	1 PC	100.00	
99 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	150.00	
100 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	60.00	
101 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	
102 TO DISMANTLE & INSTALL/REPLACE REAR THIRD SEATBELT	1 PC	80.00	
103 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	
104 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	120.00	
105 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	
106 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD TAILAMP PANEL,END PANEL,SPARE TYRE PANEL,RR FENDER,RR CHASSIS FRAME & SIDE PANEL & OUTER PANEL.TO KNOCK & REPAIR FLOOR PANEL,REAR WHEELHOUSE,RR FENDER INNER.TO REFIT LISTED PARTS BACK SAME.	1 PC	2,200.00	
107 TO SPRAY TAILGATE,RR BUMPER,END PANEL,SPARE TYRE PANEL,TAILAMP PANEL,RR FENDER,RR FENDER INNER,RR CHASSIS FRAME,RR CHASSIS SIDE PANEL OUTER,RR CHASSIS SIDE PANEL,FLOOR PANEL,RR WHEELHOUSE	1 PC	1,600.00	
		6,830.00	6,830.00
		Total	SS 26,753.79
		Less Excess	SS 0.00
		Amount Before GST	SS 26,753.79
		Add GST @ 7%	1,872.77
		Total Amount Payable	SS 28,626.56

24,800

TOTAL: SINGAPORE DOLLAR TWENTY EIGHT THOUSAND SIX HUNDRED TWENTY SIX AND CENTS FIFTY SIX ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 18/07/2018

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Not Notched
11 Lugs B?
Missing After Paint

28 days

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT BONNET	1 PC	693.40	—
2 FRONT BONNET HINGE	2 PC	134.40	—
3 FRONT BONNET INSULATOR	1 PC	356.20	12012
4 FRONT BONNET INSULATOR CLIPS	12 PC	38.52	X
5 FRONT BONNET RUBBER CTR	1 PC	45.90	X
6 FRONT BONNET INNER LOCK	1 PC	149.70	—
7 FRONT BONNET INNER LOCK CABLE	1 PC	67.92	—
8 FRONT BONNET STAND	1 PC	57.40	—
9 FRONT BONNET STAND HOLDER	1 PC	18.75	—
10 FRONT BONNET STAND CLIPS (AT SUPPORT)	1 PC	17.92	—
11 FRONT GRILLE WITH CHROME ASSY	1 PC	389.81	—
12 FRONT GRILLE EMBLEM CHROME	1 PC	85.90	—
13 FRONT GRILLE TOP RUBBER	1 PC	85.90	—
14 FRONT GRILLE CLIPS	8 PC	25.68	—
15 HEADLAMP (NOT HID)	2 PC	1,811.22	—
16 HEADLAMP TOP RUBBER - CHECK PRICE	2 PC	0.00	—
17 HEADLAMP HIGH BEAM BULB	2 PC	123.40	—
18 HEADLAMP SIGNAL BULB	2 PC	36.04	—
19 HEADLAMP LOWER BEAM - CHECK PRICE	2 PC	0.00	—
20 HEADLAMP CLIPS	4 PC	12.84	—
21 FRONT BUMPER	1 PC	493.35	—
22 FRONT BUMPER SIDE RETAINER	2 PC	162.50	—
23 FRONT BUMPER CLIPS	12 PC	46.68	—
24 FRONT BUMPER TOW COVER	2 PC	48.04	X
25 FRONT BUMPER LOWER GRILLE CTR	1 PC	107.20	X
26 FRONT BUMPER TOP CTR BEAM	1 PC	149.80	—
27 FRONT BUMPER REINFORCEMENT	1 PC	425.90	—
28 FRONT BUMPER REINFORCEMENT BRACKET	1 PC	217.60	—
29 FRONT BUMPER SPONGE	1 PC	68.80	—
30 FRONT BUMPER LOWER RUBBER CTR	1 PC	135.60	X
31 ENGINE UNDER COVER CTR	1 PC	225.90	X
32 ENGINE UNDER COVER CLIPS	10 PC	31.10	X
33 FOGLAMP	2 PC	472.80	X
34 FOGLAMP OUTER SIDE COVER	2 PC	249.40	X
35 FRONT FENDER	2 PC	1,164.80	X
36 FRONT FENDER COWLING	2 PC	423.34	—
37 FRONT FENDER COWLING CLIPS	20 PC	42.20	—
38 FRONT FENDER RIVET CLIPS - CHECK PRICE	10 PC	0.00	—





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO.06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		SS	SS
39 A/C COMPRESSOR ASSY	1 PC	2,512.60 ?	
40 AIR CON CONDENSER ASSY	1 PC	1,751.60 ✓	
41 AIR CON CONDENSER PIPE (COND-VALVE)	1 PC	711.64 ?	
42 AIR CON CONDENSER PIPE (COND-COMP)	1 PC	375.60 ?	
43 AIR CON CONDENSER PIPE (COMP-VALVE)	1 PC	566.40 ?	
44 AIR CON CONDENSER FAN BLADE	1 PC	156.30 ?	
45 AIR CON CONDENSER FAN MOTOR	1 PC	511.67 ?	
46 AIR CON CONDENSER FAN COWLING	1 PC	274.63 ?	
47 RADIATOR ASSY	1 PC	2,159.60 ?	
48 RADIATOR TOP CTR PLATE	1 PC	86.01 ✓	
49 RADIATOR TOP HOSE	1 PC	69.70 ?	
50 RADIATOR BOTTOM HOSE	1 PC	61.20 ?	
51 RADIATOR TOP BRACKET	2 PC	134.80 ?	
52 RADIATOR TOP BRACKET BUSH	2 PC	49.40 ?	
53 RADIATOR LOWER BUSH	2 PC	45.40 ?	
54 RADIATOR FAN MOTOR	1 PC	511.67 ?	
55 RADIATOR FAN BLADE	1 PC	126.70 ?	
56 RADIATOR SPARE TANK	1 PC	430.40 ?	
57 RADIATOR SPARE TANK HOSE	2 PC	95.60 ?	
58 RADIATOR SPARE TANK CTR PIPE	1 PC	86.90 ?	
59 RADIATOR SUPPORT PANEL	1 PC	1,021.70 ✓	
60 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE	2 PC	88.54 ✓	
61 RADIATOR SUPPORT PANEL TOP GARNISH	1 PC	197.60 ✓	
62 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	12 PC	50.52 ✓	
63 HORN	2 PC	285.40 ?	
64 ALTERNATOR ASSY	1 PC	2,370.50 ?	
65 ALTERNATOR BELTING	1 PC	196.70 ?	
66 ALTERNATOR WIRE SOCKET - CHECK PRICE	1 PC	0.00 ?	
67 RESONATOR TANK LH	1 PC	109.55 ?	
68 RESONATOR TANK UPPER HOSE LH	1 PC	95.70 ?	
69 WIPER WASHER TANK RH	1 PC	141.70 ?	
70 WIPER WASHER TANK NECK RH	1 PC	57.80 X	
71 HEADLAMP BULB LOWER	2 PC	123.40 ?	
72 WIPER WASHER TANK MOTOR	2 PC	393.92 X	
73 BATTERY TRAY	1 PC	87.90 X	
74 BATTERY TRAY TOP BRACKET	1 PC	47.90 X	
75 AIR CLEANER BOX COMPLETE	1 PC	919.60 ?	
76 AIR DUCT OUTER	1 PC	100.70 ?	
77 AIR DUCT OUTER CLIPS	2 PC	6.42 ?	





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO-06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
 BLK 430C FERNVALE LINK
 #17-233
 SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
78 ENGINE ECU UNIT LH	1 PC	2,768.70 X	
79 ENGINE MOUNTING RH	1 PC	298.70 ?	
80 ENGINE MOUNTING FRONT	1 PC	141.70 ?	
81 ENGINE MOUNTING REAR	1 PC	207.80 ?	
82 GEARBOX MOUNTING LH	1 PC	244.67 ?	
83 REAR WINDSCREEN MOULDING	1 PC	137.30 ✓	
84 TAILGATE	1 PC	1,592.70 ✓	
85 TAILGATE HINGE	2 PC	137.40 ?	
86 TAILGATE ABSORBER MOTOR - CHECK PRICE	2 PC	0.00 ?	
87 TAILGATE EMBLEM	1 PC	65.70 ✓	
88 TAILGATE LOGO (ESTIMA) LH	1 PC	56.95 ✓	
89 TAILGATE LOGO (X) RH	1 PC	41.75 ✓	
90 TAILGATE NO PLATE CHROME MOULDING	1 PC	245.60 ?	
91 TAILGATE NO PLATE LAMP	2 PC	119.40 X	
92 TAILGATE INNER LOCK	1 PC	391.60 ✓	
93 TAILGATE INNER LOCK COVER	1 PC	41.25 ?	
94 TAILGATE INNER LOCK CATCH	1 PC	39.67 ✓	
95 TAILGATE OUTER SWITCH OPENING - CHECK PRICE	1 PC	0.00 ?	
96 TAILGATE OUTER SWITCH OPENING COVER - CHECK PRICE	1 PC	0.00 ?	
97 TAILGATE CTR REFLECTOR WHITE	1 PC	345.20 ?	
98 TAILGATE CTR REFLECTOR CLIPS	2 PC	15.60 ?	
99 TAILGATE LAMP WHITE	2 PC	843.40 ?	
100 TAILGATE LAMP CLIPS	6 PC	40.20 ?	
101 TAILGATE WIPER MOTOR	1 PC	720.85 ?	
102 TAILGATE RUBBER (AT BODY)	1 PC	386.40 508.20	
103 TAILGATE SIDE STOPPER RUBBER ADJUSTER	2 PC	15.68 ?	
104 TAILGATE OUTER SIDE HOLDER COVER RH	1 PC	45.90 ?	
105 TAILGATE INNER TRIMBOARD	1 PC	481.74 ✓	
106 TAILGATE INNER TRIMBOARD SIDE COVER LAMP LED - CHECK PRICE	2 PC	0.00 ?	
107 TAILGATE INNER UPPER SIDE GARNISH	2 PC	309.40 ?	
108 REAR BUMPER	1 PC	686.20 ✓	
109 REAR BUMPER SIDE RETAINERS	2 PC	119.20 ✓	
110 REAR BUMPER CTR RETAINERS	2 PC	123.40 ✓	
111 REAR BUMPER CLIPS	12 PC	46.68 ✓	
112 REAR BUMPER SPONGE	1 PC	75.30 ✓	
113 REAR BUMPER TOW COVER	2 PC	55.20 ✓	
114 REAR BUMPER SIDE REFLECTOR LAMP LED WHITE - CHECK PRICE	2 PC	0.00 ✓	
115 REAR END PANEL	1 PC	691.70 ✓	





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
 BLK 430C FERNVALE LINK
 #17-233
 SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
116 REAR END PANEL TOP GARNISH	1 PC	<i>Dit</i> 298.90	—
117 REAR END PANEL TOP GARNISH CLIPS	12 PC	<i>ma</i> 87.00	—
118 REAR END PANEL TOP GARNISH CTR COVER	1 PC	41.70	?
119 REAR END PANEL INNER LOWER GARNISH	1 PC	<i>Bu</i> 201.70	—
120 SPARE TYRE PANEL	1 PC	<i>Bu</i> 380.90	—
121 SPARE TYRE PANEL LOWER SIDE RUBBER	4 PC	247.00	?
122 SPARE TYRE PANEL LOWER SIDE BRACKET	2 PC	149.70	?
123 SPARE TYRE PANEL BRACKET	1 PC	100.70	?
124 SPARE TYRE PANEL CTR BRACKET	1 PC	244.89	?
125 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	1,048.40	?
126 REAR CHASSIS SIDE PANEL LH & RH	2 PC	<i>R</i> 2,497.40	?
127 REAR CHASSIS SIDE PANEL PUTER LH & RH	2 PC	1,137.80	?
128 REAR CHASSIS FRAME LH & RH	2 PC	1,855.60	?
129 REAR FENDER OUTER LH & RH	2 PC	2,095.40	?
130 REAR FENDER LOWER AIR VENT	2 PC	259.48	?
131 REAR FENDER INNER TRIMBOARD LH & RH	2 PC	<i>Return</i> 1,440.30	—
132 REAR FENDER INNER SIDE TOOL JACK COVER	1 PC	206.70	?
133 REAR A/C BLOWER & COOLING COIL ASSY	1 PC	<i>SL</i> 2,111.70	X ?
134 REAR FENDER GLASS WITH MOULDING LH & RH	2 PC	<i>SL</i> 1,392.60	X
135 REAR EXHAUST BOX	1 PC	1,202.70	?
136 REAR EXHAUST BOX TOP HEAT PLATE	1 PC	126.70	?
137 REAR EXHAUST BOX MOUNTING	4 PC	309.96	?
138 REAR EXHAUST CTR PIPE	1 PC	1,916.74	?
139 REAR EXHAUST CTR PIPE MOUNTING	3 PC	232.47	?
140 TAILAMP WHITE	2 PC	799.40	?
141 TAILAMP CLIPS - CHECK PRICE	6 PC	0.00	?
142 TAILAMP PANEL	2 PC	505.40	?
143 FLOOR PANEL CARPET - CHECK PRICE	1 PC	0.00	?
144 SPARE TYRE PANEL CARPET - CHECK PRICE	1 PC	0.00	?
145 REAR THIRD SEATBELT - CHECK PRICE	2 PC	0.00	?
		58,053.46	
	Less 25%	14,513.37	43,540.10



Special Nett

146 TAILGATE REVERSE CAMERA - CHECK PRICE	1 PC	0.00	?
147 NUMBER PLATE FRONT	1 PC	<i>mi's</i> 35.00	—
148 RADIATOR COOLANT	1 PC	<i>ma</i> 35.00	205.00
149 BATTERY ASSY	1 PC	250.00	?
150 POWER EARTH MODULE - CHECK PRICE	1 PC	0.00	?