



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:

Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

*Not Authorised
Lily B?
Mercury After Paint*

28 days

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 FRONT BONNET	1 PC	693.40	—
2 FRONT BONNET HINGE	2 PC	134.40	—
3 FRONT BONNET INSULATOR	1 PC	356.20	1201A
4 FRONT BONNET INSULATOR CLIPS	12 PC	38.52	X
5 FRONT BONNET RUBBER CTR	1 PC	45.90	X
6 FRONT BONNET INNER LOCK	1 PC	149.70	✓
7 FRONT BONNET INNER LOCK CABLE	1 PC	67.92	✓
8 FRONT BONNET STAND	1 PC	57.40	✓
9 FRONT BONNET STAND HOLDER	1 PC	18.75	—
10 FRONT BONNET STAND CLIPS (AT SUPPORT)	1 PC	17.92	—
11 FRONT GRILLE WITH CHROME ASSY	1 PC	389.81	—
12 FRONT GRILLE EMBLEM CHROME	1 PC	85.90	—
13 FRONT GRILLE TOP RUBBER	1 PC	85.90	—
14 FRONT GRILLE CLIPS	8 PC	25.68	—
15 HEADLAMP (NOT HID)	2 PC	1,811.22	my CM
16 HEADLAMP TOP RUBBER - CHECK PRICE	2 PC	0.00	— ?
17 HEADLAMP HIGH BEAM BULB	2 PC	123.40	—
18 HEADLAMP SIGNAL BULB	2 PC	36.04	?
19 HEADLAMP LOWER BEAM - CHECK PRICE	2 PC	0.00	?
20 HEADLAMP CLIPS	4 PC	12.84	—
21 FRONT BUMPER	1 PC	493.35	—
22 FRONT BUMPER SIDE RETAINER	2 PC	162.50	—
23 FRONT BUMPER CLIPS	12 PC	46.68	—
24 FRONT BUMPER TOW COVER	2 PC	48.04	X
25 FRONT BUMPER LOWER GRILLE CTR	1 PC	107.20	X
26 FRONT BUMPER TOP CTR BEAM	1 PC	149.80	✓
27 FRONT BUMPER REINFORCEMENT	1 PC	425.90	?
28 FRONT BUMPER REINFORCEMENT BRACKET	1 PC	217.60	?
29 FRONT BUMPER SPONGE	1 PC	68.80	?
30 FRONT BUMPER LOWER RUBBER CTR	1 PC	135.60	X
31 ENGINE UNDER COVER CTR	1 PC	225.90	X
32 ENGINE UNDER COVER CLIPS	10 PC	31.10	X
33 FOGLAMP	2 PC	472.80	X
34 FOGLAMP OUTER SIDE COVER	2 PC	249.40	X
35 FRONT FENDER	2 PC	1,164.80	X
36 FRONT FENDER COWLING	2 PC	423.34	✓
37 FRONT FENDER COWLING CLIPS	20 PC	42.20	—
38 FRONT FENDER RIVET CLIPS - CHECK PRICE	10 PC	0.00	?





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
39 A/C COMPRESSOR ASSY	1 PC	2,512.60	?
40 AIR CON CONDENSER ASSY	1 PC	<i>Pr</i> 1,751.60	✓
41 AIR CON CONDENSER PIPE (COND-VALVE)	1 PC	711.64	?
42 AIR CON CONDENSER PIPE (COND-COMP)	1 PC	375.60	?
43 AIR CON CONDENSER PIPE (COMP-VALVE)	1 PC	566.40	?
44 AIR CON CONDENSER FAN BLADE	1 PC	156.30	?
45 AIR CON CONDENSER FAN MOTOR	1 PC	511.67	?
46 AIR CON CONDENSER FAN COWLING	1 PC	274.63	?
47 RADIATOR ASSY	1 PC	2,159.60	?
48 RADIATOR TOP CTR PLATE	1 PC	<i>CM</i> 86.01	✓
49 RADIATOR TOP HOSE	1 PC	69.70	?
50 RADIATOR BOTTOM HOSE	1 PC	61.20	?
51 RADIATOR TOP BRACKET	2 PC	134.80	?
52 RADIATOR TOP BRACKET BUSH	2 PC	49.40	?
53 RADIATOR LOWER BUSH	2 PC	45.40	?
54 RADIATOR FAN MOTOR	1 PC	511.67	?
55 RADIATOR FAN BLADE	1 PC	126.70	?
56 RADIATOR SPARE TANK	1 PC	430.40	?
57 RADIATOR SPARE TANK HOSE	2 PC	95.60	?
58 RADIATOR SPARE TANK CTR PIPE	1 PC	86.90	?
59 RADIATOR SUPPORT PANEL	1 PC	<i>Pr</i> 1,021.70	✓
60 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE	2 PC	<i>CM</i> 88.54	✓
61 RADIATOR SUPPORT PANEL TOP GARNISH	1 PC	<i>CM</i> 197.60	✓
62 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	12 PC	<i>Pr</i> 50.52	✓
63 HORN	2 PC	285.40	?
64 ALTERNATOR ASSY	1 PC	2,370.50	?
65 ALTERNATOR BELTING	1 PC	196.70	?
66 ALTERNATOR WIRE SOCKET - CHECK PRICE	1 PC	0.00	?
67 RESONATOR TANK LH	1 PC	109.55	?
68 RESONATOR TANK UPPER HOSE LH	1 PC	95.70	?
69 WIPER WASHER TANK RH	1 PC	141.70	?
70 WIPER WASHER TANK NECK RH	1 PC	<i>Pr</i> 57.80	X
71 HEADLAMP BULB LOWER	2 PC	<i>Pr</i> 123.40	?
72 WIPER WASHER TANK MOTOR	2 PC	<i>Pr</i> 393.92	X
73 BATTERY TRAY	1 PC	<i>Pr</i> 87.90	X
74 BATTERY TRAY TOP BRACKET	1 PC	<i>Pr</i> 47.90	X
75 AIR CLEANER BOX COMPLETE	1 PC	919.60	?
76 AIR DUCT OUTER	1 PC	100.70	?
77 AIR DUCT OUTER CLIPS	2 PC	6.42	?





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:

Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
78 ENGINE ECU UNIT LH	1 PC	2,768.70	X
79 ENGINE MOUNTING RH	1 PC	298.70	?
80 ENGINE MOUNTING FRONT	1 PC	141.70	?
81 ENGINE MOUNTING REAR	1 PC	207.80	?
82 GEARBOX MOUNTING LH	1 PC	244.67	?
83 REAR WINDSCREEN MOULDING	1 PC	137.30	✓
84 TAILGATE	1 PC	1,592.70	✓
85 TAILGATE HINGE	2 PC	137.40	?
86 TAILGATE ABSORBER MOTOR - CHECK PRICE	2 PC	0.00	?
87 TAILGATE EMBLEM	1 PC	65.70	✓
88 TAILGATE LOGO (ESTIMA) LH	1 PC	56.95	✓
89 TAILGATE LOGO (X) RH	1 PC	41.75	✓
90 TAILGATE NO PLATE CHROME MOULDING	1 PC	245.60	?
91 TAILGATE NO PLATE LAMP	2 PC	119.40	X
92 TAILGATE INNER LOCK	1 PC	391.60	✓
93 TAILGATE INNER LOCK COVER	1 PC	41.25	?
94 TAILGATE INNER LOCK CATCH	1 PC	39.67	✓
95 TAILGATE OUTER SWITCH OPENING - CHECK PRICE	1 PC	0.00	?
96 TAILGATE OUTER SWITCH OPENING COVER - CHECK PRICE	1 PC	0.00	?
97 TAILGATE CTR REFLECTOR WHITE	1 PC	345.20	?
98 TAILGATE CTR REFLECTOR CLIPS	2 PC	15.60	?
99 TAILGATE LAMP WHITE	2 PC	843.40	?
100 TAILGATE LAMP CLIPS	6 PC	40.20	?
101 TAILGATE WIPER MOTOR	1 PC	720.85	?
102 TAILGATE RUBBER (AT BODY)	1 PC	386.40	508.20
103 TAILGATE SIDE STOPPER RUBBER ADJUSTER	2 PC	15.68	?
104 TAILGATE OUTER SIDE HOLDER COVER RH	1 PC	45.90	?
105 TAILGATE INNER TRIMBOARD	1 PC	481.74	✓
106 TAILGATE INNER TRIMBOARD SIDE COVER LAMP LED - CHECK PRICE	2 PC	0.00	?
107 TAILGATE INNER UPPER SIDE GARNISH	2 PC	309.40	?
108 REAR BUMPER	1 PC	686.20	✓
109 REAR BUMPER SIDE RETAINERS	2 PC	119.20	✓
110 REAR BUMPER CTR RETAINERS	2 PC	123.40	✓
111 REAR BUMPER CLIPS	12 PC	46.68	✓
112 REAR BUMPER SPONGE	1 PC	75.30	✓
113 REAR BUMPER TOW COVER	2 PC	55.20	✓
114 REAR BUMPER SIDE REFLECTOR LAMP LED WHITE - CHECK PRICE	2 PC	0.00	✓
115 REAR END PANEL	1 PC	691.70	✓





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
 BLK 430C FERNVALE LINK
 #17-233
 SINGAPORE 793430

Estimate No: MC0913266
 Date: 13 Jul 2018
 Policy No: D17MTPV01016659
 Veh Reg No: SLH5358B
 Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
 Your Ref No: SLH5358B
 Claim Type: Third Party
 Accident Date: 10/07/2018
 TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		S\$	S\$
116 REAR END PANEL TOP GARNISH	1 PC	298.90	—
117 REAR END PANEL TOP GARNISH CLIPS	12 PC	87.00	—
118 REAR END PANEL TOP GARNISH CTR COVER	1 PC	41.70	?
119 REAR END PANEL INNER LOWER GARNISH	1 PC	201.70	—
120 SPARE TYRE PANEL	1 PC	380.90	—
121 SPARE TYRE PANEL LOWER SIDE RUBBER	4 PC	247.00	?
122 SPARE TYRE PANEL LOWER SIDE BRACKET	2 PC	149.70	?
123 SPARE TYRE PANEL BRACKET	1 PC	100.70	?
124 SPARE TYRE PANEL CTR BRACKET	1 PC	244.89	?
125 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	1,048.40	?
126 REAR CHASSIS SIDE PANEL LH & RH	2 PC	2,497.40	?
127 REAR CHASSIS SIDE PANEL PUTER LH & RH	2 PC	1,137.80	?
128 REAR CHASSIS FRAME LH & RH	2 PC	1,855.60	?
129 REAR FENDER OUTER LH & RH	2 PC	2,095.40	?
130 REAR FENDER LOWER AIR VENT	2 PC	259.48	?
131 REAR FENDER INNER TRIMBOARD LH & RH	2 PC	1,440.30	—
132 REAR FENDER INNER SIDE TOOL JACK COVER	1 PC	206.70	?
133 REAR A/C BLOWER & COOLING COIL ASSY	1 PC	2,111.70	?
134 REAR FENDER GLASS WITH MOULDING LH & RH	2 PC	1,392.60	X
135 REAR EXHAUST BOX	1 PC	1,202.70	?
136 REAR EXHAUST BOX TOP HEAT PLATE	1 PC	126.70	?
137 REAR EXHAUST BOX MOUNTING	4 PC	309.96	?
138 REAR EXHAUST CTR PIPE	1 PC	1,916.74	?
139 REAR EXHAUST CTR PIPE MOUNTING	3 PC	232.47	?
140 TAILAMP WHITE	2 PC	799.40	?
141 TAILAMP CLIPS - CHECK PRICE	6 PC	0.00	?
142 TAILAMP PANEL	2 PC	505.40	?
143 FLOOR PANEL CARPET - CHECK PRICE	1 PC	0.00	?
144 SPARE TYRE PANEL CARPET - CHECK PRICE	1 PC	0.00	?
145 REAR THIRD SEATBELT - CHECK PRICE	2 PC	0.00	?
		58,053.46	
	Less 25%	14,513.37	43,540.10



Special Nett

146 TAILGATE REVERSE CAMERA - CHECK PRICE	1 PC	0.00	?
147 NUMBER PLATE FRONT	1 PC	35.00	—
148 RADIATOR COOLANT	1 PC	35.00	205.00
149 BATTERY ASSY	1 PC	250.00	?
150 POWER EARTH MODULE - CHECK PRICE	1 PC	0.00	?



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:

Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		S\$	S\$
151 POWER EARTH MODULE WIRE - CHECK PRICE	1 PC	0.00	?
152 FRONT GRILLE STICKER - CHECK PRICE	1 PC	na	0.00 ✓
153 REAR WINDSCREEN SEALANT	1 PC	na	60.00 80.00
154 REAR WINDSCREEN INNER SEAL	1 PC	na	60.00 30.00
155 REAR FENDER GLASS SEALANT	2 PC	na	80.00 X
156 REAR FENDER GLASS INNER SEAL	2 PC	na	80.00 1
157 NUMBER PLATE REAR	1 PC	na	35.00 ✓
158 REAR CAMERA RECORDER - CHECK PRICE	1 PC	0.00	?
159 TAILGATE LAMP STICKER - CHECK PRICE	2 PC	0.00	?
160 TAILAMP STICKER - CHECK PRICE	2 PC	0.00	?
161 TAILGATE CTR REFLECTOR LAMP STICKER - CHECK PRICE	1 PC	na	0.00 ✓
162 TAILGATE TOP CTR PLATE WITH STICKER - CHECK PRICE	1 PC	0.00	?
163 REAR BUMPER REFLECTOR LAMP WHITE - CHECK PRICE	2 PC	0.00	?
164 TAILGATE INNER TRIMBOARD SIDE LAMP - CHECK PRICE	2 PC	0.00	?
165 REVERSE SENSOR	1 SET	200.00	✓
166 REVERSE SENSOR MODULE & WIRE HARNESS - CHECK PRICE	1 SET	0.00	?
		835.00	835.00

LABOUR

167 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
168 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	150.00
169 TO REMOVE & REPLACE ALTERNATOR BELTING A/C COMPRESSOR	1 PC	200.00	?
170 TO RESET ENGINE LIGHT, HEADLAMP ECU AIRBAG	1 PC	280.00	1201
171 TO REMOVE & REINSTALL/REPLACE AIR CLEANER BOX, ENGINE ECU MODULE, POWER EARTH MODULE & WIRE	1 PC	200.00	?
172 TO REMOVE & REINSTALL, REPLACE ENGINE MOUNTING FRONT, REAR, GEARBOX MOUNTING	1 PC	180.00	?
173 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	180.00	601
174 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT BUMPER REINFORCEMENT. TO KNOCK & REPAIR FRONT DOOR LH, & RH, FRONT WHEELHOUSE, FRONT CHASSIS FRAME INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,400.00	7001
175 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT DOOR LH & RH, RADIATOR SUPPORT PANEL, FRONT WHEELHOUSE, FRONT CHASSIS FRAME.	1 PC	1,200.00	10001
176 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
177 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	120.00	100
178 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	?
179 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	150.00	120
180 TO REMOVE & REINSTALL/REPLACE TAILGATE MOTOR	1 PC	150.00	60
181 TO REMOVE & REINSTALL/REPLACE REAR A/C BLOWER & COOLING COIL ASSY	1 PC	250.00	?
182 TO REMOVE & REINSTALL/REPLACE REAR FENDER GLASS WITH MOULDING LH & RH	1 PC	na 240.00	X
183 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	380.00	150
184 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	380.00	?
185 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	180.00	60
186 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	100.00	60
187 TO DISMANTLE & INSTALL/REPLACE REAR THIRD SEATBELT	1 PC	200.00	?
188 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	✓
189 TO RESET TAILGATE MOTOR,SRS LIGHT,ENGINE LIGHT	1 PC	380.00	?
190 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	280.00	120
191 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	180.00	80
192 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD TAILAMP PANEL,END PANEL,SPARE TYRE PANEL,RR FENDER,RR CHASSIS FRAME & SIDE PANEL & OUTER PANEL.TO KNOCK & REPAIR FLOOR PANEL,REAR WHEELHOUSE,RR FENDER INNER.TO REFIT LISTED PARTS BACK SAME.	1 PC	3,000.00	2200
193 TO SPRAY TAILGATE,RR BUMPER,END PANEL,SPARE TYRE PANEL,TAILAMP PANEL,RR FENDER,RR FENDER INNER,RR CHASSIS FRAME,RR CHASSIS SIDE PANEL OUTER,RR CHASSIS SIDE PANEL,FLOOR PANEL,RR WHEELHOUSE	1 PC	2,300.00	1600

12,320.00 12,320.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LOY LE HUI (LIU LEHUI)
BLK 430C FERNVALE LINK
#17-233
SINGAPORE 793430

Estimate No: MC0913266
Date: 13 Jul 2018
Policy No: D17MTPV01016659
Veh Reg No: SLH5358B
Make/Model: TOYOTA ESTIMA 2.4A

ATTN:
Your Ref No: SLH5358B
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SJX8053A

Estimate Repair Cost to Vehicle No :SLH5358B

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 56,695.10
		Add GST @ 7%	3,968.66
		Total Amount Payable	S\$ 60,663.76

TOTAL: SINGAPORE DOLLAR SIXTY THOUSAND SIX HUNDRED SIXTY THREE AND CENTS SEVENTY SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: