

FIRST AUTOWORKS

Repair Estimate

Date : 17/07/2018

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLD1629S
CHASSIS NO.: W0LSH9EM3G4038079
ENGINE NO.: B14NEL19KM0361

Name of insured : Chong Kum Weng
Date of accident : 13/07/2018

Reference: SLD1629S

Make: OPEL

Meriva

*Not Allowed
when*

Take photo before work

18/7/18

5 - Body

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	REAR BUMPE FASCIA UPPER	1,690.00
2	1	REAR BUMPE FASCIA LOWER, Extension	1,350.00
3	1	REAR BUMPE REINFORCEMENT	850.00
4	1	REAR END PANEL TOP COVER	220.00
5	1	REAR END PANEL	560.00
6	1	SPARE TIRE PANEL	1,550.00
7	1	SPARE TIRE BOARD	890.00
8	1	TAIL LID	2,450.00
9	1	TAIL LID W/STRIP	320.00
10	1	TAIL LID LOCK	250.00
11	1	TAIL LID TRIM BOARD	390.00
12	1	TAIL LID WIPER MOTOR	1,381.00
13	1	TAIL LID WIPER ARM	121.00
14	1	TAIL LID ABSORBER	330.00
15	1	TAIL LID CHROME HANDLE	950.00
16	1	LHR TAIL LID LAMP	780.00
17	1	RHR TAIL LID LAMP	780.00
18	1	RR WINDSCREEN	798.00
19	1	RR WINDSCREEN MOULDING	130.00
20	1	REAR EMBLEM	80.00
21	1	LETTERING "MERIVA"	70.00
22	1	LETTERING "TURBO" - Chrome	60.00
23	1	GUIDE,RR BPR FASCIA CTR	90.00
24	1	GUIDE,RR BPR FASCIA OTR RH	70.00
25	1	GUIDE,RR BPR FASCIA OTR LH	70.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

26	1	LHR TAIL LAMP	11	850.00	X
27	1	RHR TAIL LAMP	11	850.00	X
28	1	SENSOR,RR OBJECT with Ring, Service kit	11	450.00	✓
29	1	FRT AIR BAG SENSOR	11	356.00	X
30	1	AIR BAG CONTROL UNIT	Actual	980.00	✓
31	1	FRT DRIVER SEAT BELT RH	11	880.00	X
32	1	FRT DRIVER SEAT BELT PRETENSIONER RH, INNER	11	1,020.00	✓
33	1	FRT DRIVER SEAT BELT LH	11	880.00	X
34	1	FRT DRIVER SEAT BELT PRETENSIONER LH, INNER	11	1,020.00	✓

Parts Total: 23,516.00

Less 10%: 2,351.60

Total : 21,164.40

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2500.00 1625
2	Carry out spray painting on accident affected area.	2000.00 1650
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	70.00 50
4	To remove and refix rear tail gate windscreen	120.00 80.00 ✓
5	To conduct transfer of parts from old tailgate to new tailgate	180.00 120
6	Remove and refix seat cushion/upholstery to facilitate repair	150.00 120
7	To remove and refix reverse sensor and conduct test	150.00 90
8	To remove and refix reverse camera and conduct test	160.00 90
9	To conduct reset & reprogram system of air bag & seat belt light on	450.00 2

Labour Total : 5780.00

Other

No.	Other Description	Price (SGD)
1	Rear bumper clip set	50.00 ✓
2	Rear Number Plate	50.00 40
3	Rear Windscreen Sealant	60.00 40
4	Rear Tailage inner trim clip	78.00 X
5	Rear end panel trim clip	52.00 X
6	Reverse sensor(1 set)	250.00 X
7	Rear end panel insulation seal	60.00 X
8	Towing Service	60.00 X

Other Total : 660.00

Total : 27,604.40

Gst (7%) : 1

GRAND TOTAL:

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, I WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Ronnie Tan

DID: 6844 1985 Fax:6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: