

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

Liberty
clear

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Estimate No: EST1800210
Date: 17 Jul 2018

ATTN: Motor Claim Department

Veh Reg No: SJM8045G
Make/Model: NISSAN LATIO CVT
1.5L ABS
Chasis No: JN1BAAC11Z0020977
Reg. Date: 16/01/2009
Your Ref No: SKK5823X

Claim Type: Third Party
Accident Date: 16/07/2018
TP Veh Reg No: SKK5823X

Estimate Repair Cost to Vehicle No :SJM8045G

Quantity	Description	List Price	Amount
		SS	SS
	Net Price		
1	1 PC BOOT LID <i>Defect</i>	787.50	✓
2	1 PC BOOT LID LOGO	59.70	✓
3	1 PC BOOTLID "LATIO" EMBLEM	50.90	✓
4	1 PC BOOT LID CHROME <i>new</i>	270.60	+ x
5	2 PCS BOOT LID HINGE <i>new</i>	174.40	+ x
6	1 PC BOOT LID RUBBER <i>lit</i>	88.40	✓
7	1 PC BOOT LID LOCK <i>Paint</i>	123.20	✓
8	1 PC BOOT LID LOCK CHECKER <i>new Best</i>	63.70	✓
9	1 PC BOOT LID TRIM <i>new</i>	163.80	+ x
10	1 PC REAR FENDER LH <i>Repair</i>	1,004.70	+ x
11	1 PC REAR FENDER TRIM LH <i>new</i>	254.90	+ x
12	1 PC REAR FENDER RH <i>Repair</i>	1,004.70	+ x
13	1 PC REAR FENDER TRIM RH <i>new</i>	254.90	+ x
14	1 PC REAR WINDSCREEN RUBBER <i>new</i>	172.00	+ x
15	1 PC SPARE TYRE PANEL <i>Repair</i>	757.00	+ x
16	1 PC SPARE TYRE COVER <i>Defect</i>	452.30	✓
17	1 PC REAR PANEL <i>Distorted</i>	434.00	✓
18	1 PC REAR PANEL TRIM <i>Defect</i>	92.00	✓
19	1 PC REAR PANEL BOOTLID RELAY <i>Paint</i>	88.00	✓
20	1 PC TAIL LAMP - RH <i>new Cracked</i>	279.00	✓
21	1 PC TAIL LAMP PANEL RH <i>Repair</i>	168.80	+ x
22	1 PC TAIL LAMP LH <i>lit</i>	279.00	✓
23	1 PC TAIL LAMP PANEL LH <i>Repair</i>	168.80	+ x
24	1 PC REAR BUMPER <i>Dislodged</i>	532.40	✓
25	2 PCS REAR BUMPER BRACKET <i>Defect</i>	99.60	✓
26	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	70.00	✓
27	1 PC REAR BUMPER MUDFLAP LH <i>new</i>	24.50	+ x
28	1 PC REAR BUMPER SPONGE <i>Defect</i>	35.60	✓
29	1 PC EXHAUST PIPE <i>Repair</i>	480.00	✓

1 tail lamp 2p.
ex pipe
survey by
Andrian
18/7/18

Best

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 16/07/2018
TP Veh Reg No: SKK5823X

Estimate No: EST1800210

Date: 17 Jul 2018

Veh Reg No: SJM8045G

Make/Model: NISSAN LATIO CVT
1.5L ABS

Chasis No: JN1BAAC11Z0020977

Reg. Date: 16/01/2009

Your Ref No: SKK5823X

Estimate Repair Cost to Vehicle No :SJM8045G

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
30	2 PCS EXHAUST PIPE MOUNTING <i>not new</i>	32.00 <i>x</i>	
	<i>4015.30</i>	8,466.40	
	<i>3613.77</i>	Less 10%	7,619.76
	Special Net		
31	1 SET BOOT LID TRIM CLIPS <i>not new</i>	48.00 <i>+ 20</i>	
32	1 SET REAR FENDER TRIM CLIPS LH <i>2 new</i>	48.00 <i>+ 30</i>	
33	1 SET REAR FENDER TRIM CLIPS RH <i>1</i>	48.00 <i>x</i>	
34	1 PC REAR WINDSCREEN SEAL <i>3 new</i>	60.00 <i>x</i>	
35	1 PC REAR WINDSCREEN SEALANT <i>3 new</i>	60.00 <i>x</i>	
36	1 PC REAR NUMBER PLATE <i>new</i>	50.00 <i>x</i>	
37	1 SET REAR BUMPER CLIPS <i>new</i>	48.00 <i>30</i>	
38	1 SET REVERSE SENSORS <i>Damaged</i>	250.00 <i>200</i>	
		612.00	612.00
	Labour		
39	1 TO CHECK WIRING	30.00 <i>30</i>	
40	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 <i>x</i>	
41	1 TO REMOVE AND REFIT SEAT CUSHION	200.00 <i>80</i>	
42	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00 <i>80</i>	
43	1 TO SPRAY UNDERSEAL	120.00 <i>80</i>	
44	1 (REAR) TO SPRAY PAINTING	1,600.00 <i>1200</i>	
45	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00 <i>1200</i>	
46	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 <i>50</i>	
		4,120.00	4,120.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 16/07/2018
TP Veh Reg No: SKK5823X

Estimate No: EST1800210

Date: 17 Jul 2018

Veh Reg No: SJM8045G

Make/Model: NISSAN LATIO CVT
1.5L ABS

Chasis No: JN1BAAC11Z0020977

Reg. Date: 16/01/2009

Your Ref No: SKK5823X

Estimate Repair Cost to Vehicle No :SJM8045G

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 12,351.76
		Add GST @ 7%	864.62
		Total Amount Payable	S\$ 13,216.38

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND TWO HUNDRED SIXTEEN AND CENTS THIRTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
17/07/18
07 Days
total: 6623.77
1/5: 5.3K
5.3K