

KCC | 004. ASM 12972 Kha392 LKK: 57785

ASSIGNMENT

Surveyor: KCC

DOI: 12/7/18

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

%

Final ? Yes / No

SLQ 55562

SJS 5884P

SLQ 3812



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE/ PIC
20/8	675 5884P - X;	Non-Reporting ltr (1st):	
21/8	SLQ 55562 - 053/AXA 170/8046/Apa352: 0085 28/11	Non-Reporting ltr (2nd):	
24/08/18	- CAN DO PLS	Non-Reporting ltr (Final):	
	- BUILD LIABILITY CLAIM	Notification ltr (if non-pickup):	
	- TP LOD IN BY BMAIL	Call OI:	
		After call ltr to OI:	14/08/18 - JP
14/08/18 @ 1:50pm	- SPOKE TO OI. CONTINUOUS ACCIDENT	Documentation Check List:	Handler Typist
	- DRIVER 4 WAS INVOLVED IN A 3 VEH. CC.	Notification ltr (if non-pickup)	☐
	- 4 WAS THE LAST CAR IN PARK - BOMBED	After call ltr to OI:	☒
	- TP. INFORMED TP CLAIM, AGREED TO	Authorisation To Act:	☒
	- 053/84 ANOTHER NCD ISSUES.	Release Voucher:	☒
19/08/18	- SEND 12/11/18 TO AXA BY QUOTATION.	Final Repair Bill:	☒
	- HUB PRES TO REPORT TO THE REPORT	Car Rental Invoice:	☐
	- AXA APPROVED WORKERS. CON @ 37,125.00	Towing Invoice:	☐
20/08/18	- SEND 1st OFFER TO TP.	LTA / GIA:	☒
27/08/18	- TP ACCEPTED OFFER.	Medical Bill:	☐
	- ALL DOCS IN ORDER.	PIR:	☐
	- TO CLOSE.	Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐

PRELIMINARY ADVICE Date/Time: 18/8 Sent By: HMK (Voy only)

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS (days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 24/08/18	Confirm with: VRONICA	Email ☒ Call ☐
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.:	28	If NO or B 28, Ass. Lia: 100%
Repair Cost: (w/ GST)	SS 7,623.75		(3 VEH. CC; OI UNIT)
Loss of Rental (LOR):	SS (days)		
Loss of Use (LOU):	SS 1,500.00 x 23 days		
Loss of Income (LOI):	SS (\$ x days)		
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	SS 200		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS 9,005.75	Global Sum SS: -	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1	SS 9,005.75	Name 1: CITY AUTO PTE LTD	
Payee 2: (Strike if N.A.)	SS -	Name 2: -	
Payee 3: (Strike if N.A.)	SS -	Name 3: -	



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. EST, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Kh

AXA INSURANCE SINGAPORE PTE LTD

NO. 8

SHENTON WAY

AXA TOWER

SINGAPORE 068811

Contact : -

Not Insured

11 days @ 7500

Repair After Point

Fax No. :

22 days

Estimate : QUOT201807-000279(00)

Date : 17/07/2018

Vehicle No. : SJS5884P

Make/Model : TOYOTA COROLLA ALTIS 1.6
AUTO

Mileage (km) : 0

Chassis No. : MR053ZEE106151319

Accident Date : 12/07/2018 00:00:00

Claim No. : SLQ5556Z

Reference : SJS5884P

Policy No. : J3000005698MY

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Rear boot	1.0	558.50	558.50 ✓
2	Rear boot hinge	2.0	19.20	38.40 X
3	Rear boot lock	1.0	102.90	102.90 ✓
4	Rear boot lock cover	1.0	25.00	25.00 X
5	Rear boot innertrim	1.0	192.00	192.00 X
6	Rear boot innertrim clip	8.0	2.00	16.00 ✓
7	Rear boot striker	1.0	32.00	32.00 ✓
8	Rear boot weatherstrip	1.0	301.17	301.17
9	Rear boot logo	1.0	39.80	39.80 ✓
10	Rear boot emblem - 1.6	1.0	44.17	44.17 ✓
11	Rear boot emblem - corolla	1.0	40.24	40.24 ✓
12	Rear boot emblem - altis	1.0	41.79	41.79 ✓
13	Rear boot outer chrome moulding	1.0	182.00	182.00 ✓
14	Rear boot cylinder lock	1.0	98.30	98.30 X
15	Rear boot stopper	4.0	15.00	60.00 X
16	Rear boot lamp	2.0	253.40	506.80 ✓
17	License plate lamp	2.0	48.20	96.40 X
18	Rear bumper	1.0	534.00	534.00 ✓
19	Rear bumper bracket	2.0	35.60	71.20 ✓
20	Rear bumper support	2.0	55.20	110.40 X
21	Rear bumper retainer	2.0	52.30	104.60 ✓
22	Rear bumper clip	8.0	2.00	16.00 ✓
23	Rear bumper sponge	1.0	124.70	124.70 ✓
24	Rear bumper reinforcement	1.0	102.80	102.80 ✓
25	Rear bumper reflector	2.0	58.00	116.00 ✓
26	Rear bumper grommet	2.0	10.00	20.00 ✓
27	Rear end panel	1.0	580.60	580.60 ✓
28	Rear end panel top garnish	1.0	44.36	44.36 ✓
29	Rear end panel support	2.0	132.40	264.80 X
30	Trunk floor panel	1.0	889.90	889.90 ✓
31	Trunk floor side panel	2.0	265.00	530.00 X
32	Trunk floor board	1.0	198.00	198.00 ✓
33	Spare wheel carrier	1.0	81.50	81.50 X
34	Rear exhaust muffler	1.0	355.20	355.20 ✓

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000279(00)

Date : 17/07/2018

Vehicle No. : SJS5884P

Make/Model : TOYOTA COROLLA ALTIS 1.6
AUTO

Mileage (km) : 0

Chassis No. : MR053ZEE106151319

Accident Date : 12/07/2018 00:00:00

Claim No. : SLQ5556Z

Reference : SJS5884P

Policy No. : J3000005698MY

AXA INSURANCE SINGAPORE PTE LTD

NO. 8

SHENTON WAY

AXA TOWER

SINGAPORE 068811

Contact : -

Fax No. :

S/No	Particular	Quantity	Unit Price	Amount S\$	
35	Rear exhaust heatshiedl	1.0	188.20	188.20	✓
36	Front bumper	1.0	423.96	423.96	✓
37	Front bumper retainer	2.0	56.40	112.80	✓
38	Front bumper reinforcement	1.0	329.31	329.31	✓
39	Front bumper lower grille	1.0	98.30	98.30	✓
40	Front bumper logo	1.0	55.80	55.80	✓
41	Front bumper upper grille	1.0	261.90	261.90	✓
42	Front bumper top rubber moulding	1.0	38.20	38.20	X
43	Front bumper clip	8.0	5.00	40.00	✓
44	Headlamp	2.0	455.20	910.40	X
45	Support panel	1.0	2,121.90	2,121.90	X
46	Brace panel	1.0	101.40	101.40	✓
47	Bonnet lock	1.0	79.90	79.90	✓
48	Air condenser	1.0	1,211.50	1,211.50	X
49	Air-cond-pipe - suction	1.0	265.90	265.90	X
50	Air-cond-pipe - discharge	1.0	330.70	330.70	X
51	Air cond pipe - liquid	1.0	195.00	195.00	X
52	Radiator	1.0	1,681.95	1,681.95	X
53	Radiator top housing	1.0	38.00	38.00	X
54	Horn	2.0	68.80	137.60	X
55	Fan motor	1.0	156.70	156.70	X
56	Fan blade	1.0	63.70	63.70	X
57	Fan cowling	1.0	124.80	124.80	X
58	Rear exhaust mounting	2.0	48.00	96.00	X
59	Rear LH chassis member	1.0	588.20	588.20	X
60	Rear LH fender	1.0	602.95	602.95	✓
61	Rear LH fender inner trim	1.0	322.10	322.10	✓
62	Rear LH fender inner trim clip	6.0	3.89	23.34	✓
63	Rear LH fender air duct	1.0	98.00	98.00	✓
64	Rear LH bumper splash guard	1.0	102.00	102.00	✓
65	Fuel lid cover	1.0	58.00	58.00	✓
66	Fuel lid rivet	2.0	10.00	20.00	X
67	Fuel filler pipe cushion	1.0	38.00	38.00	X
68	Fuel lid cable	1.0	98.00	98.00	X
69	Rear LH fender inner panel	1.0	566.26	566.26	X

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-00/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Service Tel: 9823 9895

Co. Reg. No.: 199503435C GST Reg. No.: M2-0920979-4

AXA INSURANCE SINGAPORE PTE LTD

NO. 8

SHENTON WAY

AXA TOWER

SINGAPORE 068811

Contact : -

Fax No. :

Estimate : QUOT201807-000279(00)

Date : 17/07/2018

Vehicle No. : SJS5884P

Make/Model : TOYOTA COROLLA ALTIS 1.6
AUTO

Mileage (km) : 0

Chassis No. : MR053ZEE106151319

Accident Date : 12/07/2018 00:00:00

Claim No. : SLQ5556Z

Reference : SJS5884P

Policy No. : J3000005698MY

S/No	Particular	Quantity	Unit Price	Amount S\$
70	Rear windscreen glass moulding	1.0	98.00	98.00 ✓
71	Taillamp	2.0	259.90	519.80 ✓
72	Taillamp panel LH	1.0	155.00	155.00 ✓
73	Rear LH door lock	1.0	401.60	401.60 X
List Total :				19,274.70
25% Discount S\$				4,818.59
				14,456.11 = 3
SPECIAL NET :				
1	Rear view camera	1.0	350.00	350.00 X
2	Number plate - Front & Rear	2.0	20.00	40.00 ✓
3	Number plate casing (Front & Rear)	2.0	25.00	50.00 ✓
4	Reverse sensor	1.0	200.00	200.00 ✓
5	Trunk floor insulator paste	1.0	150.00	150.00 ✓
6	Rear windscreen glass sealant	1.0	40.00	40.00 ✓
SPECIAL NET Total S\$:				830.00
LABOUR :				
	*To check wiring and lighting	1.0	80.00	80.00 401
	*To supply panel sealant and to seal all weld seam and gaps	1.0	90.00	90.00 ✓
	*To remove and install rear windscreen glass	1.0	150.00	150.00 1201
	*To remove and install rear seats and upholstery	1.0	160.00	160.00 1001
	*To remove and install fuel filler pipe and hoses	1.0	80.00	80.00 601
	*To remove and install rear suspension and axle beam	1.0	180.00	180.00 ✓
	*To remove and install rear view camera and reverse sensor	1.0	120.00	120.00 801
	*To remove and install air condenser and recharge air cond gas	1.0	65.00	65.00 ✓
	*To remove and install radiator and perform leakage test	1.0	80.00	80.00 501
	*To use hydradic pump and jack chassis member	1.0	250.00	250.00 ✓
	*To spray undercoating	1.0	120.00	120.00 ✓
	*To conduct wheel alignment	1.0	65.00	65.00 ✓
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	3,000.00	3,000.00 2600
	- Spray painting on affected & replace parts	1.0	2,400.00	2,400.00 2200
	*To towing	1.0	90.00	90.00 501
				6,930.00

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA INSURANCE SINGAPORE PTE LTD

NO. 8

SHENTON WAY

AXA TOWER

SINGAPORE 068811

Contact : -

Fax No. :

Estimate : QUOT201807-000279(00)

Date : 17/07/2018

Vehicle No. : SJS5884P

Make/Model : TOYOTA COROLLA ALTIS 1.6
AUTO

Mileage (km) : 0

Chassis No. : MR053ZEE106151319

Accident Date : 12/07/2018 00:00:00

Claim No. : SLQ5556Z

Reference : SJS5884P

Policy No. : J3000005698MY

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

Total S\$ 22,216.11 ⁰³

GST 7% S\$ 1,555.13

Amount Due S\$ 23,771.24 ¹⁵


for CITY AUTO PTE LTD



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA INSURANCE SINGAPORE PTE LTD

NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Contact : -

Not Ashanti
11 days & ?
Repair After Paint
22 days

Estimate : QUOT201807-000279(00)

Date : 17/07/2018

Vehicle No : SJS5884P

Make/Model : TOYOTA COROLLA ALTIS 1.6
AUTO

Mileage (km) : 0

Chassis No : MR053ZEE106151319

Accident Date : 12/07/2018 00:00:00

Claim No : SLQ5556Z

Reference : SJS5884P

Policy No : J3000005698MY

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Rear boot	1.0	558.50	558.50 ✓
2	Rear boot hinge	2.0	19.20	38.40 X
3	Rear boot lock	1.0	102.90	102.90 ✓
4	Rear boot lock cover	1.0	25.00	25.00 X
5	Rear boot innertrim	1.0	192.00	192.00 X
6	Rear boot innertrim clip	8.0	2.00	16.00 ✓
7	Rear boot striker	1.0	32.00	32.00 ✓
8	Rear boot weatherstrip	1.0	301.17	301.17 ✓
9	Rear boot logo	1.0	39.80	39.80 ✓
10	Rear boot emblem - 1.6	1.0	44.17	44.17 ✓
11	Rear boot emblem - corolla	1.0	40.24	40.24 ✓
12	Rear boot emblem - altis	1.0	41.79	41.79 ✓
13	Rear boot outer chrome moulding	1.0	182.00	182.00 ✓
14	Rear boot cylinder lock	1.0	98.30	98.30 X
15	Rear boot stopper	4.0	15.00	60.00 X
16	Rear boot lamp	2.0	253.40	506.80 ✓
17	License plate lamp	2.0	48.20	96.40 X
18	Rear bumper	1.0	534.00	534.00 ✓
19	Rear bumper bracket	2.0	35.60	71.20 ✓
20	Rear bumper support	2.0	55.20	110.40 ?
21	Rear bumper retainer	2.0	52.30	104.60 ✓
22	Rear bumper clip	8.0	2.00	16.00 ✓
23	Rear bumper sponge	1.0	124.70	124.70 ✓
24	Rear bumper reinforcement	1.0	102.80	102.80 ✓
25	Rear bumper reflector	2.0	58.00	116.00 ✓
26	Rear bumper grommet	2.0	10.00	20.00 ✓
27	Rear end panel	1.0	580.60	580.60 ✓
28	Rear end panel top garnish	1.0	44.36	44.36 ✓
29	Rear end panel support	2.0	132.40	264.80 ?
30	Trunk floor panel	1.0	889.90	889.90 ✓
31	Trunk floor side panel	2.0	265.00	530.00 ?
32	Trunk floor board	1.0	198.00	198.00 ✓
33	Spare wheel carrier	1.0	81.50	81.50 ?
34	Rear exhaust muffler	1.0	355.20	355.20 ✓

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000279(00)

AXA INSURANCE SINGAPORE PTE LTD

NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Contact : -

Fax No. :

Date : 17/07/2018

Vehicle No. : SJS5884P

Make/Model : TOYOTA COROLLA ALTIS 1.6
AUTO

Mileage (km) : 0

Chassis No. : MR053ZEE106151319

Accident Date : 12/07/2018 00:00:00

Claim No. : SLQ5556Z

Reference : SJS5884P

Policy No. : J3000005698MY

S/No	Particular	Quantity	Unit Price	Amount S\$	
35	Rear exhaust heatshiedl	1.0	188.20	B ₂ 188.20	✓
36	Front bumper	1.0	423.96	B ₂ 423.96	✓
37	Front bumper retainer	2.0	56.40	D1J 112.80	✓
38	Front bumper reinforcement	1.0	329.31	B ₂ 329.31	✓
39	Front bumper lower grille	1.0	98.30	D14 98.30	✓
40	Front bumper logo	1.0	55.80	M 55.80	✓
41	Front bumper upper grille	1.0	261.90	CM 261.90	✓
42	Front bumper top rubber moulding	1.0	38.20	.	?
43	Front bumper clip	8.0	5.00	M 40.00	✓
44	Headlamp	2.0	455.20		?
45	Support panel	1.0	2,121.90		?
46	Brace panel	1.0	101.40	B ₂ 101.40	✓
47	Bonnet lock	1.0	79.90	D17 79.90	✓
48	Air condenser	1.0	1,211.50		?
49	Air cond pipe - suction	1.0	265.90	S ₂ 265.90	✓
50	Air cond pipe - discharge	1.0	330.70	S ₂ 330.70	✓
51	Air cond pipe - liquid	1.0	195.00		?
52	Radiator	1.0	1,681.95		?
53	Radiator top housing	1.0	38.00		?
54	Horn	2.0	68.80		?
55	Fan motor	1.0	156.70		?
56	Fan blade	1.0	63.70		?
57	Fan cowling	1.0	124.80		?
58	Rear exhaust mounting	2.0	48.00		?
59	Rear LH chassis member	1.0	588.20	M 588.20	X
60	Rear LH fender	1.0	602.95	B ₂ 602.95	✓
61	Rear LH fender inner trim	1.0	322.10	Return 322.10	✓
62	Rear LH fender inner trim clip	6.0	3.89	M 23.34	✓
63	Rear LH fender air duct	1.0	98.00	CM 98.00	✓
64	Rear LH bumper splash guard	1.0	102.00	M17 102.00	✓
65	Fuel lid cover	1.0	58.00	B ₂ 58.00	✓
66	Fuel lid rivet	2.0	10.00		?
67	Fuel filler pipe cushion	1.0	38.00		?
68	Fuel lid cable	1.0	98.00		?
69	Rear LH fender inner panel	1.0	566.26		?

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000279(00)

AXA INSURANCE SINGAPORE PTE LTD

NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Contact : -

Fax No. :

Date : 17/07/2018

Vehicle No. : SJS5884P

Make/Model : TOYOTA COROLLA ALTIS 1.6
AUTO

Mileage (km) : 0

Chassis No. : MR053ZEE106151319

Accident Date : 12/07/2018 00:00:00

Claim No. : SLQ5556Z

Reference : SJS5884P

Policy No. : J3000005698MY

S/No	Particular	Quantity	Unit Price	Amount S\$
70	Rear windscreen glass moulding	1.0	98.00	98.00 ✓
71	Taillamp	2.0	259.90	519.80 ✓
72	Taillamp panel LH	1.0	155.00	155.00 ✓
73	Rear LH door lock	1.0	401.60	401.60 ✓
List Total :				19,274.70
25% Discount S\$				4,818.59
				14,456.11

SPECIAL NET :

1	Rear view camera	1.0	350.00	350.00 ?
2	Number plate - Front & Rear	2.0	20.00	40.00 ✓
3	Number plate casing (Front & Rear)	2.0	25.00	50.00 ✓
4	Reverse sensor	1.0	200.00	200.00 ✓
5	Trunk floor insulator paste	1.0	150.00	150.00 ✓
6	Rear windscreen glass sealant	1.0	40.00	40.00 ✓
SPECIAL NET Total S\$:				830.00

LABOUR :

*To check wiring and lighting	1.0	80.00	80.00	✓
*To supply panel sealant and to seal all weld seam and gaps	1.0	90.00	90.00	✓
*To remove and install rear windscreen glass	1.0	150.00	150.00	1200
*To remove and install rear seats and upholstery	1.0	160.00	160.00	1000
*To remove and install fuel filler pipe and hoses	1.0	80.00	80.00	600
*To remove and install rear suspension and axle beam	1.0	180.00	180.00	✓
*To remove and install rear view camera and reverse sensor	1.0	120.00	120.00	800
*To remove and install air condenser and recharge air cond gas	1.0	65.00	65.00	✓
*To remove and install radiator and perform leakage test	1.0	80.00	80.00	500
*To use hydradic pump and jack chassis member	1.0	250.00	250.00	✓
*To spray undercoating	1.0	120.00	120.00	✓
*To conduct wheel alignment	1.0	65.00	65.00	✓
-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	3,000.00	3,000.00	2600
- Spray painting on affected & replace parts	1.0	2,400.00	2,400.00	2200
*To towing	1.0	90.00	90.00	500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CONTINUE NEXT PAGE

Page 3 of 4 Acknowledged by Repairer

Signature:



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000279(00)

AXA INSURANCE SINGAPORE PTE LTD

NO. 8

SHENTON WAY

AXA TOWER

SINGAPORE 068811

Contact : -

Fax No. :

Date : 17/07/2018

Vehicle No. : SJS5884P

Make/Model : TOYOTA COROLLA ALTIS 1.6
AUTO

Mileage (km) : 0

Chassis No. : MR053ZEE106151319

Accident Date : 12/07/2018 00:00:00

Claim No. : SLQ5556Z

Reference : SJS5884P

Policy No. : J3000005698MY

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

E. & O.E.

Total S\$ 22,216.11

GST 7% S\$ 1,555.13

Amount Due S\$ 23,771.24

for CITY AUTO PTE LTD



Service Request Details

Claim

S8M000GE

Reference

None

Loss Date

July 12, 2018

Request Date

July 16, 2018

Due Date

July 23, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJS5884P

Make

TPVD TOYOTA

16072018 @ 424pm City Auto
Vanica veh in 160 Sin Ming #05-01
Kenneth

Model

COROLLA ALTIS 1.6 AUTO

Service Address

...

Primary Contact/Insured

TING YI SHENG AUGUSTINE

BLK 641 HOUGANG AVE 8, #08-175, 530641, Singapore

96936479

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Vic (LKKAUTO)

From: City Auto <cityauto@singnet.com.sg>
Sent: Monday, 27 August, 2018 4:18 PM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: LOD of SJS5884R LKK REF: CC4/ASM18012972/Kha3 Our ref: SJS5884R D.O.A: 12/07/2018 LKK REF CC4/ASM18012972/Kha3
Attachments: DV-5884.pdf

Dear Vic,

DV is attached.

Thank you.

Best Regards,

Vronica Law
City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate,
#01-60/62 Sin Ming Road,
Singapore 575643
Tel : 6453 1235
Fax : 6453 7944

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Monday, 20 August, 2018 1:41 PM
To: City Auto
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: LOD of SJS5884R LKK REF: CC4/ASM18012972/Kha3 Our ref: SJS5884R D.O.A: 12/07/2018 LKK REF CC4/ASM18012972/Kha3

Without Prejudice

Dear Vronica,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we offer settlement as below:

Cost of Repair @ L/S \$7,125.00 (w/gst)	\$ 7,623.75
Loss of Use (\$60 x 23 days)	\$ 1,380.00
GIA Search Fee	\$ 2.00
TOTAL	\$ 9,005.75

If agreeable, kindly let the owner sign the attached DV then forward back to us a copy for payment processing.

The above amount is to be made payable to CITY AUTO PTE LTD.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Friday, 17 August, 2018 4:51 PM

To: City Auto

Cc: Admin A; Vic (LKKAuto)

Subject: RE: LOD of SJS5884R LKK REF: CC4/ASM18012972/Kha3 Our ref: SJS5884R D.O.A: 12/07/2018 LKK REF CC4/ASM18012972/Kha3

Without Prejudice

Dear Vronica,

We refer to your below email and the contents were noted.

We will get back to you for an update/offer in due course.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: City Auto [<mailto:cityauto@singnet.com.sg>]

Sent: Friday, 17 August, 2018 12:30 PM

To: Vic (LKKAuto)

Subject: LOD of SJS5884R LKK REF: CC4/ASM18012972/Kha3 Our ref: SJS5884R D.O.A: 12/07/2018

Dear Vic,

Please find attached the LOD of above-mentioned claims.

Thank you.

Best Regards,

Vronica Law

City Auto Pte Ltd

Blk 8 Sin Ming Industrial Estate,

#01-60/62 Sin Ming Road,

Singapore 575643

Tel : 6453 1235

Fax : 6453 7944

From: Vic (LKKAuto) [<mailto:vicalpeh@lkkauto.com>]

Sent: Tuesday, 24 July, 2018 4:15 PM

To: City Auto

Cc: Hsiao Tong (LKKAuto); Admin A; Vic (LKKAuto)

Subject: RE: Arrange survey on SJS5884R D.O.A: 12/07/2018 *** LKK REF: CC4/ASM18012972/Kha3

WITHOUT PREJUDICE

Dear Vronica,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: City Auto [<mailto:cityauto@singnet.com.sg>]
Sent: Tuesday, 24 July, 2018 9:14 AM
To: Mei Kwan (LKKAUTO)
Cc: Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Arrange survey on SJS5884R D.O.A: 12/07/2018 *** LKK REF: CC4/ASM18012972/Kha3

Dear Mei Kwan,

As spoken just now, please confirm the above-mentioned claims will be direct settlement.

Thank you.

Best Regards,

Vronica Law
City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate,
#01-60/62 Sin Ming Road,
Singapore 575643
Tel : 6453 1235
Fax : 6453 7944


From: Mei Kwan (LKKAUTO) [<mailto:Meikwan@lkkauto.com>]
Sent: Tuesday, 17 July, 2018 4:07 PM
To: City Auto
Cc: Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Arrange survey on SJS5884R D.O.A: 12/07/2018 *** LKK REF: CC4/ASM18012972/Kha3

Dear Sir / Madam,

We refer to the above matter.

Please be informed that we are currently **pending verification for direct settlement.**

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

front veh suddenly stop, & cannot stop intial
hit veh B. veh B forward hit veh C. n

Please note that for liability, claim negotiation and settlement, please contact Vic at 6841 2096.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: City Auto [<mailto:cityauto@singnet.com.sg>]

Sent: Monday, 16 July, 2018 12:56 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Subject: Arrange survey on SJS5884R D.O.A: 12/07/2018

Hi Arrangement survey dept,

Kindly arrange **LKK Auto Consultants Pte Ltd** survey on **Tuesday 17/07/2018** on following vehicle :

TP Survey

Your vehicle : SLQ5556Z

Our vehicle : SJS5884R

D.O.A : 12/07/2018

LOCATION : Blk 160, Sin Ming Drive, Sin Ming Auto City #05-01 Singapore 575722

Thank you.

Best Regards,

Vronica Law

City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate,
#01-60/62 Sin Ming Road,
Singapore 575643
Tel : 6453 1235
Fax : 6453 7944



Re:SEEK MANDATE S8M00OGE

Type

i Information

Message

PLS PROCEED FOR DS QUANTUM NOT EXCEEDING \$9,005.75 COR:\$7,623.75 W/GST LOU \$1,380.00
LTA:\$2.00 =\$9,005.75

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ 5556Z (Insd veh)	Model:	TOYOTA
	SJS 5884P (TP veh)		COROLLA ALTIS 1.6 AUTO
Date of Accident:	12/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	23,771.15
Final Repair Cost	:	\$	7,623.75
Loss of Use	:	\$	1,380.00
Rental (if any)	:	\$	23 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	9,005.75

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown		
1)	CITY AUTO PTE LTD	\$ 9,005.75

NUR SHAQILAH BTE ABDOL
WAHAB

24/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< Service Request Details

Claim	S8M000GE
Reference	
CC4/ASM18012972/Kha3s2	Loss Date
July 12, 2018	Request Date
September 5, 2018	Due Date
July 16, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss
Third Party Vehicle Damage	Services
Pending verification - Direct Settlement	
Additional Instructions	

Actions

Next Step

Finish the work

Complete Work

Document Type

Document Sub Type

Upload Documents

Vehicle Information

Incident Vehicle Registration #

SJS5994P

Make

Service Address

TPVD TOYOTA

Model

COROLLA ALTIS 1.6 AUTO

Primary Contact/Insured

TING YI SHENG AUGUSTINE

BLK 641 HOUGANG AVE 8, #08-175, 530641, Singapore

96936479

Claim Handler

CHAN Kian Chuan

6568904269

kianchuan.chan@axa.com.sg

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

DATE UPLOADED

<< Service Request Details

Claim

S8M000GE

Reference

CC4/ASM18012372/Kha3s2 

Loss Date

July 12, 2018

Request Date

September 5, 2018

Due Date

July 16, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

Share

Add

Vehicle Information

Incident Vehicle Registration #

SJS5884P

Make

TPVD TOYOTA

Model

...

Service Address

COROLLA ALTIS 1.6 AUTO

Primary Contact/Insured

TING YI SHENG AUGUSTINE
BLK 641 HOUGANG AVE 8, #08-175, 530641,
Singapore
96936479

Claim Handler

CHAN Kian Chuan
656804269
kianchuan.chan@axa.com.sg

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SJS5884P	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	08/25/2009
Mileage	74035	Age of Vehicle	8

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2010	2009	Driver Name	HASHIMOTO TAKASHI	
Make	BMW	TOYOTA	Date of Birth	June 15, 1971	mm/dd/yyyy
Model	325 I COUPE	COROLLA ALTIS 1.6 AU	Age	47	

Type		Occupation	Unknown
Type of Paint		Education Qualification	Other

Chassis No	WBAAKE32060E446954	Driving Experience	0
Engine No	05127396N52825AF	Driver License #	

Engine Capacity	1598 cc
-----------------	---------

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	07/17/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unlicensed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	195/65R15	Rear Tyre Size	195/65R15
Front left side	BRIDGESTONE 7mm	Rear left side	BRIDGESTONE 8mm
Front right side	BRIDGESTONE 7mm	Rear right side	BRIDGESTONE 8mm

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTK%	DISC.OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE	
	1	1			REAR BOOT			Bent	558.5		25		418.88	Reviewing		
	2	2			REAR BOOT HINGE			Repair	0		25		0	Reviewing		
	3	1			REAR BOOT LOCK			Dented	102.9		25		77.18	Reviewing		
	4	1			REAR BOOT LOCK COVER			Serviceable	0		25		0	Reviewing		
	5	1			REAR BOOT INNER TRIM			Serviceable	0		25		0	Reviewing		
	6	8			REAR BOOT INNER TRIM CLIP			Necessary	2		25		12	Reviewing		
	7	1			REAR BOOT STRIKER			Damaged	32		25		24	Reviewing		
	8	1			REAR BOOT LOGO			Necessary	39.8		25		29.85	Reviewing		
	9	1			REAR BOOT EMBLEM - 1.6			Necessary	44.17		25		33.13	Reviewing		
	10	1			REAR BOOT EMBLEM - COROLLA			Necessary	40.24		25		30.18	Reviewing		
	11	1			REAR BOOT EMBLEM - ALTIS			Necessary	41.79		25		31.34	Reviewing		
	12	1			REAR BOOT OUTER CHROME MOULDING			Damaged	182		25		136.5	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTRR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	30	1			TRUNK FLOOR PANEL			Bent	889.9		25		667.43	Reviewing	
	31	2			TRUNK FLOOR SIDE PANEL			Repair	0		25		0	Reviewing	
	32	1			TRUNK FLOOR BOARD			Cracked	198		25		148.5	Reviewing	
	33	1			SPARE WHEEL CARRIER			Serviceable	0		25		0	Reviewing	
	34	1			REAR EXHAUST MUFFLER			Bent	355.2		25		268.4	Reviewing	
	35	1			REAR EXHAUST HEATSHIELD			Bent	188.2		25		141.15	Reviewing	
	36	1			FRONT BUMPER			Bent	423.96		25		317.97	Reviewing	
	37	2			FRONT BUMPER RETAINER			Damaged	56.4		25		84.6	Reviewing	
	38	1			FRONT BUMPER REINFORCEMENT			Bent	329.31		25		246.98	Reviewing	
	39	1			FRONT BUMPER LOWER GRILLE			Damaged	98.3		25		73.73	Reviewing	
	40	1			FRONT BUMPER LOGO			Necessary	55.8		25		41.85	Reviewing	
	41	1			FRONT BUMPER UPPER GRILLE			Cracked	261.9		25		196.43	Reviewing	
	42	1			FRONT BUMPER TOP RUBBER MOULDING			Serviceable	0		25		0	Reviewing	
	43	8			FRONT BUMPER CLIP			Necessary	5		25		30	Reviewing	
	44	2			HEADLAMP			Serviceable	0		25		0	Reviewing	
	45	1			SUPPORT PANEL			Repair	0		25		0	Reviewing	
	46	1			BRACE PANEL			Bent	101.4		25		76.05	Reviewing	
	47	1			BONNET LOCK			Damaged	79.9		25		59.93	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTH%	DISC QUNTY%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	66	2			FUEL LID RIVET			Serviceable	0		25		0	Reviewing	
	67	1			FUEL FILLER PIPE CUSHION			Serviceable	0		25		0	Reviewing	
	68	1			FUEL LID CABLE			Serviceable	0		25		0	Reviewing	
	69	1			REAR LH FENDER INNER PANEL			Repair	0		25		0	Reviewing	
	70	1			REAR WINDSCREEN GLASS MOULDING			Necessary	96		25		73.5	Reviewing	
	71	2			TAILLAMP			Cracked	259.9		25		389.85	Reviewing	
	72	1			TAILLAMP PANEL LH			Bent	155		25		116.25	Reviewing	
	73	1			REAR LH DOOR LOCK			Repair	0		25		0	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RAR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO CHECK WIRING AND LIGHTING.	40	0	0	Reviewing		
	2		TO SUPPLY PANEL SEALANT AND TO SEAL ALL WELD SEAM AND GAPS.	90	0	0	Reviewing		
	3		TO REMOVE AND INSTALL REAR WINDSCREEN GLASS.	120	0	0	Reviewing		
	4		TO REMOVE AND INSTALL REAR SEATS AND UPHOLSTERY.	100	0	0	Reviewing		
	5		TO REMOVE AND INSTALL FUEL FILLER PIPE AND HOSES.	60	0	0	Reviewing		
	6		TO REMOVE AND INSTALL REAR SUSPENSION AND AXLE BEAM.	180	0	0	Reviewing		
	7		TO REMOVE AND INSTALL REAR VIEW CAMERA AND REVERSE SENSOR.	80	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS

« Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		22	
	2	REAR BOOT WEATHERSTRIP	Reviewing	150.58	DISTORTED / CUT	
	3	REAR VIEW CAMERA	Reviewing	0	SERVICEABLE	
	4	NUMBER PLATE - FRONT & REAR	Reviewing	40	BENT	
	5	NUMBER PLATE CASING (FRONT & REAR)	Reviewing	50	BENT	
	6	REVERSE SENSOR	Reviewing	200	TORN	
	7	TRUNK FLOOR INSULATOR PASTE	Reviewing	80	NECESSARY	
	8	REAR WINDSCREEN GLASS SEALANT	Reviewing	40	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$12,924.86

Claim Amount \$12,924.86

CATEGORY ESTIMATE REVISED AMOUNT

Spare Parts \$6,294.28 \$6,294.28

Labour \$6,070.00 \$6,070.00

Miscellaneous \$560.58 \$560.58

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE

1

Reviewing

7500

FINAL LUMP SUM