

REF CS/ASM18012977/R1sd302

ASSIGNMENT (Office)

From (Person)

Rasih  
Peter Wang

of

ASM (AXA)

Date/Time

17/07/2018

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No

SLX 4563Y

Insured

at Workshop n/o

Stuttgart Auto

Tel

6360 2846

of

No. 12 Bunggai Kadut

Policy No

Claim No

S8M00012

Sum Insured

Excess

\$ 4,000.00

Make of Veh

(Client's Record)

D.O.A 12/07/2018

CA (REV)

/ REP. / REV 24 HRS

18/07/2018

I.O.U. Endorsement

Date/Time

3:04pm @ 17/7/18

Person Contacted

EVA

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLX 4563Y-X

17/07/18

@ 15:58 p.m. revised IA & requested authorise repair to Peter Wang via smart claim.

26/07/18

@ 11:37 a.m. authorise repair approved by Peter Wang via smart claim

26/7/18

@ 12:00 p.m. revert authorise repair to Eva (Gopner) via email.

Surveyor *John*

9.550C

COT XPRY: 2025/mar

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

(OD) TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 45634at Workshop m/s STUTTGARTof No. 12, Sunway Karu

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: 4000

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

EVA

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 110K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLX 45634 Yr Regn: 2008 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PORSCHE 987 BOXSTER C.C. 2687Colour: Red A/C: Insured / Std / NI / NASp. Reading: 3781 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WPO22298Z8U 701710Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/40ZR18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/07/18 D.O.I. 18/07/18Survey held at StuttgartDes. of Damages: Ext / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/09/18 Confirmed P/P \$ 17,427.28 @ 7 days with Rese!  
(\$ 6,069.68 Red - 26% )

RECEIVED 1 OCT 2018

Date/Time, File Pass to?

02/10/18

1) Type

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 300

Transportation: \_\_\_\_\_

S + RS: \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

300

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ 17,427.28 P/P)



## Service Request Details

Claim

S8M00OIZ

Reference

None 

Loss Date

July 12, 2018

Request Date

July 17, 2018

Due Date

July 24, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SLX4563Y

Make

PORSCHE



## Service Address

...

## Primary Contact/Insured

BABU GOVINDASAMY NAIDU SHURENDRA

15 ANG MO KIO AVENUE 9, #08-02 FAR HORIZON GARDEN, 569765, Singapore

spynaidu@gmail.com

## Claim Handler

WANG Peter

peter.wang@axa.com.sg

### Additional Instructions

Wkshop: Stuttgart Auto Excess: \$4000 To survey WP due to large repair cost

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18012977/R1sd3

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 17-07-2018



Code : ASM

## 1. Policy Particulars :- OWN DAMAGE

|                                     |                |            |
|-------------------------------------|----------------|------------|
| Insured Veh.                        | Veh. Inspected | SLX 4563Y  |
| Policy No.                          | Coverage (\$)  | 0.00       |
| Claim No. S8M000IZ                  | Excess (\$)    | 4,000.00   |
| Assign From SMARTCLAIM (PETER WANG) | Assign Date    | 17/07/2018 |

## 2. Vehicle Particulars & Condition

|                   |              |   |
|-------------------|--------------|---|
| Make & Model      | c.c          | 0 |
| Engine No. HIDDEN | Year of Reg. |   |
| Chassis No.       | Colour       |   |
| Odometer -        | Steering     |   |
| Brakes            | Modification |   |
| General           |              |   |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                                                                    |                 |            |
|----------------|--------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 12/07/2018                                                         | Inspection Date | 17/07/2018 |
| Survey held at | STUTTGART AUTO PTE LTD<br>12 SUNGEI KADUT AVE.<br>SINGAPORE 729648 |                 |            |

## 5a. Remarks

|                                                                    |
|--------------------------------------------------------------------|
| A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)                     |
| B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Details          |                          |
|--------------------------------|--------------------------|
| Owner ID Type:                 | Singapore NRIC           |
| Owner ID:                      | 9550C                    |
| Vehicle Details                |                          |
| Vehicle No.:                   | SLX4563Y                 |
| Vehicle to be Exported:        | No                       |
| Intended De-registration Date: | 19 Jul 2018              |
| Vehicle Make:                  | PORSCHE                  |
| Vehicle Model:                 | 987 BOXSTER TIPTRONIC    |
| Primary Colour:                | Red                      |
| Secondary Colour:              | Black                    |
| Manufacturing Year:            | 2008                     |
| Engine No.:                    | 65806972                 |
| Chassis No.:                   | WPOZZZ98Z8U701710        |
| Maximum Power Output:          | 180.0 kW (241 bhp)       |
| Open Market Value:             | \$76,283.00              |
| Original Registration Date:    | 28 Mar 2008              |
| First Registration Date:       | 28 Mar 2008              |
| Transfer Count:                | 1                        |
| Actual ARF Paid:               | \$76,283.00              |
| Incoming PARF Rebate Details   |                          |
| PARF Eligibility:              | Forfeited                |
| PARF Eligibility Expiry Date:  | -                        |
| PARF Rebate Amount:            | \$0.00                   |
| Incoming COE Rebate Details    |                          |
| COE Expiry Date:               | 27 Mar 2028              |
| COE Category:                  | B - Car (1601cc & above) |
| COE Period(Years):             | 10                       |
| PQP Paid:                      | \$44,998.00              |
| COE Rebate Amount:             | \$43,594.00              |
| <b>Total Rebate Amount:</b>    | <b>\$43,594.00</b>       |

The information contained herein is correct as at 19 Jul 2018

OK

 **Service Request Details**

Claim

SBM00OIZ

Reference

None 

Loss Date

July 12, 2018

Request Date

July 17, 2018

Due Date

October 17, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

**Actions**

Next Step

Finish the work

[Complete Work](#)[More ▾](#)**Vehicle Information**

Incident Vehicle Registration #

SLX4563Y

Make

PORSCHE

Model  
BOXSTER

### Service Address

---

...

### Primary Contact/Insured

---

BABU GOVINDASAMY NAIDU SHURENDRA  
15 ANG MO KIO AVENUE 9, #08-02 FAR HORIZON GARDEN, 569765, Singapore

spynaidu@gmail.com

### Claim Handler

---

WANG Peter

peter.wang@axa.com.sg

#### Additional Instructions

Wkshop: Stuttgart Auto Excess: \$4000 To survey WP due to large repair cost

Messages   Invoices   History   Documents   Assessment   Metrics   Notes

---

New Message

|         |                                                                                     |
|---------|-------------------------------------------------------------------------------------|
| TYPE    |  |
| SENT    | 7/26/18 11:37 AM                                                                    |
| FROM    | WANG Peter                                                                          |
| SUBJECT | Authorized                                                                          |
| BODY    | Pls proceed to authorize OD repair, Excess: \$400                                   |



|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| TYPE |  |
| SENT | 7/25/18 8:47 AM                                                                     |
| FROM | LKK AUTO CONSULTANTS PTE LTD (OD)                                                   |

SUBJECT

RE: Pending mandate approval

BODY

Hi all, any updated for this case? From : Shirley



TYPE



SENT

7/20/18 5:00 PM

FROM

WANG Peter

SUBJECT

Pending mandate approval

BODY

Pending mandate approval from Yvonne. Will update ...



TYPE



SENT

7/19/18 3:58 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT

IA - SLX 4563Y

BODY

Dear Peter, damages consistent, repair cost econom...





## Authorized

Type

🔗 Question

Message

Pls proceed to authorize OD repair. Excess: \$400

Reply



## Revised parts price authorized

Type

🔗 Question

Message

Hi Shirley, revised parts price authorized.

Reply



## IA - SLX 4563Y

Type

🔗 Question

Message

Hi Peter, IA updated & uploaded. Kindly informed part prices item no 29 changed. Thanks. From : Shirley Hiew

Reply

## ⏪ Typo - Excess should be \$4000

Type

🔗 Question

Message

I made a typo error. Excess should be \$4000 - refer to schedule.

Reply



## RE: Authorized

Type

🔗 Question

Message

Hi Peter, Confirmed Excess \$ 400.00? From : Shirley

Reply

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 30 July 2018 8:59 AM  
**To:** eva.kok@eurokars.com.sg; Admin A; Admin-D (LKKAuto); Hsiao Tong (LKKAuto); Rasul (LKKAuto)  
**Cc:** janice.syn@porsche.com.sg; rickteo@eurokars.com.sg; jobithomas@eurokars.com.sg  
**Subject:** RE: OD CLAIMS- SLX4563Y DOA 12/07/2018

Dear Eva,

As spoken, re-confirmed excess figure is \$ 4,000.00.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Thursday, 26 July 2018 1:10 PM  
**To:** eva.kok@eurokars.com.sg; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Cc:** janice.syn@porsche.com.sg; rickteo@eurokars.com.sg; jobithomas@eurokars.com.sg  
**Subject:** RE: OD CLAIMS- SLX4563Y DOA 12/07/2018

Dear Eva,

As spoken, we will re-check the excess figure with the insurance and update you once done.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Thursday, 26 July 2018 12:00 PM  
**To:** 'eva.kok@eurokars.com.sg' <eva.kok@eurokars.com.sg>; 'Admin A' <admin-a@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>; 'Rasul (LKKAuto)' <Rasul@lkkauto.com>  
**Cc:** 'janice.syn@porsche.com.sg' <janice.syn@porsche.com.sg>; 'rickteo@eurokars.com.sg' <rickteo@eurokars.com.sg>; 'jobithomas@eurokars.com.sg' <jobithomas@eurokars.com.sg>  
**Subject:** RE: OD CLAIMS- SLX4563Y DOA 12/07/2018

Dear Eva,

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 26 July 2018 12:00 PM  
**To:** eva.kok@eurokars.com.sg; Admin A; Admin-D (LKKAuto); Hsiao Tong (LKKAuto); Rasul (LKKAuto)  
**Cc:** janice.syn@porsche.com.sg; rickteo@eurokars.com.sg; jobithomas@eurokars.com.sg  
**Subject:** RE: OD CLAIMS- SLX4563Y DOA 12/07/2018

Dear Eva,

As instructed by our client, please proceed to repair the insured vehicle **SLX 4563Y (Excess \$ 400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]  
**Sent:** Thursday, 26 July 2018 10:21 AM  
**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Cc:** janice.syn@porsche.com.sg; rickteo@eurokars.com.sg; jobithomas@eurokars.com.sg  
**Subject:** RE: OD CLAIMS- SLX4563Y DOA 12/07/2018

Hi Shirley,

Kindly assist on the authorization repair for the above claims.

Thank you so much

Eva Kok  
Insurance Claims Officer  
Trans Eurokars Pte Ltd  
12 Sungei Kadut Avenue  
Singapore 729648  
Dir: +65 6360 2846 | Fax: +65 63602899 | Email: [eva.kok@eurokars.com.sg](mailto:eva.kok@eurokars.com.sg)  
Website: [www.eurokarsgroup.com](http://www.eurokarsgroup.com)

**\*\*\*DISCLAIMER\*\*\***

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.

Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

**Sent:** Monday, July 23, 2018 11:22 AM

**To:** Eva Kok <[eva.kok@eurokars.com.sg](mailto:eva.kok@eurokars.com.sg)>; 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; 'Admin-D (LKKAuto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; 'Hsiao Tong (LKKAuto)' <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; 'Rasul (LKKAuto)' <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>

**Cc:** Janice Syn <[janice.syn@porsche.com.sg](mailto:janice.syn@porsche.com.sg)>; Rick Teo Fu Shen <[rickteo@eurokars.com.sg](mailto:rickteo@eurokars.com.sg)>; Jobi Thomas <[jobithomas@eurokars.com.sg](mailto:jobithomas@eurokars.com.sg)>

**Subject:** RE: OD CLAIMS- SLX4563Y DOA 12/07/2018

Hi Eva,

Kindly informed we are still pending approval from insurance.

We will update you once done.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** [eva.kok@eurokars.com.sg](mailto:eva.kok@eurokars.com.sg) [<mailto:eva.kok@eurokars.com.sg>]

**Sent:** Monday, 23 July 2018 11:16 AM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>

**Cc:** [janice.syn@porsche.com.sg](mailto:janice.syn@porsche.com.sg); [rickteo@eurokars.com.sg](mailto:rickteo@eurokars.com.sg); [jobithomas@eurokars.com.sg](mailto:jobithomas@eurokars.com.sg)

**Subject:** RE: OD CLAIMS- SLX4563Y DOA 12/07/2018

Hi,

Any update on authorization repair for the above vehicle ?

Thank you

Eva Kok

Insurance Claims Officer

Trans Eurokars Pte Ltd

12 Sungei Kadut Avenue

Singapore 729648

Dir: +65 6360 2846 | Fax: +65 63602899 | Email: [eva.kok@eurokars.com.sg](mailto:eva.kok@eurokars.com.sg)

Website: [www.eurokarsgroup.com](http://www.eurokarsgroup.com)

\*\*\*DISCLAIMER\*\*\*

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.

Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.

---

**From:** Eva Kok

**Sent:** Wednesday, July 18, 2018 5:05 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Nivitha (LKK Auto) ([admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; 'Hsiao Tong (LKKAuto)' <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; 'Rasul (LKKAuto)' <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>

**Cc:** Janice Syn <[janice.syn@porsche.com.sg](mailto:janice.syn@porsche.com.sg)>; Rick Teo Fu Shen <[rickteo@eurokars.com.sg](mailto:rickteo@eurokars.com.sg)>; Jobi Thomas <[jobithomas@eurokars.com.sg](mailto:jobithomas@eurokars.com.sg)>

**Subject:** RE: OD CLAIMS- SLX4563Y DOA 12/07/2018

Hi All,

Please refer to the attached for your perusal.

Please let us have your authorization repair for the above vehicle.

Thank you

Eva Kok

Insurance Claims Officer

Trans Eurokars Pte Ltd

12 Sungei Kadut Avenue

Singapore 729648

Dir: +65 6360 2846 | Fax: +65 63602899 | Email: [eva.kok@eurokars.com.sg](mailto:eva.kok@eurokars.com.sg)

Website: [www.eurokarsgroup.com](http://www.eurokarsgroup.com)

\*\*\*DISCLAIMER\*\*\*

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.

Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.

---

**From:** Eva Kok

**Sent:** Tuesday, July 17, 2018 11:06 AM

**To:** 'motor.survey@axa.com.sg' <[motor.survey@axa.com.sg](mailto:motor.survey@axa.com.sg)>

**Cc:** Janice Syn <[janice.syn@porsche.com.sg](mailto:janice.syn@porsche.com.sg)>; Rick Teo Fu Shen <[rickteo@eurokars.com.sg](mailto:rickteo@eurokars.com.sg)>; Jobi Thomas <[jobithomas@eurokars.com.sg](mailto:jobithomas@eurokars.com.sg)>

**Subject:** OD CLAIMS- SLX4563Y DOA 12/07/2018

**OUR REF: SLX4563Y OWN DAMAGE CLAIM**

Dear Sir/Mdm,

Please arrange the survey of our client's vehicle. (Vehicle in workshop)

Attached is the ESTIMATE AND SAS REPORT for your perusal.

Thank you

Eva Kok  
Insurance Claims Officer  
Trans Eurokars Pte Ltd  
12 Sungei Kadut Avenue  
Singapore 729648  
Dir: +65 6360 2846 | Fax: +65 63602899 | Email: [eva.kok@eurokars.com.sg](mailto:eva.kok@eurokars.com.sg)  
Website: [www.eurokarsgroup.com](http://www.eurokarsgroup.com)



\*\*\*DISCLAIMER\*\*\*

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.  
Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

31 UBI AVE 1, #02-25 UBI INDUSTRIAL PARK, SINGAPORE 408033 TEL : (065) 62563361 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/09/2018

### Survey Details:

|                     |                                |
|---------------------|--------------------------------|
| Date of loss        | 12-Jul-18                      |
| Date of appointment | 17-Jul-18                      |
| Date of survey      | 18-Jul-18                      |
| Location of survey  | 12 SUNGEI KADUT AVE,<br>729648 |

### Vehicle Details:

|                      |                     |
|----------------------|---------------------|
| Claim Type:          | Own Damage          |
| Vehicle number       | SLX 4563Y           |
| Make and Model       | PORSCHE 987 BOXSTER |
| Date of registration | 28/3/2008           |
| Excess               | 4000                |
| Sum Insured          | \$110,000.00        |
| Parf Rebate          | \$43,594.00         |
| Nett Loss            | \$66,406.00         |

### Repair details:

|                  |           |
|------------------|-----------|
| Initial Estimate | 23,496.96 |
|------------------|-----------|

### Proposed/Revised repair cost:

|                         |             |
|-------------------------|-------------|
| Parts                   | \$6,517.28  |
| Check items (estimate)  |             |
| Labour                  | \$10,910.00 |
| Total                   | \$17,427.28 |
| Lump Sum(if applicable) | \$          |

|                           |        |
|---------------------------|--------|
| Number of days for repair | 7 DAYS |
|---------------------------|--------|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607158R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408943 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

PART PRICES ITEM NO 29 CHANGED.

**Mandate:**

| Liability(TP)        | %       |             |
|----------------------|---------|-------------|
| Proposed repair cost | \$      |             |
| Loss of use          | \$      | no. of days |
| Loss of rental       | \$      | no. of days |
| Loss of income       | \$      | no. of days |
| LTA search fees      | \$      |             |
| Others               | \$      |             |
| Proposed Total       | #VALUE! |             |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

11 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408903 TEL : (66) 62563561 FAX : (66) 62564318

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 19/07/2018

### Survey Details:

|                     |                                         |
|---------------------|-----------------------------------------|
| Date of loss        | 12-Jul-18                               |
| Date of appointment | 17-Jul-18                               |
| Date of survey      | 18-Jul-18                               |
| Location of survey  | 12 SUNGEI KADUT AVE<br>SINGAPORE 729648 |

### Vehicle Details:

|                      |                     |
|----------------------|---------------------|
| Claim Type:          | Own Damage          |
| Vehicle number       | SLX 4563Y           |
| Make and Model       | PORSCHE 987 BOXSTER |
| Date of registration | 28/3/2008           |
| Excess               | 4000                |
| Market Value         | \$110,000           |
| Parf Rebate          | \$43,594            |
| Nett Loss            | \$66,406            |

### Repair details:

|                  |          |
|------------------|----------|
| Initial Estimate | 22878.16 |
|------------------|----------|

### Proposed/Revised repair cost:

|                         |                    |
|-------------------------|--------------------|
| Parts                   | \$4,578.32         |
| Check items (estimate)  | \$1,436.72         |
| Labour                  | \$10,910.00        |
| <b>Total</b>            | <b>\$16,925.04</b> |
| Lump Sum(if applicable) |                    |

|                           |               |
|---------------------------|---------------|
| Number of days for repair | <u>7 DAYS</u> |
|---------------------------|---------------|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 3, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 409933 TEL : (65) 62563561 FAX : (65) 62564315

### Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL.WE  
HAVE NOT AUTHORISE REPAIR.

### Mandate:

| Liability(TP)         | %              |             |
|-----------------------|----------------|-------------|
| Proposed repair cost  | \$             |             |
| Loss of use           | \$             | no. of days |
| Loss of rental        | \$             | no. of days |
| Loss of income        | \$             | no. of days |
| LTA search fees       | \$             |             |
| Others                | \$             |             |
| <b>Proposed Total</b> | <b>#VALUE!</b> |             |

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT                                                           |                                  |
|------------------------------------------------------------------------------|----------------------------------|
| Date Of Report                                                               | 14/07/2018 10:19                 |
| Date Of Accident                                                             | 12/07/2018 20:00                 |
| Exact Location Of Accident                                                   | AYE TOWARDS CLEMENTI             |
| Country/State of Loss                                                        | SINGAPORE                        |
| DETAILS OF OWN VEHICLE                                                       |                                  |
| Vehicle Registration Number                                                  | SLX4563Y                         |
| <b>Insured/Policyholder</b>                                                  |                                  |
| Name Of Registered Owner                                                     | GOVINDASAMY NAIDU SHURENDRA BABU |
| NRIC No                                                                      | S6939550C                        |
| Email Address                                                                | NOEMAIL                          |
| Mobile Phone No                                                              | (LOCAL) +65-96715041             |
| Alternative Phone No                                                         | OTHERS-96181924                  |
| <b>Vehicle Particulars</b>                                                   |                                  |
| Manufacturer                                                                 | PORSCHE                          |
| Model                                                                        | BOXSTER-TIPTRONIC (A)            |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE                      |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES                              |
| If No, Please state action to be taken                                       |                                  |
| Vehicle Category                                                             | PRIVATE CAR                      |
| <b>Insurance Company</b>                                                     |                                  |
| Name of Insurance Company                                                    | AXA INSURANCE PTE LTD            |
| Type Of Coverage                                                             | COMPREHENSIVE                    |
| Fleet Policy                                                                 | NO                               |
| Policy Number                                                                | GA346908                         |
| Cover Note Number                                                            | 23/04/2018 - 27/09/2019          |
| <b>Driver</b>                                                                |                                  |
| Name of Driver                                                               | LIM WEI YEN SHARON               |
| NRIC No                                                                      | S6836500G                        |
| Date Of Birth                                                                | 08/09/1968                       |
| Occupation                                                                   | INDOOR                           |
| Date Of Driving Pass                                                         | 14/02/1992                       |
| Driving Experience                                                           | 26 YEARS AND 4 MONTHS            |
| Gender                                                                       | FEMALE                           |
| Mobile Number                                                                | (LOCAL) +65-96181924             |
| Fax Number                                                                   |                                  |
| Contact Number                                                               | OTHERS-96715041                  |
| EEmail Address                                                               | SHARON.NAIDULIM@GMAIL.COM        |

|                                                     |                               |
|-----------------------------------------------------|-------------------------------|
| Address                                             | 15 ANG MO KIO AVE 9<br>#08-02 |
| Postcode                                            | 569765                        |
| Was driver an employee of the Insured's Company     | NO                            |
| If No, Relationship of the Driver with the Insured  | SPOUSE                        |
| Vehicle Registration Number of Driver's Own Vehicle | -                             |
|                                                     | -                             |
|                                                     | -                             |
| Insurance Company of Driver's Own Vehicle           | -                             |
|                                                     | -                             |
|                                                     | -                             |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Number of vehicles involved in the accident                                                 |     |
| Was any body injured in the Accident?                                                       | NO  |
| Was any injured conveyed to hospital by ambulance?                                          | NO  |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | YES |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                           |
|-------------------------------------|---------------------------|
| Vehicle Registration Number         | SLM8296A                  |
| Vehicle Make/Model/Colour           |                           |
| Details Of Properties               |                           |
| Vehicle Category                    | PRIVATE CAR               |
| Name of Driver                      | GOH TAT LEONG (WU DALONG) |
| NRIC/Passport Number                | S8230926H                 |
| Contact Number                      |                           |
| Address                             |                           |
| Postcode                            |                           |
| Insurance Company Name              |                           |
| Nature Of Damage                    |                           |
| No. Of Passenger (Including Driver) |                           |

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:




Reporting Officer/Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

Date of accident: 12/7/18 Time: 8pm Location: AYE (towards Clementi)  
 My Vehicle A: SLX 4563 Y Vehicle B: SLM 8296 A Vehicle C: N.A.

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

at Merchant Road  
 Entered AYE (towards Clementi), filtered to extreme right lane. Traffic was moving normally and smoothly. I was behind a Honda Shuttle (SLM 8296 A) at a safe distance. The Honda stopped suddenly, I was unable to brake in time and hit the rear of the Honda.

Shen

☐ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :  
 Email address : shen.naidulim@gmail.com  
 & myself :  
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Shen Naidulim*

Policyholder's Signature  
 Date & Time:

*[Signature]*

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:



Reporting Company Personnel's Signature  
 Name:  
 NRIC/FIN No.:



PORSCHE

STUTTGART AUTO PTE LTD  
NO:12 SUNGEI KADUT, SINGAPORE 729648  
ESTIMATE COST OF REPAIRS



|                              |                     |                   |                                     |                         |              |
|------------------------------|---------------------|-------------------|-------------------------------------|-------------------------|--------------|
| <b>AXA INSURANCE PTE LTD</b> |                     | <b>NAME :</b>     | MR GOVINDASAMY NAIDU SHURENDRA BABU | <b>WIP :</b>            | 35775        |
| 8 SHENTON WAY                |                     | <b>ADDRESS :</b>  | 15 ANG MO KIO AVE 9                 | <b>EXCESS :</b>         |              |
| #24-01 AXA TOWER             |                     |                   | #08-02                              | <b>DATE:</b>            | 17.07.2018   |
| SINGAPORE 068811             |                     |                   | SINGAPORE 569765                    |                         |              |
| <b>ATTN. :</b>               | MOTOR CLAIM DEPT    | <b>TEL :</b>      |                                     |                         |              |
| <b>FAX :</b>                 | 68804838 / 68804739 |                   |                                     |                         |              |
| <b>VEH NO :</b>              | SLX4563Y            | <b>DATE IN :</b>  |                                     | <b>CONTACT PERSON :</b> | EVA 63602846 |
| <b>CHASSIS NO :</b>          | WP0ZZZ98Z8U701710   | <b>MILEAGE :</b>  |                                     | <b>TYPE OF CLAIM :</b>  | OD           |
| <b>MODEL :</b>               | Boxster             | <b>DATE REG.:</b> | 28.03.2008                          | <b>POLICY NO. :</b>     |              |

NATURE OF WORKS

| S/NO             | Parts Description                   |              |                                           | REVISED          | PRICES                     |
|------------------|-------------------------------------|--------------|-------------------------------------------|------------------|----------------------------|
|                  | QTY                                 |              |                                           |                  |                            |
| 1                | FRONT FENDER (RH)                   | 1            | P987-503-932-00-GRV <i>Repair damaged</i> | X                | \$ 949.80                  |
| 2                | FENDER RIVET                        | 3            | P999-591-712-40-                          | X                | \$ 3.60                    |
| 3                | FUEL CAP LID HINGE                  | 1            | P997-201-063-00-                          | ✓ <i>3. CRAS</i> | \$ 38.20                   |
| 4                | FRONT BUMPER                        | 1            | P987-505-191-36-                          | DE-              | \$ 1,590.40                |
| 5                | FRONT BUMPER GRILLE FRAME RH        | 1            | P987-505-554-00-01C                       | ✓ <i>3. CRAS</i> | \$ 155.50                  |
| 6                | FRONT BUMPER GUIDE PLATE            | <i>1 PL</i>  | P987-505-709-00-                          | M-               | \$ 24.40 <i>12.20</i>      |
| 7                | FRONT BUMPER FIXING CLIP            | 1            | P981-505-719-01-                          | ✓                | \$ 20.30                   |
| 8                | TOW COVER                           | 1            | P987-505-703-00-G2X                       | CRAS             | \$ 32.70                   |
| 9                | LICENSE PLATE BRACKET               | 1            | P987-701-105-00-01C                       | cut              | \$ 31.80                   |
| 10               | FRONT BUMPER REINFORCEMENT          | 1            | P997-505-141-06-                          | ✓ <i>3. PR</i>   | \$ 362.20                  |
| 11               | REINFORCEMENT BOLT                  | 2            | P900-378-088-01-                          | ✓ <i>3. new</i>  | \$ 22.80                   |
| 12               | IMPACT ABSORBER-FRT                 | 2            | P997-505-319-00-                          | ✓ <i>3. PR</i>   | \$ 498.40                  |
| 13               | SCREW                               | 6            | P900-378-351-01-                          | ✓ <i>3. new</i>  | \$ 25.20                   |
| 14               | SEAL-IMPACT ABSORBER FRT            | 2            | P997-505-751-02-                          | ✓ <i>3. new</i>  | \$ 15.20                   |
| 15               | FRONT BUMPER RETAINING STRIP CENTER | 1            | P997-505-531-00-                          | ✓ <i>3. new</i>  | \$ 101.90                  |
| 16               | BONNET                              | 1            | P997-511-011-02-GRV                       | PR               | \$ 1,910.60                |
| 17               | BONNET DAMPER                       | 2            | P997-511-551-01-                          | X                | \$ 147.40                  |
| 18               | BONNET HINGE LH                     | 1            | P997-511-151-01-                          | X                | \$ 133.80                  |
| 19               | BONNET HINGE RH                     | 1            | P997-511-152-01-                          | X <i>3. new</i>  | \$ 133.80                  |
| 20               | FENDER TOP GARINSH RH               | 1            | P997-572-466-03-02A                       | X                | \$ 69.70                   |
| 21               | FRONT BUMPER TOP GARNISH CENTER     | 1            | P997-504-811-04-FMT                       | cut              | \$ 57.10                   |
| 22               | BONNET WEATHER STRIP                | 1            | L997-511-611-01-                          | X <i>3. new</i>  | \$ 153.60                  |
| 23               | TOP GARNISH VELCRO FASTENER         | <i>3 pcs</i> | P999-902-049-40-                          | new              | \$ 20.40 <i>6120</i>       |
| 24               | FRONT BONNET LOCK PLATE             | 1            | P996-511-653-00-                          | PR               | \$ 25.40                   |
| 25               | SCREW                               | 2            | P900-075-466-01-                          | new              | \$ 4.20                    |
| 26               | BONNET LOCK                         | 1            | P997-511-053-01-                          | PR               | \$ 265.10                  |
| 27               | BONNET LOCK ACTUATOR                | 1            | P997-511-117-00-                          | cut              | \$ 105.00                  |
| 28               | HEADLAMP NOZZLE RH                  | 1            | P997-628-133-01-                          | X <i>3. new</i>  | \$ 186.50                  |
| 29               | HEADLAMP (RH), HALOGEN              | 1            | P987-631-164-11-                          | new              | \$ 1,257.70 <i>2031.20</i> |
| 30               | FOG LAMP LH                         | 1            | P987-631-081-05-                          | ✓ <i>3. CRAS</i> | \$ 390.00                  |
| 31               | FOG LAMP RH                         | 1            | P987-631-082-05-                          | CRAS             | \$ 390.00                  |
| TOTAL PARTS      |                                     |              |                                           |                  | \$ 9,122.70 <i>9866.2</i>  |
| LESS 20%         |                                     |              |                                           |                  | \$ 1,824.54                |
| TOTAL PARTS COST |                                     |              |                                           |                  | \$ 7,298.16 <i>7916.9</i>  |

|   | Labour Description                                                                                                    |                    |                         |
|---|-----------------------------------------------------------------------------------------------------------------------|--------------------|-------------------------|
| 1 | TO REMOVE / REPLACE FRONT BUMPER, BONNET, RH FRONT FENDER & TO REPAIR FRONT END PANEL AREAS AFFECTED BY THE ACCIDENT. | 5460               | \$ <del>7,880.00</del>  |
| 2 | TO RESPRAY FRONT BUMPER, BONNET, RH FRONT FENDER & FRONT END PANEL.                                                   | 4600               | \$ <del>5,080.00</del>  |
| 3 | TO CARRY-OUT BODY CAVITY PRESERVATION.                                                                                | 100                | \$ <del>250.00</del>    |
| 4 | TO REMOVE & REFIT CARPET & TRIMS ON THE FRONT COMPARTMENT TO GIVE WAY TO THE REPAIR ON THE FRONT END PANEL.           | XAN                | \$ 1,560.00             |
| 5 | TO SUPPLY 1 PC FRONT NUMBER PLATE.                                                                                    | NETT ✓             | \$ <del>300</del> 70.00 |
| 6 | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                                                                    | 150                | \$ <del>250.00</del>    |
| 7 | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                                                                       | NETT 480           | \$ <del>600.00</del>    |
| 8 | TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.                                                            |                    | TBA                     |
| 9 | SUNDRIES.                                                                                                             | NETT               | \$ 50.00                |
|   |                                                                                                                       | TOTAL LABOUR       | \$ - \$ 15,580.00       |
|   |                                                                                                                       | TOTAL PARTS        | \$ - \$ 7,298.16        |
|   |                                                                                                                       | TOTAL              | \$ - \$ 22,878.16       |
|   |                                                                                                                       | LESS EXCESS        | \$ - \$ -               |
|   |                                                                                                                       | TOTAL AFTER EXCESS | \$ -                    |
|   |                                                                                                                       | GST 7%             | \$ - \$ -               |
|   |                                                                                                                       | GRAND TOTAL        | \$ - \$ -               |

03496

#### REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey (before/after spray painting)
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Phone  
Hp 90010068

7 days

P/P

18/07/18 @ 1630

Excess: 4000

Reset

Resay 64 point

27/7/18



PORSCHE

STUTTGART AUTO PTE LTD  
NO:12 SUNGEI KADUT, SINGAPORE 729648  
FINALIZATION COST OF REPAIRS

EUROKARS GROUP

| AXA INSURANCE PTE LTD<br>8 SHENTON WAY<br>#24-01 AXA TOWER<br>SINGAPORE 068811<br>ATTN : MOTOR CLAIM DEPT<br>FAX : 68804838 / 68804739 |                                     | NAME : MR GOVINDASAMY NAIDU SHURENDRA BABU<br>ADDRESS : 15 ANG MO KIO AVE 9<br>#08-02<br>SINGAPORE 569765<br>TEL : |                     | WIP : 35775<br>EXCESS :<br>DATE: 17.07.2018 |              |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|--------------------------------------------------------------------------------------------------------------------|---------------------|---------------------------------------------|--------------|
| VEH NO :                                                                                                                               | SLX4563Y                            | DATE IN :                                                                                                          |                     | CONTACT PERSON :                            | EVA 63602846 |
| CHASSIS NO :                                                                                                                           | WPOZZZ98Z8U701710                   | MILEAGE :                                                                                                          |                     | TYPE OF CLAIM :                             | OD           |
| MODEL :                                                                                                                                | Boxster                             | DATE REG.:                                                                                                         | 28.03.2008          | POLICY NO. :                                |              |
| NATURE OF WORKS                                                                                                                        |                                     |                                                                                                                    |                     |                                             |              |
| S/NO                                                                                                                                   | Parts Description                   |                                                                                                                    |                     | REVISED                                     | PRICES       |
|                                                                                                                                        | QTY                                 |                                                                                                                    |                     |                                             |              |
| 1                                                                                                                                      | FRONT FENDER (RH)                   | 1                                                                                                                  | P987-503-932-00-GRV | \$ -                                        | \$ 949.80    |
| 2                                                                                                                                      | FENDER RIVET                        | 3                                                                                                                  | P999-591-712-40-    | \$ -                                        | \$ 3.60      |
| 3                                                                                                                                      | FUEL CAP LID HINGE                  | 1                                                                                                                  | P997-201-063-00-    | \$ 38.20                                    | \$ 38.20     |
| 4                                                                                                                                      | FRONT BUMPER                        | 1                                                                                                                  | P987-505-191-36-    | \$ 1,590.40                                 | \$ 1,590.40  |
| 5                                                                                                                                      | FRONT BUMPER GRILLE FRAME RH        | 1                                                                                                                  | P987-505-554-00-01C | \$ 155.50                                   | \$ 155.50    |
| 6                                                                                                                                      | FRONT BUMPER GUIDE PLATE            | 1                                                                                                                  | P987-505-709-00-    | \$ 12.20                                    | \$ 24.40     |
| 7                                                                                                                                      | FRONT BUMPER FIXING CLIP            | 1                                                                                                                  | P981-505-719-01-    | \$ 20.30                                    | \$ 20.30     |
| 8                                                                                                                                      | TOW COVER                           | 1                                                                                                                  | P987-505-703-00-G2X | \$ 32.70                                    | \$ 32.70     |
| 9                                                                                                                                      | LICENSE PLATE BRACKET               | 1                                                                                                                  | P987-701-105-00-01C | \$ 31.80                                    | \$ 31.80     |
| 10                                                                                                                                     | FRONT BUMPER REINFORCEMENT          | 1                                                                                                                  | P997-505-141-06-    | \$ 362.20                                   | \$ 362.20    |
| 11                                                                                                                                     | REINFORCEMENT BOLT                  | 2                                                                                                                  | P900-378-088-01-    | \$ 22.80                                    | \$ 22.80     |
| 12                                                                                                                                     | IMPACT ABSORBER-FRT                 | 2                                                                                                                  | P997-505-319-00-    | \$ 498.40                                   | \$ 498.40    |
| 13                                                                                                                                     | SCREW                               | 6                                                                                                                  | P900-378-351-01-    | \$ 25.20                                    | \$ 25.20     |
| 14                                                                                                                                     | SEAL-IMPACT ABSORBER FRT            | 2                                                                                                                  | P997-505-751-02-    | \$ 15.20                                    | \$ 15.20     |
| 15                                                                                                                                     | FRONT BUMPER RETAINING STRIP CENTER | 1                                                                                                                  | P997-505-531-00-    | \$ 101.90                                   | \$ 101.90    |
| 16                                                                                                                                     | BONNET                              | 1                                                                                                                  | P997-511-011-02-GRV | \$ 1,910.60                                 | \$ 1,910.60  |
| 17                                                                                                                                     | BONNET DAMPER                       | 2                                                                                                                  | P997-511-551-01-    | \$ -                                        | \$ 147.40    |
| 18                                                                                                                                     | BONNET HINGE LH                     | 1                                                                                                                  | P997-511-151-01-    | \$ -                                        | \$ 133.80    |
| 19                                                                                                                                     | BONNET HINGE RH                     | 1                                                                                                                  | P997-511-152-01-    | \$ -                                        | \$ 133.80    |
| 20                                                                                                                                     | FENDER TOP GARINSH RH               | 1                                                                                                                  | P997-572-466-03-02A | \$ -                                        | \$ 69.70     |
| 21                                                                                                                                     | FRONT BUMPER TOP GARNISH CENTER     | 1                                                                                                                  | P997-504-811-04-FMT | \$ 57.10                                    | \$ 57.10     |
| 22                                                                                                                                     | BONNET WEATHER STRIP                | 1                                                                                                                  | L997-511-611-01-    | \$ -                                        | \$ 153.60    |
| 23                                                                                                                                     | TOP GARNISH VELCRO FASTENER         | 12                                                                                                                 | P999-902-049-40-    | \$ 61.20                                    | \$ 20.40     |
| 24                                                                                                                                     | FRONT BONNET LOCK PLATE             | 1                                                                                                                  | P996-511-653-00-    | \$ 25.40                                    | \$ 25.40     |
| 25                                                                                                                                     | SCREW                               | 2                                                                                                                  | P900-075-466-01-    | \$ 4.20                                     | \$ 4.20      |
| 26                                                                                                                                     | BONNET LOCK                         | 1                                                                                                                  | P997-511-053-01-    | \$ 265.10                                   | \$ 265.10    |
| 27                                                                                                                                     | BONNET LOCK ACTUATOR                | 1                                                                                                                  | P997-511-117-00-    | \$ 105.00                                   | \$ 105.00    |
| 28                                                                                                                                     | HEADLAMP NOZZLE RH                  | 1                                                                                                                  | P997-628-133-01-    | \$ -                                        | \$ 186.50    |
| 29                                                                                                                                     | HEADLAMP (RH), HALOGEN              | 1                                                                                                                  | P987-631-158-13     | \$ 2,031.20                                 | \$ 1,257.70  |
| 30                                                                                                                                     | FOG LAMP LH                         | 1                                                                                                                  | P987-631-081-05-    | \$ 390.00                                   | \$ 390.00    |
| 31                                                                                                                                     | FOG LAMP RH                         | 1                                                                                                                  | P987-631-082-05-    | \$ 390.00                                   | \$ 390.00    |
| TOTAL PARTS                                                                                                                            |                                     |                                                                                                                    |                     | \$ 8,146.60                                 | \$ 9,122.70  |
| LESS 20%                                                                                                                               |                                     |                                                                                                                    |                     | \$ 1,629.32                                 | \$ 1,824.54  |

|   |                                                                                                                       |                           |                     |                     |
|---|-----------------------------------------------------------------------------------------------------------------------|---------------------------|---------------------|---------------------|
|   |                                                                                                                       | <b>TOTAL PARTS COST</b>   | <b>\$ 6,517.28</b>  | <b>\$ 7,298.16</b>  |
|   |                                                                                                                       |                           |                     |                     |
|   |                                                                                                                       | <b>Labour Description</b> |                     |                     |
|   |                                                                                                                       |                           |                     |                     |
| 1 | TO REMOVE / REPLACE FRONT BUMPER, BONNET, RH FRONT FENDER & TO REPAIR FRONT END PANEL AREAS AFFECTED BY THE ACCIDENT. |                           | \$ 5,460.00         | \$ 7,800.00         |
|   |                                                                                                                       |                           |                     |                     |
| 2 | TO RESPRAY FRONT BUMPER, BONNET, RH FRONT FENDER & FRONT END PANEL.                                                   |                           | \$ 4,600.00         | \$ 5,000.00         |
|   |                                                                                                                       |                           |                     |                     |
| 3 | TO CARRY-OUT BODY CAVITY PRESERVATION.                                                                                |                           | \$ 100.00           | \$ 250.00           |
|   |                                                                                                                       |                           |                     |                     |
| 4 | TO REMOVE & REFIT CARPET & TRIMS ON THE FRONT COMPARTMENT TO GIVE WAY TO THE REPAIR ON THE FRONT END PANEL.           |                           | \$ -                | \$ 1,560.00         |
|   |                                                                                                                       |                           |                     |                     |
| 5 | TO SUPPLY 1 PC FRONT NUMBER PLATE.                                                                                    |                           | \$ 70.00            | \$ 70.00            |
|   |                                                                                                                       |                           |                     |                     |
| 6 | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                                                                    |                           | \$ 150.00           | \$ 250.00           |
|   |                                                                                                                       |                           |                     |                     |
| 7 | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                                                                       |                           | \$ 480.00           | \$ 600.00           |
|   |                                                                                                                       |                           |                     |                     |
| 8 | TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.                                                            |                           | \$ -                | TBA                 |
|   |                                                                                                                       |                           |                     |                     |
| 9 | SUNDRIES.                                                                                                             |                           | \$ 50.00            | \$ 50.00            |
|   |                                                                                                                       |                           |                     |                     |
|   |                                                                                                                       | <b>TOTAL LABOUR</b>       | <b>\$ 10,910.00</b> | <b>\$ 15,580.00</b> |
|   |                                                                                                                       | <b>TOTAL PARTS</b>        | <b>\$ 6,517.28</b>  | <b>\$ 7,298.16</b>  |
|   |                                                                                                                       | <b>TOTAL</b>              | <b>\$ 17,427.28</b> | <b>\$ 22,878.16</b> |
|   |                                                                                                                       | <b>LESS EXCESS</b>        | <b>\$ -</b>         | <b>\$ -</b>         |
|   |                                                                                                                       | <b>TOTAL AFTER EXCESS</b> | <b>\$ 17,427.28</b> |                     |
|   |                                                                                                                       | <b>GST 7%</b>             | <b>\$ 1,219.91</b>  | <b>\$ -</b>         |
|   |                                                                                                                       | <b>GRAND TOTAL</b>        | <b>\$ 18,647.19</b> | <b>\$ -</b>         |

NUMBER OF DAYS: 7 WORKING DAYS(EXCLUDE WAITING FOR PARTS,SURVEY,AUTHORIZATION,SATURDAY,SUNDAY & PH)

| Line | T | Product             | Description                           | Quantity | Price  | Disc% | Total         |
|------|---|---------------------|---------------------------------------|----------|--------|-------|---------------|
| 1    | L | CST                 | OD CLAIM UNDER AXA                    | 0        | 0      | 0     | 0             |
| 5    | P | P987-505-191-36-    | LINING                                | 1        | 1590.4 | 20    | \$ 1,590.40   |
| 6    | P | P987-505-554-00-01C | GRILLE FRAME                          | 1        | 155.5  | 20    | \$ 155.50     |
| 7    | P | P987-505-709-00-    | GUIDE PLATE                           | 1        | 12.2   | 20    | \$ 12.20      |
| 8    | P | P981-505-719-01-    | P987-505-719-00-/FIXING DEVICE        | 1        | 20.3   | 20    | \$ 20.30      |
| 9    | P | P987-505-703-00-G2X | CAP                                   | 1        | 32.7   | 20    | \$ 32.70      |
| 10   | P | P987-701-105-00-01C | LICENSE PLATE BRACKET                 | 1        | 31.8   | 20    | \$ 31.80      |
| 11   | P | P997-505-141-06-    | P997-505-141-02-/BUMPER REINFORCEME   | 1        | 362.2  | 20    | \$ 362.20     |
| 12   | P | P900-378-088-01-    | P900-378-088-09-/BOLT-HEX HEAD (M12 X | 2        | 11.4   | 20    | \$ 22.80      |
| 13   | P | P997-505-319-00-    | IMPACT ABSORBER-FRT                   | 2        | 249.2  | 20    | \$ 498.40     |
| 14   | P | P900-378-351-01-    | SCREW                                 | 6        | 4.2    | 20    | \$ 25.20      |
| 15   | P | P997-505-751-02-    | SEAL-IMPACT ABSORBER FRT              | 2        | 7.6    | 20    | \$ 15.20      |
| 16   | P | P997-505-531-00-    | RETAINING STRIP                       | 1        | 101.9  | 20    | \$ 101.90     |
| 17   | P | P997-511-011-02-GRV | P997-511-011-00-GRV/BONNET            | 1        | 1910.6 | 20    | \$ 1,910.60   |
| 22   | P | P997-504-811-04-FMT | P997-504-811-03-FMT/TRIM              | 1        | 57.1   | 20    | \$ 57.10      |
| 24   | P | P999-902-049-40-    | VELCRO FASTENER                       | 12       | 5.1    | 20    | \$ 61.20      |
| 25   | P | P996-511-653-00-    | FRONT BONNET LOCK COVER               | 1        | 25.4   | 20    | \$ 25.40      |
| 26   | P | P900-075-466-01-    | P900-075-466-09-/SCREW                | 2        | 2.1    | 20    | \$ 4.20       |
| 27   | P | P997-511-053-01-    | P997-511-053-00-/LOCK, LOWER PART     | 1        | 265.1  | 20    | \$ 265.10     |
| 28   | P | P997-511-117-00-    | ACTUATOR                              | 1        | 105    | 20    | \$ 105.00     |
| 31   | P | P987-631-081-05-    | P987-631-081-04-/ADDITIONAL HEADLAMP  | 1        | 390    | 20    | \$ 390.00     |
| 32   | P | P987-631-082-05-    | P987-631-082-04-/ADDITIONAL HEADLAMP  | 1        | 390    | 20    | \$ 390.00     |
| 34   | P | P997-201-063-00-    | HINGE, FUEL CAP LID                   | 1        | 38.2   | 20    | \$ 38.20      |
| 35   | P | P987-631-158-13-    | HEADLAMP XENON (RH)                   | 1        | 2031.2 | 20    | \$ 2,031.20   |
| 36   | L | EXC                 | Insurance Excess                      | -4000    | 1      | 0     | \$ (4,000.00) |
| 37   | L | EXC                 | Insurance Excess                      | 4000     | 1      | 0     | \$ 4,000.00   |

\$ 8,146.60



PORSCHE

**AXA INSURANCE PTE LTD**  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811  
**ATTN : MOTOR CLAIMS DEPARTMENT**

DATE: 24/09/2018

Car Regn No : **SLX4563Y**

**Accident involving SLX4563Y & SLM8296A on 12/07/2018**

**Own Damage Claim**

Dear Sirs

The repairs have been completed for **SLX4563Y**. We submit the following documents for your perusal :

|                                       |                     |
|---------------------------------------|---------------------|
| 1) Invoice No: <b>13204599</b>        | <b>\$ 14,367.19</b> |
| 2) Discharge voucher signed by client |                     |
| <b>TOTAL</b>                          | <b>\$ 14,367.19</b> |

Please pay **Stuttgart Auto Pte Ltd** the sum of **\$14,367.19** as soon as possible and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648.**

Yours faithfully,

**Stanley Ngu**  
**Manager - Body & Paint Division**  
DID: 63602845  
FAX: 63602899  
e-mail: stanley@eurokars.com.sg

**Eurokars Centre**

12 Sungei Kadut Avenue  
Singapore 729648  
Telephone: (65) 6363 0911  
Fax: (65) 6363 3911



-P

**PORSCHE****INSURANCE INVOICE**

GST Reg No:M90364005A

CODE: A0031 AXA  
 CUSTOMER: AXA INSURANCE PTE LTD  
 ADDRESS: 8 Shenton Way  
 #24-01 AXA Tower  
 Singapore 068811

PAGE NO: 1  
 DOCUMENT NO: 13204599  
 JOB NO: 35775  
 DATE IN: 14/07/2018  
 DATE PRINTED: 19/09/2018  
 CSO/OP CODE: Janice Syn  
 SVC MNT EXP: 27/03/2013

MODEL: Boxster  
 CHASSIS NO: WP0ZZZ98Z8U701710  
 ENGINE NO: 65806972  
 DESCRIPTION: Own Damaged Claim

REGN NO: SLX4563Y  
 REGN DATE: 28/03/2008  
 MILEAGE: 37880

| Item            | Description                                                                                                           | Unit | U/Price | Disc% | Con% | Amount   |
|-----------------|-----------------------------------------------------------------------------------------------------------------------|------|---------|-------|------|----------|
| CST             | OD CLAIM UNDER AXA                                                                                                    |      |         | 0.00  |      | 0.00     |
| EXC             | Insurance Excess                                                                                                      |      |         | 0.00  |      | -4000.00 |
| SUB             | TO REMOVE / REPLACE FRONT BUMPER, BONNET, RH FRONT FENDER & TO REPAIR FRONT END PANEL AREAS AFFECTED BY THE ACCIDENT. |      |         | 0.00  |      | 5460.00  |
| SUB             | TO RESPRAY FRONT BUMPER, BONNET, RH FRONT FENDER & FRONT END PANEL.                                                   |      |         | 0.00  |      | 4600.00  |
| SUB             | TO CARRY-OUT BODY CAVITY PRESERVATION.                                                                                |      |         | 0.00  |      | 100.00   |
| SUB             | TO SUPPLY 1 PC FRONT NUMBER PLATE.                                                                                    |      |         | 0.00  |      | 70.00    |
| SUB             | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                                                                    |      |         | 0.00  |      | 150.00   |
| SUB             | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                                                                       |      |         | 0.00  |      | 480.00   |
| SUB             | SUNDRIES.                                                                                                             |      |         | 0.00  |      | 50.00    |
| 900-075-466-01- | SCREW                                                                                                                 | 2    | 2.10    | 20.00 |      | 3.30     |
| 900-378-088-01- | BOLT-HEX HEAD (M12 X 100)                                                                                             | 2    | 11.40   | 20.00 |      | 18.20    |
| 900-378-351-01- | SCREW                                                                                                                 | 6    | 4.20    | 20.00 |      | 20.10    |

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER  
 NO:

Customer Signature

Porsche Centre Singapore  
 29 Leng Kee Road Tel: (65) 6472 4433  
 Singapore 159099

Aftersales Centre  
 27A Tanjong Penjuru Tel: (65) 6331 0700  
 Singapore 609042

**STUTTGART AUTO PTE LTD**

Authorized Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd  
 Eurokars Group  
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

**PORSCHE****INSURANCE INVOICE**

GST Reg No:M90364005A

CODE: A0031 AXA  
 CUSTOMER: AXA INSURANCE PTE LTD  
 ADDRESS: 8 Shenton Way  
 #24-01 AXA Tower  
 Singapore 068811

MODEL: Boxster  
 CHASSIS NO: WP0ZZZ98Z8U701710  
 ENGINE NO: 65806972  
 DESCRIPTION: Own Damaged Claim

PAGE NO: 2  
 DOCUMENT NO: 13204599  
 JOB NO: 35775  
 DATE IN: 14/07/2018  
 DATE PRINTED: 19/09/2018  
 CSO/OP CODE: Janice Syn  
 SVC MNT EXP: 27/03/2013  
 EXT. WTY: 30/03/2012  
 REGN NO: SLX4563Y  
 REGN DATE: 28/03/2008  
 MILEAGE: 37880

| Item               | Description              | Unit | U/Price | Disc% | Con% | Amount |
|--------------------|--------------------------|------|---------|-------|------|--------|
| 981-505-719-01-    | FIXING DEVICE            | 1    | 20.30   | 20.00 |      | 16.2   |
| 987-505-191-36-    | LINING                   | 1    | 1590.40 | 20.00 |      | 1272.3 |
| 987-505-554-00-01C | GRILLE FRAME             | 1    | 155.50  | 20.00 |      | 124.4  |
| 987-505-703-00-G2X | CAP                      | 1    | 32.70   | 20.00 |      | 26.1   |
| 987-505-709-00-    | GUIDE PLATE              | 1    | 12.20   | 20.00 |      | 9.7    |
| 987-631-081-05-    | ADDITIONAL HEADLAMP      | 1    | 390.00  | 20.00 |      | 312.0  |
| 987-631-082-05-    | ADDITIONAL HEADLAMP      | 1    | 390.00  | 20.00 |      | 312.0  |
| 987-631-158-13-    | HEADLAMP XENON (RH)      | 1    | 2031.20 | 20.00 |      | 1624.9 |
| 987-701-105-00-01C | LICENSE PLATE BRACKET    | 1    | 31.80   | 20.00 |      | 25.4   |
| 996-511-653-00-    | FRONT BONNET LOCK COVER  | 1    | 25.40   | 20.00 |      | 20.3   |
| 997-201-063-00-    | HINGE, FUEL CAP LID      | 1    | 38.20   | 20.00 |      | 30.5   |
| 997-504-811-04-FMT | TRIM                     | 1    | 57.10   | 20.00 |      | 45.6   |
| 997-505-141-06-    | BUMPER REINFORCEMENT     | 1    | 362.20  | 20.00 |      | 289.7  |
| 997-505-319-00-    | IMPACT ABSORBER-FRT      | 2    | 249.20  | 20.00 |      | 398.7  |
| 997-505-531-00-    | RETAINING STRIP          | 1    | 101.90  | 20.00 |      | 81.5   |
| 997-505-751-02-    | SEAL-IMPACT ABSORBER FRT | 2    | 7.60    | 20.00 |      | 12.1   |
| 997-511-011-02-GRV | BONNET                   | 1    | 1910.60 | 20.00 |      | 1528.4 |
| 997-511-053-01-    | LOCK, LOWER PART         | 1    | 265.10  | 20.00 |      | 212.0  |

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER  
 NO:

Customer Signature

Porsche Centre Singapore  
 29 Leng Kee Road Tel : (65) 6472 4433  
 Singapore 159099

AfterSales Centre  
 27A Tanjong Penjuru Tel : (65) 6331 0700  
 Singapore 609042

**STUTTGART AUTO PTE LTD**

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd  
 Eurokars Group  
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

**PORSCHE****INSURANCE INVOICE**

GST Reg No: M90364005A

CODE: A0031 AXA  
 CUSTOMER: AXA INSURANCE PTE LTD  
 ADDRESS: 8 Shenton Way  
 #24-01 AXA Tower  
 Singapore 068811

MODEL: Boxster  
 CHASSIS NO: WP0ZZZ98Z8U701710  
 ENGINE NO: 65806972  
 DESCRIPTION: Own Damaged Claim

PAGE NO: 3  
 DOCUMENT NO: 13204599  
 JOB NO: 35775  
 DATE IN: 14/07/2018  
 DATE PRINTED: 19/09/2018  
 CSO/OP CODE: Janice Syn  
 SVC MNT EXP: 27/03/2013  
 EXT. WTY: 30/03/2012  
 REGN NO: SLX4563Y  
 REGN DATE: 28/03/2008  
 MILEAGE: 37880

| Item            | Description     | Unit | U/Price | Disc% | Con% | Amount |
|-----------------|-----------------|------|---------|-------|------|--------|
| 997-511-117-00- | ACTUATOR        | 1    | 105.00  | 20.00 |      | 84.0   |
| 999-902-049-40- | VELCRO FASTENER | 12   | 5.10    | 20.00 |      | 48.9   |

Parts 6,517.28  
 Sundries 0.00  
 Labour 10,910.00  
 Menus 0.00

Net 13427.28  
 G.S.T. 7% 939.91  
 Total 14367.19  
 Paid 0.00  
 Amount Due 14367.19

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER  
 NO:

Customer Signature

**Porsche Centre Singapore**  
 29 Leng Kee Road Tel: (65) 6472 4433  
 Singapore 159099

**Aftersales Centre**  
 27A Tanjong Penjuru Tel: (65) 6331 0700  
 Singapore 609042

**STUTTGART AUTO PTE LTD**

Authorised Signature

ORIGINAL COPY

**Stuttgart Auto Pte Ltd**  
 Eurokars Group  
 Company Reg. No. 198403740N

www.porsche.com.sg



## DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned  
Repairers my/our vehicle No: 32X 45634 which has been  
repaired to my satisfaction and I/we admit that the payment for such repairs  
by **Stuttgart Auto Pte Ltd** is in full and final discharge of my claim under  
policy number: GA34690811 in respect of damage  
caused to the said vehicle as a result of an accident that occurred on  
12/07/2018 at AIE towards Clementi.

Janice Syn  


Witnessed by Repairers

14/08/2018  
Date:

SAWaid

Signature by Insured

14/08/2018  
Date: