

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7050Z

DATE 13/7/2018 16:59

MAKE :

MODEL : HYUNDAI i40

QBE
JM

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Mirror (LH) <i>Broken</i>			\$ 980.50
	SUB TOTAL			\$ 980.50
	LESS 20% <i>25%</i>			\$ 196.10
	DISCOUNTED TOTAL			\$ 784.40
	Labour Charge			
	Panel Beating			\$ 250.00 <i>100</i>
	Spray Painting Charge			\$ 150.00 <i>50</i>
	Wiring Charge			\$ 50.00 <i>X2</i>
	TOTAL LABOUR			\$ 450.00
	ESTIMATE TOTAL			\$ 1,234.40
<p><i>Ka Wai Ching</i></p> <p><i>16/7/18 1000h.</i></p> <p><i>1 Day</i></p> <p><i>P/P</i></p> <p><i>Before Paint photo</i></p>				
<div> <p>UKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				