

1/5/2010

INS. CASE OWNER:

JANOT

CC 4/EQ1801 2480, A 166352

LKK:

IDAC:

Surveyor:

KADIAN

DOI:

ASSIGNMENT

17107118

Date / Time:

16/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

G1BD 7651E

Name of Insured:

CMA HANDINGS PH

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

17/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN SEON H KHOON

Driver Tel No.:

(V/L) (YES / NO)

Claim No.:

DM1840078415T

Policy No.:

DM1840078-001942

Make / Model:

MSSAM

Place of Accident:

BRADDELL RD TMS TOA

PAYON

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

CMA SEM 5701H

INSRS:
WSP:
Tel:
Liability:
RMKS:Kah
motorINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
18/8/18	RECEIVED 18 OCT 2018	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	18/08/18 - vic
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup):	☒
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	DO DV
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE	Date/Time: 18/08/18	Sent By: BS
FINALIZATION	Date/Time: 18/08/18	Confirm with: BS
Repair Cost: P1P	\$S 15,342.71 (12 days) Reduction: 38 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 18/08/18	Confirm with: KADIAN
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 27	Email ☐ Call ☐
Repair Cost: (w/Get)	\$S 14,276.69	CO16 Repair - Garage - TP
Loss of Rental (LOR):	\$S - (days)	
Loss of Use (LOU):	\$S 700.00 x 14 days	
Loss of Income (LOI):	\$S - (S x days)	
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	\$S 2.00	
Medical:	\$S -	
Disbursement:	\$S - (e.g. Tow/ Independent)	
Legal Cost	\$S -	
Total:	\$S 14,978.69	Global Sum \$S: -
FINAL PAYMENT	Date/Time: 18/08/18	Confirm with: KADIAN
Payee 1:	\$S 14,978.69	Name 1: KAH MOTOR CO. SDN. BHD.
Payee 2: (Strike if N.A.)	\$S -	Name 2: -
Payee 3: (Strike if N.A.)	\$S -	Name 3: -

(08/11/13) wef

ASS. REC. BY:

REF:

EQI

ASSIGNMENT

From:

Date:

17/07/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SCM 5701H

at Workshop m/s

Kah Motor

of

15 ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Any @ Morning

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12/8/18

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC5701H

Yr Regn:

2018, July

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV

c.c

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

156

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMR41830JX200008

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

215/60R16

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

17/07/18

Survey held at

Kah Motor

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP EQ.

P/R 413,342.71

CRSD: 48,242.25/30%

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ18012980/hb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 17-07-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 7651E	Veh. Inspected	SCM 5701H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/07/2018	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQI18012980/Ahb3

Date: 18.07.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SMC5701H


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.07.2018 at the premises of M/s Kah Motor Co Sdn Bhd and have the following to report:-

Workshop Estimate Amount	: S\$	20,689.25
Revised Estimate Amount	: S\$	12,036.92
"Check" Items Amount	: S\$	1,256.01
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 12 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

64811977 LK auto

Customer : EQ INSURANCE COMPANY LTD
 5 MAXWELL ROAD
 #17-00 TOWER BLK MND BUILDING
 SINGAPORE 069110

Registration No : SMC5701H
 Chassis No : JHMRU1830JX200008
 Model : HRV LX-SIN CVT YM 2018
 Owner's Name : AMIT SHARMA
 Ins Policy No. : 18-MT103994-R00
 Date of Accident : 13/7/2018

Document No. : SQT18002908 Page 1
 Date : 13. Jul 2018
 Customer No. : WZE011
 Svc Advisor : ARY CHUA WAI NGEE
 Engine No : L15B5670008
 Date | Time : 13. Jul 2018 4:57:56 PM
 Surveyor Name :
 Survey Date : DID : +65 6846 5673
 Authorisation Date : HP : +65 8100 6306
 Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70859) OWNER: AMIT SHARMA OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 13/07/2018@12.55PM SURVEYED BY: REF NO: TP INSURER: EQ INSURANCE COMPANY LTD TP VEH: GBD7651E						
91505-TM8-003	CLIPBUMPER <i>new</i>	14	2.00 <i>25-</i>	25	21.00	1.47	✓ 22.47
04715-T7A-900ZZ	FACE,RR.BUMPER <i>rehd</i>	1	463.70	25	347.77	24.34	✓ 372.11
71598-T7A-000	SPACERL.RR.BUMPER SIDE <i>3mm</i>	1	11.50	25	8.62	0.60	✓ 9.22
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	✓ 9.22
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER <i>3 rehd</i>	1	92.30	25	69.22	4.85	✓ 74.07
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	✓ 74.07
33555-T7A-J01	REFLECTOR ASSYL.RR. <i>3 new</i>	1	151.80	25	113.85	7.97	✓ 121.82
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	151.80	25	113.85	7.97	✓ 121.82
74410-T7A-J01ZN	PROTECTOR,R,RR.WHEEL ARCH <i>3 new</i>	1	165.40	25	124.05	8.68	✓ 132.73
74450-T7A-J01ZQ	PROTECTORL.RR.WHEEL ARCH	1	165.40	25	124.05	8.68	✓ 132.73
75722-T7W-A01	EMBLEMRR. <i>3 new</i>	1	12.90	25	9.67	0.68	✓ 10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	✓ 11.31
74890-T7A-J13ZB	GARNISH ASSY,RR.LICENSE <i>crushed</i>	1	221.00	25	165.75	11.60	✓ 177.35
34100-T5A-003	LIGHT ASSYLICENSE <i>new</i>	2	31.20	25	46.80	3.28	✓ 50.08
33502-T7A-J31	LAMP UNIT,R. <i>3 crushed</i>	1	401.60	25	301.20	21.08	✓ 322.28
33552-T7A-J31	LAMP UNIT,L.	1	401.60	25	301.20	21.08	✓ 322.28
34150-T7A-J31	LIGHT ASSY,R,LID <i>3 crushed</i>	1	269.90	25	202.42	14.17	✓ 216.59
34155-T7A-J31	LIGHT ASSY,L,LID <i>3 new</i>	1	269.90	25	202.42	14.17	✓ 216.59
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	3.05	✓ 46.62
74940-TZ5-A01	BUZZER ASSYSMART <i>new</i>	1	59.30	25	44.47	3.11	✓ 47.58
04655-T7A-310ZZ	PANEL SETRR.FLOOR <i>3 crushed</i>	1	662.20	25	496.65	34.77	✓ 531.42
74646-T7A-010	COVERRR.FLOOR UN <i>3 new</i>	1	118.30	25	88.72	6.21	✓ 94.93

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SMC5701H
Chassis No : JHMRU1830JX200008
Model : HRV LX-SIN CVT YM 2018
Owner's Name : AMIT SHARMA
Ins Policy No. : 18-MT103994-R00
Date of Accident : 13/7/2018

Document No. : SQT18002908 Page 2
Date : 13. Jul 2018
Customer No. : WZE011
Svc Advisor : ARY CHUA WAI NGE
Engine No : L15B5670008
Date | Time : 13. Jul 2018 4:57:56 PM
Surveyor Name :
Survey Date : DID : +65 6845 6573
HP : +65 8100 6306
Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR ? <i>me</i>	1	81.20	25	60.90	4.26	✓ 65.16
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	60.20	25	45.15	3.16	✓ 48.31
65540-T7A-310ZZ	STIFFENER COMPR.RR.FRAME UPP <i>me</i>	1	103.20	25	77.40	5.42	? 82.82 X
65590-T7A-310ZZ	STIFFENER COMPL.RR.FRAME UPP <i>me</i>	1	103.20	25	77.40	5.42	? 82.82 X
04656-T7A-900ZZ	FRAME B SET,R.RR. <i>me</i>	1	405.40	25	304.05	21.28	? 325.33 X
04657-T7A-900ZZ	FRAME B SET,L.RR. <i>me</i>	1	405.40	25	304.05	21.28	? 325.33 X
66100-T7A-300ZZ	PANEL COMPRR. <i>Disturbed</i>	1	365.70	25	274.27	19.20	✓ 293.47
72841-SH3-315	OILSHEET <i>me</i>	1	39.90	25	29.92	2.09	✓ 32.01 X
68100-T7A-J20ZZ	TAIL GATE COMP <i>Disturbed</i>	1	838.90	25	629.17	44.04	✓ 673.21
74440-T7A-003	WEATHERSTRIPTAILGATE <i>me</i>	1	96.80	25	72.60	5.08	✓ 77.68
74820-T7A-003	STAY ASSYR.TAILGATE OPEN <i>me</i>	1	92.10	25	69.07	4.83	+ 73.90
74870-T7A-003	STAY ASSYL.TAILGATE OPEN <i>me</i>	1	92.10	25	69.07	4.83	+ 73.90
74800-T7A-J02	LOCK ASSYTAILGATE <i>me</i>	1	76.60	25	57.45	4.02	✓ 61.47
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>me</i>	1	19.30	25	14.47	1.01	✓ 15.48
73226-SZW-000	DAMPERSTD 5X5 <i>me</i>	1	8.30	25	6.22	0.44	✓ 6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>me</i>	1	19.30	25	14.47	1.01	✓ 15.48
76711-T6A-003	CAPPVOT <i>me</i>	1	4.70	25	3.52	0.25	✓ 3.77
91501-S70-003	FASTENER BW/SHIELD <i>me</i>	4	3.20	25	9.60	0.67	✓ 10.27
91502-S70-003	FASTENER B <i>me</i>	2	4.90	25	7.35	0.51	✓ 7.86
91536-SS0-J01	FASTENER AW/SHIELD <i>me</i>	2	3.50	25	5.25	0.37	✓ 5.62
84660-T7A-J01ZA	BASE COMPL.TRUNK SIDE LINING <i>me</i>	1	144.20	25	108.15	7.57	? 115.72 ? X
84610-T7A-J01ZA	BASE COMPR.TRUNK SIDE LINING <i>me</i>	1	144.20	25	108.15	7.57	? 115.72 ? X
84640-T7A-J01ZA	LINING ASSYRR.PANEL <i>me</i>	1	43.00	25	32.25	2.26	✓ 34.51
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR <i>me</i>	1	186.00	25	139.50	9.77	+ 149.27
84441-S2K-000ZB	POCKETTAILGATE PULL <i>me</i>	1	14.90	25	11.17	0.78	+ 11.95
84433-T7A-J01ZA	LINING ASSYTAILGATE UPPER <i>me</i>	1	58.10	25	43.57	3.05	+ 46.62
84435-T7A-J01ZA	LINING ASSYR.TAILGATE SIDE <i>me</i>	1	20.90	25	15.67	1.10	+ 16.77
84485-T7A-J01ZA	LINING ASSYL.TAILGATE SIDE <i>me</i>	1	20.90	25	15.67	1.10	+ 16.77
84431-T7A-J01ZA	LINING ASSYTAILGATE <i>me</i>	1	133.40	25	100.05	7.00	✓ 107.05
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>me</i>	12	60.00	25	120.00	8.40	✓ 128.40

Printed on 14/7/2018 9:18:07 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SMC5701H
Chassis No : JHMRU1830JX200008
Model : HRV LX-SIN CVT YM 2018
Owner's Name : AMIT SHARMA
Ins Policy No. : 18-MT103994-R00
Date of Accident : 13/7/2018

Document No. : SQT18002908 Page 3
Date : 13. Jul 2018
Customer No. : WZE011
Svc Advisor : ARY CHUA WAI NGE
Engine No : L15B5670008
Date | Time : 13. Jul 2018 4:57:56 PM
Surveyor Name : DID : +65 6846 5673
Survey Date : HP : +65 6100 6306
Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
					Sum Item	6059.25	424.12
							6,483.37
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	17.50	267.50
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN-(N)	1	350.00		350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	350.00		350.00	24.50	374.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00		350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	550.00		550.00	38.50	588.50
BMU02R	REMOVE & REPLACE RR UNDERCARRIAGE PARTS. (N)	1	550.00		550.00	38.50	588.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	4800.00		4800.00	336.00	5136.00
BKRP22B	CUT OFF & RENEW RR FLOOR PANEL RR PANEL.(400X560)	1	5600.00		5600.00	392.00	5992.00
					Sum Labor	14630.00	1,024.10
							15,654.10

Survey By

Date & Time

Excess

Status

Signature

Adrian Lim

17/07/2018

Not Authorised

Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Amount 20,689.25 1,448.22 22,137.47

Total (Inclusive of GST) 22,137.47

Printed on 14/7/2018 9:18:07 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZE011 / EQ INSURANCE
Chassis No: JHMRU1830JX200008
License No: SMC5701H
Mileage: 157
Engine No: L15B5670008

Document No: SVO18041723
Printed By: ARYCHUA
Order Date: 17. July 2018
Order Time: 3:44:39 PM
Service Advisor: ARY CHUA WAI NGE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70859)						
	OWNER: AMIT SHARMA						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 13/07/2018@12.55PM						
	SURVEYED BY: ADRIAN LING(LKKAUTO)17/07/2018@14.14PM						
	REF NO: CC4/EQI18012980/HB3						
	TP INSURER: EQ INSURANCE COMPANY LTD						
	TP VEH: GBD7651E						
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
74890-T7A-J13ZB	GARNISH ASSY,RR LICENSE	1	221.00	25	165.75	11.60	177.35
33502-T7A-J31	LAMP UNIT,R.	1	401.60	25	301.20	21.08	322.28
33552-T7A-J31	LAMP UNIT,L.	1	401.60	25	301.20	21.08	322.28
34150-T7A-J31	LIGHT ASSY,R.LID	1	269.90	25	202.42	14.17	216.59
34155-T7A-J31	LIGHT ASSY,L.LID	1	269.90	25	202.42	14.17	216.59
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	662.20	25	496.65	34.77	531.42
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR	1	81.20	25	60.90	4.26	65.16
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	60.20	25	45.15	3.16	48.31
66100-T7A-300ZZ	PANEL COMPRR.	1	365.70	25	274.27	19.20	293.47
68100-T7A-J20ZZ	TAIL GATE COMP	1	838.90	25	629.17	44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	25	72.60	5.08	77.68
74800-T7A-J02	LOCK ASSYTAILGATE	1	76.60	25	57.45	4.02	61.47
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT	1	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.00	25	32.25	2.26	34.51
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
65770-T7J-H00ZZ	CROSSMEMBER COMPRR.FLOOR RR.	1	144.70	25	108.52	7.60	116.12
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	133.40	25	100.05	7.00	107.05
84550-T7A-J00	BOX ASSY,CARGO FLOOR	1	126.90	25	95.17	6.66	101.83
74646-T7A-010	COVERRR.FLOOR UN	1	118.30	25	88.72	6.21	94.93
39530-T7A-003	CAMERA ASSYRR.VIEW	1	611.00	25	458.25	32.08	490.33
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
	SUM PARTS:				4,402.71	308.18	4,710.89
BOSUN	0672	1	20.00		20.00	1.40	21.40

WIP = 12

SNPP

Bent
Deta
Deta
Deta
Deta

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZE011 / EQ INSURANCE
Chassis No: JHMRU1830JX200008
License No: SMC5701H
Mileage: 157
Engine No: L15B5670008

Document No: SVO18041723
Printed By: ARYCHUA
Order Date: 17. July 2018
Order Time: 3:44:39 PM
Service Advisor: ARY CHUA WAI NGEE

	SUNDRIES					
BOBC	EXT-YBH	1	100.00 ✓	100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)					
BOJSE	0672	1	100.00 ✓	100.00	7.00	107.00
	BODY JOINT SEALANT.					
BML02I	EXT-YJ	1	120.00 ✓	120.00	8.40	128.40
	INSPECT RR LIGHTING MECHANISMS.					
	PERFORM WATER					
	TEST.(N)					
BA02R	EXT-YJ	1	140.00 ✓	140.00	9.80	149.80
	REMOVE & INSTALL REVERSE					
	SENSORS-4 PCS (N)					
BP00R	EXT-YBH	1	180.00 ✓	180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).					
BOMISC1	EXT-YJ	1	280.00 ✓	280.00	19.60	299.60
	REMOVE & INSTALL REVERSE CAMERA					
	& CALIBRATION					
BMI03D	EXT-YJ	1	280.00 ✓	280.00	19.60	299.60
	REMOVE & INSTALL REAR					
	COMPARTMENT LININGS					
	GARNISHES.(N)					
BG02D	EXT-YJ	1	300.00 ✓	300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN.					
	(N)					
BOMISC1	EXT-YJ	1	350.00 ✓	350.00	24.50	374.50
	RESET VEHICLE SMART KEY					
	ACCESS/ENTRY SYSTEM					
BKTG02R	EXT-YJ	1	450.00 ✓	450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW					
	TAILGATE. ADJUST &					
	ALIGN TAILGATE.(N)					
BP06R	EXT-YBH	1	2,700.00 ✓	2,700.00	189.00	2,889.00
	SPRAY PAINT ON REPAIRED/REPLACED					
	AREAS.(6PX\$450)					
BKRP22B	EXT-YJ	1	3,920.00 ✓	3,920.00	274.40	4,194.40
	CUT OFF & RENEW RR FLOOR PANEL					
	RR PANEL.(07DX\$560)					
	STRAIGHTEN ALIGN & RENEW DAMAGE					
	PARTS.					
			SUM LABOUR:	8,940.00	625.80	9,565.80
			TOTAL SGD	13,342.71	933.98	14,276.69

Total Payable (SGD)**14,276.69**

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: G5481215P / AMIT SHARMA
Chassis No: JHMRU1830JX200008
License No: SMC5701H
Mileage: 157
Engine No: L15B5670008

Document No: SVO18041723
Printed By: ARYCHUA
Order Date: 17. July 2018
Order Time: 3:44:39 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Includ Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 70859) OWNER: AMIT SHARMA OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 13/07/2018@12.55PM SURVEYED BY: ADRIAN LING(LKKAUTO)17/07/2018@14.14PM REF NO: CC4/EQ118012980/HB3 TP INSURER: EQ INSURANCE COMPANY LTD SUPPLIMENTARY ITEM PARTS & LABOR TP VEH: GBD7651E						
65770-T7J-H00ZZ	CROSSMEMBER COMPRR.FLOOR RR.	1	144.70	25	108.52	7.60	116.12
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	133.40	25	100.05	7.00	107.05
84550-T7A-J00	BOX ASSY.CARGO FLOOR	1	126.90	25	95.17	6.66	101.83
74646-T7A-010	COVERRR.FLOOR UN	1	118.30	25	88.72	6.21	94.93
39530-T7A-003	CAMERA ASSYRR.VIEW	1	611.00	25	458.25	32.08	490.33
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
	SUM PARTS:				895.71	62.70	958.41
	TOTAL SGD				895.71	62.70	958.41
	Total Payable (SGD)						958.41

GST Amount is calculated from individual line(s)

Vic (LKKAUTO)

From: Ary Chua <arychua@honda.com.sg>
Sent: Wednesday, 8 August, 2018 9:33 AM
To: Shu Pei (LKKAUTO); Admin A; Admin-D (LKKAUTO); Vic (LKKAUTO); Adrian Ling (LKKAUTO)
Cc: Liew Thye Wui; Faeaz
Subject: RE: Finalise TPDS: SMC5701H (TM) & GBD7651E (AXA) DOA: 13/07/2018@12.55PM – 2ND REMINDER
Attachments: 3790_001.pdf

Hi Adrian Ling,

Kindly Finalise TPDS: SMC5701H (TM) & GBD7651E (AXA) DOA: 13/07/2018@12.55PM – 2ND REMINDER

Final Repair Costs (include GST)	\$13,342.71 + (\$933.98) = \$14,276.69
Repair Period* (Working Day)	12

*NOTES: The Repair Not Includes Public Holiday & Sunday. Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306

From: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>

Sent: Friday, 3 August, 2018 11:53 AM

To: Ary Chua <arychua@honda.com.sg>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>

Subject: FW: Finalise TPDS: SMC5701H (TM) & GBD7651E (AXA) DOA: 13/07/2018@12.55PM

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/EQ118012980/Ahb3	Adrian / Vic

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ary Chua <arychua@honda.com.sg>

Sent: Friday, 3 August 2018 10:18 AM

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: Finalise TPDS: SMC5701H (TM) & GBD7651E (AXA) DOA: 13/07/2018@12.55PM

Hi Adrian Ling,

Kindly Finalise TPDS: SMC5701H (TM) & GBD7651E (AXA) DOA: 13/07/2018@12.55PM

Final Repair Costs (include GST)	\$13,342.71 + (\$933.98) = \$14,276.69
Repair Period* (Working Day)	12

***NOTES: The Repair Not Includes Public Holiday & Sunday.** Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Nivitha (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Monday, 16 July 2018 5:47 PM
To: Ary Chua; 'assignments'
Cc: Liew Thye Wui; Faeaz; Admin A
Subject: RE: TPDS: SCM5701H (TM) & GBD7651E (EQ) DOA: 13/07/2018@12.55PM
Attachments: 3235_001.pdf

5-52pm @ 16/07/2018
vehicle in
person @ Ary Chua
arrange on 17/07/18

Without Prejudice
Save As To Costs

Dear Ary

Liability is cleared, we can agree on direct settlement if possible.

Aside to surveyor, please arrange to attend to the PRS.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Ary Chua [mailto:arychua@honda.com.sg]
Sent: Monday, July 16, 2018 5:34 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: RE: TPDS: SCM5701H (TM) & GBD7651E (EQ) DOA: 13/07/2018@12.55PM

Hi Janet Tan,
We Choose no 6 LKK AUTO Consultant Pte Ltd. Kindly Establish this Case Liability Issue ASAP.

Thank you.
Best Regards,
Ary Chua Wai Ngee
Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610
E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Monday, 16 July, 2018 5:27 PM

To: Ary Chua <arychua@honda.com.sg>

Subject: RE: TPDS: SCM5701H (TM) & GBD7651E (EQ) DOA: 13/07/2018@12.55PM

Without Prejudice Save As To Costs

Dear Sir/Madam,

For pre repair survey request, please email to egiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan

Senior Executive | Claims




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Ary Chua [<mailto:arychua@honda.com.sg>]

Sent: Saturday, July 14, 2018 9:48 AM

To: EQI PRS <EQIPRS@eqinsurance.com.sg>

Subject: TPDS: SCM5701H (TM) & GBD7651E (EQ) DOA: 13/07/2018@12.55PM

Hi OIC-EQ,

Kindly arrange for car survey on next Monday 16/07/2018@09.00am Vehicle is In Ubi waiting for Survey & Proceed for Repair by EQ Insurance. Please Establish this Case Liability Issue ASAP.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Tuesday, 16 October, 2018 11:53 AM
To: Emillin Liew
Cc: Faeaz; Admin A; Vic (LKKAuto)
Subject: RE: LKK C/O EQ- Submission of Third Party Direct Settlement, Y/R: CC4/EQI18012980/Ahb3 : O/R: SMC5701H

Without Prejudice

Dear Emillin,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we confirm acceptance of your offer of **\$14,978.69** (all in) to settle your client's claim.

Please be informed that no DV is required.

The above amount is to be made payable to **KAH MOTOR CO. SDN. BHD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)
Sent: Tuesday, 21 August, 2018 5:34 PM

To: 'Emillin Liew'; Admin A
Cc: Adrian Ling (LKKAuto); 'janet.tan@eqinsurance.com.sg'; Faeaz
Subject: RE: LKK C/O EQ- Submission of Third Party Direct Settlement, Y/R: CC4/EQ18012980/Ahb3 : O/R: SMC5701H

Without Prejudice

Dear Emillin,

We refer to your below email and the contents were noted.

We will get back to you for an update/offer in due course.

Thank you.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Emillin Liew [<mailto:emillinliew@honda.com.sg>]

Sent: Tuesday, 21 August, 2018 5:16 PM

To: Vic (LKKAuto); Admin A

Cc: Adrian Ling (LKKAuto); 'janet.tan@eqinsurance.com.sg'; Faeaz

Subject: LKK C/O EQ- Submission of Third Party Direct Settlement, Y/R: CC4/EQ18012980/hb3 : O/R: SMC5701H

Dear Vic,

RE: ACCIDENT INVOLVING SMC5701H AND GBD7651E ON 13.07.18

Attached please find our Original repair invoice and other relevant documents for the direct settlement claim.

Kindly email me the DV as soon as possible.

Please contact us if you need any clarifications.

Warmest Regards,

Emillin Liew

DID: +65 6514 5684

Email: emillinliew@honda.com.sg

KAH MOTOR CO. SDN. BHD.

(A member of Oriental Holdings Berhad)

15 Ubi Road 4 Singapore 408610

Tel: +65 6743 4333 Fax: +65 6748 0770



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ18012980/Ahb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 23-10-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 7651E	Veh. Inspected	SMC 5701H
Policy No.	DMCPHQ18-001942	Coverage (\$)	0.00
Claim No.	DM18HO01784/JT	Excess (\$)	0.00
Assign From	JANET TAN	Assign Date	16/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMRU1830JX200008	Colour	BLUE
Odometer	156	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	6 mm
L/H Front Tyre	215/60R16	DUNLOP	6 mm
R/H Rear Tyre	215/60R16	DUNLOP	6 mm
L/H Rear Tyre	215/60R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/07/2018	Inspection Date	17/07/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 5701H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
14	CLIPBUMPER (SN)	NECESSARY	21.00	21.00
1	FACE,RR.BUMPER (SN)	DEFORMED	347.77	347.77
1	SPACERL.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
1	SPACERR.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
1	FACER.RR.BUMPER CORNER (SN)	DEFORMED	69.22	69.22
1	FACEL.RR.BUMPER CORNER (SN)	DEFORMED	69.22	69.22
1	REFLECTOR ASSYL.RR. (SN)	NOT NECESSARY	113.85	-
1	REFLECTOR ASSYR.RR. (SN)	NOT NECESSARY	113.85	-
1	PROTECTOR,R,RR.WHEEL ARCH (SN)	NOT NECESSARY	124.05	-
1	PROTECTORL.RR.WHEEL ARCH (SN)	NOT NECESSARY	124.05	-
1	EMBLEMRR. (SN)	NECESSARY	9.67	9.67
1	EMBLEM,RR. I-VTEC (SN)	NECESSARY	10.57	10.57
1	GARNISH ASSY, RR.LICENCE (SN)	CRACKED	165.75	165.75
2	LIGHT ASSYLICENCE (SN)	NOT NECESSARY	46.80	-
1	LAMP UNIT,R. (SN)	CRACKED	301.20	301.20
1	LAMP UNIT,L. (SN)	CRACKED	301.20	301.20
1	LIGHT ASSY,R.LID (SN)	CRACKED	202.42	202.42
1	LIGHT ASSY,L.LID (SN)	CRACKED	202.42	202.42
1	ANTENNA ASSYL.F. (SN)	NOT NECESSARY	43.57	-
1	BUZZER ASSYSMART (SN)	NOT NECESSARY	44.47	-
1	PANEL SETRR.FLOOR (SN)	DISTORTED	496.65	496.65
1	COVERRR.FLOOR UN (SN)	NOT NECESSARY	88.72	-
1	CROSSMEMBER COMPRR.FLOOR (SN)	NECESSARY	60.90	60.90
1	STIFFENERRR.JACK UP (SN)	NECESSARY	45.15	45.15
1	STIFFENER COMPR.RR.FRAME UPP (SN)	NOT NECESSARY	77.40	-
1	STIFFENER COMPL.RR.FRAME UPP (SN)	NOT NECESSARY	77.40	-
1	FRAME B SET,R.RR. (SN)	NOT NECESSARY	304.05	-
1	FRAME B SET,L.RR. (SN)	NOT NECESSARY	304.05	-
1	PANEL COMPRR. (SN)	DISTORTED	274.27	274.27
1	OILSHEET (SN)	NOT NECESSARY	29.92	-
1	TAIL GATE COMP (SN)	DISTORTED	629.17	629.17

Report Ref No. CC4/EQ18012980/Ahb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WEATHERSTRIPTAILGATE (SN)	CUT	72.60	72.60
1	STAY ASSYR.TAILGATE OPEN (SN)	NOT NECESSARY	69.07	-
1	STAY ASSYL.TAILGATE OPEN (SN)	NOT NECESSARY	69.07	-
1	LOCK ASSYTAILGATE (SN)	DAMAGED	57.45	57.45
1	RUBBER CR.WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.22	6.22
1	RUBBER CL.WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	CAPPIVOT (SN)	NECESSARY	3.52	3.52
4	FASTENER BW/SHIELD (SN)	NECESSARY	9.60	9.60
2	FASTENER B (SN)	NECESSARY	7.35	7.35
2	FASTENER AW/SHIELD (SN)	NECESSARY	5.25	5.25
1	BASE COMPL.TRUNK SIDE LINING (SN)	NOT NECESSARY	108.15	-
1	BASE COMPR.TRUNK SIDE LINING (SN)	NOT NECESSARY	108.15	-
1	LINING ASSYRR.PANEL (SN)	DEFORMED	32.25	32.25
1	BOARD ASSYTRUNK FLOOR (SN)	NOT NECESSARY	139.50	-
1	POCKETTAILGATE PULL (SN)	NOT NECESSARY	11.17	-
1	LINING ASSYTAILGATE UPPER (SN)	NOT NECESSARY	43.57	-
1	LINING ASSYR.TAILGATE SIDE (SN)	NOT NECESSARY	15.67	-
1	LINING ASSYL.TAILGATE SIDE (SN)	NOT NECESSARY	15.67	-
1	LINING ASSYTAILGATE (SN)	DEFORMED	100.05	100.05
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
4	ACT RR.SENSOR (SN)	NOT NECESSARY	320.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	CROSSMEMBER COMPRR. FLOOR RR. (SN) (ADDITIONAL)	BENT	108.52	108.52
1	LINING ASSYTAILGATE (SN) (ADDITIONAL)	REPEATED	100.05	-
1	BOX ASSY, CARGO FLOOR (SN) (ADDITIONAL)	CRACKED	95.17	95.17
1	COVERRR.FLOOR UN (SN) (ADDITIONAL)	DEFORMED	88.72	88.72
1	CAMERA ASSYRR.VIEW (SN) (ADDITIONAL)	DAMAGED	458.25	458.25
1	NUMBER PLATE WITH CASING (SN) (ADDITIONAL)	BENT	45.00	45.00
			7,054.96	4,422.71
	LABOUR			
	BODY UNDERSIDE COATING.		100.00	100.00

Report Ref No. CC4/EQ118012980/Ahb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	BODY JOINT SEALANT.		100.00	100.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		180.00	120.00
	REMOVE & RENEW REVERSE SENSORS.		250.00	140.00
	APPLY BODY UNDERSIDE COATING.		250.00	180.00
	REMOVE & INSTALL RR.WINDSCREEN.		350.00	300.00
	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION.		350.00	280.00
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	350.00	-
	RESET VEHICLE SMART KEY ACCESS / ENTRY SYSTEM.		450.00	350.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		550.00	280.00
	REMOVE & REPLACE RR UNDERCARRIAGE PARTS.	NOT NECESSARY	550.00	-
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		650.00	450.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		4,800.00	2,700.00
	CUT OFF & RENEW RR FLOOR PANEL RR PANEL.		5,600.00	3,920.00
			14,530.00	8,920.00
GRAND TOTAL			21,584.96	13,342.71
RECOMMENDED COST OF REPAIRS				13,342.71

Report Ref No. CC4/EQ18012980/Ahb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.