



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

6481977 LK Auto

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SMC5701H

Chassis No : JHMRU1830JX200008

Model : HRV LX-SIN CVT YM 2018

Owner's Name : AMIT SHARMA

Ins Policy No. : 18-MT103994-R00

Date of Accident : 13/7/2018

Document No. : SQT18002908

Date : 13. Jul 2018

Customer No. : WZE011

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B5670008

Date | Time : 13. Jul 2018 4:57:56 PM

Surveyor Name : DID : +65 6846 5673

Survey Date : HP : +65 8100 6306

Authorisation Date : Email : arychua@honda.com.sg

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70859)						
	OWNER: AMIT SHARMA						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 13/07/2018@12.55PM						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: EQ INSURANCE COMPANY LTD						
	TP VEH: GBD7651E						
91505-TM8-003	CLIPBUMPER <i>new</i>	14	2.00	25	21.00	1.47	22.47
04715-T7A-900ZZ	FACE,RR.BUMPER <i>Rehd</i>	1	463.70	25	347.77	24.34	372.11
71598-T7A-000	SPACERL,RR.BUMPER SIDE <i>3mm</i>	1	11.50	25	8.62	0.60	9.22
71593-T7A-000	SPACERR,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
04717-T7A-000ZZ	FACER,RR.BUMPER CORNER <i>Rehd</i>	1	92.30	25	69.22	4.85	74.07
04718-T7A-000ZZ	FACEL,RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
33555-T7A-J01	REFLECTOR ASSYL,RR. <i>3mm</i>	1	151.80	25	113.85	7.97	121.82
33505-T7A-J01	REFLECTOR ASSYR,RR.	1	151.80	25	113.85	7.97	121.82
74410-T7A-J01ZN	PROTECTOR,R,RR.WHEEL ARCH <i>3mm</i>	1	165.40	25	124.05	8.68	132.73
74450-T7A-J01ZQ	PROTECTORL,RR.WHEEL ARCH	1	165.40	25	124.05	8.68	132.73
75722-T7W-A01	EMBLEMRR. <i>3mm</i>	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
74890-T7A-J13ZB	GARNISH ASSY,RR.LICENSE <i>canhd</i>	1	221.00	25	165.75	11.60	177.35
34100-T5A-003	LIGHT ASSYLICENSE <i>new</i>	2	31.20	25	46.80	3.28	50.08
33502-T7A-J31	LAMP UNIT,R. <i>canhd</i>	1	401.60	25	301.20	21.08	322.28
33552-T7A-J31	LAMP UNIT,L.	1	401.60	25	301.20	21.08	322.28
34150-T7A-J31	LIGHT ASSY,R,LID <i>canhd</i>	1	269.90	25	202.42	14.17	216.59
34155-T7A-J31	LIGHT ASSY,L,LID	1	269.90	25	202.42	14.17	216.59
38387-TZ5-A01	ANTENNA ASSYL,F. ?	1	58.10	25	43.57	3.05	46.62
74940-TZ5-A01	BUZZER ASSYSMART ?	1	59.30	25	44.47	3.11	47.58
04655-T7A-310ZZ	PANEL SETRR,FLOOR <i>Rehd</i>	1	662.20	25	496.65	34.77	531.42
74646-T7A-010	COVERRR,FLOOR UN ?	1	118.30	25	88.72	6.21	94.93



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLK MND BUILDING SINGAPORE 069110	Document No.	: SQT18002908	Page	2
Registration No	: SMC5701H	Date	: 13. Jul 2018		
Chassis No	: JHMRU1830JX200008	Customer No.	: WZE011		
Model	: HRV LX-SIN CVT YM 2018	Svc Advisor	: ARY CHUA WAI NGEE		
Owner's Name	: AMIT SHARMA	Engine No	: L15B5670008		
Ins Policy No.	: 18-MT103994-R00	Date Time	: 13. Jul 2018 4:57:56 PM		
Date of Accident	: 13/7/2018	Surveyor Name	: DID : +65 6848 5673 HP : +65 8100 6306		
		Authorisation Date	: Email : arychua@honda.com.sg		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR ?	1	81.20	25	60.90	4.26	✓ 65.16
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	60.20	25	45.15	3.16	✓ 48.31
65540-T7A-310ZZ	STIFFENER COMPR.RR.FRAME UPP ?	1	103.20	25	77.40	5.42	? 82.82
65590-T7A-310ZZ	STIFFENER COMPL.RR.FRAME UPP ?	1	103.20	25	77.40	5.42	? 82.82
04656-T7A-900ZZ	FRAME B SET,R.RR. ?	1	405.40	25	304.05	21.28	? 325.33
04657-T7A-900ZZ	FRAME B SET,L.RR. ?	1	405.40	25	304.05	21.28	? 325.33
66100-T7A-300ZZ	PANEL COMPRR. Distorted	1	365.70	25	274.27	19.20	✓ 293.47
72841-SH3-315	OILSHEET	1	39.90	25	29.92	2.09	✓ 32.01
68100-T7A-J20ZZ	TAIL GATE COMP Distorted	1	838.90	25	629.17	44.04	✓ 673.21
74440-T7A-003	WEATHERSTRIPTAILGATE at	1	96.80	25	72.60	5.08	✓ 77.68
74820-T7A-003	STAY ASSYR.TAILGATE OPEN ?	1	92.10	25	69.07	4.83	+ 73.90
74870-T7A-003	STAY ASSYL.TAILGATE OPEN ?	1	92.10	25	69.07	4.83	+ 73.90
74800-T7A-J02	LOCK ASSYTAILGATE Distorted	1	76.60	25	57.45	4.02	✓ 61.47
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	✓ 15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	✓ 6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	✓ 15.48
76711-T6A-003	CAPPIVOT	1	4.70	25	3.52	0.25	✓ 3.77
91501-S70-003	FASTENER BW/SHIELD ?	4	3.20	25	9.60	0.67	✓ 10.27
91502-S70-003	FASTENER B ?	2	4.90	25	7.35	0.51	✓ 7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	✓ 5.62
84660-T7A-J01ZA	BASE COMPL.TRUNK SIDE LINING ?	1	144.20	25	108.15	7.57	✓ 115.72 ?
84610-T7A-J01ZA	BASE COMPR.TRUNK SIDE LINING ?	1	144.20	25	108.15	7.57	✓ 115.72 ?
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.00	25	32.25	2.26	✓ 34.51
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	186.00	25	139.50	9.77	+ 149.27
84441-S2K-000ZB	POCKETTAILGATE PULL	1	14.90	25	11.17	0.78	+ 11.95
84433-T7A-J01ZA	LINING ASSYTAILGATE UPPER ?	1	58.10	25	43.57	3.05	+ 46.62
84435-T7A-J01ZA	LINING ASSYR.TAILGATE SIDE ?	1	20.90	25	15.67	1.10	+ 16.77
84485-T7A-J01ZA	LINING ASSYL.TAILGATE SIDE	1	20.90	25	15.67	1.10	+ 16.77
84431-T7A-J01ZA	LINING ASSYTAILGATE ?	1	133.40	25	100.05	7.00	? 107.05
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	✓ 128.40

Printed on 14/7/2018 9:18:07 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLK MND BUILDING SINGAPORE 069110	Document No.	: SQT18002908	Page	3
Registration No	: SMC5701H	Date	: 13. Jul 2018	Customer No.	: WZE011
Chassis No	: JHMRU1830JX200008	Svc Advisor	: ARY CHUA WAI NGEE	Engine No	: L15B5670008
Model	: HRV LX-SIN CVT YM 2018	Date Time	: 13. Jul 2018 4:57:56 PM	Surveyor Name	: DID : +65 6846 5673
Owner's Name	: AMIT SHARMA	Survey Date	: HP : +65 8100 6306	Authorisation Date	: Email : arychua@honda.com.sg
Ins Policy No.	: 18-MT103994-R00				
Date of Accident	: 13/7/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					6059.25	424.12	6,483.37
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	17.50	267.50
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00		350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	350.00		350.00	24.50	374.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00		350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	550.00		550.00	38.50	588.50
BMU02R	REMOVE & REPLACE RR UNDERCARRIAGE PARTS. (N)	1	550.00		550.00	38.50	588.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	4800.00		4800.00	336.00	5136.00
BKRP22B	CUT OFF & RENEW RR FLOOR PANEL RR PANEL.(10DX \$560)	1	5600.00		5600.00	392.00	5992.00
Sum Labor					14630.00	1,024.10	15,654.10

Survey By

Date & Time

Excess

Status

Signature

Adrian Ling

17/07/12

Not Authorised

Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Amount 20,689.25 1,448.22 22,137.47

Total (Inclusive of GST) 22,137.47

Printed on 14/7/2018 9:18:07 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)