

1/10/2018

INS. CASE OWNER:

Rahmadah

CC 6/AIG1801

2983,

Agab

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

12/3/18

Date / Time

12/3/18

Registered in Merimen:

12/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJM 7557C

Name of Insured:

LATIPAH BTE WATIHAH

Insured Tel No.:

HP:

16/3/18

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: AMIRUL BIN SUKAPRI

Driver Tel No.:

(V/L, YES / NO)

Claim No.:

662251273956

Policy No.:

150114V587

Make / Model:

TOYOTA

Place of Accident:

UPP ALJUNED RD 2nos

Aljunied Rd by Jln Mambur

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SJC 1803J



INSRS:

WSP:

Tel:

Liability:

RMKS:

modom



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/3/18
TTH

SJC 1803J 7am/21/6/2018/12/3/18
SJM 7557C

Old rear ended tip

12/1/19
11

Dr's
File & sum

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

12/3/19

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(W) (Assessed / Assessed) BOLA S/N No.:

If NO for B 28, Ass. Lia:

Repair Cost: W/L

SS

5350.00

Loss of Rental (LOR):

SS

9w.w

(9 days)

x \$1w

Loss of Use (LOU):

SS

-

(\$)

x

days

Loss of Income (LOI):

SS

-

(\$)

x

days

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320-

Total:

SS

6252.00

Global Sum SS:

6252.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6252.00

Name 1:

Modom Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY Adrian Ling

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJC1803J

Yr Regn:

2008, Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

cc 1595

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

178499

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMF2462085200779

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

17/07/18

Survey held at

Modern

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP A/G.

COE Expiry: 31/01/23

MV: 30K

TV: RSC

Nett: 10.5K

RPP #

4/5 of sum (Red 4568.37 53%).

Date/Time, File Pass to/

☐

Prel. Report

1/

☐

Final Report

Date/Time, File Return to/

2/

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RSC \$

Phone

Others

TOTAL

Report Format:

Lump Sum / LB1: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekly (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18012983/Aub3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-07-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 7557C	Veh. Inspected	SJC 1803J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/07/2018	Inspection Date	17/07/2018	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747-6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building

78 Shenton Way #07-16

Singapore 079120

Tel : 6419 - 3000

Fax : 6835 - 7416

Quotation

DATE : 17.07.2018

VEH NO : SJC1803J

MODEL : Honda Civic

D O A : 16.07.2018

YR REF : SJM7557C

Attn : Motor Claim Dept.

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJC1803J (Honda Civic)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	638.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	40.80 ✓
4	Rear End Panel <i>Distorted</i>	1	300.50 ✓
5	Rear End Panel Top Garnish <i>Deformed</i>	1	78.60 ✓
6	Taillamp - LH & RH <i>caulked</i>	2	452.00 ✓
7	Taillamp Panel - LH & RH <i>RH Distorted</i>	2	142.60 71.30
8	Bootlid <i>Distorted</i>	1	693.80 ✓
9	Bootlid Lock <i>changed</i>	1	88.30 ✓
10	Bootlid Weatherstripe <i>cut</i>	1	100.30 ✓
11	Bootlid Lamp - LH & RH <i>cut</i>	2	306.60 ✓
12	Bootlid Hinge - LH & RH <i>Bent</i>	2	120.80 ✓
13	Bootlid Hinge Cover - LH & RH <i>new</i>	2	123.00 x
14	Bootlid Inner Trim Cover <i>Crumpled</i>	1	133.70 ✓
15	Bootlid Inner Trim Cover Clips <i>new</i>	1 set	30.00 ✓
16	Honda Logo	1	36.90 ✓
17	Civic Emblem <i>new</i>	1	34.60 ✓
18	1.6 Emblem	1	23.70 ✓
19	i-Vtec Emblem	1	40.50 ✓
20	Spare Tyre Panel <i>Repair</i>	1	911.40 x
21	Spare Tyre Panel Top Board <i>Deformed</i>	1	303.80 ✓
22	Spare Tyre Panel Lock Screw <i>new</i>	1	30.90 x
23	Rear Fender - RH <i>Repair</i>	1	853.90 x
24	Rear Fender Inner Trim Board - LH & RH <i>RH Crumpled</i>	2	434.80 217.40
25	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	60.00 30
26	Rear Exhaust Pipe	1	514.20 x
27	Rear Exhaust Mounting	1	36.00 x
28	Rear Exhaust Heat Shield	1	88.60 x

RE: ESTIMATE FOR ACCIDENT REPAIR SJC1803J (Honda Civic)

29	Rear Windscreen Moulding <i>Not new</i>	1	85.10 <i>X</i>
	3773.60		6,735.40
	3018.88	Less 20%	(1,347.08)
			<u>\$ 5,388.32</u>

S/NETT ITEMS

1	Rear Number Plate <i>Not new</i>	1	30.00 <i>X</i>
2	Rear Number Plate Holder <i>Not new</i>	1	30.00 <i>X</i>
3	Reverse Sensor <i>Damaged</i>	1 set	280.00 <i>200</i>
4	Rear End Panel Sealant <i>new</i>	1	60.00 <i>✓</i>
5	Spare Tyre Panel Insulation Pad <i>new</i>	1	280.00 <i>200</i>
6	Rear Exhaust Chrome Pipe <i>Not new</i>	2	200.00 <i>X</i>
7	Rear Windscreen Sealant <i>Not new</i>	1	60.00 <i>X</i>
	Total Parts		<u>\$ 6,328.32</u>

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,800.00 <i>1200</i>
2	To putty & spray up paint works	\$	1,500.00 <i>1200</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To remove reverse sensor	\$	100.00 <i>50</i>
5	To remove upholstery	\$	150.00 <i>80</i>
6	To remove exhaust pipe	\$	250.00 <i>200</i>
7	To underseal	\$	150.00 <i>60</i>
8	To remove rear windscreen	\$	180.00 <i>X</i>
9	To transfer bootlid fittings	\$	150.00 <i>80</i>
	Total Labour	\$	<u>4,330.00</u>

Grand Total

\$ 10,658.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

NOTE:

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY

Signature:
Date:

Total: 6258.88
L/S: SK 08 Days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8157G
Vehicle Details	
Vehicle No.:	SJC1803J
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6L VTI AUTO
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	R16A13002378
Chassis No.:	JHMF462085200779
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$18,993.00
Original Registration Date:	01 Feb 2008
First Registration Date:	01 Feb 2008
Transfer Count:	2
Actual ARF Paid:	\$20,893.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,485.00
COE Rebate Amount:	\$19,498.00
Total Rebate Amount:	\$19,498.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Jul 2018

OK

Hsiao Tong (LKKAuto)

From: Chin <chin@modernautomotive.com.sg>
Sent: Tuesday, 11 September 2018 2:35 PM
To: Thin Thin (LKKAuto)
Cc: Vivian Lau (LKKAuto)
Subject: Re: TP Settlement SJC1803L (AIG)
Attachments: 20180911144134.pdf

Dear Thin Thin

We refer to the above matter.

Kindly confirm settlement below:

Repair Cost: \$5350.00 (Incl GST)
LOR (\$120 x 9 days): \$1080.00
Search fee : \$2.00
Total: \$6,432.00

We enclosed herewith our LOD for your perusal.

Thank you

Regards,
Grace Chin
Modern Automotive Pte Ltd
Blk 3023-A, Ubi Road 1 #01-61
Singapore 408717

Tel: 6748 4422
Fax: 6747 6720

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SJM7557C

Our Ref : SJC1803J

Date : 11.09.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-3000 Fax : 6-415-3727

Attn : The Motor Claim Dept

**RE : ACCIDENT INVOLVING SJC1803J & SJM7557C ON 16.07.2018
AT UPPER ALJUNIED ROAD TOWARDS GEYLANG**

We refer to the above matter.

We have been authorized by our client Mr Lim Kian Soon to make claim against your insured vehicle No. SJM7557C in respect of the above accident for the following :

Repair Cost	\$ 5,350.00	(Incl GST)
Loss of rental (\$120 x 9 days)	\$ 1,080.00	
Search fee	\$ 2.00	
Total :	\$ 6,432.00	

9w
2w

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully


Modern Automotive Pte Ltd

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 10 January 2019 5:29 PM
To: Chin (chin@modernautomotive.com.sg)
Cc: Admin A
Subject: RE: TP Settlement SJC1803L (AIG) *LKK REF: CC6/AIG18012983/Apb3

Without Prejudice

Dear Sirs/Mdm.

We refer to the above matter.

We propose settlement at a global sum of **\$6,250.00(all-in)**

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chin <chin@modernautomotive.com.sg>
Sent: Tuesday, 11 September 2018 2:35 PM
To: Thin Thin (LKKAUTO) <thinthin@lkkauto.com>
Cc: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>
Subject: Re: TP Settlement SJC1803L (AIG)

Dear Thin Thin

We refer to the above matter.

Kindly confirm settlement below:

Repair Cost: \$5350.00 (Incl GST)
LOR (\$120 x 9 days): \$1080.00
Search fee : \$2.00
Total: \$6,432.00

We enclosed herewith our LOD for your perusal.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18012983/Apb3

04 JAN 2019

LATIFAH BTE WAGIMAN
BLK 680C JURONG WEST CENTRAL 1
#10-58
SINGAPORE 643680

Dear Sir/Madam,

**ACCIDENT INVOLVING SJM 7557C & SJC 1803J ALONG/AT UPP ALJUNIED
RD TWDS ALJUNIED RD BEFORE JLN MULIA ON 16/07/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJC 1803J against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORIZATION

Date: 17/7/2018

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SJC 1803J / SJM 7557C

ON 16/7/18 ALONG Upper Aljunied Road
Towards Geylang.

This letter is to authorize MODERN AUTOMOTIVE PTE LTD at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, MODERN AUTOMOTIVE PTE LTD has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of MODERN AUTOMOTIVE PTE LTD.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



Signature of Owner

Lim Kian Soon S7638157G

Name / NRIC

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,250.00 (Global Sum) for vehicle no. SJC 1803J that was damaged pursuant to the accident which occurred on 16/07/2018 (date) along UPPER ALJUNIED ROAD TWDS GEYLANG involving vehicle no/s SJM 7557C.

This is pursuant to the inspection conducted on 17/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner MR LIM KIAN SOON ("the third party claimant") of vehicle no. SJC 1803J make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJC 1803J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 14 (day) of Jan (month) 2019 (year)



Lup
Signed by appointed surveyor



Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01- 58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department
Contact : 6415-3727 6419-3000

Tax Invoice : TP001248

Date : 06/09/2018
Vehicle Num. : SJC 1803J
Make/Model : HONDA CIVIC-2008
Chassis/Eng# :
Accident Date : 16/07/2018
Claim No. :
Reference :
Policy No. : DMPCSN3017031800

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		5,000.00
		Labour Total S\$:		5,000.00

Total S\$: 5,000.00
GST @ 7% S\$: 350.00
Amount Due S\$: 5,350.00
=====



MODERN AUTOMOTIVE PTE LTD

MODERN LEASING

TP 53CL803J

REG NO. 53324316E

BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717 TEL : 6747 4422

FAX : 6747 6720

MODERN SALES & LEASING

BLK 3023A UBI ROAD 1

No. 0126

DATE: 17/7/18

#01-61, SINGAPORE 408717

TEL: 6747 4422 FAX: 6747 6720

VEHICLE RENTAL AGREEMENT

PARTICULARS OF HIRER

Name : Lim Kian Soon

Address : Blk 872B Tampines St 86
#07-65 Spore 522872

Tel (O) : (Fax) :

(HP): 97649746 Email :

Contact Person :

PARTICULARS OF DRIVER / AUTHORISED DRIVER

Name (as in IC) : As above

I/C or Passport No. :

Address :

Nationality :

D/Exp : (Yrs) D/L No. :

D/L Type : Local / International (please circle)

D/L Pass Date : (dd/mm/yy)

Date of Birth : (dd/mm/yy)

Tel (O) : (Fax) :

(HP): Email :

Additional Remarks:

VEHICLE DETAILS

Vehicle No : 3JP9709C

Vehicle Type : Kia Cerato

Vehicle Make :

Vehicle Model :

Vehicle Colour :

Vehicle Mileage :

RENTAL DETAILS

Start Date and Time : 17/7/18 @ 10-45am

End Date and Time : 26/7/18

RENTAL CHARGES

Daily Charge : \$120 x 9 days Deposit : -

Weekly Charge : Adv. Payment :

Monthly Charge : Total Charges : \$1080.00

***Note :** INTEREST OF LATE PAYMENT IS AT 2% PER MTH.
THE ABOVE RENTAL CHARGES INCLUDE SERVICING,
PREVENTIVE MAINTENANCE & REPAIR OF THE SAID
VEHICLE UNLESS THE DAMAGES WERE CAUSED
BY OPERATOR'S NEGLIGENCE OR ACCIDENTS.

IMPORTANT NOTICE

1. Hirer is **LIABLE** for the first (\$) 2000 excess in any accident plus cost of repair to the rented vehicle.
2. For usage to Malaysia subject to higher excess all claims of \$5000/- and different rental rate.
3. Driver or authorized driver should be at least 22 years old with minimum 2 years of driving experience.
4. Hirer is fully liable for all damages, losses, fines, summons and claims to and against the vehicle.
5. The vehicle is not to be used in any activities which may violate traffic rule or law, or in any other manner by which the vehicle might become liable to seizure or confiscation.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Replacement car will be given, if vehicle is under repair in workshop during rental period for more than 1 working day.
9. By signing this agreement, the hirer confirms having read all the terms and conditions and acknowledges that all information given above is true to his/her knowledge.

Stamp and/or Signature of Hirer

Signature of Driver / Authorised Driver

MODERN LEASING



MODERN SALES & LEASING

BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

TEL : 67474422 FAX : 67476720

REG NO. 53324316E

OFFICIAL RECEIPT

No. C/00001

Date: 26.07.2018

Received from Lim Kian Soon the sum of Dollars One Thousand & Eighty Only

being payment of SJP9709C from 17.07.2018 to 26.07.2018

For Modern Sales & Leasing





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-18-109009

Date of Request: 17/07/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date: 17/07/2018
Enquiry By: Chin Soi Shong
TP Vehicle No: SJM7557C
Accident Date: 16/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-109009

Date of Request: 17/07/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 17/07/2018
Enquiry By Chin Sol Shong
TP Vehicle No. SJM7557C
Accident Date 16/07/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJM7557C	AIG Asia Pacific Insurance Pte. Ltd.	21/09/2017-20/09/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING



















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018 Edit Reg		17 Jul 2018 00:00 Edit Adj Rpt	\$45,000.00 Edit Estimates	\$45,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LATIFAH BTE WAGIMAN , ID: S2180099F									
Main Claimant: MR LIM KIAN SOON , ID: S7638157G									
Vehicle Reg. No.: SJC1803J		Date of Loss: 16/07/2018 18:00 - :59 [125 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6622512739SG		Policy/Cover Note No.: 1700042587							
Vehicle Reg. No. (Insured): SJM7557C		Policy No. (Claimant): DMPCSN3017031800							
		Excess:							
Repairer: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJC1803J (6622512739SG)
[SJM7557C]
TP
MR LIM KIAN SOON
Jul 16 2018 6:00PM
[LATIFAH BTE WAGIMAN]
Modern Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ) Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	18/07/18 10:54	AIG Asia Pacific Insurance Pte. Ltd. (SG) Accident Statement <small>From: SC - Reg. No: SJM7557C, Claimant: LATIFAH BTE WAGIMAN</small>		Load HTM
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)				
1	03/09/18 18:02	General View		Load JPG
2	03/09/18 18:02	General View		Load JPG
3	03/09/18 18:02	General View		Load JPG
4	03/09/18 18:02	General View		Load JPG
5	03/09/18 18:02	General View		Load JPG
6	03/09/18 18:02	General View		Load JPG
7	03/09/18 18:02	General View		Load JPG
8	03/09/18 18:02	General View		Load JPG
9	03/09/18 18:02	General View		Load JPG
10	03/09/18 18:02	General View		Load JPG
11	03/09/18 18:02	General View		Load JPG
12	03/09/18 18:02	General View		Load JPG
13	03/09/18 18:02	General View		Load JPG
14	03/09/18 18:02	General View		Load JPG
15	03/09/18 18:02	General View		Load JPG
16	03/09/18 18:02	General View		Load JPG
17	03/09/18 18:02	General View		Load JPG
18	03/09/18 18:02	General View		Load JPG
19	03/09/18 18:02	General View		Load JPG
20	03/09/18 18:02	General View		Load JPG
21	03/09/18 18:02	General View		Load JPG
22	03/09/18 18:02	General View		Load JPG
23	03/09/18 18:02	General View		Load JPG
24	03/09/18 18:02	General View		Load JPG
25	03/09/18 18:02	General View		Load JPG
26	03/09/18 18:02	General View		Load JPG
27	03/09/18 18:02	General View		Load JPG
28	03/09/18 18:02	General View		Load JPG
29	03/09/18 18:02	General View		Load JPG
30	03/09/18 18:02	General View		Load JPG

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
32	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
33	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
34	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
35	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
36	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
37	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
38	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
39	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
40	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
41	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
42	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
43	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
44	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
45	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
46	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
47	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
48	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
49	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
50	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
51	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
52	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
53	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
54	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
55	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
56	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
57	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
58	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
59	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
60	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
61	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
62	03/09/18 18:02	General View		<input checked="" type="checkbox"/>
63	03/09/18 18:03	General View		<input checked="" type="checkbox"/>
64	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
65	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
66	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
67	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
68	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
69	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
70	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
71	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
72	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
73	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
74	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
75	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
76	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
77	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
78	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
79	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>
80	03/09/18 18:03	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
96	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
97	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
98	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
100	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
101	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
102	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
103	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
104	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
105	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
106	03/09/18 18:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 16:42	TP GIA REPORT	Load PDF	
2	04/01/19 08:12	TP ESTIMATE_MARKED	Load PDF	
3	18/01/19 08:54	WORKSHOP INVOICE	Load PDF	
4	18/01/19 08:54	AUTHORISATION TO ACT FORM	Load PDF	
5	18/01/19 08:54	Release Voucher	Load PDF	
6	18/01/19 08:54	RENTAL RECEIPT	Load PDF	
7	18/01/19 08:54	GIA SEARCH	Load PDF	
8	18/01/19 08:54	LETTER TO OI	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJM7557C (Insd veh)	Model:	HONDA CIVIC 1.3 EC8 (M)
	SJC1803J (TP veh)		
Date of Accident:	16/07/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	11,404.40
Final Repair Cost	:	\$	6,250.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	9 days
LTA / GIA Search Fee	:	\$	_____
Others:	:	\$	_____
	:	\$	_____
Final Settlement Sum (Global Sum)	:	\$	6,250.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 6,250.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

18 Jan
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18012983/APB3Q2

Date: 18/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700042587
Claimant Vehicle No : SJC1803J **Insured Vehicle No :** SJM7557C
 Date of Loss: 16/07/2018 Nature of Claim: TP Claim No: 6622512739SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC1803J**
 Make & Model: HONDA CIVIC, 1.3 EC8 (M) Engine No: R16A13002378
 Reg. Date: 01/02/2008 (Man. Year: 2007) Chassis No: JHMFD46208S200779
 Colour: Black Odometer: 178499 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,328.32	3,478.88	2,849.44	45.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,780.00	1,550.00	35.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,658.32	6,258.88	4,399.44	41.28
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	10,658.32	5,000.00	5,658.32	53.09
+ GST 7.00/7.00% (S\$)	746.08	350.00	396.08	53.09
Nett Amount (S\$)	11,404.40	5,350.00	6,054.40	53.09
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,252.00		
Global Sum Settlement (S\$)		6,250.00		

INSPECTION

Date of Assignment: 17/07/2018
 Date Inspected: 17/07/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	638.00 FL	*638.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	40.80 FL	*40.80 FL
4	1		*REAR END PANEL	Dented	300.50 FL	*300.50 FL
5	1		*REAR END PANEL TOP GARNISH	Deformed	78.60 FL	*78.60 FL
6	2		*TAILLAMP -LH & RH	Cracked	452.00 FL	*452.00 FL
7	1		*TAILLAMP PANEL -LH & RH	O/S Dented	142.60 FL	*71.30 FL
8	1		*BOOTLID	Dented	693.80 FL	*693.80 FL
9	1		*BOOTLID LOCK	Damaged	88.30 FL	*88.30 FL
10	1		*BOOTLID WEATHERSTRIPE	Cut	100.30 FL	*100.30 FL
11	2		*BOOTLID LAMP -LH& RH	Cut	308.60 FL	*308.60 FL
12	2		*BOOTLID HINGE -LH& RH	Bent	120.80 FL	*120.80 FL
13	2		*BOOTLID HINGE COVER -LH & RH	Not Necessary	123.00 FL	*- FL
14	1		*BOOTLID INNER TRIM COVER	Crumpled	133.70 FL	*133.70 FL
15	1		*SET BOOTLID INNER TRIM COVER CLIPS	Necessary	30.00 FL	*30.00 FL
16	1		*HONDA LOGO	Necessary	36.90 FL	*36.90 FL
17	1		*CIVIC EMBLEM	Necessary	34.60 FL	*34.60 FL
18	1		*1.6 EMBLEM	Necessary	23.70 FL	*23.70 FL
19	1		*I-VTEC EMBLEM	Necessary	40.50 FL	*40.50 FL
20	1		*SPARE TYRE PANEL	Repair	911.40 FL	*- FL
21	1		*SPARE TYRE PANEL TOP BOARD	Deformed	303.80 FL	*303.80 FL
22	1		*SPARE TYRE PANEL LOCK SCREW	Not Necessary	30.90 FL	*- FL
23	1		*REAR FENDER-RH	Repair	853.90 FL	*- FL
24	1		*REAR FENDER INNER TRIM BOARD -LH & RH	O/S Crumpled	434.80 FL	*217.40 FL
25	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*30.00 FL
26	1		*REAR EXHAUST PIPE	Not fitted	514.20 FL	*- FL
27	1		*REAR EXHAUST MOUNTING	Not Necessary	36.00 FL	*- FL
28	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	88.60 FL	*- FL
29	1		*REAR WINDSCREEN MOULDING	Not Necessary	85.10 FL	*- FL
30	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
31	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
32	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
34	1		*SPARE TYRE PANEL INFLATION PAD	Necessary	280.00 FS	*200.00 FS
35	2		*REAR EXHAUST CHROME PIPE	Not Necessary	200.00 FS	*- FS
36	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,675.40	4,233.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,347.08	754.72
Total Parts (\$\$)	6,328.32	3,478.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,800.00	1,200.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,500.00	1,200.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE EXHAUST PIPE	New	250.00	80.00
7	TO UNDERSEAL	New	150.00	60.00
8	TO REMOVE REAR WINDSCREEN	New	180.00	0.00
9	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			4,330.00	2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >