

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Thin Thin

Quotation

DATE : 17.07.2018
 VEH NO : SJC1803J
 MODEL : Honda Civic
 D O A : 16.07.2018
 YR REF : SJM7557C

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJC1803J (Honda Civic)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	638.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	40.80 ✓
4	Rear End Panel <i>Dented</i>	1	300.50 ✓
5	Rear End Panel Top Garnish <i>Deformed</i>	1	78.60 ✓
6	Taillamp - LH & RH <i>cracked</i>	2	452.00 ✓
7	Taillamp Panel - LH & RH <i>RH Dented</i>	2	142.80 71.30
8	Bootlid <i>Dented</i>	1	693.80 ✓
9	Bootlid Lock <i>Damaged</i>	1	88.30 ✓
10	Bootlid Weatherstripe <i>cut</i>	1	100.30 ✓
11	Bootlid Lamp - LH & RH <i>cut</i>	2	308.60 ✓
12	Bootlid Hinge - LH & RH <i>But</i>	2	120.80 ✓
13	Bootlid Hinge Cover - LH & RH <i>new</i>	2	123.00 ✓
14	Bootlid Inner Trim Cover <i>crumpled</i>	1	133.70 ✓
15	Bootlid Inner Trim Cover Clips <i>new</i>	1 set	30.00 ✓
16	Honda Logo	1	36.90 ✓
17	Civic Emblem <i>new</i>	1	34.60 ✓
18	1.6 Emblem	1	23.70 ✓
19	i-Vtec Emblem	1	40.50 ✓
20	Spare Tyre Panel <i>Repair</i>	1	911.40 ✓
21	Spare Tyre Panel Top Board <i>Deformed</i>	1	303.80 ✓
22	Spare Tyre Panel Lock Screw <i>new</i>	1	30.90 ✓
23	Rear Fender - RH <i>Repair</i>	1	853.90 ✓
24	Rear Fender Inner Trim Board - LH & RH <i>RH crumpled</i>	2	434.80 217.40
25	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	60.00 30
26	Rear Exhaust Pipe	1	514.20 ✓
27	Rear Exhaust Mounting <i>new</i>	1	36.00 ✓
28	Rear Exhaust Heat Shield	1	88.60 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SJC1803J (Honda Civic)

29	Rear Windscreen Moulding <i>new</i>	1	85.10 <i>X</i>
	3773.60		
	3018.88	Less 20%	
			6,735.40
			(1,347.08)
			<u>\$ 5,388.32</u>

S/NETT ITEMS

1	Rear Number Plate <i>new</i>	1	30.00 <i>X</i>
2	Rear Number Plate Holder <i>new</i>	1	30.00 <i>X</i>
3	Reverse Sensor <i>new</i>	1 set	280.00 <i>200</i>
4	Rear End Panel Sealant <i>new</i>	1	60.00 <i>40</i>
5	Spare Tyre Panel Insulation Pad <i>new</i>	1	280.00 <i>200</i>
6	Rear Exhaust Chrome Pipe <i>new</i>	2	200.00 <i>X</i>
7	Rear Windscreen Sealant <i>new</i>	1	60.00 <i>X</i>
	Total Parts		\$ 6,328.32

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,800.00 <i>1200</i>
2	To putty & spray up paint works	\$	1,500.00 <i>1200</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To remove reverse sensor	\$	100.00 <i>50</i>
5	To remove upholstery	\$	150.00 <i>80</i>
6	To remove exhaust pipe	\$	250.00 <i>200</i>
7	To underseal	\$	150.00 <i>60</i>
8	To remove rear windscreen	\$	180.00 <i>X</i>
9	To transfer bootlid fittings	\$	150.00 <i>80</i>
	Total Labour	\$	4,330.00

Grand Total

\$ 10,658.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

NOTE :

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY

Signature:

Date:

Total: 6258.88
L/S: SK 08 Days