


Customer Details:

SONG FENG
-
-
SINGAPORE
Fax: -
Handphone: 85118243



[View Photo](#) [Accident Photo](#)

Vehicle Details

Vehicle No : SLK 6073 A
Vehicle Make : HONDA
Vehicle Model : VEZEL 2017
Vehicle Engine No : T7AG7C1-NH788P
Engine
Chasis :
No
Mileage :

Owner's Accident Details

SN-
Job No : 002012-18-20027
TP -
JobCategory : Lump Sum
Date of Accident :
Owner's Insurer :
Location of Accident :

Surveyor's Details

Surveyor Name :
Surveyor :
Company
Surveyor :
ContactNo
Surveyor FaxNo :
Quotation :
Submission Date
Surveyor :
Approve Date
Supplementary :
Date
Supplementary :
Approve Date

Item No	Ref No	Description	QTY	Unit List Price	Mark Up / Discount %	Mark Up / Discount Price	Total Price	Rev Qty	Rev Unit Price	Remarks	Final Total Price	Surveyor Approval
---------	--------	-------------	-----	-----------------	----------------------	--------------------------	-------------	---------	----------------	---------	-------------------	-------------------

Materials												
1	1	Tailgate	1	\$953.30	-20.00	\$762.64	\$762.64	0	0		\$0.00	
2	2	Rear Bumper	1	\$508.80	-20.00	\$407.04	\$407.04	0	0		\$0.00	
3	3	Rear Bumper Clips	10	\$3.80	-20.00	\$3.04	\$30.40	0	0		\$0.00	
4	4	Rear End Panel	1	\$352.00	-20.00	\$281.60	\$281.60	0	0		\$0.00	

Material Total: \$1,481.68 Final Sub-Total : \$0.00

Special Nett Items

1	5	Reverse Sensor	1	\$220.00	0.00	\$220.00	\$220.00	0	0		\$0.00	
2	6	Reverse Camera	1	\$380.00	0.00	\$380.00	\$380.00	0	0		\$0.00	

Special Nett Items Total: \$600.00 Final Sub-Total : \$0.00

<u>Labour</u>										
1	7	Straighten & panel beat 1	\$800.00	0.00	\$800.00	\$800.00	0	0	\$0.00	_____
		accident damaged area								
2	8	Respray Accident damaged area 1	\$600.00	0.00	\$600.00	\$600.00	0	0	\$0.00	_____

Labour Total: \$1,400.00 Final Sub-Total : \$0.00

Others

Others Total: \$0.00 Final Sub-Total : \$0.00

Total Price: \$3,481.68 Final Total Price : \$0.00