

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18012989/R1RD3N2
Date: 03/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	CMPCSN3037051801
Claimant Vehicle No :	SLV2174K	Insured Vehicle No :	SLM4269E
Date of Loss:	14/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03502C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV2174K	Engine No:	P520450589
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0157879
Reg. Date:	26/12/2017 (Man. Year: 2017)	Odometer:	25866 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,597.20	1,212.00	1,385.20	53.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	460.00	1,130.00	71.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,187.20	1,672.00	2,515.20	60.07
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	4,187.20	1,150.00	3,037.20	72.54
+ GST 7.00/7.00% (S\$)	293.10	80.50	212.60	72.53
Nett Amount (S\$)	4,480.30	1,230.50	3,249.80	72.54

INSPECTION

Date of Assignment:	17/07/2018		
Date Inspected:	17/07/2018	Inspected At:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)
Parts:	143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SLV2174K/03/12/2019 11:33	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,075.00 FL	*1,075.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	18.00 FL	*- FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	102.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	74.00 FL	*- FL
5	2		*REAR BUMPER SIDE GUIDE	Necessary	92.00 FL	*92.00 FL
6	6		*REAR BUMPER SIDE GUIDE RIVETS	Necessary	30.00 FL	*30.00 FL
7	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
8	1		*REAR BUMPER END SPLASHIELD COVER	Not Necessary	80.00 FL	*- FL
9	1		*BOOTLID	Not Necessary	958.00 FL	*- FL
10	1		*BOOTLID LOCK	Not Necessary	153.00 FL	*- FL
11	1		*BOOTLID LOCK STRIKER BOTTOM	Not Necessary	34.00 FL	*- FL
12	1		*REAR BUMPER PARKING SENSOR	Not Working	450.00 FS	*200.00 FS
13	1		*REAR BUMPER TOW COVER RH	Missing	18.00 FL	*18.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,134.00	1,465.00
- List Item Discount on L Items 20.00/20.00% (\$)	536.80	253.00
Total Parts (\$)	2,597.20	1,212.00

LKK Auto Consultants Pte Ltd/SLV2174K/03/12/2019 11:33. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REINSTALL REAR BUMPER PARKING SENSOR	New	120.00	60.00
2	TO TRANSFER OF BOOTLID FITTINGS.ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	150.00	-
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	-
4	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	600.00	200.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	600.00	200.00
Gross Labour Cost (\$\$)			1,590.00	460.00

LKK Auto Consultants Pte Ltd/SLV2174K/03/12/2019 11:33. Not valid without Reference section.

< END OF ESTIMATES >