

**ComfortDelgro Engineering
Pte Ltd (Spark Car Care)
Pandan Branch
45 Pandan Road
Singapore 609286**

Claim Reference:
Assessment Number: RM000097
Version: CDGEPAND/1
Date Calculated: 17/07/2018 12:56

Full Report - V1
Registration: SGV4964T
Printed: 17/07/2018 19:57

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CDGE Pandan	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer: HONDA
Model: Edix
Sub Model: ES
Model Sheet Number: H38 11
Registration: SGV4964T
Registration Month: June
Registration Year: 2007
VIN Number:
Manufacture Month: June
Manufacture Year: 2007
Odometer: Not Known
Colour:
Engine Number:
Fuel Level: %

Model Specs

FROM MODEL 2007
1.8 LTR 103 KW
TYRES 195/65 HR 15
FRONT SPOILER
TWO COAT METALLIC
FOG LAMPS
AUTO GEARBOX 5 SPEED
WHEELS 6.5J X 16 ALU
REAR SKIRT
PAINTING OFF VEHICLE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Tanpin 97495447
wp
16/7/18 @ 1430
Resurvey before paint
12 days
sure 1/18/18 auto.com

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:



Acknowledged by Repairer
Signature: Severity of Impact:
Date: Vehicle Status on

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Inspection:
Date of Inspection: 17/07/2018

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

ComfortDelgro Engineering Pte Ltd (Spark Car Care)**Claim Reference:****Full Report - V1****Assessment Number: RM000097****Registration: SGV4964T****Version: CDGEPAND/1****Printed: 17/07/2018 19:57****Date Calculated: 17/07/2018 12:56****Addresses****Claimant**

Name : KEE KEY TECK

Address :

25 HAZEL PARK TERRACE #09-01
SINGAPORE

Post Code : 678948

Email Address : keeteckkee@gmail.com

Repairer

Name : COMFORTDELGRO ENGINEERING PTE LTD

Address :

45 PANDNAN ROAD

Post Code : 609286

Email Address : pandan_cr@sparkcarcare.com

Cost Summary

Total Labour	\$2,405.25
Total Paint/Material	\$420.93
Total Parts	\$7,459.00
Total of Additional Costs	\$210.00
Excess:	TBA
Grand Total Exc GST:	\$10,495.18
7 % GST:	\$734.66
Grand Total Inc GST:	\$11,229.84

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR****Price/Dent = \$45.00/HR****Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
71101-SJD)	R + R FRONT BUMPER	4.0	18.00
71101-SJD)	RENEW FRONT BUMPER (REMOVED)	2.0	9.00
33901-SJD	R + R L/F FOGLAMP	2.0	9.00
33901-SJD	R + R R/F FOGLAMP	2.0	9.00
NO NUMBER	R + R REAR BUMPER SPOILER	3.0	13.50
33101-SJD)	R + R LEFT HEADLAMP UNIT (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMP	4.0	18.00
33101-SJD)	R + R RIGHT HEADLAMP UNIT (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMP	4.0	18.00
71121-SJD)	RENEW RADIATOR GRILLE	1.0	4.50
60100-SJD)	R + R BONNET	3.0	13.50
60100-SJD)	RENEW BONNET (REMOVED)	4.0	18.00
60120-SAA	R + R L/BONNET HINGE	3.0	13.50
60120-SAA	R + R R/BONNET HINGE	3.0	13.50
74130-SJD)	R + R BONNET OPENER CABLE	1.0	4.50
76841-SJD)	R + R WASHER TANK	4.0	18.00

ComfortDelgro Engineering Pte Ltd (Spark Car Care)

Claim Reference:

Full Report - V1

Assessment Number: RM000097

Registration: SGV4964T

Version: CDGEPAND/1

Printed: 17/07/2018 19:57

Date Calculated: 17/07/2018 12:56

60261-SJD	R + R LEFT FRONT WING	5.0	22.50
60261-SJD	R + R RIGHT FRONT WING	5.0	22.50
60400-SJD	RENEW FRONT PANEL CPL	21.0	94.50
71501-SJD)	R + R REAR BUMPER	3.0	13.50
71530-SJD	R + R REAR BUMPER CARRIER	3.0	13.50
33501-SJD)	R + R L/TAILLAMP	1.0	4.50
33501-SJD)	R + R R/TAILLAMP	1.0	4.50
NO NUMBER	R + R L/R BUMPER BRACKET	1.0	4.50
NO NUMBER	R + R R/R BUMPER BRACKET	1.0	4.50
73511-SJD)	R + R LEFT REAR SIDE WINDOW GLASS	10.0	45.00
74551-SJD)	R + R L/R WHEELARCH SHELL	3.0	13.50
74480-SJD	R + R FUEL FLAP	1.0	4.50
68100-SJD)	R + R TAILGATE	6.0	27.00
68100-SAA)	RENEW TAILGATE	47.0	211.50
	(REMOVED)		
	INCLUDES: R + R REAR WINDOW, REAR WIPER, REAR WIPER MOTOR, LOCK, NUMBER PLATE LAMPS AND TAILGATE TRIMS		
68210-S5A)	R + R LEFT TAILGATE HINGE	1.0	4.50
68210-S5A)	R + R RIGHT TAILGATE HINGE	1.0	4.50
74440-SJD	R + R TAILGATE SEAL	3.0	13.50
74813-SED	R + R TAILGATE LOCK STRIKER	3.0	13.50
66100-SJD	RENEW REAR END PANEL CPL	44.0	198.00
04636-SJD	RENEW LEFT SIDE PANEL	84.0	378.00
83111-SJD)	R + R R/LOWER A-PILLAR TRIM	1.0	4.50
84131-SJD)	R + R L/UPPER C-PILLAR TRIM	3.0	13.50
84640-SJD	R + R REAR END PANEL TRIM	1.0	4.50
84601-SAA)	R + R L/BOOT COVER	2.0	9.00
84601-SAA)	R + R R/BOOT COVER	2.0	9.00
19010-RH0)	R + R RADIATOR CPL WITH ATTACHED PARTS	8.0	36.00
NO NUMBER	R + R LEFT REAR WHEEL	2.0	9.00
3221	CHECK REAR WIPER MOTOR	2.0*	9.00
7761	CHECK RADIATOR	5.0*	22.50

LABOUR COST

Total Work Units	310.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	31.0HRS	\$1,395.00
Labour Markup	(15.0 %)	\$209.25
Paint Labour	17.8HRS	\$801.00
Total Labour	48.8HRS	\$2,405.25

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PAINTING OFF VEHICLE		
340	BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	19.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
2711	REAR PANEL CPL NEW PART PAINTING	18.0	

ComfortDelgro Engineering Pte Ltd (Spark Car Care)

Claim Reference:

Assessment Number: RM000097

Version: CDGEPAND/1

Date Calculated: 17/07/2018 12:56

Full Report - V1

Registration: SGV4964T

Printed: 17/07/2018 19:57

2931	BOOTLID/TAILGATE NEW PART PAINTING	16.0	
3481	L/R WING NEW PART PAINTING	27.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
391	FRONT BUMPER SPOILER NEW PART PAINT K1R	7.0	
2583	REAR BUMPER NEW PART PAINT K1R	12.0	
2585	REAR BUMPER SPOILER NEW PART PAINT K1R	7.0	
2979	REAR NO PLATE TRIM NEW PART PAINT K1R	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	152.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	178.0	
	Total Paintwork Labour	17.8HRS	\$801.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$200.55
	New Part Painting - Plastic K1R		\$180.08
	Surface-/Blend Paint		\$13.20
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$420.93
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$420.93

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
3015	1	BADGE HONDA	75701SJD003		0% <i>ne</i> 18.00*
471	1	BONNET	60100SJD305ZZ		0% <i>bt</i> 380.00*
500	1	BONNET CABLE	74130SJD003		0% <i>x</i> 48.00*
481	1	BONNET INSULATION	74141SJD023		0% <i>x</i> 65.00*
492	1	BONNET LOCK	74120SJE12		0% <i>?</i> 28.00*
2977	1	BOOT/TAILGATE LOCK	74801S7S003		0% <i>?</i> 80.00*
2931	1	BOOTLID/TAILGATE	68100SJE90ZZ		0% <i>bt</i> 500.00*
343	1	BUMPER GRILLE	71102SJHE00		0% <i>?</i> 65.00*
340	1	BUMPER SUPPORT	71130SJDG00ZZ		0% <i>bt</i> 150.00*
283	1	FRONT BUMPER	71101SJDG00ZG		0% <i>de</i> 340.00*
391	1	FRONT BUMPER SPOILER	08F01SJD610		0% <i>x</i> 680.00*
1009	1	FRONT PANEL	60400SJDG01ZZ		0% <i>?</i> 305.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% <i>ne</i> 15.00*
410	1	GRILLE	71121SJD000		0% <i>ne</i> 140.00*
431	1	GRILLE BADGE	75700S9AG00		0% <i>ne</i> 13.00*
475	1	L/BONNET HINGE	60170SJD000ZZ		0% <i>Ry</i> 28.00*
345	1	L/F BUMPER COVER	71108SJD000		0% <i>x</i> 17.00*
1000	1	L/F CLIPS FENDER CVR	Renew		0% <i>ne</i> 6.00*
561	1	L/F HEADLAMP CPL	33151SJDE71		0% <i>aut</i> 420.00*
317	1	L/F OUT BUMPER BRKT	71198SJD013		0% <i>ne</i> 12.00*
319	1	L/F UPP BUMPER BRKT	71146SJD010		0% <i>ne</i> 28.00*
741	1	L/F WING	60261SJD000ZZ		0% <i>bt</i> 280.00*
2619	1	L/R BUMPER BRACKET	71598SJD003		0% <i>ne</i> 15.00*
3819	1	L/R CORNER WDW SEAL	73576SJD000		0% <i>ne</i> 80.00*
3281	1	L/R LAMP	33551SJE11		0% <i>cur</i> 210.00*
3571	1	L/R LAMP PANEL	63730SJDG00ZZ		0% <i>bt</i> 110.00*
3481	1	L/R WING	04646SJD310ZZ		0% <i>bt</i> 680.00*

ComfortDelgro Engineering Pte Ltd (Spark Car Care)

Claim Reference:
 Assessment Number: RM000097
 Version: CDGEPAND/1
 Date Calculated: 17/07/2018 12:56

Full Report - V1
 Registration: SGV4964T
 Printed: 17/07/2018 19:57

2953	1	L/TAILGATE HINGE	68260SJD003ZZ	0%	Ry	35.00*
841	1	L/WHEELHOUSE SHELL	74151SJD900	0%	?	55.00*
1000	1	R/ F CLIP FENDER CVR	Renew	0%	na	6.00*
476	1	R/BONNET HINGE	60120SJD000ZZ	0%	Ry	28.00*
346	1	R/F BUMPER COVER	71103SJD000	0%	?	17.00*
562	1	R/F HEADLAMP CPL	33101SJDE71	0%	?	420.00*
318	1	R/F OUT BUMPER BRKT	71193SJD013	0%	?	12.00*
320	1	R/F UPP BUMPER BRKT	71141SJD010	0%	?	28.00*
742	1	R/F WING	60211SJD000ZZ	0%	X	280.00*
2620	1	R/R BUMPER BRACKET	71593SJD003	0%	na	15.00*
842	1	R/WHEELHOUSE SHELL	74101SJD000	0%	X	55.00*
411	1	RAD GRILLE COVER	71123SJD010	0%	de	35.00*
414	1	RADIATOR GRILLE TRIM	71126SJDE00	0%	at	115.00*
2583	1	REAR BUMPER	71501SJD000ZH	0%	de	340.00*
2585	1	REAR BUMPER SPOILER	08F03SJD611	0%	X	800.00*
2979	1	REAR NO PLATE TRIM	74890SJDN41ZA	0%	X	110.00*
2711	1	REAR PANEL CPL	66100SJDG00ZZ	0%	bt	350.00*
3161	1	REAR SCREEN SEAL	04733SJD000	0%	na	30.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS	0%	na	15.00*
f: OEM Parts				Sub Total		\$7,459.00
g: Original				Sundry Parts		(Fixed) \$0.00
h: Secondhand				Total Parts		\$7,459.00
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FR NO.PLATE WCSIG SPECIALIST	0%	bt \$35.00
RR.NO PLATE W/CSIGSPECIALIST		X \$35.00
BODY SEALANT SPECIALIST	0%	/ \$60.00
WINDSCREEN SPECIALIST		/ \$60.00
SEALANT		
RAD COOLANT SPECIALIST	0%	? \$20.00
Total Extras		\$210.00

Final Calculation

Total Parts	\$7,459.00
Labour	
Total Panel/Mechanical	\$1,395.00
Total Paintwork	\$801.00
Labour Markup (15.0 %)	\$209.25
Total Labour	\$2,405.25
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$210.00
Total of Additional Costs	\$210.00
Total Paint/Material Costs	\$420.93
Grand Total Excludes GST	\$10,495.18
GST @ 7 %	\$734.66
Grand Total Includes GST	\$11,229.84

ComfortDelgro Engineering Pte Ltd (Spark Car Care)

Claim Reference:

Full Report - V1

Assessment Number: RM000097

Registration: SGV4964T

Version: CDGEPAND/1

Printed: 17/07/2018 19:57

Date Calculated: 17/07/2018 12:56

Assessment Notes
