

CARI KIAN HONG

CC 4, ALG 180

13014, T. 183 g

LKK:
IDAC

Surveyor:

Tan Fik

DOI:

27/1/18

Date / Time:

12/1/18

Registered in Merimen:

12/1/18

Pre-assigned / CCU / FTE



Insured Vehicle No.:

SKP 3416A

Name of Insured:

HENG CHENG MENG

Insured Tel No.:

HP:

90120337

Excess Ser II :SS

D.O.A.:

12/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

325001200006

Policy No.:

2100384109

Make / Model:

MITSUBISHI TRANA

Place of Accident:

SOUTH BUONA VISTA

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLZ 2410H



INSRS:

WSP:

Tel:

Liability:

RMKS:

12/1/18



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

19/1
CDESLZ 2410H. CC4/ALG 180/12033/183; VISA 30/6/18
SKP 3416A-X28/1/18
SitapInfo to UJD, confirmed accident status (Bola 71), informed
TP claim and HLD 18/1. UJ agreed to settle private HLD 18/1
and mention he have HLD protection. Send letter to UJ.
Send liability clear to TP workshop

Pending Estimate ✓

pass file to finalise

- FINALISED

- TP LOB IN, PENDING MATERIAL AGREEMENT

06/02/2020 - SEND EMAIL TO TP 1ST OFFER

07/02/2020 - TP ACCEPTED OFFER.

- ALL DOCS IN ORDER

- TO close.

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act: NO RIA

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA

Medical Bill:

PTR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

10/2/18

Sent By:

H/HK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: P/P

SS

1,144.23

(3 days)

Reduction:

63 %

Email

Call

FINAL SETTLEMENT

Date/Time:

06/02/2020

Confirm with:

KA YB

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost: (w/ GST)

SS

1,227.54

Loss of Rental (LOR) (w/ GST)

SS

53.60

(4 days)

x 120.00

Loss of Use (LOU):

SS

—

(5 x days)

Loss of Income (LOI):

SS

—

(5 x days)

LOR only ☒ LOU only ☐

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

—

Disbursement:

SS

—

(e.g. Tow/ Independent)

Legal Cost

SS

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4320.00

Total:

SS

1,743.14

Global Sum SS:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1,743.14

Name 1:

HUA HONG PRIVATE LIMITED

Payee 2: (Strike if N.A.)

SS

—

Name 2:

—

Payee 3: (Strike if N.A.)

SS

—

Name 3:

—

COPY SENT
27/1/2018

(08/11/13)

Surveyor:

Tanylin

REF:

ALG

11 Feb + 13

ASSIGNMENT

SL724104

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: _____ Yr Regn: 2010 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota CH-K C.C. 1797

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 20452 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 25X102114262

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____ D.O.I. 22/3/13 CIVIL

Survey held at: Due May

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	P/P \$1,147.23
	CROD: \$1,947.17 (63%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$ _____)

Transportation:

☐ : Interview (\$ _____)

S + RS, SI

☐ : Tech. Invs (\$ _____)

Photos

☐ : Weekend (\$ _____)

Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL



HUA HONG PRIVATE LIMITED

23D Sungai Kodat Street | Singapore 729332
Tel: (65) 6661 9668 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

23 July 2018

HHTPClaims18-72

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore 079120

Attn: Motor Claims Department

ACCIDENT INVOLVING SLZ 2410 H & SKP 3416 A ON 13/07/2018 ALONG BUONA VISTA RD AT ABOUT 0100 HOURS

Insured : HUA HONG PTE. LTD.
Vehicle Registration No : SLZ 2410 H
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No : ZYX102114262
Policy No : 5087272208-01
Date of Accident : 13/07/2018

			Type of Claim: Third Party	
S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 950.00 <i>EX</i>
2	2	Rear Bumper Retainer (LH/RH)	\$ 65.00	\$ 130.00 <i>EX</i>
3	15	Rear Bumper Clip	\$ 3.00	\$ 45.00 <i>EX</i>
4	1	Rear Bumper Lower Garnish		\$ 650.00 <i>al 472.4</i>
5	1	Rear Reinforcement		\$ 520.00 <i>318.9</i>
6	1	Rear Bumper Tow Cover		\$ 48.00 <i>EX</i>
				\$ 2,343.00 <i>836.3</i>
			Less 20%	\$ (468.60) <i>25%</i>
				\$ 1,874.40 <i>627.23</i>

To dismantle & change rear bumper, rear reinforcement, knocking & pull straight rear panel and all area affected by accident.

\$ 800.00 *250*

To perform wire checking.

\$ 20.00 *✓*

To spray rear bumper, rear reinforcement and rear panel. *plus to*

\$ 600.00 *250*

\$ 3,094.40
\$ 216.61
\$ 3,311.01

1147.23

7% GST
Total

Authorised by Claims Dept
Mrs Tan @ 9639 9195

LIK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495744
-WP-
27/7/18 @ 145
3 days

Repair before paint
suve@likauto.com



HUA HONG PRIVATE LIMITED

25D Sungel Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huhong.com.sg

Estimate Repair List

23 July 2018

HHTPClaims18-72

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore 079120

Attn: Motor Claims Department

ACCIDENT INVOLVING SLZ 2410 H & SKP 3416 A ON 13/07/2018 ALONG BUONA VISTA RD AT ABOUT 0100 HOURS

Insured : HUA HONG PTE. LTD.
Vehicle Registration No : SLZ 2410 H
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No : ZYX102114262
Policy No : 5087272209-01
Date of Accident : 13/07/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 950.00 <i>ex</i>
2	2	Rear Bumper Retainer (LH/RH)	\$ 65.00	\$ 130.00 <i>x</i>
3	15	Rear Bumper Clip	\$ 3.00	\$ 45.00 <i>nd</i>
4	1	Rear Bumper Lower Garnish		\$ 650.00 <i>at</i>
5	1	Rear Reinforcement		\$ 520.00 <i>?</i>
6	1	Rear Bumper Tow Cover		\$ 48.00 <i>x</i>
				\$ 2,343.00
				Less 20%
				\$ (468.60)
				\$ 1,874.40

To dismantle & change rear bumper, rear reinforcement, knocking & pull straight rear panel and all area affected by accident.

\$ 600.00 *250*

To perform wire checking.

\$ 20.00 *✓*

To spray rear bumper, rear reinforcement and rear panel. *plaster* *plaster*

\$ 600.00 *250*

\$ 3,094.40

7% GST

\$ 216.61

Total

\$ 3,311.01

Authorised by Claims Dept
Mrs Tan @ 9639 9195



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 97495749

-WP-
27/7/18 @ 1145

3 days

Repairing before paint

suor@lkkauto.com

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 23 July 2018 5:33 PM
To: 'Yvonne Toh'
Cc: Hsiao Tong (LKKAUTO); Admin A; assignments; 'jerleen@huahong.com.sg'
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKP3416A AND SLZ 2410 H ON 13/07/2018 *** LKK REF: CC4/AIG18013014/fa3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/AIG18013014/fa3
Your Ref: SLZ 2410H

Dear Yvonne,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, Kindly arrange for TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

- Pre repair inspection request - SLZ2410H VS SKP3416A (OI) DOA 13/07/2018

From: Mithoosingh, Aashweenjeetkaur

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Chan, Yoke Shi; Azlan, Syazairdina

Sent: 17/07/2018 5:17:52 PM

Attachments:  SKP3416A - PRLTIF

Hi,

Please refer to the enclosed request from HUA HONG PRIVATE LIMITED.

Claim no: 3256012888SG003

Case Owner: JACLYN MANIAM KESAVAL

If you have any queries/concerns, please let us know

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Yvonne Toh [mailto:yvonne@huahong.com.sg]

Sent: Tuesday, July 17, 2018 5:12 PM

To: Mithoosingh, Aashweenjeetkaur

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Chan, Yoke Shi; Azlan, Syazairdina; 'Jerleen Tang'

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKP3416A AND SLZ 2410 H ON 13/07/2018

Dear Sirs,

We choose LKK Auto Consultant.

Kindly advise on liability before survey.

Thank you.

Regards,

Yvonne Toh

Claims Department



HUA HONG PRIVATE LIMITED
250 SUNGAI KADUT STREET 1 SINGAPORE 729333
T: 6661 9688 | F: 6661 9699 | huahong.com.sg

From: Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>

Sent: Tuesday, 17 July 2018 4:20 PM

To: claims@huahong.com.sg

Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKP3416A AND SLZ2410H ON 13/07/2018

Without Prejudice

Your Reference: SLZ2410H

Our Reference: 3256012888SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kinh Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Quang	LKK Auto Consultants Pte Ltd

5.33pm @ 17/7/18
vehicle not in
person @ Yvonne

Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweneet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**HUA HONG PRIVATE LIMITED**

260 Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: claims@huahong.com.sg

16 July 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 Chartis Building
Singapore 079120

Attn: Motor Claims Dept
Fax: 6415 3727

Dear Sir/Mdm

ACCIDENT INVOLVING SLZ 2410 H & SKP 3416 A ON 13/07/18 ALONG BUONA VISTA RD AT ABOUT 0100 HOURS (THIRD PARTY CLAIM)

I refer to the matter above.

Please advise on the liability of the above-mentioned accident. A copy of the GIA report as attached for your perusal (total 5 pages including this letter).

Should you need any clarification, please email to claims@huahong.com.sg.

Thank you.

Yours Sincerely



Yvonne Koh
Motor Claims Dept
Tel: 6661 9688
Fax: 6661 9699

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jul 2018 Edit Reg		17 Jul 2018 00:00 Edit Adj Rpt	\$51,147.22 Edit Estimates	\$51,147.22 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	HENG CHENG MENG , ID: S13360793		
Main Claimant:	HUA HONG PTE LTD , Co. Reg. No.: 200900309M		
Vehicle Reg. No.:	SLZ2410H	Date of Loss:	13/07/2018 01:00 - :59 [2 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3256012888SG	Policy/Cover Note No.:	2100384109 (Comprehensive)
Vehicle Reg. No. (Insured):	SKP3416A	Policy No. (Claimant):	5087272209-01
		Excess:	
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/07/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ2410H (3256012888SG)
[SKP3416A]

TP

HUA HONG PTE LTD
Jul 13 2018 1:00AM
[HENG CHENG MENG]
Hua Hong Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page 1 ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown						1 Edit			
Assessment Reports										1 per page 1 ☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	18/07/18 09:34	Accident Statement From: SC - Reg. No: SKP3416A, Claimant: HENG CHENG MENG						1 Load HTM			
Photos/Images										3 per page 3 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	17/06/19 10:07	Odometer Reading						1 Load JPG		☒	
2	17/06/19 10:07	General View						1 Load JPG		☒	
3	17/06/19 10:07	General View						1 Load JPG		☒	
4	17/06/19 10:07	Chassis Number						1 Load JPG		☒	
5	17/06/19 10:07	General View						1 Load JPG		☒	
6	17/06/19 10:07	General View						1 Load JPG		☒	
7	17/06/19 10:07	General View						1 Load JPG		☒	
8	17/06/19 10:07	General View						1 Load JPG		☒	
9	17/06/19 10:07	General View						1 Load JPG		☒	
10	17/06/19 10:07	General View						1 Load JPG		☒	
11	17/06/19 10:07	General View						1 Load JPG		☒	
12	17/06/19 10:07	General View						1 Load JPG		☒	
13	17/06/19 10:07	General View						1 Load JPG		☒	
14	17/06/19 10:07	General View						1 Load JPG		☒	
15	17/06/19 10:07	General View						1 Load JPG		☒	
16	17/06/19 10:07	General View						1 Load JPG		☒	
17	17/06/19 10:07	General View						1 Load JPG		☒	
18	17/06/19 10:07	General View						1 Load JPG		☒	
19	17/06/19 10:07	General View						1 Load JPG		☒	
20	17/06/19 10:07	General View						1 Load JPG		☒	
21	17/06/19 10:07	General View						1 Load JPG		☒	
22	17/06/19 10:07	General View						1 Load JPG		☒	
23	17/06/19 10:07	Reinspection Photo						1 Load JPG		☒	
24	17/06/19 10:07	Reinspection Photo						1 Load JPG		☒	
25	17/06/19 10:07	Reinspection Photo						1 Load JPG		☒	
26	17/06/19 10:07	Reinspection Photo						1 Load JPG		☒	
27	17/06/19 10:07	Reinspection Photo						1 Load JPG		☒	
28	17/06/19 10:07	Reinspection Photo						1 Load JPG		☒	
29	17/06/19 10:07	Reinspection Photo						1 Load JPG		☒	
Documentation										1 per page 1 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	17/07/18 20:01	ACKNOWLEDGEMENT EMAIL TO AIG DD 17.07.2018						1 Load PDF			
2	17/07/18 20:01	EMAIL FROM AIG DD 17.07.2018						1 Load PDF			
3	17/07/18 20:01	NOTIFICATION FROM WORKSHOP + TP GIA REPORT						1 Load TIF			
4	23/07/18 17:52	LETTER TO OI						1 Load PDF			
5	10/08/18 00:45	TP ESTIMATE - MARKED						1 Load PDF			

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	10/02/20 08:57	WORKSHOP INVOICE	1	Load PDF	
7	10/02/20 08:57	Release Voucher	1	Load PDF	
8	10/02/20 08:57	RENTAL RECEIPT	1	Load PDF	
9	10/02/20 08:57	GIA SEARCH	1	Load PDF	
10	10/02/20 08:57	LOD	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKP3416A (Insd veh)	Model:	TOYOTA C-HR HYBRID 1.8
	SLZ2410H (TP veh)		S CVT (A)
Date of Accident:	13/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	3,311.01
Final Repair Cost	:	\$	1,227.54
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	513.60 4 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,743.14

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hua Hong Pte Ltd	:	\$ 1,743.14
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 Feb

2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18013014/T1HA3Q2

Date: 10/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100384109
Claimant
Vehicle No : SLZ2410H **Insured Vehicle No :** SKP3416A
Date of Loss: 13/07/2018 **Nature of Claim:** TP **Claim No:** 3256012888SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ2410H**
 Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8411838
 Reg. Date: 26/04/2018 (Man. Year: 2018) Chassis No: ZYX102114262
 Colour: Silver Odometer: 20452 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,874.40	627.22	1,247.18	66.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	520.00	700.00	57.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,094.40	1,147.22	1,947.18	62.93
+ GST 7.00/7.00% (S\$)	216.61	80.31	136.30	62.92
Nett Amount (S\$)	3,311.01	1,227.53	2,083.48	62.93
+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$)		513.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,743.13		

INSPECTION

Date of Assignment: 17/07/2018
 Date Inspected: 27/07/2018 Inspected At: Hua Hong Pte Ltd (Sungei Kadut)
 25D Sungei Kadut Street 1
 Singapore 729332
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	950.00 FL	*- FL
2	2		*REAR BUMPER RETAINER (LH/RH)	Not Necessary	130.00 FL	*- FL
3	15		*REAR BUMPER CLIP	Necessary	45.00 FL	*45.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Cut	650.00 FL	*472.40 FL
5	1		*REAR REINFORCEMENT	Bent	520.00 FL	*318.90 FL
6	1		*REAR BUMPER TOW COVER	Not Necessary	48.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,343.00	836.30
- List Item Discount on L Items 20.00/25.00% (\$\$)	468.60	209.08
Total Parts (\$\$)	1,874.40	627.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & CHARGE REAR BUMPER ,REAR REINFORCEMENT ,KNOCKING & PULL STRAIGHT REAR PANEL AND ALL AREA AFFECTED BY ACCIDENT	New	600.00	250.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO SPRAY REAR BUMPER,REAR REINFORCEMENT AND REAR PANEL	New	600.00	250.00
Gross Labour Cost (\$\$)			1,220.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >