

ASSIGNMENT

From: Date: 17/07/18

Estimated Cost:

OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SLF 4864Z

at Workshop m/s

of

Comfort Delgro
205 Briddell Road

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF 4864Z

Yr Regn:

29 Aug 2016Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda vesel

C.C.

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

104617

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU11117392Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ Rim or

Tyre Size:

F:

215/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

17-07-18

Survey held at

W/S4pmDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/7 + 4,997.30 (RSD: 1,998.36 29%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLF4864Z Case Owner : WILLIAM

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11117392 Engine No : L15B4037398

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : IP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing ✓ <i>WTS</i>	1				\$ 45.00	✓
2	Rear number plate lamp LH } x <i>NIN</i>	1		\$ 35.60			
3	Rear number plate lamp RH } x <i>NIN</i>	1		\$ 35.60			
4	Rear bumper ✓ <i>DE</i>	1		\$ 508.50	✓		
5	Rear bumper corner LH x } <i>DE</i>	1		\$ 195.00			
6	Rear bumper corner RH x }	1		\$ 195.00			
7	Rear bumper reflector LH x }	1		\$ 135.00			
8	Rear bumper reflector RH x } <i>NIN</i>	1		\$ 135.00			
9	Rear bumper retainer LH x }	1		\$ 17.50			
10	Rear bumper retainer RH x }	1		\$ 17.50			
11	Rear bumper clips ✓ <i>NEL</i>	1		\$ 31.20	✓		
12	Tail lamp LH ✓ <i>DE</i>	1		\$ 428.70	✓		
13	Tail lamp RH ✓ <i>DE</i>	1		\$ 428.70	✓		
14	Tailgate ✓ <i>DE</i>	1		\$ 1,100.90	✓		
15	Tailgate badge logo ✓ <i>NEL</i>	1		\$ 27.10	✓		
16	Tailgate emblem - VEZEL ✓ <i>NEL</i>	1		\$ 47.90	✓		
17	Tailgate emblem - HYBRID x <i>NIN</i>	1		NA			
18	Tailgate weatherstrip x <i>NIN</i>	1		\$ 96.80			
19	Tailgate lamp LH ✓ <i>DE</i>	1		\$ 240.00	✓		
20	Tailgate lamp RH x <i>NIN</i>	1		\$ 240.00			
21	Tailgate upper lock ✓ <i>BT</i>	1		\$ 96.60	✓		
22	Tailgate outer garnish ✓ <i>DE</i>	1		\$ 189.80	✓		
23	Tailgate inner lower trimboard ✓ <i>DE</i>	1		\$ 153.40	✓		
24	Tailgate opening switch x <i>NIN</i>	1		\$ 175.50			
25	Rear windscreen moulding ✓ <i>NEL</i>	1		\$ 151.80	✓		
26	Rear windscreen sealant ✓ <i>NEL</i>	1				\$ 40.00	✓
27	Rear windscreen inner seal ✓ <i>NEL</i>	1				\$ 30.00	✓
28	Rear end panel x <i>NIN</i>	1		\$ 365.70			
29	Rear end panel inner garnish ✓ <i>DE</i>	1		\$ 98.30	✓		
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

17/07/2018

6:00 PM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary items must be resurveyed and subject to final approval from Insurance Company

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284 62815767

Date:

Labour

Vehicle No. : **SLF4864Z**
Make & Model : **HONDA VEZEL 1.5X CVT**

Case Owner : **WILLIAM**
Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove/refit rear windscreen to facilitate repairs.	\$120.00	/
2	To transfer tailgate parts and fittings to new tailgate.	\$120.00	100
3	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$180.00	/
4	Labour charges to repair and panel beat rear end panel, bootfloor/spare tyre panel and replace damaged parts (PER DAY \$240)	\$960.00	780 2240 720
5	To replace reverse sensor set and check wiring functions.	\$180.00	80 80
6	To putty, apply primer & spray-paint the rear bumper, tailgate, rear end panel, bootfloor/spare panel and affected areas. (PER PANEL \$250)	\$1,000.00	750
7	To apply rust-proofing on repaired/replaced panels.	\$150.00	80
To: Guo Qiang			
Parts = 3500.90			
-20% 700.58			
= 2800.32			
+ SN 115.00			
+ Labour 2030.00			
= 4945.32			
21/8/18			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLF4864ZMake & Model : HONDA VEZEL 1.5X CVTYear of Manufacture : 2016Chassis No. : RU11117392Ins Company : AIG VS FWDEngine No. : L15B4037398Excess : -Policy No. : -Date of Accident : 14.07.2018Time of Accident : 12:15Suggested Days of Repair : -

In-house Vehicle Assessor

Repair EstimateCase Owner : WILLIAMSignature : -Parts (a) Cost / List Price Items : \$ 5,141.10 -Plus/Less 20% : \$ 1,009.42 -Total of Cost / List : \$ 4,131.68 -(b) Nett Price Items : \$ -Less : -Total of Nett Item : -(c) Special Nett Items : \$ 115.00 -Total Parts Cost (Appendix A) : \$ -Labour (Appendix B) : \$ 2,710.00Total Repair Cost : \$ 2,710.00 6942.68

Contact No
Frt Counter Operation
 63837103 - Patrick Tia
 63837730 - Brenda Ng
 63837466 - Rohani
braddell_cn@sparkcarcare.com

Workshop Operation
 63837656 - Ngo Toh Wee
 63837362 -
 63838115 - William Wang
 63838115 - Andrew Goh
braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang - 82880282Company : UKICSurvey conducted on : 17/7/18 at -**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 5-6 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ -(e) Signature of surveyor : - Date: -

part by part.
 before paint photos.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLF4864Z Case Owner : WILLIAM

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11117392 Engine No : L15B4037398

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing / <i>GA</i>	1					
2	Rear number plate lamp LH / <i>GA</i>	1					
3	Rear number plate lamp RH / <i>CPA</i>	1					
4	Rear bumper / <i>RE</i>	1					
5	Rear bumper corner LH <i>X</i> (<i>Repair</i>)	1					
6	Rear bumper corner RH <i>X</i> (<i>Repair</i>)	1					
7	Rear bumper reflector LH <i>X</i>	1					
8	Rear bumper reflector RH <i>X</i>	1					
9	Rear bumper retainer LH / <i>GA</i>	1					
10	Rear bumper retainer RH / <i>GA</i>	1					
11	Rear bumper clips	1					
12	Taillamp LH <i>X</i> / <i>CPA</i>	1					
13	Taillamp RH / <i>CPA</i>	1					
14	Tailgate / <i>GA</i>	1					
15	Tailgate badge logo	1					
16	Tailgate emblem - VEZEL / <i>GA</i>	1					
17	Tailgate emblem - HYBRID	1					
18	Tailgate weatherstrip	1					
19	Tailgate lamp LH / <i>CPA</i>	1					
20	Tailgate lamp RH	1					
21	Tailgate upper lock <i>X</i> / <i>BI</i>	1					
22	Tailgate outer garnish / <i>CPA</i>	1					
23	Tailgate inner lower trimboard <i>X</i> / <i>RE</i>	1					
24	Tailgate opening switch	1					
25	Rear windscreen moulding	1					
26	Rear windscreen sealant	1					
27	Rear windscreen inner seal	1					
28	Rear end panel	1					
29	Rear end panel inner garnish <i>X</i> / <i>RE</i>	1					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Case Owner	:	<u>WILLIAM</u>
Year of Manufacture	:	2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SLF4864Z
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR
Chassis No. :	RU11117392
Propellant :	Petrol
Engine No. :	L15B4037398
Engine Capacity :	1496 cc
Maximum Power Output :	96.0 kW (128 bhp)
Maximum Laden Weight :	1465 kg
Unladen Weight :	1190 kg
Year Of Manufacture :	2016
Original Registration Date :	29 Aug 2016
Lifespan Expiry Date :	-
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	\$47,020.00
COE Expiry Date :	28 Aug 2026
Road Tax Expiry Date :	28 Feb 2019
PARF Eligibility Expiry Date :	28 Aug 2026
Inspection Due Date :	28 Aug 2019
Intended Transfer Date :	20 Jul 2018
CO2 Emission :	117.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$10,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLF4864Z Case Owner : WILLIAM

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11117392 Engine No : L15B4037398

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing / GA	1					
2	Rear number plate lamp LH / W	1					
3	Rear number plate lamp RH / CPA	1					
4	Rear bumper / RE	1					
5	Rear bumper corner LH ?	1					
6	Rear bumper corner RH ?	1					
7	Rear bumper reflector LH X	1					
8	Rear bumper reflector RH X	1					
9	Rear bumper retainer LH / LAL	1					
10	Rear bumper retainer RH / LAL	1					
11	Rear bumper clips /	1					
12	Taillamp LH ?	1					
13	Taillamp RH / CPA	1					
14	Tailgate / bu	1					
15	Tailgate badge logo /	1					
16	Tailgate emblem - VEZEL / LAL	1					
17	Tailgate emblem - HYBRID /	1					
18	Tailgate weatherstrip ?	1					
19	Tailgate lamp LH / CPA	1					
20	Tailgate lamp RH	1					
21	Tailgate upper lock ?	1					
22	Tailgate outer garnish / CPA	1					
23	Tailgate inner lower trimboard ?	1					
24	Tailgate opening switch ?	1					
25	Rear windscreen moulding /	1					
26	Rear windscreen sealant /	1					
27	Rear windscreen inner seal /	1					
28	Rear end panel ?	1					
29	Rear end panel inner garnish ?	1					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Case Owner	:	<u>WILLIAM</u>
Year of Manufacture	:	2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 24 July 2018 11:17 AM
To: 'CDGE Braddell Private Cars Crash Repair Operation'
Cc: CDGE Braddell Private Cars Crash Repair Counter
Subject: RE: SLF4864Z CLAIMING AGAINST SLF6990D DOA14072018 CHECK LIABILITY (LCR VEHICLE)

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Sent: Wednesday, 18 July 2018 11:07 AM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Cc: CDGE Braddell Private Cars Crash Repair Counter <braddell_cr@sparkcarcare.com>
Subject: Re: SLF4864Z CLAIMING AGAINST SLF6990D DOA14072018 CHECK LIABILITY (LCR VEHICLE)

Dear Sir / Madam,

We wait for your reply.

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Sent: Wednesday, 18 July 2018 8:53:07 AM

To: CDGE Braddell Private Cars Crash Repair Operation

Cc: CDGE Braddell Private Cars Crash Repair Counter

Subject: RE: SLF4864Z CLAIMING AGAINST SLF6990D DOA14072018 CHECK LIABILITY (LCR VEHICLE)

Without Prejudice

Hi Sir,

We refer to the email below.

We yet to received our insured report till date.

Shall revert to you once we received our insured report.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]

Sent: Tuesday, 17 July 2018 6:18 PM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Cc: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>; CDGE Braddell Private Cars Crash Repair Counter <braddell_cr@sparkcarcare.com>

Subject: SLF4864Z CLAIMING AGAINST SLF6990D DOA14072018 CHECK LIABILITY (LCR VEHICLE)

Dear Sir / Madam,

Please be inform that the said vehicle had been survey today. Kindly assist to check liability for this case.

Your insured vehicle number is SLF6990D
Please see attached and reply as soon as possible.

William Wang

Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)
Fax: 6281 5767
www.SPARKcarcare.com

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	17 Jul 2018 20:18	Cim Veh Model Changed	(204735) HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A).		[A] HOW MEI KWAN
2	17 Jul 2018 20:18	Cim Created	Reg No: SLF4864Z. Acct Date: 2018/07/14. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Comfort DelGro Engineering Pte Ltd (Braddell)		[A] HOW MEI KWAN
3	17 Jul 2018 20:18	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : VICOM Ltd.		[A] HOW MEI KWAN
4	17 Jul 2018 20:18	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/26		[A] HOW MEI KWAN
5	17 Jul 2018 20:18	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] HOW MEI KWAN
6	17 Jul 2018 20:19	Adj Adjuster Assigned	[None] -> XING GUO QIANG		[A] HOW MEI KWAN
7	18 Jul 2018 10:36	Cim Registration Modified	Pol No:->PNPV2017-00007815.		[I] Josey Loh
8	12 Dec 2018 10:10	Label Added	(20005):Direct Settlement .		[A] Asher Sng Rong Yi
9	12 Dec 2018 10:12	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/07/26		[A] Asher Sng Rong Yi
10	02 Jan 2019 15:27	Adj Rpt Initiated			[A] JOANNE LEE KHANG MIN
11	02 Jan 2019 15:27	Cim Dtl Modified	3PJ Reg. Date: -> 2016/08/29.		[A] JOANNE LEE KHANG MIN
12	02 Jan 2019 15:27	Cim Details Notified			[A] JOANNE LEE KHANG MIN
13	02 Jan 2019 17:32	Adj Mandate Request	Cur.Req:6045.63:LIABILITY: 100% B:27 OI REAR ENDED TP QUANTUM: (a) COR w/GS T: 5,293.63 + (b) LOR: \$750.00 (10days x \$75) + (c) LTA :\$2.00 Total: a+b+c = \$6,045.63 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.		[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

[20/07/2018 19:43] HOW MEI KWAN:
estimated cost of repair incomplete - no parts price

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2000946	12/12/2018 10:12	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLF4864Z	SLF6990D	10.70

Print Received Message

This mail is associated with :

***SLF4864Z (1201800009025)**
[SLF6990D]

TP

LCRF PTE LTD

Jul 14 2018 12:00PM

[Mosses Lee Siu Wen]

ComfortDelGro Engineering Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 23/01/2019 09:23 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6045.63) - SLF4864Z - Claim Handler: Lionel Tan

Approved:6045.63:To offer LOU at \$60 per day.

PTE/SLF4864Z/20180714/DS-CL
29/10/2018

M/s FWD SINGAPORE PTE.LTD.
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Attn: Motor Claims Department

WITHOUT PREJUDICE.

Dear Sirs

ACCIDENT ON 14/07/2018 INVOLVING SLF4864Z & SLF6990D
ALONG SLIP ROAD OF WOODLANDS AVE 5 TOWARDS WOODLANDS AVE 3

We are the authorised repair workshop for the owner of vehicle, SLF4864Z, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorised us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, SLF6990D, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repairs	5,293.63
2. 12.5 days Car Rental @ \$75	937.50
3. Loss of Use	-
4. Surveyor Fee	-
5. LTA Fee	-
6. TP/GIA Fee	2.00
7. Medical	-
8. Others	-

(E&OE) 6,233.13

We enclose the following documents to support the claims: -

- | | |
|---|---|
| <input checked="" type="checkbox"/> Repair/Excess Bill | <input checked="" type="checkbox"/> Insurance Certificate |
| <input checked="" type="checkbox"/> Surveyor Report | <input checked="" type="checkbox"/> Power of Attorney |
| <input checked="" type="checkbox"/> Coloured Photographs | <input checked="" type="checkbox"/> Car Rental Bill |
| <input checked="" type="checkbox"/> GIA/Police Report(s) | <input checked="" type="checkbox"/> Medical Bill |
| <input checked="" type="checkbox"/> GIA/TP Search | <input checked="" type="checkbox"/> Witness Statement |
| <input checked="" type="checkbox"/> Others: <u>Rental Agreement & vehicle Replacement Voucher</u> | |

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully

Cecilia Lee

CDGE Claims Department

59 Loyang Drive S(508969)

DID: 6214 8354

FAX: 6214 1843

Email: cecilialee@sparkcarcare.com



ComfortDelGro Engineering

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road Singapore 579701
Mobile +65 9353 6280
Facsimile +65 6290 0755

Company Registration No: 199700009

Car Care Centres

Braddell
205 Braddell Road
Singapore 579701
Tel 6253 6110

Loyang
59 Loyang Drive
Singapore 508969
Tel 6214 8355

Pandan
65 Pandan Road
Singapore 605006
Tel 6328 0175

Sin Ming
59 Sin Ming Drive
Singapore 575717
Tel 6253 0400

Sungei Kadut
2 Sungei Kadut Way
Singapore 729781
Tel 6260 7300

Ubi
120 Ubi Road 1
Singapore 620048
Tel 6248 0721

www.SPARKS-CAR-CARE.com

A member of

COMFORTDELGRO



COMFORTDELGRO ENGINEERING PTE LTD

A member of COMFORT Group

POWER OF ATTORNEY

ACCIDENT INVOLVING (Owner's Vehicle No.) SLF4864Z and (Third Party's Vehicle No.)
SLF6990D on 14/7/18 along Ship Road of Woodlands Ave 5
Twice Woodlands Ave 3

Policy Nos: 1

BY THIS POWER OF ATTORNEY, *I/We, LCRF pte ltd *NRIC/Passport

No. 201624597K (Address)* _____

_____ a company

incorporate in Singapore and having its registered office at (Address)* _____

_____ owner of Vehicle Registered No. SLF4864Z

_____ hereby irrevocably appoint ComfortDelGro Engineering Pte Ltd (CDGE), a
company incorporated in Singapore and having its registered office at 205 Braddell Road (S) 57970

its agents or any person authorized by CDGE to be *my/our Attorney and in *my/our name(s) and on *my/our behalf
to do all or any of the following:

1. To submit, resolve and make any claim(s) (including the commencement of legal proceedings) which *I/we may have against the other *party/parties to the Accident and under the insurance *policy/policies taken up by such *party/parties or alternatively under Insurance Policy No. _____ taken up by *me/us in respect of the cost of repairs, loss of use and at all other costs and expenses, etc. suffered by *me/us arising from the Accident (loss and damage).
2. For the purpose of such claim(s) as aforesaid, to appoint solicitors on *my/our behalf as *my/our Attorney **shall in his absolute discretion, deem fit.**
3. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of cheque in favor of ComfortDelGro Engineering Pte Ltd, CDGE and to give a valid receipt and discharge therefor.
4. For any of the purposes aforesaid, **to execute, sign, seal and deliver all documents whatsoever in relation thereto.**
5. Generally **do all such acts as it shall deem necessary for the purpose of settling such claim(s) and**
6. **To agree to any settlement at the absolute discretion of CDGE.**

*I/We hereby declare that all acts, instruments and documents done by virtue of this Power of Attorney on *my/our behalf by the Attorney, its agents or any person authorized by CDGE in that behalf shall be as good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by *me/us in *my/our own proper person(s) and *I/We hereby ratify and confirm, all acts, instruments and documents done or executed by virtue of the authority and powers hereby conferred.

*I/We hereby further declare that **the powers and authority hereby conferred shall remain irrevocable.**

*I/We further confirm that the acceptance by CDGE of the settlement amount in respect of such constitute the full discharge of my/our claim(s) in respect of such loss and damage.

*IN WITNESS WHEREOF, *I/We have hereunto to set *my/our hand and seal this day 17 of the month of
07, Year Two Thousand 18 (2018)

Signed, Sealed & Delivered By



Customers Name: LCRF P/L
NRIC No.: 201624597K
Co's rubber Stamp

delete as appropriate. Insurance

RELEASE

Claim Reference:	1201800009025
Surveyor's Reference:	CC4/FWD18013015/Gea3
TP Reference:	PTE/SLF4864Z/20180714/DS-CL

We, **COMFORTDELGRO ENGINEERING PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SLF 4864Z** ("Vehicle") to accept the sum of **\$5,895.63**, being the amount claimed for **\$5,293.63** (repair costs), **\$600.00** (loss of rental/ use), **\$ -** (loss of income), **\$2.00** (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **14/07/2018** (date of accident) at / along **SUP RD OF WOODLANDS AVE 5 TWDS WOODLANDS AVE 3** (location) involving vehicle no/s. **SLF 4864Z** and **SLF 6990D**.

This is pursuant to the inspection conducted on **17/07/2018** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SLF 6990D** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 27 day of Nov 2019

CLAIMANT

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
205 BRADDELL ROAD
SINGAPORE 579701

[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



XGQ

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road
Singapore 579701
Mainline + 65 6383 6280
Facsimile + 65 6380 9755
www.cdge.com.sg

Car Care Centres
205 Braddell Road Singapore 579701
59 Luyang Drive Singapore 508960
45 Pandan Road Singapore 605286
383 Sin Ming Drive Singapore 575717
7 Sungei Kadut Way Singapore 728791
320 Ubi Road 3 Singapore 408649
501 Hishun Industrial Park A Singapore 768732
www.SPARKcarcare.com

Tel: 6383 8110
Tel: 6214 8300
Tel: 6338 8778
Tel: 6553 0400
Tel: 6360 7369
Tel: 6646 5721
Tel: 6757 7898



ComfortDelGro Engineering
COMPANY REG. NO: 199506048W
GST REG. NO. M2-0021817-3

TAX INVOICE

8010655.

FWD SINGAPORE PTE LTD
SUNTEC TOWER 4

18-01 6 TEMASEK BOULEVARD

SINGAPORE SG 038986

CONTACT NO: 67275700

VEHICLE NO
SLF4864Z

MAKE
HONDA

MODEL
VEZEL

DATE OF REG
29.08.2016

CHASSIS CODE
RU11117392

INVOICE NO. /DATE
91403835 25.10.2018

JOB NO.
305188157

ODOMETER READING

Description : TP - AIG - FWD

S/No	Part No. Description	Qty	Unit Price	Net
01	20-501 LABOUR CHARGES	1 EAC	2,030.00 SGD	2,030.00
02	29904 INNER SEAL	1 PC	30.00 SGD	30.00
03	29906 SEALANT	1 EAC	40.00 SGD	40.00
04	1979 REAR NO. PLATE W/CASING	1 PC	45.00 SGD	45.00
05	1979 REAR BUMPER	1 PC	406.80 SGD	406.80
06	1979 REAR BUMPER CLIPS	8 PC	3.12 SGD	24.96
07	1979 TAILLAMP RH	1 PC	342.96 SGD	342.96
08	1979 TAILGATE	1 PC	880.72 SGD	880.72

Cheque should be crossed and made payable to "ComfortDelGro Engineering Pte Ltd"

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Blk C Ext 1 Level 2
Singapore 579701

Attn: Finance Department

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010655	91403835	5,293.63	

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road
Singapore 579701
MObline: +65 6383 6283
Facsimile: +65 6380 9755
www.cdg.com.sg

Car Care Centres
205 Braddell Road Singapore 579701
39 Luyang Drive Singapore 508969
45 Pandan Road Singapore 608286
381 Sin Ming Drive Singapore 575717
7 Sungei Kadut Way Singapore 728791
320 Ubi Road 3 Singapore 408649
501 Yohon Industrial Park A Singapore 768733
www.SPARKcarcare.com

Tel: 6383 8110
Tel: 6214 8900
Tel: 6338 8778
Tel: 6553 0400
Tel: 6368 7369
Tel: 6648 5721
Tel: 6757 7998



ComfortDelGro Engineering
COMPANY REG. NO: 199506048W
GST REG. NO. M8021817-3

TAX INVOICE

8010655.

FWD SINGAPORE PTE LTD
SUNTEC TOWER 4

18-01 6 TEMASEK BOULEVARD

SINGAPORE SG 038986

VEHICLE NO
SLF4864Z

MAKE
HONDA

MODEL
VEZEL

DATE OF REG
29.08.2016

CHASSIS CODE
RU11117392

INVOICE NO./DATE
91403835 25.10.2018

JOB NO.
305188157

ODOMETER READING

S/No	Part No. Description	Qty	Unit Price	Net
09	1979 TAILGATE BADGE LOGO	1 PC	21.68 SGD	21.68
10	1979 TAILGATE EMBLEM VEZEL	1 PC	38.32 SGD	38.32
11	1979 TAILGATE LAMP LH	1 PC	192.00 SGD	192.00
12	1979 TAILGATE OUTER GARNISH	1 PC	151.84 SGD	151.84
13	1979 REAR WINDSCREEN MLDG	1 PC	121.44 SGD	121.44
14	1979 TAILLAMP LH	1 PC	342.96 SGD	342.96
15	1979 TAILGATE UPPER LOCK	1 PC	77.28 SGD	77.28
16	1979 TAILGATE INNER LOWER TRIMBOARD	1 PC	122.72 SGD	122.72
17	1979 REAR END PANEL INNER GARNISH	1 PC	78.64 SGD	78.64

Items total 4,947.32
Add GST @ 7.000 % 346.31
Invoice amount 5,293.63

Issued by : STEWHA 25.10.2018 15:28:22
Repair type : CESO/52/5T
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office should be crossed and made payable to "ComfortDelGro Engineering Pte Ltd"
205 Braddell Road
Blk C Ext 1 Level 2
Singapore 579701

Attn: Finance Department

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.

INVOICE No.

AMOUNT

BANK/CHQ No.

ComfortDelGro Engineering Pte Ltd			



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**8 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**Our Ref No: GR-18-108019
Date of Request: 16/07/2018

Your Ref No: Online Purchase

ComfortDelGro Engineering Pte Ltd
205 Braddell Road
Singapore 579701

Dear Sir/Madam,

Enquiry Date: 16/07/2018
Enquiry By: Kristy Tay Siew Hwa
TP Vehicle No: SLF6990D
Accident Date: 14/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2018 Edit Reg		16 Jul 2018 00:00 Edit Adj Rpt	S\$4,947.32 Edit Estimates	S\$4,947.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Mosses Lee Siu Wen , ID: 57228975G									
Main Claimant: LCRF PTE LTD , Co. Reg. No.: 201624597K									
Vehicle Reg. No.: SLF4864Z		Date of Loss: 14/07/2018 12:00 - :59 [22 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1201800009025		Policy/Cover Note No.: PNPV2017-00007815 (Comprehensive)							
Vehicle Reg. No. (Insured): SLF6990D		Policy No. (Claimant): -							
		Excess:							
Repairer: ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (23/01/2019): Alert - Adj Mandate Approved (S\$6045.63) - SLF4864Z - Claim Handler: Lionel Tan FWD_SG (08/01/2019): Alert - Adj Mandate Maintained - SLF4864Z - Claim Handler: Lionel Tan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF4864Z (1201800009025)
[SLF6990D]
TP
LCRF PTE LTD
Jul 14 2018 12:00PM
[Mosses Lee Siu Wen]
ComfortDelGro Engineering Pte Ltd












































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1 Edit		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	12/12/18 10:12	Adjuster Immediate Advice	1 Load HTML		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
2	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
3	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
4	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
5	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
6	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
7	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
8	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
9	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
10	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
11	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
12	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
13	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
14	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
15	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
16	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
17	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
18	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
19	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
20	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
21	12/12/18 10:13	Chassis Number	1 Load JPG		<input checked="" type="checkbox"/>
22	12/12/18 10:13	Odometer Reading	1 Load JPG		<input checked="" type="checkbox"/>
23	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
24	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
25	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
26	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
27	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
28	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
29	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>
30	12/12/18 10:13	General View	1 Load JPG		<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
31	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
34	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
35	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
36	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
37	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
38	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
39	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
40	12/12/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>	
41	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
42	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
43	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
44	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
45	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
46	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
47	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
48	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
49	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
50	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
51	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
52	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
53	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
54	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
55	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
56	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
57	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
58	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
59	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
60	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
61	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
62	12/12/18 10:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/07/18 20:20	ACKNOWLEDGEMENT EMAIL TO FWD DD 17.07.2018	 Load PDF		
2	17/07/18 20:20	TP ESTIMATE	 Load PDF		
3	17/07/18 20:20	TP GIA REPORT	 Load PDF		
4	18/07/18 12:11	EMAIL - FWD TO OI DD 18.07.2018	 Load PDF		
5	23/07/18 08:54	TP ESTIMATE - MARKED	 Load PDF		
6	02/01/19 15:37	WORKSHOP INVOICE	 Load PDF		
7	02/01/19 15:37	LOD	 Load PDF		
8	02/01/19 15:37	GIA SEARCH	 Load PDF		
9	01/04/19 15:23	AUTHORISATION TO ACT FORM	 Load PDF		
10	01/04/19 15:23	Release Voucher	 Load PDF		
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print	
1	18/07/18 10:37	Insured GIA Report	 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF6990D (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT
	SLF4864Z (TP veh)		ABS D/AIRBAG 2WD 5DR (A)
Date of Accident:	14/07/2018		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	7,428.67
Final Repair Cost	: \$	5,293.63
Loss of Use	: \$	600.00
Rental (if any)	: \$	0.00
LTA / GIA Search Fee	: \$	2.00
Others:	: \$	0.00
	: \$	
Final Settlement Sum	: \$	5,895.63

10.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	: \$	5,895.63
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

01 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18013015/GEA3Q2

Date: 01/04/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00007815

Claimant Vehicle No: SLF4864Z Insured Vehicle No: SLF6990D

Date of Loss: 14/07/2018 Nature of Claim: TP Claim No: 1201800009025

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF4864Z**

Make & Model: HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: L15B4037398

Reg. Date: 29/08/2016 (Man. Year: 2016) Chassis No: RU11117392

Colour: Silver Odometer: 104617 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm

Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,232.68	2,917.32	1,315.36	31.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	2,030.00	680.00	25.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,942.68	4,947.32	1,995.36	28.74
+ GST 7.00/7.00% (S\$)	485.99	346.31	139.68	28.74
Nett Amount (S\$)	7,428.67	5,293.63	2,135.04	28.74
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,895.63		

INSPECTION

Date of Assignment: 16/07/2018

Date Inspected: 17/07/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2019)
Parts:	144	HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF4864Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE LAMP LH	Not Necessary	35.60 FL	*- FL
2	1		*REAR NUMBER PLATE LAMP RH	Not Necessary	35.60 FL	*- FL
3	1		*REAR BUMPER	Deformed	508.50 FL	*508.50 FL
4	1		*REAR BUMPER CORNER LH	Repair	195.00 FL	*- FL
5	1		*REAR BUMPER CORNER RH	Repair	195.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR LH	Not Necessary	135.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR RH	Not Necessary	135.00 FL	*- FL
8	1		*REAR BUMPER RETAINER LH	Not Necessary	17.50 FL	*- FL
9	1		*REAR BUMPER RETAINER RH	Not Necessary	17.50 FL	*- FL
10	1		*REAR BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
11	1		*TAILLAMP LH	Cracked	428.70 FL	*428.70 FL
12	1		*TAILLAMP RH	Cracked	428.70 FL	*428.70 FL
13	1		*TAILGATE	Buckled	1,100.90 FL	*1,100.90 FL
14	1		*TAILGATE BADGE LOGO	Necessary	27.10 FL	*27.10 FL
15	1		*TAILGATE EMBLEM -VEZEL	Necessary	47.90 FL	*47.90 FL
16	1		*TAILGATE EMBLEM -HYBRID(NPA)	Not Necessary	0.00 FL	*- FL
17	1		*TAILGATE WEATHERSTRIP	Not Necessary	96.80 FL	*- FL
18	1		*TAILGATE LAMP LH	Cracked	240.00 FL	*240.00 FL
19	1		*TAILGATE LAMP RH	Not Necessary	240.00 FL	*- FL
20	1		*TAILGATE UPPER LOCK	Bent	96.60 FL	*96.60 FL
21	1		*TAILGATE OUTER GARNISH	Cracked	189.80 FL	*189.80 FL
22	1		*TAILGATE INNER LOWER TRIMBOARD	Deformed	153.40 FL	*153.40 FL
23	1		*TAILGATE OPENING SWITCH	Not Necessary	175.50 FL	*- FL
24	1		*REAR WINDSCREEN MOULDING	Necessary	151.80 FL	*151.80 FL
25	1		*REAR NUMBER PLATE WITH CASING	Cut	45.00 FS	*45.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
27	1		*REAR WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
28	1		*REAR END PANEL	Not Necessary	365.70 FL	*- FL
29	1		*REAR END PANEL INNER GARNISH	Deformed	98.30 FL	*98.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,262.10	3,617.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,029.42	700.58
Total Parts (\$\$)	4,232.68	2,917.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	New	120.00	120.00
2	TO TRANSFER TAILGATE PARTS AND FITTINGS TO NEW TAILGATE	New	120.00	100.00
3	TO REMOVE/REFIT BOOT COMPARTMENT TRIMS AND GARNISH TO FACILITATE REPAIRS	New	180.00	180.00
4	LABOUR CHARGES TO REPAIR AND PANEL BEAT REAR END PANEL,BOOTFLOOR /SPARE TYRE PANEL AND REPLACE DAMAGED PARTS	New	960.00	720.00
5	TO REPLACE REVERSE SENSOR SET AND CHECK WIRING FUNCTIONS	New	180.00	80.00
6	TO PUTTY ,APPLY PRIMER & SPRAY -PAINT THE REAR BUMPER,TAILGATE,REAR END PANEL,BOOTFLOOR/SPARE PANEL AND AFFECTED AREAS	New	1,000.00	750.00
7	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	150.00	80.00
Gross Labour Cost (S\$)			2,710.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >