



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SLF4864ZMake & Model : HONDA VEZEL 1.5X CVTYear of Manufacture : 2016Chassis No. : RU11117392Ins Company : AIG VS FWDEngine No. : L15B4037398Excess : -Policy No. : -Date of Accident : 14.07.2018Time of Accident : 12:15

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**Case Owner : WILLIAM

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 2,710.00

Total Repair Cost \$ 2,710.00

Contact No

**Frt Counter Operation**

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell\_cr@sparkcarcare.com Consultants hence notify

the Reparer of the following:

by before/after spray painting

63837656 - Ngo Toh Wee damaged part(s) during resurvey

63837362 -

63838115 - William Wang Parts are subject to confirmation

63838115 - Andrew Goh survey is on a "Without Prejudice" basis

braddell\_operation@sparkcarcare.com legal modification(s) is allowed

must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang - 82880282Company : UKCSurvey conducted on : 17/7/18 at \_\_\_\_\_**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 5-6 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

part buy part.  
before paint photos.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLF4864Z Case Owner : WILLIAM

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11117392 Engine No : L15B4037398

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing / <i>cut</i>	1					
2	Rear number plate lamp LH / <i>cut</i>	1					
3	Rear number plate lamp RH / <i>CPA</i>	1					
4	Rear bumper / <i>Re</i>	1					
5	Rear bumper corner LH ?	1					
6	Rear bumper corner RH ?	1					
7	Rear bumper reflector LH X	1					
8	Rear bumper reflector RH X	1					
9	Rear bumper retainer LH / <i>LMC</i>	1					
10	Rear bumper retainer RH / <i>LMC</i>	1					
11	Rear bumper clips /	1					
12	Taillamp LH ?	1					
13	Taillamp RH / <i>CPA</i>	1					
14	Tailgate / <i>bum</i>	1					
15	Tailgate badge logo /	1					
16	Tailgate emblem - VEZEL / <i>LMC</i>	1					
17	Tailgate emblem - HYBRID /	1					
18	Tailgate weatherstrip ?	1					
19	Tailgate lamp LH / <i>CPA</i>	1					
20	Tailgate lamp RH	1					
21	Tailgate upper lock ?	1					
22	Tailgate outer garnish / <i>CPA</i>	1					
23	Tailgate inner lower trimboard ?	1					
24	Tailgate opening switch ?	1					
25	Rear windscreen moulding /	1					
26	Rear windscreen sealant /	1					
27	Rear windscreen inner seal /	1					
28	Rear end panel ?	1					
29	Rear end panel inner garnish ?	1					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Case Owner	:	<u>WILLIAM</u>
Year of Manufacture	:	<u>2016</u>

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*