

6, Wk 180 13016, Kda3

LOG
IDAC

Surveyor:

Kenneth

DOI:

12/7/18

Date / Time:

12/7/18

Registered in Merimen:

12/7/18

Pre-assign / CCU / FTE

SLM 776 U



Insured Vehicle No.:

LEBF P/L

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 11/7/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Drykambon, Ivan

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLM 1268C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Optima



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/7/18

SLM 1268C-X; SLM 776U-X

12/7/18

OIL HIT TP FROM REAR

12/7/18

HUE PASS TO HMK TO CLOS

28-1-19

PENDING FINALISE

SEEK COR MANDATE
LOD IN.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

20-7-18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Shaon

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/gst)

SS 48150.00

Loss of Rental (LOR):

(w/gst)

SS 4815.00 (30 days) x \$150

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

36.45

Medical:

SS

-

Disbursement: (Towing)

SS

100.00

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

Total:

SS

53101.45

Global Sum SS: 53000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

53000.00

Name 1:

Optima Werke Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF: 1161

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vsh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.


L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

18/7 File pass to Catherine, parts prices not ready

R/S - \$45000 (Red \$14033.75 / 24%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + R/S \$

: Fuel

: Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

Not Notarised
1.B.1
Preserving Bq paint

24 days

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>RT</i>		2,225.30
1	REAR TAILGATE WINDSCREEN <i>(7) x</i>	<i>5m</i>	1,251.70
1	REAR TAILGATE WINDSCREEN MOULDING <i>me</i>		201.00
1	REAR TAILGATE WINDSCREEN INNER GARNISH TOP <i>5m x</i>		130.60
2	REAR TAILGATE WINDSCREEN INNER GARNISH SIDE LH/RH <i>1150x4</i>	108.50	217.00
8	REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS <i>me</i>	6.50	52.00
1	REAR TAILGATE WEATHER STRIP <i>1150x4</i>		557.00
1	REAR TAILGATE SPOILER <i>x</i>	<i>5m</i>	3,981.60
8	REAR TAILGATE SPOILER CLIPS <i>x</i>	5.50 <i>me</i>	44.00
2	REAR TAILGATE HINGE LH/RH <i>RT</i>	138.60	277.20
2	REAR TAILGATE DAMPLE LH/RH <i>me</i>	396.30	792.60
1	REAR TAILGATE OUTER GARNISH <i>me</i>	<i>cm</i>	2,152.50
1	REAR TAILGATE OUTER LOCK HANDLE SWITCH <i>RT</i>		147.90
2	REAR TAILGATE NUMBER PLATE LAMP LH/RH <i>5m x</i>	120.00	240.00
1	REAR TAILGATE NUMBER PLATE LAMP COVER LH <i>(2)</i>	<i>5cm</i>	42.10
1	REAR TAILGATE EMBLEM 'LOGO' <i>me</i>		58.40
1	REAR TAILGATE EMBLEM 'HARRIER' <i>me</i>		76.30
2	REAR TAILGATE REFLECTOR LAMP LH/RH <i>cm</i>	480.06	960.12
6	REAR TAILGATE REFLECTOR LAMP CLIPS <i>me</i>	5.50	33.00
1	REAR TAILGATE INNER UPHOLSTERY BOARD <i>me</i>		2,080.00
14	REAR TAILGATE INNER UPHOLSTERY BOARD CLIPS <i>me</i>	6.50	91.00
2	REAR TAILGATE INNER HANDLE LH/RH <i>me</i>	48.20	96.40
2	REAR TAILGATE RUBBER STOPPER <i>me</i>	15.00	30.00
1	REAR TAILGATE MECHANISM LOCK <i>me</i>		554.70
1	REAR TAILGATE MECHANISM LOCK GARNISH <i>me</i>		24.90
1	REAR TAILGATE WIPER MOTOR <i>(2)</i>	<i>7m</i>	833.90
2	REAR TAILLAMP LH/RH <i>01/1 cm 1150x4</i>	472.70	945.40
6	REAR TAILLAMP CLIPS <i>me</i>	11.00	66.00
2	REAR TAILLAMP LOWER BRACKET LH/RH <i>01/1</i>	90.70	181.40
2	REAR TAILLAMP INNER PANEL LH/RH <i>RT</i>	288.60	577.20
2	REAR FENDER LH/RH <i>RT/RT</i>	1,618.30	3,236.60
2	REAR FENDER INNER SHIELD LH/RH <i>RT</i>	259.30	518.60
2	REAR FENDER INNER SHIELD CLIPS LH/RH <i>me</i>	6.50	13.00
2	REAR FENDER INNER UPHOLSTERY TRIM BOARD LH/RH <i>me</i>	728.30	1,456.60
12	REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS LH/RH <i>me</i>	5.50	66.00
2	REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS (SPECIAL) <i>me</i>	6.50	13.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR FENDER INNER AIR VENT LH <i>CM</i>		124.40
2	REAR FENDER INNER PANEL LH/RH <i>CM</i>	273.60	747.20
2	REAR FENDER QUARTER GLASS WITH MOULDING LH/RH <i>ACC</i>	208.00	416.00
1	REAR WHEELHOUSE INNER PANEL RH <i>CM</i>		358.70
1	REAR WHEELHOUSE OUTER PANEL RH <i>CM</i>		358.70
1	REAR BUMPER <i>ACC</i>		1325.20
2	REAR BUMPER SCREW WITH CLIPS LH/RH <i>ACC</i>	12.40	24.80
12	REAR BUMPER CLIPS <i>ACC</i>	6.50	78.00
2	REAR BUMPER SIDE RETAINER LH/RH <i>CM</i>	89.10	178.20
2	REAR BUMPER INNER SIDE SHIELD LH/RH <i>CM</i>	85.60	171.20
8	REAR BUMPER INNER SIDE SHIELD CLIPS <i>ACC</i>	5.71	45.68
1	REAR BUMPER INNER SPONGE <i>ACC</i>		130.60
1	REAR BUMPER LOWER DIFFUSER <i>ACC</i>		461.60
2	REAR BUMPER REFLECTOR LH/RH <i>ACC</i>	65.70	131.40
1	REAR END PANEL <i>ACC</i>		188.01
1	REAR END PANEL LOCK STRIKER <i>ACC</i>		42.70
1	REAR END PANEL INNER TOP GARNISH <i>CM</i>		347.00
6	REAR END PANEL INNER TOP GARNISH CLIP <i>ACC</i>	6.21	37.26
1	REAR END PANEL TAILGATE ANTENA SENSOR <i>CM</i>		153.20
1	REAR WELL PANEL <i>ACC</i>		385.60
1	REAR WELL PANEL LOWER CROSS MEMBER <i>ACC</i>		686.70
1	REAR WELL PANEL INNER TOP TOOLS TRAY LH <i>CM</i>		576.40
1	REAR WELL PANEL INNER TOP TOOLS TRAY RH <i>CM</i>		262.60
1	REAR WELL SIDE PANEL INNER TOP TOOLS TRAY LH <i>CM</i>		640.50
1	REAR WELL SIDE PANEL INNER TOP TOOLS TRAY RH <i>CM</i>		445.20
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (SMALL) <i>ACC</i>		329.60
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (BIG) <i>ACC</i>		889.51
1	REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD LH <i>CM</i>		215.70
1	REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD RH <i>CM</i>		225.70
1	REAR WELL PANEL INNER UPHOLSTERY TRIM <i>CM</i>		452.60
2	REAR SUB CHASSIS FRAME LH/RH <i>ACC</i>	225.78	451.56
1	REAR SUB CHASSIS FRAME TOW HOOK BRACKET <i>ACC</i>		63.40
2	REAR 17" SPORT RIM LH/RH <i>ACC</i>	1,818.10	3,636.20
1	REAR SUSPENSION STABILIZER BAR <i>ACC</i>		384.20
2	REAR SUSPENSION STABILIZER BAR BRACKET LH/RH <i>ACC</i>	28.60	57.20
2	REAR SUSPENSION STABILIZER BAR RUBBER BUSH LH/RH <i>ACC</i>	36.80	73.60
2	REAR SUSPENSION STABILIZER BAR LINK LH/RH <i>ACC</i>	129.70	259.40
2	REAR SUSPENSION SHOCK ABSORBER LH/RH <i>ACC</i>	128.75	257.50

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer:

AIG

Vehicle No: SLM1268C

Third Party Veh No:

SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident:

11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR SUSPENSION SHOCK ABSORBER BRACKET RH	R ₁	145.21
2	REAR SUSPENSION TRAILING ARM LH/RH	11/1 723.30	1,446.60
1	REAR SUSPENSION TRAILING ARM BRACKET RH	R ₁	95.20
2	REAR SUSPENSION THRU ARM LH/RH	R ₁ 295.30	590.60
2	REAR SUSPENSION LOWER ARM LH/RH	528.60	1,057.20
1	REAR SUSPENSION LOWER ARM BOLT RH	R ₁	18.40
2	REAR SUSPENSION COIL SPRING LH/RH	228.10	456.20
2	REAR SUSPENSION KNUCKLE ARM LH/RH	423.60	847.20
2	REAR SUSPENSION KNUCKLE ARM BEARING LH/RH	855.60	1,711.20
2	REAR SUSPENSION TORSION ARM LH/RH	285.70	571.40
1	REAR SUSPENSION CROSS MEMBER	R ₁	2,531.48
2	REAR SUSPENSION CROSS MEMBER BRACKET LH/RH	R ₁ 72.60	145.20
4	REAR SUSPENSION CROSS MEMBER SKRU	x2 25.00	100.00
2	REAR SUSPENSION CROSS MEMBER NUT LH/RH	R ₁ 9.30	18.60
2	REAR SUSPENSION CROSS MEMBER BOLT (FRONT) LH/RH	15.00	30.00
2	REAR SUSPENSION CROSS MEMBER BOLT (REAR) LH/RH	15.00	30.00
1	REAR SUSPENSION LEVERING SENSOR	128.90	128.90
1	REAR DISC BRAKE PIPE RH	133.10	133.10
1	REAR DISC BRAKE PIPE BRACKET RH	53.60	53.60
1	REAR DISC BRAKE HOSE RH	129.70	129.70
1	REAR DISC BRAKE ROTOR COVER PLATE RH	118.70	118.70
1	REAR EXHAUST SILENCES BOX	18.70	18.70
2	REAR EXHAUST SILENCES BOX BOLT	12.10	24.20
3	REAR EXHAUST RUBBER MOUNTING	85.60	256.80
1	REAR EXHAUST GASKET	2,525.90	2,525.90
1	EXHAUST MID PIPE	96.30	96.30
3	EXHAUST MID PIPE RUBBER MOUNTING	43.30	129.90
1	EXHAUST MID PIPE GASKET	5,330.06	5,330.06
1	FRONT DRIVER SEAT FRAME RH		

SUB TOTAL	57,216.65	50,709.91
Less 25%	-14,304.16	-12,677.46
PARTS TOTAL	42,912.49	38,032.43

we will notify you following:

- We will notify you of any damage to your vehicle during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 3

Acknowledged by Repairer

Signature:

Date:

50,709.91
-12,677.46
38,032.43

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer:

AIG

Vehicle No: SLM1268C

Third Party Veh No:

SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR Date of Accident:

11 JULY 2018

Chassis: ZSU600099823

SUPPLEMENTARY

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR SEAT LH CUSHION- PASSENGER VEHICLE TRUCK BOARD	1	\$1,055.80
1	REAR SEAT RH CUSHION PASSENGER VEHICLE TRUCK BOARD	1	\$798.50
1	REAR END PANEL TAILGATE ANTENA SENSOR WIRE HARDNESS SET	1	\$240.70
1	REAR SUSPENSION LEVERING SENSOR WIRE HARDNESS SET	1	\$230.70
SUB TOTAL			\$2,325.50
LESS 25%			-\$581.38
PARTS TOTAL			\$1,744.13

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
2	REAR FENDER QUARTER GLASS SOLAR FILM	\$180.00	\$360.00
S/N TOTAL			\$360.00

PUI THENG	TOTAL	\$2,104.13
-----------	-------	------------

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	12 JULY 2018	Third Party Insurer:	AIG
Vehicle No:	SLM1268C	Third Party Veh No:	SLM7176U
Model:	TOYOTA HARRIER ELEGANCE 2.0 CVT SR	Date of Accident:	11 JULY 2018
Chassis:	ZSU600099823		

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER <i>neu</i>		100.00
1	REAR TAILGATE WINDSCREEN SOLAR FILM <i>neu</i>		380.00 <i>260.00</i>
1	REAR TAILGATE NUMBER PLATE WIRH HOLDER <i>neu</i>		65.00
1	REAR TAILGATE REVERSE CAMERA <i>shot</i>		550.00
1	REAR BUMPER REVERSE SENSOR <i>neu</i>		380.00
1	REAR LH/RH FENDER QUARTER GLASS SEALANT WITH PRIMER <i>neu</i>		60.00
1	REAR TYRE 225/65 R17 <i>neu 308.00</i>		580.00 <i>290.00</i>
S/N TOTAL			1,915.00 <i>1,125.00</i>

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer:

AIG

Vehicle No: SLM1268C

Third Party Veh No:

SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident:

11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	3600 ✓	\$4,800.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	2200 ✓	\$4,200.00
TO TUFF KOTE / ANTI-RUST	800 ✓	\$80.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	800 500 ✓	\$80.00
TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA / INNER CAMERA RECORDER	600 ✓	\$80.00
TO CHECK WIRING WITH WATER LEAKAGE TEST	300 ✓	\$120.00
TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	1200 ✓	\$150.00
TO REMOVE AND REINSTALL REAR LH/RH FENDER QUARTER GLASS PERFORM AND WATER LEAK TEST	1000 ✓	\$100.00
TO DISMANTLE & REINSTALL INTERIOR CARPET, FRONT / REAR SEAT ASSY WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	1500 ✓	\$350.00
TO DISMANTLE & REPLACED REAR EXHAUST WHOLE SYSTEM	1000 ✓	\$250.00
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	2400 ✓	\$380.00
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED ALL WHEEL ALIGNMENT	800 ✓	\$80.00
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	2500 ✓	\$450.00
TOWING OF VEHICLE USING KING-DOLLIES (FOR RECOVERY OF VEHICLE IN MULTISTOREY / BASEMENT CARPARK & ACCIDENT VEHICLE WITH WHEELS DAMAGED) - 24 HOURS, INCLUSIVE OF SUNDAY OR PUBLIC HOLIDAYS	(8.00) 1000 ✓	\$100.00
LABOUR TOTAL		\$11,220.00 2,100 ✓
PUI THENG	TOTAL	56,047.49

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	12 JULY 2018	Third Party Insurer:	AIG
Vehicle No:	SLM1268C	Third Party Veh No:	SLM7176U
Model:	TOYOTA HARRIER ELEGANCE 2.0 CVT SR	Date of Accident:	11 JULY 2018
Chassis:	ZSU600099823		

SUPPLEMENTARY_2

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
2	REAR FENDER QUATER GLASS INNER GARNISH RH/LH <i>Reform</i>	412.25	\$824.50	✓
10	REAR FENDER QUATER GLASS INNER GARNISH CLIPS <i>Re</i>	5.50	\$55.00	✓
1	REAR WELL PANEL INSULATOR MAT <i>CMS</i>		\$350.00	✓
		SUB TOTAL	\$1,229.50	1,229.50
		LESS 25%	-\$307.38	-307.38
		PARTS TOTAL	\$922.13	922.13
PUITHENG		TOTAL	\$922.13	

$$SP = 38,032.43 + 909.11 + 922.12$$

$$SM = 1,625.00 + 120.00$$

$$L = 7,160.00$$

$$48,768.66$$

$$48,768.66$$

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

Not Notified
1.B.1
Assessing B&P
24 days

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>RM</i>		2,235.30
1	REAR TAILGATE WINDSCREEN <i>?</i>		1,251.70
1	REAR TAILGATE WINDSCREEN MOULDING <i>RM</i>		213.00
1	REAR TAILGATE WINDSCREEN INNER GARNISH TOP <i>RM X</i>		130.60
2	REAR TAILGATE WINDSCREEN INNER GARNISH SIDE LH/RH <i>RM X</i>	108.50	217.00
8	REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS <i>RM</i>	6.50	52.00
1	REAR TAILGATE WEATHER STRIP <i>RM / RM</i>		357.00
1	REAR TAILGATE SPOILER <i>?</i>		3,981.60
8	REAR TAILGATE SPOILER CLIPS <i>?</i>	5.50	44.00
2	REAR TAILGATE HINGE LH/RH <i>?</i>	135.60	271.20
2	REAR TAILGATE DAMPLE LH/RH <i>?</i>	346.50	742.60
1	REAR TAILGATE OUTER GARNISH <i>?</i>		1,132.50
1	REAR TAILGATE OUTER LOCK HANDLE SWITCH <i>?</i>		147.90
2	REAR TAILGATE NUMBER PLATE LAMP LH/RH <i>RM X</i>	120.00	240.00
1	REAR TAILGATE NUMBER PLATE LAMP COVER LH <i>?</i>		48.10
1	REAR TAILGATE EMBLEM 'LOGO' <i>RM</i>		50.80
1	REAR TAILGATE EMBLEM 'HARRIER' <i>RM</i>		75.30
2	REAR TAILGATE REFLECTOR LAMP LH/RH <i>RM</i>	480.00	960.00
6	REAR TAILGATE REFLECTOR LAMP CLIPS <i>RM</i>	5.50	33.00
1	REAR TAILGATE INNER UPHOLSTERY BOARD <i>RM</i>		2,080.00
14	REAR TAILGATE INNER UPHOLSTERY BOARD CLIPS <i>RM</i>	6.50	91.00
2	REAR TAILGATE INNER HANDLE LH/RH <i>RM</i>	48.20	96.40
2	REAR TAILGATE RUBBER STOPPER <i>RM</i>	15.00	30.00
1	REAR TAILGATE MECHANISM LOCK <i>RM</i>		554.70
1	REAR TAILGATE MECHANISM LOCK GARNISH <i>RM</i>		24.90
1	REAR TAILGATE WIPER MOTOR <i>?</i>		833.90
2	REAR TAILLAMP LH/RH <i>RM</i>	472.70	945.40
6	REAR TAILLAMP CLIPS <i>RM</i>	11.00	66.00
2	REAR TAILLAMP LOWER BRACKET LH/RH <i>RM</i>	90.70	181.40
2	REAR TAILLAMP INNER PANEL LH/RH <i>RM</i>	288.60	577.20
2	REAR FENDER LH/RH <i>RM</i>	1,618.50	3,236.60
2	REAR FENDER INNER SHIELD LH/RH <i>RM</i>	254.30	508.60
2	REAR FENDER INNER SHIELD CLIPS LH/RH <i>RM</i>	6.50	13.00
2	REAR FENDER INNER UPHOLSTERY TRIM BOARD LH/RH <i>RM</i>	728.30	1,456.60
12	REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS LH/RH <i>RM</i>	5.50	66.00
2	REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS (SPECIAL) <i>?</i>	6.50	13.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave S Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR FENDER INNER AIR VENT LH <i>CMA ✓</i>		124.60
2	REAR FENDER INNER PANEL LH/RH <i>?</i>	373.60	747.20
2	REAR FENDER QUARTER GLASS WITH MOULDING LH/RH <i>MC ✓</i>	208.60	416.80
1	REAR WHEELHOUSE INNER PANEL RH <i>?</i>		358.70
1	REAR WHEELHOUSE OUTER PANEL RH <i>?</i>		358.20
1	REAR BUMPER <i>M17 ✓</i>		1,385.40
2	REAR BUMPER SCREW WITH CLIPS LH/RH <i>MC ✓</i>	12.10	24.20
12	REAR BUMPER CLIPS <i>MC ✓</i>	6.50	78.00
2	REAR BUMPER SIDE RETAINER LH/RH <i>CMA ✓</i>	89.10	178.20
2	REAR BUMPER INNER SIDE SHIELD LH/RH <i>T1 ✓</i>	85.60	171.20
8	REAR BUMPER INNER SIDE SHIELD CLIPS <i>MC ✓</i>	5.71	45.68
1	REAR BUMPER INNER SPONGE <i>B2 ✓</i>		130.60
1	REAR BUMPER LOWER DIFFUSER <i>M17 ✓</i>		466.60
2	REAR BUMPER REFLECTOR LH/RH <i>M17 ✓</i>	65.70	131.40
1	REAR END PANEL <i>B1 ✓</i>		388.01
1	REAR END PANEL LOCK STRIKER <i>B1 ✓</i>		42.30
1	REAR END PANEL INNER TOP GARNISH <i>CMA ✓</i>		347.00
6	REAR END PANEL INNER TOP GARNISH CLIP <i>MC ✓</i>	6.21	37.26
1	REAR END PANEL TAILGATE ANTENA SENSOR <i>?</i>		153.20
1	REAR WELL PANEL <i>B1A ✓</i>		385.60
1	REAR WELL PANEL LOWER CROSS MEMBER <i>B1 ✓</i>		686.30
1	REAR WELL PANEL INNER TOP TOOLS TRAY LH <i>CMA ✓</i>		576.90
1	REAR WELL PANEL INNER TOP TOOLS TRAY RH <i>CMA ✓</i>		492.80
1	REAR WELL SIDE PANEL INNER TOP TOOLS TRAY LH <i>?</i>		640.50
1	REAR WELL SIDE PANEL INNER TOP TOOLS TRAY RH <i>?</i>		445.20
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (SMALL) <i>?</i>		329.60
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (BIG) <i>?</i>		885.51
1	REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD LH <i>?</i>		215.70
1	REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD RH <i>?</i>		225.70
1	REAR WELL PANEL INNER UPHOLSTERY TRIM <i>CMA ✓</i>		312.60
2	REAR SUB CHASSIS FRAME LH/RH <i>M17 o/s B1 ✓</i>	225.78	451.56
1	REAR SUB CHASSIS FRAME TOW HOOK BRACKET <i>B1 ✓</i>		63.40
2	REAR 17" SPORT RIM LH/RH <i>C11 B1 ✓</i>	1,818.10	3,636.20
1	REAR SUSPENSION STABILIZER BAR <i>?</i>		384.20
2	REAR SUSPENSION STABILIZER BAR BRACKET LH/RH <i>?</i>	28.60	57.20
2	REAR SUSPENSION STABILIZER BAR RUBBER BUSH LH/RH <i>?</i>	36.80	73.60
2	REAR SUSPENSION STABILIZER BAR LINK LH/RH <i>?</i>	175.70	351.40
2	REAR SUSPENSION SHOCK ABSORBER LH/RH <i>?</i>	128.25	256.50

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500

Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer:

AIG

Vehicle No: SLM1268C

Third Party Veh No:

SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident:

11 JULY 2018

Chassis: Z5U600099823

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR SUSPENSION SHOCK ABSORBER BRACKET RH ?		145.31
2	REAR SUSPENSION TRAILING ARM LH/RH ?	723.30	1446.60
1	REAR SUSPENSION TRAILING ARM BRACKET RH ?		95.70
2	REAR SUSPENSION THRU ARM LH/RH ?	245.30	540.60
2	REAR SUSPENSION LOWER ARM LH/RH <i>dis R/L</i>	528.60	1057.20
1	REAR SUSPENSION LOWER ARM BOLT RH ?		18.90
2	REAR SUSPENSION COIL SPRING LH/RH ?	238.10	476.20
2	REAR SUSPENSION KNUCKLE ARM LH/RH <i>sm x</i>	423.60	847.20
2	REAR SUSPENSION KNUCKLE ARM BEARING LH/RH <i>sm x</i>	850.60	1701.20
2	REAR SUSPENSION TORSION ARM LH/RH ?	285.70	571.40
1	REAR SUSPENSION CROSS MEMBER ?		2521.40
2	REAR SUSPENSION CROSS MEMBER BRACKET LH/RH ?	72.60	145.20
4	REAR SUSPENSION CROSS MEMBER SKRU ?	25.00	100.00
2	REAR SUSPENSION CROSS MEMBER NUT LH/RH ?	9.30	18.60
2	REAR SUSPENSION CROSS MEMBER BOLT (FRONT) LH/RH ?	15.00	30.00
2	REAR SUSPENSION CROSS MEMBER BOLT (REAR) LH/RH ?	15.00	30.00
1	REAR SUSPENSION LEVERING SENSOR LH ?		182.70
1	REAR DISC BRAKE PIPE RH <i>sm x</i>		132.10
1	REAR DISC BRAKE PIPE BRACKET RH ?		55.60
1	REAR DISC BRAKE HOSE RH <i>sm x</i>		138.70
1	REAR DISC BRAKE ROTOR COVER PLATE RH <i>sm x</i>		108.70
1	REAR EXHAUST SILENCES BOX <i>sm</i>		674.10
2	REAR EXHAUST SILENCES BOX BOLT <i>sm</i>	18.70	37.40
3	REAR EXHAUST RUBBER MOUNTING <i>sm</i>	32.10	96.30
1	REAR EXHAUST GASKET <i>sm</i>		85.60
1	EXHAUST MID PIPE <i>sm</i>		2485.90
3	EXHAUST MID PIPE RUBBER MOUNTING ?		96.30
1	EXHAUST MID PIPE GASKET ?		42.30
1	FRONT DRIVER SEAT FRAME RH ?		
SUB TOTAL			57,316.65
Less 25%			- 14,329.16
PARTS TOTAL			42,987.49

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER <i>Per</i>		100.00
1	REAR TAILGATE WINDSCREEN SOLAR FILM <i>?</i>		350.00
1	REAR TAILGATE NUMBER PLATE WIRH HOLDER <i>By ✓</i>		65.00
1	REAR TAILGATE REVERSE CAMERA <i>?</i>		350.00
1	REAR BUMPER REVERSE SENSOR <i>Per ✓</i>		380.00
1	REAR LH/RH FENDER QUARTER GLASS SEALANT WITH PRIMER <i>Per</i>		60.00
1	REAR TYRE 225/65 R17 <i>Per 502m</i>		530.00
		S/N TOTAL	1,915.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	3600 \$4,800.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	2200 \$4,200.00
TO TUFF KOTE / ANTI-RUST	\$80.00 ✓
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$80.00 500
TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA / INNER CAMERA RECORDER	600 \$80.00
TO CHECK WIRING WITH WATER LEAKAGE TEST	300 \$120.00
TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	1200 \$150.00
TO REMOVE AND REINSTALL REAR LH/RH FENDER QUARTER GLASS PERFORM AND WATER LEAK TEST	\$100.00 ✓
TO DISMANTLE & REINSTALL INTERIOR CARPET, FRONT / REAR SEAT ASSY WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	1500 \$350.00
TO DISMANTLE & REPLACED REAR EXHAUST WHOLE SYSTEM	1000 \$250.00
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	2400 \$380.00
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$80.00 ✓
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	2500 \$450.00
TOWING OF VEHICLE USING KING-DOLLIES (FOR RECOVERY OF VEHICLE IN MULTISTOREY / BASEMENT CARPARK & ACCIDENT VEHICLE WITH WHEELS DAMAGED) - 24 HOURS, INCLUSIVE OF SUNDAY OR PUBLIC HOLIDAYS	(10.11) \$100.00 ✓

LABOUR TOTAL \$11,220.00

PUI THENG

TOTAL 56,047.49

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	3818H

Vehicle Details

Vehicle No.:	SLM1268C
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 CVT SR
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	3ZRB971561
Chassis No.:	Z5U600099823
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$31,503.00
Original Registration Date:	21 Mar 2017
First Registration Date:	21 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$31,105.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2027
PARF Rebate Amount:	\$23,328.00

Intended COE Rebate Details

COE Expiry Date:	20 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$43,898.00
Total Rebate Amount:	\$67,226.00

The information contained herein is correct as at 18 Jul 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3818H

Vehicle Details

Vehicle No.: SLM1268C
Vehicle to be Exported: No
Intended De-registration Date: 11 Jul 2018
Vehicle Make: TOYOTA
Vehicle Model: HARRIER ELEGANCE 2.0 CVT SR
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: 3ZRB971561
Chassis No.: ZSU600099823
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$31,503.00
Original Registration Date: 21 Mar 2017
First Registration Date: 21 Mar 2017
Transfer Count: 0
Actual ARF Paid: \$31,105.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 Mar 2027
PARF Rebate Amount: \$23,328.00

Intended COE Rebate Details

COE Expiry Date: 20 Mar 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,621.00
COE Rebate Amount: \$43,994.00
Total Rebate Amount: \$67,322.00

The information contained herein is correct as at 11 Jul 2018

OK

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 12 Jul 2018 / 09:50:54

Receipt Date/Time : 12 Jul 2018 / 09:50:53

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180712-000387

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLM7176U				
As at 11 Jul 2018/15:20:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLM7176U			
	Enquiry Fee	7.00	0.49	7.49
	20180712094845094757			
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4670	Credit Card: Visa /MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Cool Renewal Toyota Wish 1.8A



\$2990 (downpayment) Monthly
From \$888 Onwards! Lowest
Interest! JALCO Car Financing
GV Credit Pte Ltd. (2008)

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Back (1 2) Next

Sort by Date Posted

20 results/page

29 vehicles

Toyota Harrier

Advanced Search

Model

Price

Depreciation

Reg. Date

Eng Cap

Mileage

Veh Type

Vehicle ID

Search Selection

Toyota Harrier

Any

Any

2017

Any

Any

Any

Available



Toyota Harrier 2.0A Elegance Panoramic

\$125,888

\$12,190 /yr

11-Aug-2017

1,986 cc

20,000 km

SUV

Available

100% Accident- Free. Owned By Teacher. Non Smoker. Changing Car To Suit Family Needs. Full Service History, Well Maintained, Low Mileage. Nice Number Plate. Paint Protected By Glass Coat. Front And Ba...

SELECT OWNER

Posted: 17-Jul-2018

Tags: 2017 Toyota harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance Panoramic

\$128,000

\$12,670 /yr

12-Jul-2017

1,986 cc


-

SUV

Available

Posted: 17-Jul-2018

Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance Panoramic

\$125,800

\$13,060 /yr

20-Jan-2017

1,986 cc

11,000 km

SUV


Available

Nissan Certified Pre-Owned Unit.100% Loan Available!Elegant Silver With Low Mileage, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan Packages Available. Well Taken Care By 1 Careful...

Hua Yang Credit Pte Ltd

Posted: 16-Jul-2018

Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance Panoramic

\$120,300

\$12,450 /yr

11-Jan-2017

1,986 cc

20,020 km

SUV

Available

One Year Inchcape Pre-Owned Warranty Provided. 160 Points Check Done. One Owner. Huge Saving Saving From Almost Brand New Unit! Beautiful Original Paintwork With Mint Condition Interior. Selling Due T...

INCHCAPE CD

Posted: 16-Jul-2018

Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



Toyota Harrier 2.0A Elegance Panoramic

\$128,000

\$13,140 /yr

17-Feb-2017

1,986 cc

9,868 km

SUV

Available

Viewing Strictly By Appointment Only. Low Mileage Clocked At 9868Km.

Blue Toner Online!

Latest Special Offers from Toyota!

Posted: 16-Jul-2018

Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance Panoramic

\$125,800

\$12,370 /yr

16-Jun-2017

1,986 cc

21,000 km

SUV

Available

\$13k Drive Away! Warranty Till 2020. The Most Sought-After Japanese Made SUV! Popular Harrier Equipped With 2L Engine Providing Adequate Daily Power. Panoramic Roof Give You Sensational View Of The NL...

INCHCAPE CD

Posted: 15-Jul-2018

Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota

Dynamic Motoring

Compare

Toyota Harrier 2.0A M-Grade Turbo

A by STR

vised And 5 Years/Unlimited Mileage Warranty From Borneo Motors Till Sep/2022. 10% Down Payment! Up To 90% Loan! Interest From

INCHCAPE CD



2.98%! One Owner. Excellent Condition! Buy With A Peace Of Mind ...

Autolink Holdings Pte Ltd

Posted: 14-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance **\$109,800** **\$10,910 /yr** **27-Mar-2017** **1,986 cc** **17,600 km** **SUV** **Available**

Low Mileage. STA Inspection Welcome! 12 Months Warranty Available! Trade In/Loan Available.

Posted: 14-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$119,800** **\$11,390 /yr** **13-Jul-2017** **1,986 cc** **26,273 km** **SUV** **Available**

10% Down Payment! Up To 90% Loan! Interest From 2.98%! Comes With Very Nice Number! Pristine Showroom Conditions! Original Paintwork! Still Under Warranty! Call Us To Find Out More!

Autolink Holdings Pte Ltd

Posted: 14-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Style Mauve **\$126,888** **\$12,360 /yr** **20-Mar-2017** **1,986 cc** **26,800 km** **SUV** **Available**

High ARF Of \$39K! Single Owner! Well Maintained! Warranty Valid Till 2020! Seats All Taken Care Of With Seat Protector Since Day One! Beautiful Half Leather Half Alcantara Seats. Highest Spec Harrier ...

Cars 88 Pte Ltd

Posted: 13-Jul-2018 Tags: 2017 Toyota harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Sell to direct buyers at the price you want!

Make the choice to sell only if the price meets your expectations. Contact our agents to find out how to list on consignment.

Find out more!



Toyota Harrier 2.0A Premium Panoramic **\$124,800** **\$11,950 /yr** **21-Jul-2017** **1,986 cc** **20,110 km** **SUV** **Available**

Popular Harrier SUV Equipped With 2L Engine Providing Adequate Daily Power! Spacious Cabin For 5 Adults To Lounge In Comfort! Panoramic Roof Give You A Sense Of Spaciousness In The Cabin! Large Boot C...

Select By Performance: Premium Selection

Posted: 13-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance Panoramic **\$112,000** **\$11,000 /yr** **27-Apr-2017** **1,986 cc** **14,000 km** **SUV** **Available**

Friendly Honest Private Seller, Selling Due To New Family Addition Thus Need To Upgrade To A 7 Seater. Car Is Fully Serviced And In Excellent Near New Condition. Comes With A Spare Tire. High OMV. Low...

Prem Roy Motoring

Posted: 13-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance Panoramic **\$123,888** **\$12,720 /yr** **27-Feb-2017** **1,986 cc** **28,239 km** **SUV** **Available**

Massive Savings From New Car. My Loss Is Ur Gain. Owner Upgrading To Vellfire Due To New Family Members. Almost New Condition. Non Smoker Car.

Posted: 11-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$121,500** **\$11,760 /yr** **29-May-2017** **1,986 cc** **23,000 km** **SUV** **Available**

Full Modellista Bodykit. Road Tax Till May 2019. Accident Free. Full Servicing Records With MBM Wheel Power. Excellent Condition. Coated With Aurashield Ceramic Coating. Not Urgent Sale. Please Call F...

Posted: 10-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier Premium 2.0 Panoramic **\$115,500** **\$11,410 /yr** **13-Apr-2017** **1,986 cc** **13,000 km** **Sedan** **Available**

Full Service By Optima Werks, Premium Model With High Specifications, Low Maintenance Cost, Very Well Maintained, Well Kept From Inside Out! Totally Like Brand New Car! 100% Accident Free! Powerful, S...

Posted: 08-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$123,800** **\$11,960 /yr** **20-Jul-2017** **1,986 cc** **14,166 km** **SUV** **Available**

Low Interest Rate, Balloon Scheme Available, In-house Financing Options, Buy With A Peace Of Mind, 1 Owner, 100% Genuine Mileage. Well Maintained. No Chassis/Structural Damage. Immaculate Condition. A...

Posted: 07-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota

Compare

yota Harrier 2.0A M-Grade rbo **\$132,800** **\$12,730 /yr** **04-Aug-2017** **1,998 cc** **10,000 km** **SUV** **Available**



1 Owner! Agent Unit With Agent Warranty! Supreme Condition, Very Well Maintained, As Good As Brand New At A Lower Price! Flexible In House Financing And High Trade In Available! Call Our Friendly Sale...

Hui Hua Credit Pte Ltd

Posted: 06-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$140,500** **\$12,770 /yr** **29-Dec-2017** **1,986 cc** **27 km** **SUV** **Available**

New Registered Unit, Brand New Condition, Premium Model, Comes With Warranty, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 02-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Luxury **\$143,800** **\$12,980 /yr** **30-Dec-2017** **1,998 cc** **11,000 km** **SUV** **Available**

At Borneo Motors Singapore, Only The Best Can Meet The Mark. When You Purchased A Toyota Certified Pre-Owned, You Can Be Confident It Will Perform Like The Day It Left The Showroom.

Borneo Motors (5)

Posted: 02-Jul-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$126,800** **\$12,430 /yr** **15-May-2017** **1,986 cc** **12,088 km** **SUV** **Available**

Fixed Finance Packages Up To 90% High Loan Available, Bank Loan, Minimum Cash Drive Away Available, 1 Owner. Immaculate Condition, Free Servicing Till May 2020 With Warranty Till May 2024, Don't Miss...

Accendore Autolution Pte Ltd

Posted: 28-Jun-2018 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Reset Model Price Depreciation Reset Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

◀ Back (1 2) Next ▶

20 ▼ results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station-wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Harrier, Toyota Harrier Singapore, used Toyota Harrier Singapore, used Toyota Harrier, used vehicles Singapore or even buy used Toyota Harrier Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

Not Withheld
1.B.1
Preserving B4 paint
x: +65 6472 2112
: +65 6481 1011
24 days

Tel : +65 6472 1313 Fax : +65 6472 2112

24 days

Chassis: ZSU600099823

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR FENDER INNER AIR VENT LH <i>CM ✓</i>		
2	REAR FENDER INNER PANEL LH/RH <i>?</i>		
2	REAR FENDER QUARTER GLASS WITH MOULDING LH/RH <i>rec ✓</i>		
1	REAR WHEELHOUSE INNER PANEL RH <i>?</i>		
1	REAR WHEELHOUSE OUTER PANEL RH <i>?</i>		
1	REAR BUMPER <i>MS ✓</i>		
2	REAR BUMPER SCREW WITH CLIPS LH/RH <i>rec ✓</i>		
12	REAR BUMPER CLIPS <i>MS ✓</i>		
2	REAR BUMPER SIDE RETAINER LH/RH <i>CM ✓</i>		
2	REAR BUMPER INNER SIDE SHIELD LH/RH <i>T ✓</i>		
8	REAR BUMPER INNER SIDE SHIELD CLIPS <i>rec ✓</i>		
1	REAR BUMPER INNER SPONGE <i>B ✓</i>		
1	REAR BUMPER LOWER DIFFUSER <i>MS ✓</i>		
2	REAR BUMPER REFLECTOR LH/RH <i>B ✓</i>		
1	REAR END PANEL <i>B ✓</i>		
1	REAR END PANEL LOCK STRIKER <i>B ✓</i>		
1	REAR END PANEL INNER TOP GARNISH <i>CM ✓</i>		
6	REAR END PANEL INNER TOP GARNISH CLIP <i>rec ✓</i>		
1	REAR END PANEL TAILGATE ANTENA SENSOR <i>?</i>		
1	REAR WELL PANEL <i>BT/AB ✓</i>		
1	REAR WELL PANEL LOWER CROSS MEMBER <i>BT ✓</i>		
1	REAR WELL PANEL INNER TOP TOOLS TRAY LH <i>CM ✓</i>		
1	REAR WELL PANEL INNER TOP TOOLS TRAY RH <i>CM ✓</i>		
1	REAR WELL SIDE PANEL INNER TOP TOOLS TRAY LH <i>?</i>		
1	REAR WELL SIDE PANEL INNER TOP TOOLS TRAY RH <i>?</i>		
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (SMALL) <i>?</i>		
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (BIG) <i>?</i>		
1	REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD LH <i>?</i>		
1	REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD RH <i>?</i>		
1	REAR WELL PANEL INNER UPHOLSTERY TRIM <i>CM ✓</i>		
2	REAR SUB CHASSIS FRAME LH/RH <i>MSR o/s B ✓</i>		
1	REAR SUB CHASSIS FRAME TOW HOOK BRACKET <i>BT ✓</i>		
2	REAR 17" SPORT RIM LH/RH <i>CLS Red ✓</i>		
1	REAR SUSPENSION STABILIZER BAR <i>?</i>		
2	REAR SUSPENSION STABILIZER BAR BRACKET LH/RH <i>?</i>		
2	REAR SUSPENSION STABILIZER BAR RUBBER BUSH LH/RH <i>?</i>		
2	REAR SUSPENSION STABILIZER BAR LINK LH/RH <i>?</i>		
2	REAR SUSPENSION SHOCK ABSORBER LH/RH <i>?</i>		

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR SUSPENSION SHOCK ABSORBER BRACKET RH ?		
2	REAR SUSPENSION TRAILING ARM LH/RH ?		
1	REAR SUSPENSION TRAILING ARM BRACKET RH ?		
2	REAR SUSPENSION THRU ARM LH/RH ?		
2	REAR SUSPENSION LOWER ARM LH/RH <i>old R/L</i>		
1	REAR SUSPENSION LOWER ARM BOLT RH ?		
2	REAR SUSPENSION COIL SPRING LH/RH ?		
2	REAR SUSPENSION KNUCKLE ARM LH/RH <i>See X</i>		
2	REAR SUSPENSION KNUCKLE ARM BEARING LH/RH <i>See X</i>		
2	REAR SUSPENSION TORSION ARM LH/RH ?		
1	REAR SUSPENSION CROSS MEMBER ?		
2	REAR SUSPENSION CROSS MEMBER BRACKET LH/RH ?		
4	REAR SUSPENSION CROSS MEMBER SKRU ?		
2	REAR SUSPENSION CROSS MEMBER NUT LH/RH ?		
2	REAR SUSPENSION CROSS MEMBER BOLT (FRONT) LH/RH ?		
2	REAR SUSPENSION CROSS MEMBER BOLT (REAR) LH/RH ?		
1	REAR SUSPENSION LEVERING SENSOR LH ?		
1	REAR DISC BRAKE PIPE RH <i>See X</i>		
1	REAR DISC BRAKE PIPE BRACKET RH ?		
1	REAR DISC BRAKE HOSE RH <i>See X</i>		
1	REAR DISC BRAKE ROTOR COVER PLATE RH <i>See X</i>		
1	REAR EXHAUST SILENCES BOX <i>See X</i>		
2	REAR EXHAUST SILENCES BOX BOLT <i>See X</i>		
3	REAR EXHAUST RUBBER MOUNTING <i>See X</i>		
1	REAR EXHAUST GASKET <i>See X</i>		
1	EXHAUST MID PIPE <i>See X</i>		
3	EXHAUST MID PIPE RUBBER MOUNTING ?		
1	EXHAUST MID PIPE GASKET ?		
1	FRONT DRIVER SEAT FRAME RH ?		
SUB TOTAL			\$0.00
Less 25%			\$0.00
PARTS TOTAL			\$0.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER <i>me</i>		
1	REAR TAILGATE WINDSCREEN SOLAR FILM <i>?</i>		
1	REAR TAILGATE NUMBER PLATE WIRH HOLDER <i>By ✓</i>		
1	REAR TAILGATE REVERSE CAMERA <i>?</i>		
1	REAR BUMPER REVERSE SENSOR <i>7m ✓</i>		
1	REAR LH/RH FENDER QUARTER GLASS SEALANT WITH PRIMER <i>me</i>		
1	REAR TYRE 225/65 R17 <i>Per 502m</i>		
S/N TOTAL			\$0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

3600 ✓
\$4,800.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

2200 ✓
\$4,200.00

TO TUFF KOTE / ANTI-RUST

\$80.00 ✓

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$80.00 501

TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA / INNER CAMERA RECORDER

601
\$80.00

TO CHECK WIRING WITH WATER LEAKAGE TEST

301
\$120.00

TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST

1201 \$150.00

TO REMOVE AND REINSTALL REAR LH/RH FENDER QUARTER GLASS PERFORM AND WATER LEAK TEST

\$100.00 ✓

TO DISMANTLE & REINSTALL INTERIOR CARPET, FRONT / REAR SEAT ASSY WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR

1501
\$350.00

TO DISMANTLE & REPLACED REAR EXHAUST WHOLE SYSTEM

1001 \$250.00

TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR

2401 \$380.00

TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED ALL WHEEL ALIGNMENT

\$80.00 ✓

TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION

2501 \$450.00

TOWING OF VEHICLE USING KING-DOLLIES (FOR RECOVERY OF VEHICLE IN MULTISTOREY / BASEMENT CARPARK & ACCIDENT VEHICLE WITH WHEELS DAMAGED) – 24 HOURS, INCLUSIVE OF SUNDAY OR PUBLIC HOLIDAYS

(Bill) \$100.00 ✓

LABOUR TOTAL \$11,220.00

PUI THENG

TOTAL

TO BE CONFIRM

Our Ref : SLM1268C / TP#680
Your Ref : SLM7176U

WITHOUT PREJUDICE

Date : 12 March 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 Shenton Way #07-16
Singapore 079120

Attention: Motor Claims Department

**ACCIDENT INVOLVING SLM1268C & SLM7176U ON 11/07/2018
ALONG THOMSON FLYOVER TOWARDS TUAS**

We refer to the above captioned.

We are claiming the below followings:

- Cost of Repair (incl. of GST)	S\$48,150.00
- Loss of Rental (incl. of GST)	S\$9,437.40 (S\$192,60 x 49 days)
- LTA/GIA Search Fee	S\$7.45
- GIA Report (SLM7176U)	S\$29.00
- Towing fee	S\$100.00

Grand Total **S\$57,723.85**

If you have any enquiries, please contact our representative, Ms. Sharon Ten & Ms. Lily at 64849919 or email sharon@ow.sg / lily.loi@ow.sg

All payment is to be issued direct to **Optima Werkz Pte Ltd.**

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD
Encl.

This is a computer generated printout and no signature is required.

View Received Message

This mail is associated with :

***SLM1268C (8029210677SG)
[SLM7176U]**

TP
CHANG HEW KIEN
Jul 11 2018 3:00PM
[LCRF Pte Ltd]
Optima Werkz Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 08/07/2019 10:46 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$53101.45) - SLM1268C - Claim Handler: Tee, Chee-Wah

Approved:53101.45.

DOCUMENTS SUMMARY

There are no documents.

Jia Le (LKK Auto)

From: Tee, Chee-Wah <Chee-Wah.Tee@aig.com>
Sent: Monday, 8 July 2019 10:50 AM
To: Jia Le (LKK Auto)
Cc: CS A Team
Subject: RE: (SEEK MANDATE) Your Ref: 8029210677SG [ACCIDENT INVOLVING SLM7176U & SLM1268C ON 11/07/2018]

Dear Carlor,

Mandate request approved in Merimen.
Thank you.

Tee Chee Wah
AIG
Complex Claims Examiner
Claims Department

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1089

Chee-Wah.Tee@aig.com | www.aig.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]
Sent: Monday, July 08, 2019 10:37 AM
To: Tee, Chee-Wah
Cc: CS A Team
Subject: [EXTERNAL] RE: (SEEK MANDATE) Your Ref: 8029210677SG [ACCIDENT INVOLVING SLM7176U & SLM1268C ON 11/07/2018]

This message is from an external sender; be cautious with links and attachments.

Dear Chee Wah,

We have changed the status to 'Adjuster Mandate Request' in Merimen.

Kindly let us have your approval.

Thank you.

Best Regards,

Carlhor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tee, Chee-Wah [mailto:Chee-Wah.Tee@aig.com]

Sent: Wednesday, 3 July 2019 5:32 PM

To: Jia Le (LKK Auto)

Cc: CS A Team

Subject: RE: (SEEK MANDATE) Your Ref: 8029210677SG [ACCIDENT INVOLVING SLM7176U & SLM1268C ON 11/07/2018]

Dear Jia Le,

Kindly route the status to 'Adjuster Mandate Request' in Merimen.

Thank you.

Tee Chee Wah

AIG

Complex Claims Examiner

Claims Department

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1089

Chee-Wah.Tee@aig.com | www.aig.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.

[Click here to find out more](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Tee, Chee-Wah

Sent: Monday, July 01, 2019 5:33 PM

To: Jia Le (LKK Auto)

Subject: RE: (SEEK MANDATE) Your Ref: 8029210677SG [ACCIDENT INVOLVING SLM7176U & SLM1268C ON 11/07/2018]

Dear Jia Le,

Kindly submit mandate request in Merimen and change the status to 'Adjuster Mandate Request'. Thank you.

Claim Audit	History Checking	Activity Log	
Reassign/Relabel	Assign Solicitor	File Review	Ad
Change Registration	Claim Details	Set/Modify Adj Mandate	

CLAIM SUBFOLDER TRACKING					
Case	Notified	Est Submitted	Adj Assigned	Adj Submitted	In
Main	19 Jul 2018		17 Jul 2018 00:00		

Repairer:	Optima Werkz Pte Ltd (HQ) PROFILE 6 Kung Chong Road, 159143 Lang Kee - Tel: 64721313	Excess:
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah]	
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final F	
Init. Est. Repair Costs:	8,000 - 9,000	

Tee Chee Wah
AIG
Complex Claims Examiner
Claims Department

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1089

Chee-Wah.Tee@aig.com | www.aig.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Jia Le (LKK Auto) [<mailto:jiale@lkkauto.com>]
Sent: Friday, June 28, 2019 3:50 PM
To: Tee, Chee-Wah
Subject: [EXTERNAL] (SEEK MANDATE) Your Ref: 8029210677SG [ACCIDENT INVOLVING SLM7176U & SLM1268C ON 11/07/2018]

This message is from an external sender; be cautious with links and attachments.

AIG Ref: **8029210677SG**
LKK Ref: CC6/LCR18013016/Kda3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLM 7176U(OI) AND SLM 1268C(TP) ON 11/07/2018

We refer to the above matter.

It is a head-to-rear collision. Liability is not in our driver's favour.
We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "OPTIMA WERKZ PTE LTD" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 63,208.91	\$ 48,150.00
2. Loss of Rental (49days x \$180.00)(w/GST)	\$ 9,437.40	\$ 4,815.00 (30days x \$150.00)(w/GST)
3. LTA/ GIA Search Fee	\$ 36.45	\$ 36.45
4. Towing Fee	\$ 100.00	\$ 100.00
Total	\$ 72,782.76	\$ 53,101.45

****24days recommendation for repair + 4Sunday + 1PH + 1PRS = 30days**

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Jia Le (LKK Auto)

From: Sharon <sharon@ow.sg>
Sent: Thursday, 18 July 2019 11:07 AM
To: Jia Le (LKK Auto)
Cc: angela.tan@ow.sg; Lily Loi OW; Adeline Lim
Subject: Re: Finalise of SLM1268C
Attachments: 18072019104950.pdf

Without Prejudice

Dear Jia Le,

Enclosed the signed DV for your necessary action.

Thank you.

Best Regards,

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department
DID: (+65) 6481 1522 | Fax: (+65) 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 8 Kung Chong Road Singapore 159143 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112
Branch: 9A Serangoon North Ave 5 Singapore 554500 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011
Branch: 551 Upp Thomson Road Singapore 574415 Tel: (+65) 6452 8888 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person. Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

On 18-Jul-19 10:30 AM, Jia Le (LKK Auto) wrote:

WITHOUT PREJUDICE

Dear Sharon,

DV attached.

Thank you.

Best Regards,

Carlton Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon [<mailto:sharon@ow.sg>]

Sent: Tuesday, 16 July 2019 3:06 PM

To: Jia Le (LKK Auto)
Subject: Re: Finalises of SLM1268C

Without Prejudice

Dear Jia Le,

Our client accept your offer at \$53,000.00. Please send DV.

Thank you.

Best Regards,

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department
DID: (+65) 6481 1522 | Fax: (+65) 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143
Branch: 9A Serangoon North Ave 5 Singapore 554600
Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011
Tel: (+65) 6452 8868 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person. Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

On 15-Jul-19 2:20 PM, Jia Le (LKK Auto) wrote:

WITHOUT PREJUDICE

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLM 7176U & SLM 1268C ON 11/07/2018

We refer to the above matter.

We propose settlement at a global sum of \$53,000.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlør Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon [<mailto:sharon@ow.sg>]

Sent: Friday, 28 June 2019 11:33 AM

To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Subject: Finalises of SLM1268C

Dear Joy,

As per requested.

Thank you.

--

Best Regards,

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department

DID: (+65) 6481 1522 | Fax: (+65) 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143

Branch: 8A Serangoon North Ave 5 Singapore 554800

Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313

Tel: (+65) 6484 9919

Tel: (+65) 6452 8868

Fax: (+65) 6472 2112

Fax: (+65) 6481 1011

Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person. Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Friday, 20 July 2018 12:12 PM
To: Eileen Yap
Cc: Admin A; Vivian Lau (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: ACCIDENT INVOLVING SLM 7176U & SLM 1268C ON 11/07/2018 (15:30) ALONG PIE TOWARDS THOMSON FLYOVER

20 July 2018

LCRF PTE LTD

Policy Holder

Your Ref: SLM 7176U
Our Ref: CC6/LCR18013016/Kja3

Dear Sir/Madam,

ACCIDENT INVOLVING SLM 7176U & SLM 1268C ON 11/07/2018 (15:30) ALONG PIE TOWARDS THOMSON FLYOVER

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **SLM 1268C** against your insurance policy.

Based on the information on hand, we are of the opinion that we cannot be absolved from liability. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.


AUTHORISATION TO ACT


I/We Chang Hew Kien ("the third party claimant") of Blok 385
Bangkit Rd # 11-418(5) 670255 (address), owner of SLM1268C (vehicle
no.) hereby authorize Optima Werkz Pte Ltd ("the workshop")
to act for me with respect to my claim for repair costs and/or rental and/or loss of use
("claim") for my vehicle no. SLM1268C that was damaged pursuant to the accident which
occurred on 11/07/18 (date) along Thomson Highway towards Tmas
(location) involving vehicle no/s SLM71764 ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement of
my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 11 (day) of July (month) 2018 (year)


Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop"
(with chop)



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **OPTIMA WERKZ PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$53,000.00** (Global Sum) for vehicle no. **SLM 1268C** that was damaged pursuant to the accident which occurred on **11/07/2018** (date) along **THOMSON FLYOVER TOWARDS TUAS** involving vehicle no/s **SLM 7176U**.

This is pursuant to the inspection conducted on **17/07/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **CHANG HEW KIEN** ("the third party claimant") of vehicle no. **SLM 1268C** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLM 1268C** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 18 (day) of July (month) 2018 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Without Prejudice

"The contents of this document apply to property damages claim only. All personal injuries and damages arising therefore are not included from the ambit and application of this document."

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500

Tel (+65) 6484 9919 Fax: (+65) 6481 1101

Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Tel 64191000
Fax: 68357416

INV NO. : 121901549
INVOICE DATE : 12/03/2019
REF : TP#680
VEH NO. : SLM1268C
CAR MODEL : HARRIER ELEGANCE 2.0
CURRENT MILEAGE:
ADVISOR : ONG HOCK KONG
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
LUMP SUM REPAIRS AS RECOMMENDED BY SURVEYOR	1		45,000.00	45,000.00

Remarks: DOA: 11/07/18 @ 1520HRS
CLAIMANT: CHANG HEW KIEN
NRIC NO: S1593818H
TP VEHICLE: SLM7176U

Singapore Dollars: Forty-Eight Thousand One Hundred Fifty Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL	SGD	45,000.00
GST 7.00%	SGD	3,150.00
GRAND TOTAL	SGD	<u>48,150.00</u>

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs.

I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

3) Goods sold are not refundable/returnable.

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount

for Optima Werkz Pte Ltd



AUTHORISED SIGNATURE(S)

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500

Tel (+65) 6484 9919 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: CHANG HEW KIEN

BLK 255 BANGKIT ROAD
#11-418 SINGAPORE 670255

Tel 96409807

Fax:

INV NO. : 121806226
INVOICE DATE : 27/09/2018
REF : TP#680 - CR
VEH NO. : SLM1268C
MAKE : TOYOTA
MODEL : HARRIER 2.0 CVT
CURRENT MILEAGE:
ADVISOR : TP/OD
TERMS : COD

#	DESCRIPTION	QTY	UOM	U/P SGD	AMT SGD
1	CAR RENTAL CHARGES RENTAL AGREEMENT NO 2345 VEHICLE NO: SLL1425X MODEL: TOYOTA HARRIER FROM: 11-07-2018 TO 29-08-2018	49	DAYS	180.00	8,820.00

Remarks: DOA: 11/07/18 @ 1520HRS

Singapore Dollars: Nine Thousand Four Hundred Thirty-Seven And Cent Forty Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL SGD 8,820.00
GST 7.00% SGD 617.40
TOTAL SGD 9,437.40
Outstanding SGD 9,437.40

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs.

I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

3) Goods sold are not refundable/returnable.

For Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount.

Optima Werkz Pte Ltd

6 Kung Chong Rd Singapore 159143

Tel: +65 6472 1313 Fax: +65 6472 2112 Website: www.ow.sg

9A Serangoon North Ave 5 Singapore 554500

Tel: +65 6484 9919 Fax: +65 6481 1011

CO. REG NO. 201212455W

OPTIMA WERKZ



VEHICLE RENTAL AGREEMENT

No: 2345

HIRER'S PARTICULARS		Rental replacement	
Full Name: <u>Chang Hew Kien</u>		Vehicle No: <u>SLM 1268C</u>	Vehicle No: <u>SLL 1425X</u>
Nric/Passport No: <u>S1593815H</u>		Make/Model: <u>T/HARRIER</u>	Make/Model: <u>T/HARRIER</u>
Address: <u>BLK 255 Bangkit Rd #11-418</u>		Mileage Out: <u>38380</u>	<u>45250</u>
<u>Singapore 670255</u>			
Name & Address Employer:		DATE OUT <u>11.07.18</u>	TIME OUT <u>8.00</u> AM/PM
		DATE IN <u>29.8.18</u>	TIME IN <u>5.30</u> AM/PM
Occupation:	Driving Exp:	Signature: <u>[Signature]</u>	
Driving Licence No:	D/L Type: <u>Local/Int'l</u>	CHARGES	
Issue Date: <u>03/06/1984</u>	Date of Birth: <u>01/03/63</u>	SS	
Contact no(s):	HP: <u>9640 9807</u>	49 Day(s) @ <u>SS 180.00</u> per day	<u>\$8,820</u>
ADDITIONAL DRIVER'S PARTICULARS		Week(s) @ <u>SS</u> per day	
Full Name: <u>Loh Lai Heng</u>		Month(s) @ <u>SS</u> per day	
Nric/Passport No: <u>S1323466C</u>		Extension	
Address: <u>BLK 255 Bangkit Rd #11-418</u>		Delivery/Collection Charges	
<u>Singapore 670255</u>			
Contact no(s):	HP: <u>92712207</u>	Sub-Total	
Driving Licence No:	Driving Exp:	Petrol Level	
Issue Date: <u>08/08/1977</u>	D/L Type: <u>Local/Int'l</u>	Out E <u>1/4</u> 1/2 3/4 F	
Occupation:	Date of Birth: <u>27/05/58</u>	IN E <u>1/4</u> 1/2 3/4 F	
REMARKS:		MISC	
<u>EXCESS I - \$2,000</u>		TOTAL CHARGES (Inclusive of GST)	<u>\$9437.40</u>
<u>EXCESS II - \$2,000</u>		Less Deposit	
<u>[Signature]</u>		Balance Payable/Refundable	
		Refund received	

*IMPORTANT

- ONLY PERSON ABOVE 24 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE. AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- EXCESS - HIRER IS LIABLE TO PAY INSURANCE EXCESS/ES WHICH IS/ARE APPLICABLE UNDER THE RENTAL CAR INSURANCE POLICY IN ANY EACH ACCIDENT PLUS LOSS OF EARNINGS WHILE DAMAGED VEHICLE IS UNDER REPAIR.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. OUR INSURANCE DOES NOT COVER IN MALAYSIA.

I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDE OF THIS RENTAL AGREEMENT AND AGREE THEREOF.
I UNDERTAKE NOT TO USE OR LET OTHERS USE THE RENTAL VEHICLE TO CARRY OUT ANY ILLEGAL OR CRIMINAL ACTS
INCLUDING CARRYING OF DUTY UNPAID GOODS.

Hirer's
Signature: [Signature]
Date:

Driver's Signature
(if different from Hirer) [Signature]
Date:

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 12 Jul 2018 / 09:50:54

Receipt Date/Time : 12 Jul 2018 / 09:50:53

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180712-000387

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SLM7176U As at 11 Jul 2018/15:20:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.			
1	Insurance Enquiry - SLM7176U Enquiry Fee 20180712094845094757	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx4670		Credit Card: Visa /MasterCard	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

TP41680

SLM7176U



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
8 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-107716
Date of Request: 14/07/2018

Your Ref No: Online Purchase

Optima Werkz Pte Ltd
8 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 11/07/2018
Place of Accident: THOMSON FLYOVER TOWARDS TUAS
Client Vehicle No: SLM1268C

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-107716
Date of Request: 14/07/2018

Your Ref No: Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 11/07/2018
Place of Accident: THOMSON FLYOVER TOWARDS TUAS
Client Vehicle No: SLM1268C

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SLM7176U	ALONG PIE TWDS TUAS AFT THOMSON FLYOVER	11/07/2018 15:30

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-107833
Date of Request: 16/07/2018

Your Ref No: Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Date of Accident: 11/07/2018
Vehicle No: SLM1268C
Place of Accident: THOMSON FLYOVER TOWARDS TUAS
Involving Vehicle No: SLM7176U

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLM7176U	THOMSON FLYOVER TOWARDS TUAS	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



ISLAND TOWING SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400 Email: islandrecovery@gmail.com

Facsimile: 6844 7233 Web: www.islandrecovery.com.sg

Co. Reg. 53269210A

Cash Sales/ Work Order

NO. 36609

Date: 11-7-18

M/S:

Optima Werkz

Vehicle No: SLM 1268 C

Model: Toyota Harrier

From: 2 Whitley Rd.

Time Start: 16:49 PM

To: 9A Serangoon North AVE 5

Time End: 18:24 PM

Remarks:

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☒ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 100K

Received By

Y93 120 Ah Peng
Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING





































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2018 Edit Reg		17 Jul 2018 00:00 Edit Adj Rpt	\$545,000.00 Edit Estimates	\$545,000.00 View Rpt		Pending for Survey Report Cancel Case



































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	CHANG HEW KIEN, ID: S1593818H								
Vehicle Reg. No.:	SLM1268C	Date of Loss:	11/07/2018 15:00 - :59 [15 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8029210677SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLM7176U	Policy No. (Claimant):	5088536382-01						
		Excess:							
Repairer:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road, 159143 Leng Kee - Tel: 64721313								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (08/07/2019): Alert - Adj Mandate Approved (\$53101.45) - SLM1268C - Claim Handler: Tee, Chee-... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM1268C (8029210677SG)
[SLM7176U]
TP
CHANG HEW KIEN
Jul 11 2018 3:00PM
[LCRF PTE LTD]
Optima Werkz Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
2	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
3	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
4	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
5	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
6	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
7	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
8	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
9	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
10	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
11	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
12	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
13	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
14	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
15	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
16	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
17	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
18	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
19	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
20	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
21	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
22	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
23	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
24	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
25	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
26	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
27	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
28	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
29	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
30	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
31	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
32	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
33	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		
34	20/07/18 12:15	General View		Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	20/07/18 12:15	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/07/18 12:15	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/07/18 12:15	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/07/18 12:15	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	05/07/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	05/07/19 15:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 20:27	TP GIA REPORT	 Load PDF	
2	19/07/18 11:29	TP ESTIMATE - MARKED	 Load PDF	
3	20/07/18 12:14	LETTER TO LCRF	 Load PDF	
4	28/06/19 15:27	LTA/GIA Search Fee	 Load PDF	
5	28/06/19 15:27	RENTAL RECEIPT	 Load PDF	
6	28/06/19 15:27	TOWING	 Load PDF	
7	23/07/19 09:49	WORKSHOP INVOICE	 Load PDF	
8	23/07/19 09:49	AUTHORISATION TO ACT FORM	 Load PDF	
9	23/07/19 09:49	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/07/18 15:06	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLM7176U (Insd veh)	Model:	TOYOTA HARRIER 2.0 (A)
	SLM1268C (TP veh)		
Date of Accident:	11/07/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		65,095.71
Final Repair Cost	:	\$		53,000.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		30 days
LTA / GIA Search Fee	:	\$		
Others: Towing Fee	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		53,000.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Optima Werkz Pte Ltd	: \$	53,000.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

23 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18013016/KDA3Q2

Date: 23/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLM1268C

Insured Vehicle No : SLM7176U

Date of Loss: 11/07/2018

Nature of Claim: TP

Claim No: 8029210677SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM1268C

Make & Model: TOYOTA HARRIER, 2.0 (A)

Reg. Date: 21/03/2017 (Man. Year: 2016)

Colour: Metallic Black

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 3ZRB971561

Chassis No: ZSU600099823

Odometer: 40564 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size: 225/65 R17

Front Left Side: Michelin 9 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 9 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,617.11	40,862.88	8,754.23	17.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,220.00	7,160.00	4,060.00	36.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	60,837.11	48,022.88	12,814.23	21.06
Approved Total (Overridden) (S\$)		45,000.00		
(S\$)	60,837.11	45,000.00	15,837.11	26.03
+ GST 7.00/7.00% (S\$)	4,258.60	3,150.00	1,108.60	26.03
Nett Amount (S\$)	65,095.71	48,150.00	16,945.71	26.03
+ Car Rental (30.0 x S\$150.00/day + 7.00% GST) (S\$)		4,815.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		53,101.45		
Global Sum Settlement (S\$)		53,000.00		

INSPECTION

Date of Assignment: 17/07/2018

Date Inspected: 17/07/2018 Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 24.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	2,275.30 FL	*2,275.30 FL
2	1		*REAR TAILGATE WINDSCREEN	Serviceable	1,251.70 FL	*- FL
3	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	203.00 FL	*203.00 FL
4	1		*REAR TAILGATE WINDSCREEN INNER GARNISH TOP	Serviceable	130.60 FL	*- FL
5	1		*REAR TAILGATE WINDSCREEN INNER GARNISH SIDE LH/RH	N/S Dented	217.00 FL	*108.50 FL
6	8		*REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS	Necessary	52.00 FL	*52.00 FL
7	1		*REAR TAILGATE WEATHERSTRIP	Distorted /Cut	357.00 FL	*357.00 FL
8	1		*REAR TAILGATE SPOILER	Serviceable	3,981.60 FL	*- FL
9	8		*REAR TAILGATE SPOILER CLIPS	Not Necessary	44.00 FL	*- FL
10	2		*REAR TAILGATE HINGE LH/RH	Bent	277.20 FL	*277.20 FL
11	2		*REAR TAILGATE DAMPLE LH/RH	Punctured	792.60 FL	*792.60 FL
12	1		*REAR TAILGATE OUTER GARNISH	Cracked	1,132.50 FL	*1,132.50 FL
13	1		*REAR TAILGATE OUTER LOCK HANDLE SWITCH	Dented	147.90 FL	*147.90 FL
14	2		*REAR TAILGATE NUMBER PLATE LAMP LH/RH	Serviceable	240.00 FL	*- FL
15	1		*REAR TAILGATE NUMBER PLATE LAMP COVER LH	Scratched	48.10 FL	*48.10 FL
16	1		*REAR TAILGATE EMBLEM LOGO	Necessary	50.80 FL	*50.80 FL
17	1		*REAR TAILGATE EMBLEM HARRIER	Necessary	75.30 FL	*75.30 FL
18	2		*REAR TAILGATE REFLECTOR LAMP LH/RH	Cracked	960.12 FL	*960.12 FL
19	6		*REAR TAILGATE REFLECTOR LAMP CLIPS	Necessary	33.00 FL	*33.00 FL
20	1		*REAR TAILGATE INNER UPHOLSTERY BOARD	Deformed	2,080.00 FL	*2,080.00 FL
21	14		*REAR TAILGATE INNER UPHOLSTERY BOARD CLIPS	Necessary	91.00 FL	*91.00 FL
22	2		*REAR TAILGATE INNER HANDLE LH/RH	Missing	96.40 FL	*96.40 FL
23	2		*REAR TAILGATE RUBBER STOPPER	Necessary	30.00 FL	*30.00 FL
24	1		*REAR TAILGATE MECHANISM LOCK	Dented	559.70 FL	*559.70 FL
25	1		*REAR TAILGATE MECHANISM LOCK GARNISH	Dented	24.90 FL	*24.90 FL
26	1		*REAR TAILGATE WIPER MOTOR	Jammed	833.90 FL	*833.90 FL
27	2		*REAR TAILLAMP LH/RH	O/S Cracked / N/S Mtg Cracked	945.40 FL	*945.40 FL
28	6		*REAR TAILLAMP CLIPS	Necessary	66.00 FL	*66.00 FL
29	2		*REAR TAILLAMP LOWER BRACKET LH/RH	Distorted	181.40 FL	*181.40 FL
30	2		*REAR TAILLAMP INNER PANEL LH/RH	Bent	557.20 FL	*557.20 FL
31	2		*REAR FENDER LH/RH	Bent / Buckled	3,236.60 FL	*3,236.60 FL
32	2		*REAR FENDER INNER SHIELD LH/RH	Missing	518.60 FL	*518.60 FL
33	2		*REAR FENDER INNER SHIELD CLIPS LH/RH	Necessary	13.00 FL	*13.00 FL
34	2		*REAR FENDER INNER UPHOLSTERY TRIM BOARD LH/RH	Deformed	1,456.60 FL	*1,456.60 FL
35	12		*REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS LH/RH	Necessary	66.00 FL	*66.00 FL
36	2		*REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS (SPECIAL)	Necessary	13.00 FL	*13.00 FL
37	1		*REAR FENDER INNER AIR VENT LH	Cracked	124.60 FL	*124.60 FL
38	2		*REAR FENDER INNER PANEL LH/RH	Repair	747.20 FL	*- FL
39	2			Necessary	416.00 FL	*416.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR FENDER QUARTER GLASS WITH MOULDING LH/RH			
40	1		*REAR WHEELHOUSE INNER PANEL RH	Bent	358.70 FL	*358.70 FL
41	1		*REAR WHEELHOUSE OUTER PANEL RH	Bent	358.70 FL	*358.70 FL
42	1		*REAR BUMPER	Missing	1,385.40 FL	*1,385.40 FL
43	2		*REAR BUMPER SCREW WITH CLIPS LH/RH	Necessary	24.20 FL	*24.20 FL
44	12		*REAR BUMPER CLIPS	Necessary	78.00 FL	*78.00 FL
45	2		*REAR BUMPER SIDE RETAINER LH/RH	Cracked	178.20 FL	*178.20 FL
46	2		*REAR BUMPER INNER SIDE SHIELD LH/RH	Torn	171.20 FL	*171.20 FL
47	8		*REAR BUMPER INNER SIDE SHIELD CLIPS	Necessary	45.68 FL	*45.68 FL
48	1		*REAR BUMPER INNER SPONGE	Broken	120.60 FL	*120.60 FL
49	1		*REAR BUMPER LOWER DIFFUSER	Missing	466.60 FL	*466.60 FL
50	2		*REAR BUMPER REFLECTOR LH /RH	Missing	131.40 FL	*131.40 FL
51	1		*REAR END PANEL	Bent	788.01 FL	*788.01 FL
52	1		*REAR END PANEL LOCK STRIKER	Bent	42.30 FL	*42.30 FL
53	1		*REAR END PANEL INNER TOP GARNISH	Cracked	347.00 FL	*347.00 FL
54	6		*REAR END PANEL INNER TOP GARNISH CLIP	Necessary	37.26 FL	*37.26 FL
55	1		*REAR END PANEL TAILGATE ANTENA SENSOR	Cracked	153.20 FL	*153.20 FL
56	1		*REAR WELL PANEL	Bent / Buckled	785.60 FL	*785.60 FL
57	1		*REAR WELL PANEL LOWER CROSS MEMBER	Bent	686.30 FL	*686.30 FL
58	1		*REAR WELL PANEL INNER TOP TOOLS TRAY LH	Cracked	576.40 FL	*576.40 FL
59	1		*REAR WELL PANEL INNER TOP TOOLS TRAY RH	Cracked	497.80 FL	*497.80 FL
60	1		*REAR WELL SIDE PANEL INNER TOP TOOLS TRAY LH	Cracked	640.50 FL	*640.50 FL
61	1		*REAR WELL SIDE PANEL INNER TOP TOOLS TRAY RH	Cracked	445.20 FL	*445.20 FL
62	1		*REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (SMALL)	Deformed	729.60 FL	*729.60 FL
63	1		*REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (BIG)	Deformed	885.51 FL	*885.51 FL
64	1		*REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD LH	Cracked	215.70 FL	*215.70 FL
65	1		*REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD RH	Cracked	225.70 FL	*225.70 FL
66	1		*REAR WELL PANEL INNER UPHOLSTERY TRIM	Cracked	392.60 FL	*392.60 FL
67	1		*REAR SUB CHASSIS FRAME LH/RH	N/S Repair / O/S Buckled	451.56 FL	*225.78 FL
68	1		*REAR SUB CHASSIS FRAME TOW HOOK BRACKET	Bent	63.90 FL	*63.90 FL
69	1		*REAR 17 SPORT RIM LH/RH	O/S Dented	3,636.20 FL	*1,818.10 FL
70	1		*REAR SUSPENSION STABILIZER BAR	Distorted	384.20 FL	*384.20 FL
71	2		*REAR SUSPENSION STABILIZER BAR BRACKET LH/RH	Bent	57.20 FL	*57.20 FL
72	2		*REAR SUSPENSION STABILIZER BAR RUBBER BUSH LH/RH	Necessary	73.60 FL	*73.60 FL
73	2		*REAR SUSPENSION STABILIZER BAR LINK LH/RH	Distorted	251.40 FL	*251.40 FL
74	2		*REAR SUSPENSION SHOCK ABSORBER LH/RH	Bent	257.50 FL	*257.50 FL
75	1		*REAR SUSPENSION SHOCK ABSORBER BRACKET RH	Bent	148.71 FL	*148.71 FL
76	2		*REAR SUSPENSION TRAILING ARM LH/RH	Distorted	1,406.60 FL	*1,406.60 FL
77	1		*REAR SUSPENSION TRAILING ARM BRACKET RH	Bent	95.70 FL	*95.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
78	2		*REAR SUSPENSION THRU ARM LH/RH	Bent	590.60 FL	*590.60 FL
79	1		*REAR SUSPENSION LOWER ARM LH/RH	O/S Bent	1,057.20 FL	*528.60 FL
80	1		*REAR SUSPENSION LOWER ARM BOLT RH	Bent	18.90 FL	*18.90 FL
81	2		*REAR SUSPENSION COIL SPRING LH/RH	Serviceable	456.20 FL	*- FL
82	2		*REAR SUSPENSION KNUCKLE ARM LH/RH	Dented	847.20 FL	*847.20 FL
83	2		*REAR SUSPENSION KNUCKLE ARM BEARING LH/RH	Dented	1,701.20 FL	*1,701.20 FL
84	2		*REAR SUSPENSION TORSION ARM LH/RH	Distorted	571.40 FL	*571.40 FL
85	1		*REAR SUSPENSION CROSS MEMBER	Bent	2,521.40 FL	*2,521.40 FL
86	2		*REAR SUSPENSION CROSS MEMBER BRACKET LH/RH	Bent	145.20 FL	*145.20 FL
87	4		*REAR SUSPENSION CROSS MEMBER SKRU	Necessary (2 PCS ONLY)	100.00 FL	*50.00 FL
88	2		*REAR SUSPENSION CROSS MEMBER NUT LH /RH	Necessary	18.60 FL	*18.60 FL
89	2		*REAR SUSPENSION CROSS MEMBER BOLT (FRONT)LH/RH	Serviceable	30.00 FL	*- FL
90	2		*REAR SUSPENSION CROSS MEMBER BOLT (REAR)LH/RH	Necessary	30.00 FL	*30.00 FL
91	1		*REAR SUSPENSION LEVERING SENSOR	Shorted	182.70 FL	*182.70 FL
92	1		*REAR DISC BRAKE PIPE RH	Dented	132.10 FL	*132.10 FL
93	1		*REAR DISC BRAKE PIPE BRACKET RH	Distorted	58.60 FL	*58.60 FL
94	1		*REAR DISC BRAKE HOSE RH	Punctured	128.70 FL	*128.70 FL
95	1		*REAR DISC BRAKE ROTOR COVER PLATE RH	Bent	148.70 FL	*148.70 FL
96	1		*REAR EXHAUST SILENCES BOX	Bent	634.10 FL	*634.10 FL
97	2		*REAR EXHAUST SILENCES BOX BOLT	Necessary	37.40 FL	*37.40 FL
98	3		*REAR EXHAUST RUBBER MOUNTING	Torn	96.30 FL	*96.30 FL
99	1		*REAR EXHAUST GASKET	Necessary	85.60 FL	*85.60 FL
100	1		*EXHAUST MID PIPE	Bent	2,585.90 FL	*2,585.90 FL
101	3		*EXHAUST MID PIPE RUBBER MOUNTING	Distorted	96.30 FL	*96.30 FL
102	1		*EXHAUST MID PIPE GASKET	Necessary	42.30 FL	*42.30 FL
103	1		*FRONT DRIVER SEAT FRAME RH	Twisted / Bent	5,330.06 FL	*5,330.06 FL
104	1		*REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*100.00 FS
105	1		*REAR TAILGATE WINDSCREEN SOLAR FILM	Necessary	380.00 FS	*200.00 FS
106	1		*REAR TAILGATE NUMBER PLATE WITH HOLDER	Bent	65.00 FS	*65.00 FS
107	1		*REAR TAILGATE REVERSE CAMERA	Shorted	350.00 FS	*350.00 FS
108	1		*REAR BUMPER REVERSE SENSOR	Torn	380.00 FS	*380.00 FS
109	1		*REAR LH /RH FENDER QUARTER GLASS SEALANT WITH PRIMER	Necessary	60.00 FS	*60.00 FS
110	1		*REAR TYRE 225/65 R17 (50%)	Punctured	580.00 FS	*290.00 FS
111	2		*REAR FENDER QUARTER GLASS INNER GARNISH RH/LH	Deformed	824.50 FL	*824.50 FL
112	10		*REAR FENDER QUARTER GLASS INNER GARNISH CLIPS	Necessary	55.00 FL	*55.00 FL
113	1		*REAR WELL PANEL INSULATOR MAT	Cracked	350.00 FL	*350.00 FL
114	1		*REAR SEAT LH (PASSENGER UPHOLSTERY TRIM BOARD)	Cracked	1,055.60 FL	*433.25 FL
115	1		*REAR SEAT RH (PASSENGER UPHOLSTERY TRIM BOARD)	Cracked	798.50 FL	*307.50 FL
116	1		*SET REAR END PANEL TAILGATE ANTENA SENSOR WIRE HARDNESS	Torn	240.70 FL	*240.70 FL
117	1		*REAR SUSPENSION LEVERING SENSOR WIRE HARDNESS	Torn	230.70 FL	*230.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
118	2		*REAR FENDER QUARTER GLASS SOLAR FILM	Necessary	360.00 FS	*120.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					65,397.81	53,962.18
- List Item Discount on L Items 25.00/25.00% (\$\$)					15,780.70	13,099.30
Total Parts (\$\$)					49,617.11	40,862.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACED WITH PANEL BEARING ALL ACCIDENT PORTION	New	4,800.00	3,600.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	4,200.00	2,200.00
3	TO TUFF KOTE/ANTI RUST	New	80.00	80.00
4	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	New	80.00	50.00
5	TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA /INNER CAMERA RECORDER	New	80.00	60.00
6	TO CHECK WIRING WITH WATER LEAKAGE TEST	New	120.00	30.00
7	TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	New	150.00	120.00
8	TO REMOVE AND REINSTALL REAR LH/RH FENDER QUARTER GLASS PERFORM AND WATER LEAK TEST	New	100.00	100.00
9	TO DISMANTLE & REINSTALL INTERIOR CARPET ,FRONT /REAR SEAT ASSY WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	350.00	150.00
10	TO DISMANTLE & REPLACED REAR EXHAUST WHOLE SYSTEM	New	250.00	100.00
11	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	New	380.00	240.00
12	TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	80.00	80.00
13	TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR O LINER TO FACILITATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	New	450.00	250.00
14	TOWING OF VEHICLE USING KING-DOLLIES (FOR RECOVERY OF VEHICLE IN MULTISTOREY /BASEMENT CARPARK & ACCIDENT VEHICLE WITH WHEELS DAMAGED)-24 HOURS,INCLUSIVE OF SUNDRY OR PUBLIC HOLIDAYS	New	100.00	100.00
Gross Labour Cost (S\$)			11,220.00	7,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >