

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer:

AIG

Vehicle No: SLM1268C

Third Party Veh No:

SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident:

11 JULY 2018

Chassis: ZSU600099823

Not Notarized
I.B.I
Resurvey B4 pain

24 days

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>B1 ✓</i>		
1	REAR TAILGATE WINDSCREEN <i>?</i>		
1	REAR TAILGATE WINDSCREEN MOULDING <i>me ✓</i>		
1	REAR TAILGATE WINDSCREEN INNER GARNISH TOP <i>sm x</i>		
2	REAR TAILGATE WINDSCREEN INNER GARNISH SIDE LH/RH <i>n/s Ad Lt</i>		
8	REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS <i>me ✓</i>		
1	REAR TAILGATE WEATHER STRIP <i>Dis/lt ✓</i>		
1	REAR TAILGATE SPOILER <i>?</i>		
8	REAR TAILGATE SPOILER CLIPS <i>?</i>		
2	REAR TAILGATE HINGE LH/RH <i>?</i>		
2	REAR TAILGATE DAMPLE LH/RH <i>?</i>		
1	REAR TAILGATE OUTER GARNISH <i>?</i>		
1	REAR TAILGATE OUTER LOCK HANDLE SWITCH <i>?</i>		
2	REAR TAILGATE NUMBER PLATE LAMP LH/RH <i>sm x</i>		
1	REAR TAILGATE NUMBER PLATE LAMP COVER LH <i>?</i>		
1	REAR TAILGATE EMBLEM 'LOGO' <i>me ✓</i>		
1	REAR TAILGATE EMBLEM 'HARRIER' <i>me ✓</i>		
2	REAR TAILGATE REFLECTOR LAMP LH/RH <i>cm ✓</i>		
6	REAR TAILGATE REFLECTOR LAMP CLIPS <i>me ✓</i>		
1	REAR TAILGATE INNER UPHOLSTERY BOARD <i>Return</i>		
14	REAR TAILGATE INNER UPHOLSTERY BOARD CLIPS <i>me ✓</i>		
2	REAR TAILGATE INNER HANDLE LH/RH <i>me ✓</i>		
2	REAR TAILGATE RUBBER STOPPER <i>me ✓</i>		
1	REAR TAILGATE MECHANISM LOCK <i>me ✓</i>		
1	REAR TAILGATE MECHANISM LOCK GARNISH <i>me ✓</i>		
1	REAR TAILGATE WIPER MOTOR <i>?</i>		
2	REAR TAILLAMP LH/RH <i>dis/lt n/s ? Lt</i>		
6	REAR TAILLAMP CLIPS <i>me ✓</i>		
2	REAR TAILLAMP LOWER BRACKET LH/RH <i>Dis ✓</i>		
2	REAR TAILLAMP INNER PANEL LH/RH <i>B1 ✓</i>		
2	REAR FENDER LH/RH <i>B1/B2 ✓</i>		
2	REAR FENDER INNER SHILED LH/RH <i>me ✓</i>		
2	REAR FENDER INNER SHIELD CLIPS LH/RH <i>me ✓</i>		
2	REAR FENDER INNER UPHOLSTERY TRIM BOARD LH/RH <i>Return</i>		
12	REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS LH/RH <i>me ✓</i>		
2	REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS (SPECIAL) <i>?</i>		

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer:

AIG

Vehicle No: SLM1268C

Third Party Veh No:

SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident:

11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR FENDER INNER AIR VENT LH <i>CM ✓</i>		
2	REAR FENDER INNER PANEL LH/RH <i>?</i>		
2	REAR FENDER QUARTER GLASS WITH MOULDING LH/RH <i>me ✓</i>		
1	REAR WHEELHOUSE INNER PANEL RH <i>?</i>		
1	REAR WHEELHOUSE OUTER PANEL RH <i>?</i>		
1	REAR BUMPER <i>me ✓</i>		
2	REAR BUMPER SCREW WITH CLIPS LH/RH <i>me ✓</i>		
12	REAR BUMPER CLIPS <i>me ✓</i>		
2	REAR BUMPER SIDE RETAINER LH/RH <i>CM ✓</i>		
2	REAR BUMPER INNER SIDE SHIELD LH/RH <i>TA ✓</i>		
8	REAR BUMPER INNER SIDE SHIELD CLIPS <i>me ✓</i>		
1	REAR BUMPER INNER SPONGE <i>Bo ✓</i>		
1	REAR BUMPER LOWER DIFFUSER <i>me ✓</i>		
2	REAR BUMPER REFLECTOR LH/RH <i>me ✓</i>		
1	REAR END PANEL <i>BT ✓</i>		
1	REAR END PANEL LOCK STRIKER <i>BT ✓</i>		
1	REAR END PANEL INNER TOP GARNISH <i>CM ✓</i>		
6	REAR END PANEL INNER TOP GARNISH CLIP <i>me ✓</i>		
1	REAR END PANEL TAILGATE ANTENA SENSOR <i>?</i>		
1	REAR WELL PANEL <i>BT/Bo ✓</i>		
1	REAR WELL PANEL LOWER CROSS MEMBER <i>BT ✓</i>		
1	REAR WELL PANEL INNER TOP TOOLS TRAY LH <i>CM ✓</i>		
1	REAR WELL PANEL INNER TOP TOOLS TRAY RH <i>CM ✓</i>		
1	REAR WELL SIDE PANEL INNER TOP TOOLS TRAY LH <i>?</i>		
1	REAR WELL SIDE PANEL INNER TOP TOOLS TRAY RH <i>?</i>		
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (SMALL) <i>?</i>		
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD (BIG) <i>?</i>		
1	REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD LH <i>?</i>		
1	REAR WELL SIDE PANEL INNER TOP UPHOLSTERY BOARD RH <i>?</i>		
1	REAR WELL PANEL INNER UPHOLSTERY TRIM <i>CM ✓</i>		
2	REAR SUB CHASSIS FRAME LH/RH <i>me ✓</i>		
1	REAR SUB CHASSIS FRAME TOW HOOK BRACKET <i>BT ✓</i>		
2	REAR 17" SPORT RIM LH/RH <i>CL/Red ✓</i>		
1	REAR SUSPENSION STABILIZER BAR <i>?</i>		
2	REAR SUSPENSION STABILIZER BAR BRACKET LH/RH <i>?</i>		
2	REAR SUSPENSION STABILIZER BAR RUBBER BUSH LH/RH <i>?</i>		
2	REAR SUSPENSION STABILIZER BAR LINK LH/RH <i>?</i>		
2	REAR SUSPENSION SHOCK ABSORBER LH/RH <i>?</i>		

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	12 JULY 2018	Third Party Insurer:	AIG
Vehicle No:	SLM1268C	Third Party Veh No:	SLM7176U
Model:	TOYOTA HARRIER ELEGANCE 2.0 CVT SR	Date of Accident:	11 JULY 2018
Chassis:	ZSU600099823		

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR SUSPENSION SHOCK ABSORBER BRACKET RH ?		
2	REAR SUSPENSION TRAILING ARM LH/RH ?		
1	REAR SUSPENSION TRAILING ARM BRACKET RH ?		
2	REAR SUSPENSION THRUS ARM LH/RH ?		
2	REAR SUSPENSION LOWER ARM LH/RH <i>dis R/L</i>		
1	REAR SUSPENSION LOWER ARM BOLT RH ?		
2	REAR SUSPENSION COIL SPRING LH/RH ?		
2	REAR SUSPENSION KNUCKLE ARM LH/RH <i>Sm X</i>		
2	REAR SUSPENSION KNUCKLE ARM BEARING LH/RH <i>na X</i>		
2	REAR SUSPENSION TORSION ARM LH/RH ?		
1	REAR SUSPENSION CROSS MEMBER ?		
2	REAR SUSPENSION CROSS MEMBER BRACKET LH/RH ?		
4	REAR SUSPENSION CROSS MEMBER SKRU ?		
2	REAR SUSPENSION CROSS MEMBER NUT LH/RH ?		
2	REAR SUSPENSION CROSS MEMBER BOLT (FRONT) LH/RH ?		
2	REAR SUSPENSION CROSS MEMBER BOLT (REAR) LH/RH ?		
1	REAR SUSPENSION LEVERING SENSOR LH ?		
1	REAR DISC BRAKE PIPE RH <i>Sm X</i>		
1	REAR DISC BRAKE PIPE BRACKET RH ?		
1	REAR DISC BRAKE HOSE RH <i>Sm X</i>		
1	REAR DISC BRAKE ROTOR COVER PLATE RH <i>Sm X</i>		
1	REAR EXHAUST SILENCES BOX <i>Br ✓</i>		
2	REAR EXHAUST SILENCES BOX BOLT <i>Mr ✓</i>		
3	REAR EXHAUST RUBBER MOUNTING <i>Tr ✓</i>		
1	REAR EXHAUST GASKET <i>Mr ✓</i>		
1	EXHAUST MID PIPE <i>B ?</i>		
3	EXHAUST MID PIPE RUBBER MOUNTING ?		
1	EXHAUST MID PIPE GASKET ?		
1	FRONT DRIVER SEAT FRAME RH ?		
SUB TOTAL			\$0.00
Less 25%			\$0.00
PARTS TOTAL			\$0.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 JULY 2018

Third Party Insurer: AIG

Vehicle No: SLM1268C

Third Party Veh No: SLM7176U

Model: TOYOTA HARRIER ELEGANCE 2.0 CVT SR

Date of Accident: 11 JULY 2018

Chassis: ZSU600099823

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER <i>me</i>		
1	REAR TAILGATE WINDSCREEN SOLAR FILM <i>?</i>		
1	REAR TAILGATE NUMBER PLATE WIRH HOLDER <i>B4 ✓</i>		
1	REAR TAILGATE REVERSE CAMERA <i>?</i>		
1	REAR BUMPER REVERSE SENSOR <i>7m ✓</i>		
1	REAR LH/RH FENDER QUARTER GLASS SEALANT WITH PRIMER <i>me</i>		
1	REAR TYRE 225/65 R17 <i>Per 508m</i>		
		S/N TOTAL	\$0.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	12 JULY 2018	Third Party Insurer:	AIG
Vehicle No:	SLM1268C	Third Party Veh No:	SLM7176U
Model:	TOYOTA HARRIER ELEGANCE 2.0 CVT SR	Date of Accident:	11 JULY 2018
Chassis:	ZSU600099823		

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	3600	\$4,800.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	2200	\$4,200.00
TO TUFF KOTE / ANTI-RUST		\$80.00 ✓
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR		\$80.00 50
TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA / INNER CAMERA RECORDER	60	\$80.00
TO CHECK WIRING WITH WATER LEAKAGE TEST	30	\$120.00
TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	120	\$150.00
TO REMOVE AND REINSTALL REAR LH/RH FENDER QUARTER GLASS PERFORM AND WATER LEAK TEST		\$100.00 ✓
TO DISMANTLE & REINSTALL INTERIOR CARPET, FRONT / REAR SEAT ASSY WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	150	\$350.00
TO DISMANTLE & REPLACED REAR EXHAUST WHOLE SYSTEM	100	\$250.00
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	240	\$380.00
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED ALL WHEEL ALIGNMENT		\$80.00 ✓
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	250	\$450.00
TOWING OF VEHICLE USING KING-DOLLIES (FOR RECOVERY OF VEHICLE IN MULTISTOREY / BASEMENT CARPARK & ACCIDENT VEHICLE WITH WHEELS DAMAGED) – 24 HOURS, INCLUSIVE OF SUNDAY OR PUBLIC HOLIDAYS	(Bill)	\$100.00 ✓

LABOUR TOTAL \$11,220.00

PUI THENG	TOTAL	TO BE CONFIRM
-----------	-------	---------------