



SLQ4850E

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 30-06-18

Vehicle Reg. No. : SLQ4850E
Vehicle Reg. Date: 12-Jul-2017
Make / Model : T. SIENTA HYBRID 1.5X A
Engine No. : 1NZR446472
Chassis No. : NHP1707058967

COST OF CLAIMS

Parts Cost / List Items : \$ 8,870.00
Plus/Less 25% \$ 2,217.50
Total Cost / List : \$ 6,652.50
Special Nett Items : \$ 80.00
Total Parts Amount : \$ 6,732.50
Total Labour Amount : \$ 3,460.00
Gross Total : \$ 10,192.50
GST % : 7% \$ 713.48
Nett Amount : \$ 10,905.98

Surveyor Name and Company :

Rasul (LKK)

Date of survey : 18/07/18 @ 0920

Part by Part (Lump Sum) : 3 days

Resurvey Before Paint (After Paint)

Authorize/Not Authorize/Without Prejudice

Email : rasul@lkkauto.com

Fax No :

HP No :

90015068

This claim is handled by :

MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLQ4850E**

Vehicle Reg. Date: 12-07-17

Make / Model : T. SIENTA HYBRID 1.5X A

Engine No. : 1NZR446472

Chassis No. : NHP1707058967

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear sliding door LH	repair	\$ 1,658.00		
2	1	Rear sliding door outer handle LH	X	\$ 388.10		
3	1	Rear sliding door lock (front) LH	X	\$ 290.10		
4	1	Rear sliding door lock (back) LH	X	\$ 380.40		
5	1	Rear sliding door bearing LH	X	\$ 119.40		
6	1	Rear sliding door inner trimboard LH	X	\$ 1,534.50		
7	1set	Rear sliding door inner trimboard clips	X	\$ 40.00		
8	1	Rear sliding door power regulator LH	X	\$ 269.40		
9	1	Rear sliding door power regulator motor LH	X	\$ 265.40		
10	1	Rear sliding door outer channel LH	X	\$ 395.40		
11	1	Rear sliding door outer sticker LH	X	\$ 189.00		
12	1	Rear sliding door rubber LH	X	\$ 79.90		
13	1	Rear sliding door outer handle LH	X	\$ 241.40		
14	1	Rear fender LH	repair	\$ 1,676.00		
15	1	Rear fender garnish lower LH	sur	\$ 94.00		
16	1	Rear fender garnish upper LH	X	\$ 180.00		
17	1	Rear fender air duct LH	X	\$ 75.00		
18	1	Rear shock absorber LH	X	\$ 207.00		
19	1	Rear shock mounting LH	X	\$ 53.00		
20	1	Rear wheel hub with bearing LH	X	\$ 575.00		
21	1	Rear fender sealant	X		\$ 80.00	
22	1	Rear rim cover LH	sur	\$ 159.00		
23	0	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLQ4850E
Vehicle Reg. Date:	12-07-17
Make / Model :	T. SIENTA HYBRID 1.5X A
Engine No. :	1NZR446472
Chassis No. :	NHP1707058967

Estimates on Labour

[illegible]