

ASSIGNMENT

From: _____ Date: 29/03/2018
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLQ 6510Z
 at Workshop m/s: Allswell motor
 of: 25 Dela Lane 9
 Insured: 6679 1146
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: Hyam
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 300 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLQ 6510Z Yr Regn: 18 Jul 2017
 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Hybrid
 Make: Honda Vezel c.c. 1496
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 59/92 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: RU31248445
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size F: 215/60R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 86 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A.: 29-03-18
 Survey held at: W/S 11:30 AM
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 N/S Frt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: \$2,800 - \$4,000
Finalized - \$1369.44 with Ben.
 RECEIVED 10 JUL 2018
 NO BILLING AS CHARGE BEFORE PRS.

Date/Time, File Pass to? ☐ : Preli. Report
 18/7 Typist ☒ : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: 3
 Resurvey No. of Trip: 1
 Survey Fee: _____
 Transportation: _____
 Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Term Insp (\$)
☐ West-end (\$)
 Report Format: _____
 Lump Sum / I.B.I: (\$)
 TOTAL: _____

29/3/18.

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

(3rd party claim against Sompoo Insured VN 7324 A)

Estimate repair

Vehicle No. : SLA 6570Z
 Make & Model : Honda Vezel Hybrid
 Chassis No. :
 Date of survey :

Submitted by : Ben
 COE expiry : 17.07.2027
 Engine No. :

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01.	L/H mirror / Dis	01	\$792.6	720	
01a	L/H headlamp X NN	01	\$1190.6	*	repair *
02.	L/H mirror cover / cut	01	\$91.80	/	
03.	Putty, sand paper, polish and wash at affected area (bonnet, fender LH & fender arc LH and LH mirror cover	01	\$660	600	
04.	Repolished L/H headlamp	01	\$60.0	X /	
05.	Installation of L/H mirror	01	\$60.0	X /	
			2855		
	@ 3 days.				
	884.44 811.8				
	25%: 663.3				
	649.44				
	+ 600 + 120				
	1249.44				
	1369.44				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

After repair photos.
 3 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2889J
Vehicle Details	
Vehicle No.:	SLQ6510Z
Vehicle to be Exported:	No
Intended De-registration Date:	13 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	LEB5948459
Chassis No.:	RU31248445
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,169.00
Original Registration Date:	18 Jul 2017
First Registration Date:	18 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$42,801.00
Total Rebate Amount:	\$46,551.00

The information contained herein is correct as at 13 Jul 2018

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18005671/Gtd3s2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623		Date : 19-07-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7324A	Veh. Inspected	SLQ 6510Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31248445	Colour	SILVER	
Odometer	059192	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	DUNLOP	6 mm	
L/H Front Tyre	215/60R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2018	Inspection Date	29/03/2018	
Survey held at	25 DEFU LANE 9			
Repairer	ALLSWELL MOTOR TRADERS			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 6510Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	L/H MIRROR	DISTORTED	792.60	720.00
1	L/H HEADLAMP	NOT NECESSARY	1,190.60	-
1	L/H MIRROR COVER	CUT	91.80	91.80
	LESS 20% DISCOUNT		-	-162.36
			2,075.00	649.44
	<u>LABOUR</u>			
	PUTTY, SAND PAPER, POLISH AND WASH AT AFFECTED AREA (BONNET, FENDER LH & FENDER ARC L/H AND L/H MIRROR COVER).		660.00	600.00
	REPOLISHED L/H HEADLAMP		60.00	60.00
	INSTALLATION OF L/H MIRROR.		60.00	60.00
			780.00	720.00
	GRAND TOTAL		2,855.00	1,369.44
RECOMMENDED COST OF REPAIRS				1,369.44

Report Ref No. CS3/SMO18005671/Gtd3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.