

RECEIVED 13 AUG 2018

17/8/8

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

1MV9527

Yr Regn:

1Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Polen Exorn

C.C.

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

305810

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PLIF26YRRTF058541Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

135/65R15

R:

135/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

07/04/16

Survey held at

NPT.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AKA.US \$ 3,600/-Red (\$6,429 / 64%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others


TOTAL

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 193607198R GST Reg. No: 19-6607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE SINGAPORE PTE LTD		Ref: CC4/AXA16016885/Ayp3	
8 SHENTON WAY #27-01 SINGAPORE 068811		Date: 07-09-2016	
		Code: AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKH 7887P	Veh. Inspected	JMV 9927
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/09/2016
2. Vehicle Particulars & Condition			
Make & Model		C.C	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/09/2016	Inspection Date	07/09/2016
Survey held at	NEW HOCK TECK MOTOR WORKSHOP BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS			



新 福 德 車 廠

NEW HOCK TECK MOTOR WORKSHOP

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

RCB No.: 52989088K GST Reg No.: M90368118A 07th Sep 2016

EOW FEH SAN

Blk C, 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 01st Sep 2016

Estimated repair cost for vehicle no: JMV9927 PROTON EXORA

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Fender		\$680.00
2	1	Front R/H Side Mirror Assy		\$580.00
3	1	Front R/H Door		\$1,600.00
4	2	Front R/H Door Hinge	\$85.00	\$170.00
5	1	Front R/H Door Outer Handle		\$165.00
6	1	Front R/H Door Lock		\$385.00
7	1	Front R/H Door Inner Rubber		\$190.00
8	1	Front R/H Door Inner Trim Board		\$750.00
9	1	Front R/H Door Gear Motor Assy		\$560.00
10	1	Front R/H Tyre		\$350.00
11	1	Front R/H Rim		\$650.00
12	1	R/H Side Skirt		\$680.00
13	6	R/H Side Skirt Clips	\$6.50	\$39.00

Subtotal :- \$6,799.00

Labour charges

To remove & refit front R/H fender quarter glass

\$120.00

Gum

\$50.00

To remove & refit front R/H door, gear glass motor, lock, rubber & trim board

\$280.00

To check wheel alignment

\$150.00

To check wiring

\$80.00

Tuff kote

\$150.00

Panel Beating

\$1,200.00

Spray Painting

\$1,200.00

Subtotal :- \$3,230.00

Total :- \$10,029.00

NEW HOCK TECK MOTOR WORKSHOP

Our Ref : JMV9927
Your Ref : SKH7887P
Date : 22nd November 2016

Block 1 Kaki Bukit Avenue 6
#01-43
Singapore 417883
Tel: (65) 6747 9241
Fax: (65) 67417276

Axa Insurance Singapore Pte Ltd
8 Shenton Way
#27-02 AXA Tower
Singapore 068811

Dear Sirs,

RE : Accident Involving JMV9927 & SKH7887P ON 01.09.2016 Along Slip Road After TPE Exit Along Tampines Avenue 12 Towards Airport At 09:00 HRS

We are instructed by **EOW FEH CHENG** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **JMV9927** was damaged by vehicle **SKH7887P** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows :-

1) Repair Costs	\$ 3,852.00
2) Loss of Use for 6 days [5 + 1 Weekend]	\$ 600.00
3) LTA Fee	\$ 5.35
	<u>\$ 4,457.35</u>

A copy each of the following supporting documents is enclosed :-

- 1) Accident report of our client
- 2) Final repair bill
- 3) LTA Receipt **SKH7887P**

Please let us have your cheque for the sum of **\$4,457.35** made payable to us, **NEW HOCK TECK MOTOR WORKSHOP** in the next 14 days

Yours faithfully,



NEW HOCK TECK MOTOR WORKSHOP



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

05 OCTOBER 2016

TAN LAY KHENG SELINA
722 BEDOK RESERVOIR ROAD
#14-16
SINGAPORE 479251

Dear Sir/Madam,

Our Ref : CC4/AXA16016885/Ayb3
Your Ref : SKH 7887P

**ACCIDENT INVOLVING SKH 7887P AND JMV 9927 ALONG/AT TAMPINES AVE 9 ON
01/09/2016**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s New Hock Teck Motor Workshop acting on behalf of the owner of JMV 9927 against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to jaskhine@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVENUE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2928 or email us at jaskhine@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Jas Khine
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: jaskhine@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd (AXA)
(Motor Claims Dept)

Attn: Motor Claim Department

Dear Sir,

CLAIMANT: EDW Feh Cheng
ACCIDENT INVOLVING JMV 9927 & SKH 7887P ON 01/09/16
ALONG Slip Rd After TPE Exit along Tampines Ave 12 AT 09:00
I/We EDW Feh Cheng am/are the registered owner of
motor no. JMV 9927 which was involved in the above accident with motor vehicle
registered no. SKH 7887P insured by you.

Please take note that I have assigned all compensation monies due to me / us in the above
accident to **M/S NEW HOCK TECK MOTOR WORKSHOP**

I/We, hereby authorize you to release all compensation monies pertaining to the above-
mentioned accident to **M/S NEW HOCK TECK MOTOR WORKSHOP** and forward your settlement
cheque to my solicitors, M/S _____ whom I had authorized to
collect the said compensation monies.

Thank you.



Claimant :
Authorised Signatory



Witness :
Date :



redefining insurance

CLAIM REF : C0398937
INSURED : TAN LAY KHENG SELINA

DISCHARGE VOUCHER

We/I EOW FEH HONG NRIC NO. 770512-14-5344 hereby agree to accept the sum of dollars TWO THOUSAND EIGHT HUNDRED ONLY. [S\$2,800.00] paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SKH 7887P] as a result of an accident along [SLIP ROAD AFTER TPE EXIT ALONG TAMPINES AVE 12 TOWARDS AIRPORT] on [01/09/2016] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [JMV 9927].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SKH 7887P] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SKH 7887P].

Dated this 07 day of 06 2018

Claimant's Signature : [Signature]

NRIC no./ Company Stamp : 770512-14-5344

Occupation/ Business : _____

Address : NO 27 Jalan Indah 10/12 Taman Bukit Indah

Telephone No. : 9788-9652

Witness's Name : 新 福 德 車 廠

Witness's Signature : [Signature]

Witness's NRIC No. : _____

NEW ROCK TECK MOTOR WORKSHOP
1 KAS BUKIT AVE 8, BUK C
#01-43 PULAU TENGKONG
Singapore 417803
TEL: 8747 0341 FAX: 6741 2276
Email: nrtw@rockteck.com.sg
ROB No: 520800626 GST Reg. No: M50308118A



新 福 德 車 廠

NEW HOCK TECK MOTOR WORKSHOP

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

RCB No.: 52989088K GST Reg No.: M90368118A

TAX INVOICE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#B1-01,
Singapore 068811

Client: EOW FEH CHENG

Invoice No : NPI1611-0360

Date : 22-Nov-16

Date of Accident : 01-Sep-16

Vehicle No. : JMV9927

Model Type : Proton Exora

Descriptions		Amount
Lump Sum Repair Cost		3,600.00
Sub Total		3,600.00
GST 7%		252.00
Total		3,852.00

SIN DOLLARS: THREE THOUSAND EIGHT HUNDRED AND FIFTY TWO ONLY



Text size + -

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 02 Sep 2016 / 11:25:52

Receipt Date/Time : 02 Sep 2016 / 11:25:52

Tax Invoice/Receipt

Receipt No. : ITNET-00000-160902-000656

Previous Receipt No. :

**S/N Item Description/
Business Transaction
Reference No.**

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SKH7887P

As at 01 Sep 2016/21:00:00

Insurance Co: AXA INSURANCE SINGAPORE PTE LTD

1 Insurance Enquiry - SKH7887P
Enquiry Fee
20160902112225909776

5.00	0.35	5.35
------	------	------

Sub-Total	5.00	0.35	5.35
------------------	------	------	------

Total Before Rounding	5.00	0.35	5.35
------------------------------	------	------	------

Rounding Difference			0.00
----------------------------	--	--	------

Total Amount Payable			5.35
-----------------------------	--	--	------

Paid By

20160902112245546	Direct Debit: eNETS Debit (Internet Banking)	5.35
-------------------	---	------

Total			5.35
--------------	--	--	------

Cash Change			0.00
--------------------	--	--	------

Tendered Amount			5.35
------------------------	--	--	------

Excess Refundable Amount			0.00
---------------------------------	--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Sep 2016		07 Sep 2016 14:19 Edit Adj Rpt	S\$3,600.00 Edit Estimates	S\$3,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN LAY KHENG SELINA , ID: S7248314F									
Main Claimant: EOW FEH CHENG , ID: G7257610T									
Vehicle Reg. No.: JMV9927		Date of Loss: 01/09/2016 00:00 - :59 [64 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / C0398937		Policy/Cover Note No.: P1807972 (Comprehensive)							
Vehicle Reg. No. (Insured): SKH7887P		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: New Hock Teck Motor Workshop (HQ) Blk 1, Kaki Bukit Avenue 6 #01-43, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241									
Handling Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Jas Tan - 6880 4844]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/07/2018]									
Driver/Custodian (Insured): PANG CHAN YEW DERRICK () , NRIC: S7220501D, Tel: +6598006030									
Adj Asg. Remarks: XS NIL									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (07/09/2016): C0398937/P1807972 AXA_SG (07/09/2016): New TP Assignment - C0398937/P1807972 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JMV9927 (C0398937)
[SKH7887P]
TP
EOW FEH CHENG
Sep 1 2016 12:00AM
[TAN LAY KHENG SELINA]
New Hock Teck Motor Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown												1	Edit					
Assessment Reports															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	08/12/17 13:22	Adjuster Immediate Advice												1	Load HTM					
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
2	13/01/17 09:55	Odometer Reading												1	Load JPG	<input checked="" type="checkbox"/>				
3	13/01/17 09:55	Chassis Number												1	Load JPG	<input checked="" type="checkbox"/>				
4	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
5	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
6	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
7	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
8	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
9	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
10	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
11	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
12	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
13	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
14	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
15	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
16	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
17	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
18	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
19	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
20	13/01/17 09:55	General View												1	Load JPG	<input checked="" type="checkbox"/>				
21	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
22	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
23	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
24	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
25	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
26	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
27	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
28	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
29	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
30	13/01/17 09:55	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	13/01/17 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	13/01/17 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	13/01/17 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	13/01/17 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	07/09/16 11:40	EMAIL_ABS	 Load PDF	
2	07/09/16 11:40	CO-CLAIMANT_ABS	 Load PDF	
3	07/09/16 11:40	SKH7887P INSD GIA REPORT_ABS	 Load PDF	
4	07/09/16 17:20	Email_ABS	 Load PDF	
5	09/09/16 10:54	CO CLAIMANT_ABS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/09/16 17:01	TP POLICE REPORT	 Load PDF	
2	08/09/16 17:01	Malaysia Vehicle Registration Card	 Load PDF	
3	20/01/17 14:24	Police Investigation Result	 Load JPG	<input checked="" type="checkbox"/>
4	08/12/17 11:12	EMAIL CORRESPONDENCE WITH TP	 Load PDF	
5	08/12/17 11:12	WORKSHOP ESTIMATE	 Load PDF	
6	19/12/17 15:41	LETTER TO OI	 Load PDF	
7	07/08/18 15:15	LKK Survey Photo	 Load PDF	
8	07/08/18 15:15	LKK Resurvey Photo	 Load PDF	
9	24/08/18 16:39	WORKSHOP INVOICE	 Load PDF	
10	24/08/18 16:39	AUTHORISATION TO ACT FORM	 Load PDF	
11	24/08/18 16:39	DISCHARGE VOUCHER	 Load PDF	
12	24/08/18 16:39	LTA SEARCH	 Load PDF	
13	24/08/18 16:39	LOD	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKH7887P (Insd veh)	Model:	PROTON EXORA A 1.6 (A)
	JMV9927 (TP veh)		
Date of Accident:	01/09/2016		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$	10,731.03	
Final Repair Cost	:	\$	3,852.00	
Loss of Use	:	\$	180.00	6.00 days at \$30.00 per day
Rental (if any)	:	\$	0.00	days
			@50% 2,016.00	
LTA / GIA Search Fee	:	\$	5.35	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum (Global Sum)	:	\$	2,800.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 50 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Workshop	:	\$ 2,800.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

24 Aug
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16016885/AEB3Q2-1

Date: 24/08/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1807972

Claimant Vehicle No : JMV9927

Insured Vehicle No :

SKH7887P

Date of Loss: 01/09/2016

Nature of Claim:

TP

Claim No: C0398937

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JMV9927

Make & Model: PROTON EXORA A, 1.6 (A)

Engine No: S4PHR02999

Reg. Date: 28/04/2011 (Man. Year: 2011)

Chassis No: PL1FZ6YRRBF058524

Colour: Silver

Odometer: 305810 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,799.00	3,225.60	3,573.40	52.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,290.00	1,940.00	60.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,029.00	4,515.60	5,513.40	54.97
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	10,029.00	3,600.00	6,429.00	64.10
+ GST 7.00/7.00% (S\$)	702.03	252.00	450.03	64.10
Nett Amount (S\$)	10,731.03	3,852.00	6,879.03	64.10
+ Loss of Use (6.0 x S\$30.00/day) (S\$)		180.00		
(S\$)		4,032.00		
Liabile Amount (50.00%) (S\$)		2,016.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		2,021.35		
Global Sum Settlement (S\$)		2,800.00		

INSPECTION

Date of Assignment: 07/09/2016
Date Inspected: 07/09/2016 Inspected At: New Hock Teck Motor Workshop (HQ)
Blk 1, Kaki Bukit Avenue 6 #01-43,
AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2017)
Parts: M1-MPV	PROTON EXORA A 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for JMV9927)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H FENDER (CONSISTENT)	Repair	680.00 F	*- FL
2	1		*FRONT R/H SIDE MIRROR ASSY (CONSISTENT)	Cracked	580.00 F	*580.00 FL
3	1		*FRONT R/H DOOR (CONSISTENT)	Dented	1,600.00 F	*1,150.00 FL
4	2		*FRONT R/H DOOR HINGE (CONSISTENT)	Not Necessary	170.00 F	*- FL
5	1		*FRONT R/H DOOR OUTER HANDLE (CONSISTENT)	Not Necessary	165.00 F	*- FL
6	1		*FRONT R/H DOOR LOCK (CONSISTENT)	Not Necessary	385.00 F	*- FL
7	1		*FRONT R/H DOOR INNER RUBBER (CONSISTENT)	Not Necessary	190.00 F	*- FL
8	1		*FRONT R/H DOOR GEAR MOTOR ASSY (CONSISTENT)	Damaged	560.00 F	*285.00 FL
9	1		*FRONT R/H TYRE (CONSISTENT)	Not Necessary	350.00 F	*- FL
10	1		*FRONT R/H RIM (CONSISTENT)	Cut	650.00 FS	*450.00 FS
11	1		*R/H SIDE SKIRT (CONSISTENT)	Cracked	680.00 F	*680.00 FL
12	6		*R/H SIDE SKIRT CLIPS (CONSISTENT)	Necessary	39.00 F	*39.00 FL
13	1		*FRONT R/H DOOR INNER TRIM BOARD (CONSISTENT)	Cracked	750.00 F	*350.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	6,799.00	3,534.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	308.40
Total Parts (\$\$)	6,799.00	3,225.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT R/H FENDER QUARTER GLASS	New	120.00	0.00
2	GUM	New	50.00	0.00
3	TO REMOVE & REFIT FRONT R/H DOOR ,GEAR GLASS MOTOR ,LOCK ,RUBBER & TRIM BOARD	New	280.00	80.00
4	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
5	TO CHECK WIRING	New	80.00	30.00
6	TUFF KOTE	New	150.00	0.00
7	PANEL BEATING	New	1,200.00	500.00
8	SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,230.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >