



ESTEEM PERFORMANCE PTE LTD


Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

GBF 6078 G

Parts	(a) Cost / List Price Items	\$	4,042.45
	Plus/Less 10%	\$	404.25
	Total of Cost / List	\$	3,638.21
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	3,638.21
Labour		\$	1,300.00
Total		\$	4,938.21

The above total will be subjected to 7% G.S.T.



Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 19/7/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Pe Date: 19/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **GBF 6078 G**
Make & Model : **VOLK T6**
Chassis No : **WV1ZZZ7HZHH043921**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp LH	1	\$691.10		✓
2	LH front fender	1	\$676.05		✓
3	LH front fender undershield	1	\$190.75		X
4	LH front fender undershield clip	10	\$25.00		X
5	Front bumper	1	\$1,393.80		✓
6	Front bumper clip	10	\$25.00		✓
7	Front bumper reinforcement	1	\$825.35		✓
8	Front bumper side retainer LH	1	\$28.35		✓
9	Front bumper side retainer RH	1	\$28.35		X
10	Front bumper bracket LH	1	\$47.25		X
11	Front bumper bracket RH	1	\$47.25		X
12	Front bumper sponge	1	\$64.20		X
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

