

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

17-Jul-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1404 x

Sundry

\$ ~~50.00~~ <sup>x</sup>

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, etc.

\$ ~~450.00~~ <sup>100</sup>

To putty and spray painting on front bumper

\$ ~~200.00~~ <sup>180</sup>

To apply rustproofing on the repaired and replaced panels.

\$ ~~80.00~~ <sup>x</sup>

\$ 780.00

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Kalish 10004

17/7/18 1605hr

2 Days

P/P

At the Repair shop

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: