

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

17-Jul-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1404 x

Sundry	\$ 50.00
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, etc.	\$ 450.00
To putty and spray painting on front bumper	\$ 200.00
To apply rustproofing on the repaired and replaced panels.	\$ 80.00
	<hr/>
	\$ 780.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.